

serviceable part, in accordance with the alert service bulletin.

(i) If the driver link is not serviceable, prior to further flight, replace it with a new or serviceable driver link, in accordance with the alert service bulletin.

(b) Within 3 months after the effective date of this AD, perform a visual inspection to detect damage of the overcenter links (including the bearings, races, and attaching hardware, in accordance with the McDonnell Douglas DC-9 Alert Service Bulletin A78-67, dated February 27, 1995.

(1) If no damage to the overcenter links is detected, no further action is required by this paragraph.

(2) If any damage to the overcenter links is detected, prior to further flight, replace the damaged overcenter links with new or serviceable overcenter links in accordance with the alert service bulletin.

(3) If any damage to the bearings, races, or attaching hardware of the overcenter links is detected, prior to further flight, perform a visual inspection to detect damage of the drive mechanism of the thrust reverser, in accordance with the alert service bulletin. If any damage to the drive mechanism is detected, prior to further flight, repair or replace the damaged parts with new or serviceable parts, in accordance with the Chapter 78 of the DC-9 Overhaul Manual.

(c) Within 10 days after accomplishing the visual inspection of the driver links of the thrust reverser door to determine whether the driver links are chamfered, as required by paragraph (a) of this AD, submit a report of the inspection results (both positive and negative findings) to the Manager, FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, California 90712; telephone (310) 627-5245; fax (310) 627-5210; Attention: Robert Baitoo. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

(d) As of the effective date of this AD, no person shall install, on any airplane, a driver link or overcenter link that has not been previously inspected, and replaced or reworked, in accordance with McDonnell Douglas DC-9 Alert Service Bulletin A78-67, dated February 27, 1995.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to

a location where the requirements of this AD can be accomplished.

(g) Certain actions shall be done in accordance with McDonnell Douglas DC-9 Alert Service Bulletin A78-67, dated February 27, 1995. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from McDonnell Douglas Corporation, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Department C1-L51 (2-60). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, Transport Airplane Directorate, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(h) This amendment becomes effective on September 5, 1995.

Issued in Renton, Washington, on July 21, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 95-18436 Filed 8-2-95; 8:45 am]
BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-NM-129-AD; Amendment 39-9329; AD 95-16-09]

Airworthiness Directives; Jetstream Model BAe ATP Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain Jetstream Model BAe ATP airplanes. This action requires modification of the electrical connections at the switches of the scavenge oil filter and pressure oil filter. This amendment is prompted by reports indicating that the electrical connections were miswired at the switches of the scavenge oil filter and pressure oil filter. The actions specified in this AD are intended to prevent the circulation of unfiltered oil through the engine without warning to the flightcrew, due to miswiring of electrical connections. Unfiltered oil containing contaminants could lead to a precautionary shutdown of the engine.

DATES: Effective August 18, 1995.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of August 18, 1995.

Comments for inclusion in the Rules Docket must be received on or before October 2, 1995.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-129-AD, 1601 Lind Avenue SW., Renton, Washington 98055-4056.

The service information referenced in this AD may be obtained from Jetstream Aircraft, Inc., P.O. Box 16029, Dulles International Airport, Washington, DC 20041-6029. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Gregory Dunn, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington 98055-4056; telephone (206) 227-2799; fax (206) 227-1149.

SUPPLEMENTARY INFORMATION: The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, recently notified the FAA that an unsafe condition may exist on certain Jetstream Model BAe ATP airplanes. The CAA advises that it has received reports indicating that the amber light on the central warning panel did not illuminate to warn the flight crew that the engine oil filter would be bypassed. Investigation revealed that the light did not illuminate because the electrical connections were miswired at the switches of the scavenge oil filter of the reduction gearbox (RGB) and of the pressure oil filter. The miswiring configuration was inadvertently included as part of the original wiring design plan for these airplanes and, thus, the miswiring occurred during production. Such miswiring could lead to the circulation of unfiltered oil through the engine without warning to the flightcrew, which could result in a precautionary shutdown of the engine due to contaminants in the unfiltered oil.

Jetstream has issued Service Bulletin ATP-79-25-10382A, Revision 1, dated May 25, 1995, which describes procedures for modification of the electrical connections at the switches of the scavenge oil filter of the RGB and of the pressure oil filter, of the left and right engines. The modification entails rerouting of the 28-volt DC. wiring from pin A to pin C of the switches. The CAA classified this service bulletin as mandatory in order to assure the

continued airworthiness of these airplanes in the United Kingdom.

This airplane model is manufactured in the United Kingdom and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. The FAA has examined the findings of the CAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, this AD is being issued to prevent the circulation of unfiltered oil through the engine without warning to the flightcrew, which could lead to a precautionary shutdown of the engine due to contaminants in the unfiltered oil. This AD requires modification of the wiring connections at the switches of the scavenge oil filter of the RGB and of the pressure oil filter, of the left and right engines. The actions are required to be accomplished in accordance with the service bulletin described previously.

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days. Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 95-NM-129-AD." The postcard will be date stamped and returned to the commenter.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

95-16-09 Jetstream Aircraft Limited (Formerly British Aerospace Commercial Aircraft, Limited.): Amendment 39-9329. Docket 95-NM-129-AD.

Applicability: Model BAe ATP airplanes having constructor's numbers 2002 through 2056 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (b) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent the flightcrew from being unaware that unfiltered oil is being circulated through the engine, which may result in a precautionary shutdown of the engine due to the circulation of contaminants in unfiltered oil, accomplish the following:

(a) Within 60 days after the effective date of this AD, modify the wiring connections at the switches of the scavenge oil filter of the reduction gearbox (RGB) and of the pressure oil filter, of both the left and right engines, in accordance with Jetstream BAe ATP Service Bulletin ATP-79-25-10382A, Revision 1, dated May 25, 1995.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The modification shall be done in accordance with Jetstream Aircraft Limited BAe ATP Service Bulletin ATP-79-25-10382A, Revision 1, dated May 25, 1995, which contains the following effective pages:

Page No.	Revision level shown on page	Date shown on page
1, 3, 7	1	May 25, 1995.
2, 4-6, 8-13 .	Original	February 10, 1995.

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Jetstream Aircraft, Inc., P.O. Box 16029, Dulles International Airport, Washington, DC 20041-6029. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on August 18, 1995.

Issued in Renton, Washington, on July 27, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 95-18981 Filed 8-2-95; 8:45 am]

BILLING CODE 4910-13-P

14 CFR Part 39

[Docket No. 94-ANE-64; Amendment 39-9323; AD 95-16-04]

Airworthiness Directives; AlliedSignal, Inc. (Formerly Textron Lycoming) LTS101 Series Turboshaft and LTP101 Series Turboprop Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to AlliedSignal Inc. LTS101 series turboshaft and LTP101 series turboprop engines, that requires replacement of cast material axial compressor rotors with wrought material axial compressor rotors that have improved fatigue characteristics and material properties. This amendment is prompted by 36 reports of axial compressor blade failures on cast rotors. The actions specified by this AD are intended to prevent engine power loss and inflight engine shutdown.

DATES: Effective October 2, 1995.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of October 2, 1995.

ADDRESSES: The service information referenced in this AD may be obtained from AlliedSignal, Inc., 550 Main Street, Stratford, CT 06497. This information may be examined at the Federal Aviation Administration (FAA), New England Region, Office of the Assistant Chief Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Eugene Triozzi, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (617) 238-7148, fax (617) 238-7199.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to AlliedSignal Inc. (formerly Textron Lycoming) LTS101 series turboshaft and LTP101 series turboprop engines was published in the **Federal Register** on January 4, 1995 (60 FR 393). That action proposed to require replacing cast material axial compressor rotors with wrought material axial compressor rotors that have improved fatigue characteristics and material properties, in accordance with Textron Lycoming Service Bulletin No. LT 101-72-30-0088, Revision 5, dated September 25, 1992.

On October 28, 1994, AlliedSignal Inc. purchased the turbine engine product line of Textron Lycoming, and this final rule has been revised to refer to the engine by its new name.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule with the change described previously.

There are approximately 200 engines of the affected design in the worldwide fleet. The FAA estimates that 100 engines installed on aircraft of U.S. registry will be affected by this AD, that it will take approximately 50 work hours per engine to accomplish the required actions, and that the average labor rate is \$60 per work hour. Required parts will cost approximately

\$6,500 per engine, on a prorated cost basis. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$955,000.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air Transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

95-16-04 AlliedSignal, Inc.: Amendment 39-9323. Docket 94-ANE-64.

Applicability: AlliedSignal, Inc. (formerly Textron Lycoming) LTS101 turboshaft and LTP101 turboprop engines installed on but not limited to Aerospatiale AS 350 and SA366G, Bell 222, and Messerschmitt-Bolkow-Blohm (MBB) BK117 helicopters; Piaggio P166-DL3 and Airtractor AT302 airplanes. NOTE: This AD applies to each