

(b) RUS will require that any electric loan made or guaranteed by RUS after October 23, 1995 shall be subject to a provision in the loan contract or mortgage restricting investments, loans and guarantees by the borrower substantially as follows: The borrower shall not make any loan or advance to, or make any investment in, or purchase or make any commitment to purchase any stock, bonds, notes or other securities of, or guaranty, assume or otherwise become obligated or liable with respect to the obligations of, any other person, firm or corporation, except as permitted by the RE Act and RUS regulations.

(c) RUS reserves the right to change the provisions of the RUS mortgage and loan contract relating to RUS approval of investments, loans and guarantees made by the borrower, on a case-by-case basis, in connection with providing additional financial assistance to a borrower after October 23, 1995.

Dated: September 15, 1995.  
 Jill Long Thompson,  
*Under Secretary, Rural Economic and Community Development.*  
 [FR Doc. 95-23380 Filed 9-20-95; 8:45 am]  
**BILLING CODE 3410-15-P**

**Animal and Plant Health Inspection Service**

**9 CFR Part 77**

[Docket No. 93-058-2]

**Tuberculosis in Cattle and Bison; State Designation**

**AGENCY:** Animal and Plant Health Inspection Service, USDA.

**ACTION:** Affirmation of interim rule as final rule.

**SUMMARY:** We are adopting as a final rule, without change, an interim rule that amended the tuberculosis regulations concerning the interstate movement of cattle and bison by raising the designation of Kansas from a modified accredited State to an accredited-free State. We have determined that Kansas meets the criteria for designation as an accredited-free State.

**EFFECTIVE DATE:** October 23, 1995.

**FOR FURTHER INFORMATION CONTACT:** Dr. Mitchell A. Essey, Senior Staff Veterinarian, Cattle Diseases and Surveillance, VS, APHIS, 4700 River Road Unit 36, Riverdale, MD 20737-1231, (301) 734-7727.

**SUPPLEMENTARY INFORMATION:**

**Background**

In an interim rule effective and published in the Federal Register on June 27, 1995 (60 FR 33100-33101, Docket No. 93-058-1), we amended the tuberculosis regulations in 9 CFR part 77 by removing Kansas from the list of modified accredited States in § 77.1 and adding it to the list of accredited-free States in that section.

Comments on the interim rule were required to be received on or before August 28, 1995. We did not receive any comments. The facts presented in the interim rule still provide a basis for the rule.

This action also affirms the information contained in the interim rule concerning Executive Order 12866 and the Regulatory Flexibility Act, Executive Orders 12372 and 12778, and the Paperwork Reduction Act.

Further, for this action, the Office of Management and Budget has waived the review process required by Executive Order 12866.

**List of Subjects in 9 CFR Part 77**

Animal diseases, Bison, Cattle, Reporting and recordkeeping requirements, Transportation, Tuberculosis.

**PART 77—TUBERCULOSIS**

Accordingly, we are adopting as a final rule, without change, the interim rule that amended 9 CFR 77.1 and that was published at 60 FR 33100-33101 on June 27, 1995.

Authority: 21 U.S.C. 111, 114, 114a, 115-117, 120, 121, 134b, 134f; 7 CFR 2.17, 2.51, and 371.2(d).

Done in Washington, DC, this 15th day of September 1995.

Terry L. Medley,  
*Acting Administrator, Animal and Plant Health Inspection Service.*

[FR Doc. 95-23478 Filed 9-20-95; 8:45 am]

**BILLING CODE 3410-34-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. 95-CE-20-AD; Amendment 39-9379; AD 95-19-18]

**Airworthiness Directives; Twin Commander Aircraft Corporation 680, 681, 690, and 695 Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) that applies to certain Twin Commander Aircraft Corporation (Twin Commander) 680, 681, 690, and 695 series airplanes. This action requires installing a placard warning the pilot to observe turbulent air penetration speeds. Two accidents involving Model 690 airplanes where the affected airplanes encountered turbulence while descending at high speeds prompted this action. The actions specified by this AD are intended to prevent structural damage to the airplane caused by excessive turbulence, which could result in loss of control of the airplane.

**EFFECTIVE DATE:** October 25, 1995.

**ADDRESSES:** Service information that applies to this AD may be obtained from the Twin Commander Aircraft Corporation, 19010 59th Drive, N.E., Arlington, Washington 98223. This information may also be examined at the Federal Aviation Administration (FAA), Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket 95-CE-20-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Mr. David D. Swartz, Aerospace Engineer, FAA, Northwest Mountain Region, 1601 Lind Avenue S.W., Renton, Washington 98055-4056; telephone (206) 227-2624; facsimile (206) 227-1181.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to Twin Commander 680, 681, 690, and 695 series airplanes was published in the Federal Register on April 11, 1995 (60 FR 18374). The action proposed to require incorporating a placard and Airplane Flight Manual/Pilot's Operating Handbook (AFM/POH) revisions that warn the airplane operator of the importance of observing the Turbulent Air Penetration and Maneuvering speeds. The following kits include the placard and AFM/POH revisions:

Kit No.	Model affected
SB220-1 .....	680T.
SB220-2 .....	680V.
SB220-3 .....	680W.
SB220-4 .....	681.
SB220-5 .....	690.
SB220-6 .....	690A.
SB220-7 .....	690B.
SB220-8 .....	690C.
SB220-9 .....	690D.
SB220-10 .....	695.

Kit No.	Model affected
SB220-11 .....	695A.
SB220-12 .....	695B.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposed rule or the FAA's determination of the cost to the public.

After careful review of all available information related to the subject presented above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. The FAA has determined that these minor corrections will not change the meaning of the AD and will not add any additional burden upon the public than was already proposed.

The FAA estimates that 566 airplanes in the U.S. registry will be affected by this AD, that it will take approximately 1 workhour per airplane to accomplish the required action, and that the average labor rate is approximately \$60 an hour. Parts cost approximately \$38 per airplane. Based on these figures, the total cost impact of this AD on U.S. operators is estimated to be \$55,468. This figure is based on the assumption that no affected airplane owner/operator has incorporated the placard and AFM/POH revisions included with the applicable SB220 kit. Twin Commander has informed the FAA that no kits have been distributed to the owners/operators of the affected airplanes.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the

Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40101, 40113, 44701.

**§ 39.13 [Amended]**

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

95-19-18 Twin Commander Aircraft Corporation: Amendment 39-9379; Docket No. 95-CE-20-AD.

*Applicability:* The following airplane models and serial numbers, certificated in any category.

Models	Serial No.
680T and 680V .....	1473 through 1720.
680W .....	1721 through 1850.
681 .....	6001 through 6072.
690 .....	11001 through 11079.
690A .....	11100 through 11344.
690B .....	11350 through 11566.
690C .....	11600 through 11735.
690D .....	15001 through 15042.
695 .....	95000 through 95084.
695A .....	96000 through 96100.
695B .....	96201 through 96208.

Note 1: This AD applies to each airplane identified in the preceding applicability revision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

*Compliance:* Required within the next 50 hours time-in-service after the effective date of this AD, unless already accomplished.

To prevent structural damage to the airplane caused by excessive turbulence, which could result in loss of the airplane, accomplish the following:

(a) Install the placard (to the windshield centerpost) and incorporate

the airplane flight manual/pilot operating handbook (AFM/POH) revisions that are included with the kits presented below. The placard and AFM/POH revisions provide warnings to the airplane operator of the importance of observing the Turbulent Air Penetration and Maneuvering speeds:

Kit No.	Model affected
SB220-1 .....	680T.
SB220-2 .....	680V.
SB220-3 .....	680W.
SB220-4 .....	681.
SB220-5 .....	690.
SB220-6 .....	690A.
SB220-7 .....	690B.
SB220-8 .....	690C.
SB220-9 .....	690D.
SB220-10 .....	695.
SB220-11 .....	695A.
SB220-12 .....	695B.

Note 2: Twin Commander Service Bulletin No. 220, dated February 1, 1995, relates to the subject of this AD, and references the SB220 service kits specified above.

(b) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Northwest Mountain Region, 1601 Lind Avenue S.W., Renton, Washington 98055-4056. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(d) All persons affected by this directive may obtain copies of the kits referenced above that include the placard and the AFM revisions upon request to the Twin Commander Aircraft Corporation, 19010 59th Drive, NE., Arlington, Washington 98223; or may examine this document at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

(e) This amendment (39-9379) becomes effective on October 25, 1995.

Issued in Kansas City, Missouri, on September 13, 1995.

Gerald W. Pierce,

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 95-23355 Filed 9-20-95; 8:45 am]