

hours per helicopter to accomplish the modifications, approximately 3 work hours per helicopter to accomplish the 250 hours TIS inspection, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$1,100 per helicopter. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$14,880.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

Bell Helicopter Textron, Inc. (BHTI): Docket No. 95-SW-26-AD.

Applicability: Model 214ST helicopters, serial number (S/N) 28101 through 28132, with a tailboom assembly, part number (P/N)

214-031-003-111 or 214-031-003-277 and with an emergency float kit, P/N 214-706-120, installed, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (d) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any helicopter from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent cracks in the tailboom assembly, structural failure of the tailboom and subsequent loss of control of the helicopter, accomplish the following:

(a) Within the next 250 hours time-in-service (TIS) or at the next 180-day float inspection, whichever occurs first, and thereafter at intervals not to exceed each 180-day float inspection, visually inspect the tailboom assembly for cracks in accordance with the maintenance procedures contained in Part 1 of the Accomplishment Instructions of BHTI Alert Service Bulletin 214ST-95-72, dated July 24, 1995.

(b) Upon discovery of a crack or on or before accumulating an additional 500 hours TIS after the effective date of this AD, whichever occurs first, modify the tailboom assembly in accordance with Part 2 of the Accomplishment Instructions of BHTI Alert Service Bulletin No. 214ST-95-72, dated July 24, 1995.

(c) Modification of the tailboom assembly in accordance with paragraph (b) constitutes terminating action for the requirements of this AD.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used when approved by the Manager, Rotorcraft Certification Office. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Rotorcraft Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Rotorcraft Certification Office.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

Issued in Fort Worth, Texas, on October 23, 1995.

Eric Bries,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 95-27000 Filed 10-31-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-NM-115-AD]

Airworthiness Directives; McDonnell Douglas Model DC-8 Series Airplanes Equipped With Swivel-Type Bogie Beams on the Main Landing Gears

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model DC-8 series airplanes. This proposal would require an inspection to detect cracking of the swivel bogie beam lugs, and repair, if necessary. For airplanes on which no cracking is found, this proposal also would require an inspection to detect corrosion of the swivel pin lug surfaces and bores, and modification of the forward bogie beams. This proposal is prompted by reports indicating that swivel pin lugs of the main landing gear (MLG) have failed due to cracks resulting from stress corrosion. The actions specified by the proposed AD are intended to prevent such stress corrosion, which could result in failure of the swivel-type bogie beam of the MLG; this condition could result in a collapse of the MLG during landing.

DATES: Comments must be received by December 28, 1995.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-115-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from McDonnell Douglas Corporation, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Department C1-L51 (2-60). This information may be examined at the FAA, Transport Airplane Directorate,

1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, California.

FOR FURTHER INFORMATION CONTACT:

Mike Lee, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; telephone (310) 627-5325; fax (310) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 95-NM-115-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-115-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received numerous reports indicating that the swivel pin lug of the forward bogie beam on certain main landing gears (MLG) installed on McDonnell Douglas Model DC-8 series airplanes has failed. The swivel pin lug failures have been attributed, in part, to

overload due to insufficient lubrication of the swivel pin lugs, which can be prevented by proper and timely maintenance practices. The swivel pin lug failures also have been attributed, in part, to cracks resulting from stress corrosion. This stress corrosion usually occurs after approximately 10,000 hours time-in-service. These conditions, if not detected and corrected in a timely manner, could result in collapse/failure of the MLG during landing.

The FAA has reviewed and approved McDonnell Douglas DC-8 Service Bulletin 32-182, dated January 20, 1995; and McDonnell Douglas Service Bulletin DC8-32-182, Revision 1, dated July 21, 1995, and Revision 2, dated August 30, 1995, which describe procedures for a magnetic particle inspection to detect cracking of the swivel bogie beam lugs. For airplanes on which no cracking is found, these service bulletins also describe procedures for a visual inspection to detect corrosion of the swivel pin lug surfaces and bores, and modification of the forward bogie beam. This modification involves removing corrosion and sulfamate nickel or electroless nickel plating of the swivel pin lugs of the forward bogie beam. Accomplishment of this modification will minimize the possibility of failure or collapse of the landing gear due to stress corrosion cracking.

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require a magnetic particle inspection to detect cracking of the swivel bogie beam lugs, and repair, if necessary. For airplanes on which no cracking is found during the magnetic particle inspection, the proposed AD also would require a visual inspection to detect corrosion of the swivel pin lug surfaces and bores, and modification of the forward bogie beams.

Repair of any cracking detected during the magnetic particle inspection would be required to be accomplished in accordance with a method approved by the FAA. The other proposed actions (inspections and modification) would be required to be accomplished in accordance with the service bulletins described previously.

There are approximately 148 Model DC-8 series airplanes of the affected design in the worldwide fleet. The FAA estimates that 97 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 83 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Based on these

figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$483,060, or \$4,980 per airplane.

The total cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

McDonnell Douglas: Docket 95-NM-115-AD.

Applicability: Model DC-8 series airplanes equipped with main landing gears having

swivel type bogie beams on which the swivel pin lugs have not been nickel plated, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (e) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the swivel-type bogie beam of the main landing gear (MLG) due to stress corrosion, which could result in a collapse of the MLG during landing, accomplish the following:

(a) Perform a magnetic particle inspection to detect cracking of the swivel bogie beam lugs, in accordance with McDonnell Douglas DC-8 Service Bulletin 32-182, dated January 20, 1995, McDonnell Douglas Service Bulletin DC8-32-182, Revision 1, dated July 21, 1995, or Revision 02, dated August 30, 1995, at the later of the times specified in paragraphs (a)(1) and (a)(2) of this AD.

(1) Prior to the accumulation of 11,600 total flight hours, or within 10 years since the installation of the forward bogie beam of the MLG, whichever occurs first.

(2) Prior to the accumulation of 2,000 flight hours, or 2 years after the effective date of this AD, whichever occurs first.

(b) If no cracking is detected during the inspection required by paragraph (a) of this AD, prior to further flight, perform a visual inspection to detect corrosion in the swivel pin lug surfaces and bores, in accordance with McDonnell Douglas DC-8 Service Bulletin 32-182, dated January 20, 1995; McDonnell Douglas Service Bulletin DC8-32-182, Revision 1, dated July 21, 1995; or Revision 02, dated August 30, 1995.

Note 2: Particular attention should be paid to the lubrication of the swivel pin lug and the lower swivel pin bushing during regular normal maintenance.

(1) If no corrosion is detected, prior to further flight, accomplish paragraph (b)(1)(i), (b)(1)(ii), (b)(1)(iii), or (b)(1)(iv) of this AD, as applicable, in accordance with the service bulletin.

(i) For Group I airplanes on which the forward bogie beam has not been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group I airplanes) as Condition 1 of the Accomplishment Instructions of the service bulletin.

(ii) For Group I airplanes on which the forward bogie beam has been modified

previously: Modify the forward bogie beam in accordance with the actions specified (for Group I airplanes) as Condition 2 of the Accomplishment Instructions of the service bulletin.

(iii) For Group II airplanes on which the forward bogie beam has not been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group II airplanes) as Condition 1 of the Accomplishment Instructions of the service bulletin.

(iv) For Group II airplanes on which the forward bogie beam has been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group II airplanes) as Condition 2 of the Accomplishment Instructions of the service bulletin.

(2) If any corrosion is detected, prior to further flight, accomplish paragraph (b)(2)(i), (b)(2)(ii), (b)(2)(iii), or (b)(2)(iv), as applicable, in accordance with the service bulletin.

(i) For Group I airplanes on which the forward bogie beam has not been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group I airplanes) as Condition 1 of the Accomplishment Instructions of the service bulletin.

(ii) For Group I airplanes on which the forward bogie beam has been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group I airplanes) as Condition 2 of the Accomplishment Instructions of the service bulletin.

(iii) For Group II airplanes on which the forward bogie beam has not been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group II airplanes) as Condition 1 of the Accomplishment Instructions of the service bulletin. If the minimum thickness of the reworked swivel pin lug exceeds the dimensions specified in Table I of the service bulletin, prior to further flight, repair in accordance with a method approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate.

(iv) For Group II airplanes on which the forward bogie beam has been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group II airplanes) as Condition 2 of the Accomplishment Instructions of the service bulletin. If the minimum thickness of the reworked swivel pin lug exceeds the dimensions specified in Table I of the service bulletin, prior to further flight, repair in accordance with a method approved by the Manager, Los Angeles ACO.

(c) If any cracking is detected during the inspection required by paragraph (a) of this AD, prior to further flight, repair in accordance with a method approved by the Manager, Los Angeles ACO.

(d) As of the effective date of this AD, no forward bogie beam swivel pin lug shall be installed on any airplane, unless that swivel pin lug has been modified in accordance with McDonnell Douglas DC-8 Service Bulletin 32-182, dated January 20, 1995; McDonnell Douglas Service Bulletin DC8-

32-182, Revision 1, dated July 21, 1995; or Revision 02, dated August 30, 1995.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on October 26, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-27076 Filed 10-31-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 71

[Airspace Docket No. 95-AWA-7]

Proposed Modification of the Offutt AFB, Class C Airspace Area; Nebraska

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This proposed rule would modify the Class C airspace area at Offutt Air Force Base (AFB), NE. This proposal would delete the 1-mile airspace exclusion around the South Omaha Airport, due to its closure, and return this airspace to the surface area of the Class C airspace. In addition, this proposed rule would reduce controller workload.

DATES: Comments must be received on or before December 15, 1995.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Office of the Chief Counsel, Attention: Rules Docket [AGC-200], Airspace Docket No. 95-AWA-7, 800 Independence Avenue, SW., Washington, DC 20591.

The official docket may be examined in the Rules Docket, Office of the Chief Counsel, Room 916, weekdays, except Federal holidays, between 8:30 a.m. and 5:00 p.m.

An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division.

FOR FURTHER INFORMATION CONTACT: William C. Nelson, Airspace and