

(1) For all airplanes: Within 15 days after accomplishing the measurement required by paragraph (a) of this AD, perform a gap recovery procedure in accordance with paragraph 2.B.(5) of the Accomplishment Instructions of the service bulletin.

(2) For airplanes equipped with MLG barrels applicable to Table No. 2 of the service bulletin: Prior to further flight after accomplishing the gap recovery procedure required by paragraph (c)(1) of this AD, coat the MLG barrel and connecting rod nut with a rubber sealant in accordance with the service bulletin.

(3) For all airplanes: Within 15 days after accomplishing the measurement required by paragraph (a) of this AD, perform a visual inspection to detect cracks of the MLG barrel, in accordance with paragraph 2.B.1 of the Accomplishment Instructions of the service bulletin.

(i) If no crack is detected: Repeat the visual inspection thereafter at intervals not to exceed 7 days until the eddy current inspection required by paragraph (d) of this AD is accomplished.

(ii) If any crack is detected: Prior to further flight, replace the MLG barrel with a barrel that has been modified in accordance with Messier Bugatti Service Bulletin 470-32-640, dated July 11, 1988, and Messier Bugatti Service Bulletin 470-32-763, dated February 28, 1994. Accomplishment of this replacement shall be done in accordance with Messier Bugatti Airbus A310 Service Bulletin 470-32-726, Revision 2, dated February 8, 1994. After accomplishment of this replacement, no further action is required by this AD.

(d) Except as provided by paragraph (c)(3)(ii) of this AD (MLG barrel replacement): Following accomplishment of either paragraph (b) or (c) of this AD, and at the applicable times specified in Table No. 1 and Table No. 2 of Messier Bugatti Airbus A310 Service Bulletin 470-32-726, Revision 2, dated February 8, 1994, remove the rubber sealant and perform an eddy current inspection to detect cracks of the MLG barrel in accordance with Table No. 3 of that service bulletin.

(1) If no crack is detected: At the times specified in Table No. 3 of the service bulletin, perform the various follow-on actions in accordance with the service bulletin. (The follow-on actions include repetitive gap measurements, repetitive eddy current and visual inspections, installation of a new bushing, and replacement of the bronze washer with a stainless steel washer.)

(i) However, in lieu of installing a new bushing on crack-free barrels having no oxidation of the cadmium plating at the next overhaul, as specified in the service bulletin, operators must either repeat the gap measurement and eddy current inspection at intervals not to exceed 2 years, or install a new bushing and replace the bronze washer at the upper part of the MLG barrel with a stainless steel washer, in accordance with the service bulletin.

(ii) After accomplishment of the installation of a new bushing (reference Messier Bugatti Service Bulletin 470-32-640) and the replacement of the bronze washer (reference Messier Bugatti Service Bulletin

470-32-763), no further action is required by this AD.

(2) If any crack is detected: Prior to further flight, replace the barrel with a barrel that has been modified in accordance with Messier Bugatti Service Bulletin 470-32-640, dated July 11, 1988, and Messier Bugatti Service Bulletin 470-32-763, dated February 28, 1994. Accomplishment of this replacement shall be done in accordance with the Messier Bugatti Airbus A310 Service Bulletin 470-32-726, Revision 2, dated February 8, 1994. After accomplishment of this replacement, no further action is required by this AD.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on November 2, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-27648 Filed 11-7-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-NM-79-AD]

Airworthiness Directives; Saab Model SAAB SF340A and SAAB 340B Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Saab Model SAAB SF340A and SAAB 340B series airplanes. This proposal would require repetitive operational tests of the valve limit switch of the propeller brake. This proposal also provides for an optional terminating action for the repetitive tests. This proposal is prompted by a report that when the propeller brake was not properly engaged the crew did not receive a "PROP BRAKE" warning due to a faulty valve limit switch. The

actions specified by the proposed AD are intended to prevent a valve limit switch from failing to send input to the warning system; absence of a "PROP BRAKE" warning could result in the crew being unaware that the propeller brake is not properly engaged and the propeller may turn without warning.

DATES: Comments must be received by December 19, 1995.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-79-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from SAAB Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Ruth Harder, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-1721; fax (206) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice

must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 95-NM-79-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-79-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Luftfartsverket (LFV), which is the airworthiness authority for Sweden, recently notified the FAA that an unsafe condition may exist on certain Saab Model SAAB SF340A and SAAB 340B series airplanes. The LFV advises that it has received a report indicating that the flightcrew of one airplane did not receive a "PROP BRAKE" warning when the propeller brake was not properly engaged. The "PROP BRAKE" warning indicates that there is insufficient [below 2,350 pounds per square inch (psi)] hydraulic pressure to engage the propeller brake. Investigation revealed that this failure was caused by a failure mode in the valve limit switch of the propeller brake system. If a valve limit switch is faulty, no input would be sent the warning system; this situation could result in the flightcrew being unaware that the propeller brake is not properly engaged and the propeller may turn without warning.

Saab has issued Service Bulletin SAAB 340-61-032, Revision 1, dated June 30, 1995, which describes procedures for repetitive operational tests of the valve limit switch of the propeller brake. The LFV classified this service bulletin as mandatory and issued Swedish airworthiness directive (SAD) 1-064, Revision 1, effective date March 24, 1995, in order to assure the continued airworthiness of these airplanes in Sweden.

Saab has also issued Service Bulletin SAAB 340-61-033, dated March 6, 1995, which describes procedures for replacement of the propeller brake control unit having part number (P/N) HP1410100-3, -5, or -7 with a new propeller brake control unit having P/N HP1410100-10, and an operational test. Accomplishment of this replacement eliminates the need for the repetitive operational tests. The new propeller brake control unit has an improved low pressure valve limit switch installed in it to ensure that its inputs are received by the warning system. The LFV approved the technical content of this service bulletin.

These airplane models are manufactured in Sweden and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LFV has kept the FAA informed of the situation described above. The FAA has examined the findings of the LFV, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require repetitive operational tests of the valve limit switch of the propeller brake. The proposed AD also provides for the optional replacement of certain propeller brake control units with a new unit, which would constitute terminating action for the repetitive test requirements. The actions would be required to be accomplished in accordance with the service bulletins described previously.

The FAA estimates that 23 airplanes of U.S. registry would be affected by this proposed AD.

It would take approximately 1 work hour per airplane to accomplish the proposed operational tests, at an average labor rate of \$60 per work hour. Based on these figures, the total cost impact of the actions that would be required by this AD on U.S. operators is estimated to be \$1,380, or \$60 per airplane, per test cycle. This total cost impact figure is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44

FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

SAAB Aircraft AB: Docket 95-NM-79-AD.

Applicability: Model SAAB SF340A series airplanes, having serial numbers 004 through 159 inclusive; and Model SAAB 340B series airplanes, having serial numbers 160 through 369 inclusive; on which the propeller brake system is connected; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (d) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent a valve limit switch from failing to send input to the "PROP BRAKE" warning system, which could result in the crew being

unaware that the propeller brake is not properly engaged and the propeller may turn without warning, accomplish the following:

(a) Within 100 flight hours after the effective date of this AD, perform an operational test of the valve limit switch of the propeller brake in accordance with Saab Service Bulletin SAAB 340-61-032, Revision 1, dated June 30, 1995. Repeat the test thereafter at intervals not to exceed 100 flight hours.

(b) Replacement of a propeller brake control unit having part number (P/N) HP1410100-3, -5, or -7 with a new propeller brake control unit having P/N HP1410100-10, and performance of an operational test, in accordance with SAAB Service Bulletin SAAB 340-61-033, dated March 6, 1995, constitutes terminating action for the repetitive inspections required by paragraph (a) of this AD.

(c) As of the effective date of this AD, no person shall install on any airplane a propeller brake control unit having P/N HP1410100-3; or any unit having P/N HP1410100-5 or -7 unless that unit has been modified in accordance with SAAB Service Bulletin SAAB 340-61-033, dated March 6, 1995.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on November 2, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-27646 Filed 11-7-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 71

[Airspace Docket No. 95-AWP-37]

Proposed Amendment of Class E Airspace; Alturas, CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to amend the Class E airspace area at Alturas, CA. The development of a

Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP) to Runway (RWY) 31 has made this proposal necessary. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at Alturas Municipal Airport, Alturas, CA.

DATES: Comments must be received on or before December 20, 1995.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Attn: Manager, System Management Branch, AWP-530, Docket No. 95-AWP-37, Air Traffic Division, P.O. Box 92007, Worldway Postal Center, Los Angeles, California 90009.

The official docket may be examined in the Office of the Assistant Chief Counsel, Western Pacific Region, Federal Aviation Administration, Room 6007, 15000 Aviation Boulevard, Lawndale, California 90261.

An informal docket may also be examined during normal business hours at the Office of the Manager, System Management Branch, Air Traffic Division at the above address.

FOR FURTHER INFORMATION CONTACT: Scott Speer, Airspace Specialist, System Management Branch, AWP-530, Air Traffic Division, Western-Pacific Region, Federal Aviation Administration, 15000 Aviation Boulevard, Lawndale, California 90261, telephone (310) 725-6533.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with the comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Airspace Docket No. 95-AWP-37." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified

closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of comments received. All comments submitted will be available for examination in the System Management Branch, Air Traffic Division, at 15000 Aviation Boulevard, Lawndale, California 90261, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, System Management Branch, P.O. Box 92007, Worldway Postal Center, Los Angeles, California 90009. Communications must identify the notice number of this NPRM. Persons interested in being placed on a mailing list for future NPRM's should also request a copy of Advisory Circular No. 11-2A, which describes the application procedures.

The Proposal

The FAA is considering an amendment to part 71 of the Federal Aviation Regulations (14 CFR part 71) to amend the Class E airspace area at Alturas, CA. The development of a GPS SIAP at Alturas Municipal Airport has made this proposal necessary. The intended effect of this proposal is to provide adequate Class E airspace for aircraft executing the GPS RWY 31 SIAP at Alturas Municipal Airport, Alturas, CA. Class E airspace designations for airspace areas extending upward from 700 feet or more above the surface of the earth are published in Paragraph 6005 of FAA Order 7400.9C dated August 17, 1995, and effective September 16, 1995, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in this Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 10034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a