

the rule as proposed, except for some editorial changes and adding explanatory Note 1, relating to the scope of the applicability statement when modifications, alterations, or repairs have been made in the area subject to the requirements of the AD.

Additionally, the FAA has revised the proposed estimated average labor rate from \$55 per work hour to an estimated average labor rate of \$60 per work hour in the preamble portion of this final rule. This revision will increase the estimated total cost impact of the AD from \$1,045 to \$1,140. Finally, the type certificate has been transferred to a new owner since the issuance of the proposal. The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

The FAA estimates that 19 helicopters of U.S. registry will be affected by this AD, that it will take approximately one work hour per helicopter to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$1,140.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation

Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-8084 (56 FR 63631, December 5, 1991), and by adding a new airworthiness directive (AD), Amendment 39-9438, to read as follows:

AD 95-24-06 Bell Helicopter Textron, a division of Textron Canada (BHT): Amendment 39-9438, Docket No. 93-SW-04-AD. Supersedes AD 91-23-15, Amendment 39-8084.

Applicability: Model 206B and 206L helicopters, equipped with Allison 250-C20R engine power-out warning sensors, part number (P/N) 206-075-545-001, in accordance with Supplemental Type Certificate (STC) No. SH4169NM (applicable to Model 206L), SH4179NM (applicable to Model 206B), or SH4729NM (applicable to both Models 206B & L), certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (b) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any helicopter from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To alert the pilot of a potential false engine-out warning when practicing autorotations that could result in an unnecessary emergency autorotative landing, accomplish the following:

(a) Within 10 days after the effective date of this AD, revise the Limitations section of the applicable FAA-approved STC Rotorcraft Flight Manual Supplement (RFMS) by adding the warning statement and note contained in the Description section of Soly Corporation Service Bulletin 02-680, revised December 8, 1992.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used when approved by the Manager, Seattle

Aircraft Certification Office, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98055-4056. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Seattle Aircraft Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle Aircraft Certification Office.

(c) Special flight permits to accomplish the requirements of this AD will not be issued.

(d) The warning and note to be inserted into the Limitations section of the applicable STC RFMS are contained in Soly Corporation Service Bulletin 02-680, revised December 8, 1992. This incorporation by reference was previously approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51 as of December 30, 1991 (56 FR 63631, December 5, 1991). Copies may be obtained from Soly Corporation, 450 Pat Kennedy Way SW., Olympia, Washington 98501-7298. Copies may be inspected at the FAA, Office of the Assistant Chief Counsel, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on December 27, 1995.

Issued in Fort Worth, Texas, on November 8, 1995.

Eric Bries,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 95-28517 Filed 11-21-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-SW-06-AD; Amendment 39-9425; AD 95-23-05]

Airworthiness Directives; Robinson Helicopter Company Model R22 Series Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), applicable to Robinson Helicopter Company Model R22 series helicopters, that currently requires an inspection and repetitive visual checks for slippage of the tail rotor (T/R) drive and replacement of the T/R gearbox, if necessary. This amendment requires disassembly of the T/R gearbox to verify the installation of the input and output shaft keys (keys) between the input and output pinions and their respective shafts. This amendment is prompted by two incidents in which the key was not installed between the output shaft and

the output pinion during assembly of the T/R gearbox at Robinson Helicopter Company. The actions specified by this AD are intended to prevent slippage of the T/R drive, loss of directional control, and subsequent loss of control of the helicopter.

EFFECTIVE DATE: December 27, 1995.

FOR FURTHER INFORMATION CONTACT: Ms. Elizabeth Bumann, Aerospace Engineer, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Blvd., Lakewood, California 90712, telephone (310) 627-5265, fax (310) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 94-17-07, Amendment 39-9059 (59 FR 55203, November 4, 1994), which is applicable to Robinson Helicopter Company Model R22 series helicopters, was published in the Federal Register on May 26, 1995 (60 FR 27926). That action proposed to require an inspection and repetitive visual checks for slippage of the T/R drive until the T/R gearbox is disassembled to verify installation of the shaft keys. It also proposed to allow owner/operator daily preflight checks for misalignment of the alignment dots that are installed on the tail cone skin and the drive shaft flange. These checks do not require the use of tools, precision measuring equipment, training, pilot logbook endorsements, or the use of technical data not contained in the AD. Additionally, these checks are considered part of the normal pilot "Before Takeoff" and "After Landing" checks. These checks are additional measures to detect slippage of the T/R drive until installation of the keys is verified. These checks may be performed by an owner/operator holding at least a private pilot certificate, but must be entered into the aircraft records showing compliance with this AD in accordance with sections 43.11 and 91.417(a)(2)(v) of the Federal Aviation Regulations.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comment received.

The manufacturer was the only commenter, and it believes that AD 94-17-07, which required a one-time application of a 35-pound load to the tip of a tail rotor blade to induce slipping of the shaft and a daily "dot alignment" check for slippage, provides adequate safeguards to assure the safety of the helicopter. The manufacturer notes that proof tests were performed on various gearboxes with keys removed and the load required to cause slippage varied

between 14 and 27 pounds. The load tests combined with no reports of additional defective gearboxes leads the manufacturer to assert that the one-time application of the 35-pound load should be the terminating action. The FAA does not agree. The FAA has determined that the one-time application of a 35-pound weight on the tip of the tail rotor blade to test for slippage of the shaft cannot be considered terminating action for Priority Letter 94-17-07. Slippage is a function of surface friction of the material(s) and the attaching hardware clamping pressure, which may vary due to the condition of the gearbox. A no-slippage condition does not ensure that the keys have been installed. Also, there is no assurance that the torque of the retaining nuts will be maintained until the next gearbox overhaul. Although no cases of slippage have been reported as a result of Priority Letter AD 94-17-07, there is no assurance that the keys have been installed.

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed except for deleting proposed paragraph (a)(2) since this procedure is not necessary to check for the misalignment of dots, deleting the requirement to vibro-etch the AD number on the output cartridge since the requirement to vibro-etch the AD number on the input flange is sufficient to identify installation of the keys, exempting from the requirements of this AD 196 additional serial-numbered gearboxes that have been verified by the manufacturer to have both keys installed, adding certain non-substantive, descriptive, clarifying words, adding a clarifying figure, and making various editorial changes. The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

The FAA estimates that 500 helicopters of U.S. registry will be affected by this AD, that it will take approximately 5 work hours per helicopter to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$150,000.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism

implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety. Adoption of the Amendment.

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

Section 39.13 is amended by removing Amendment 39-9059 (59 FR 55203, November 4, 1994), and by adding a new airworthiness directive (AD), Amendment 39-9425, to read as follows:

AD 95-23-05 Robinson Helicopter Company: Amendment 39-9425. Docket No. 95-SW-06-AD. Supersedes AD 94-17-07, Amendment 39-9059.

Applicability: Model R22 series helicopters certified in any category, with tail rotor (T/R) gearboxes that were manufactured or overhauled by Robinson Helicopter Company prior to June 8, 1992. The following gearbox serial numbers have been determined to have the T/R input and output shaft keys installed and are therefore exempt from this AD: 0012, 0013, 0014, 0015, 0018, 0020, 0021, 0030, 0040, 0054, 0062, 0079, 0091, 0095, 0098, 0107, 0108, 0121, 0134, 0137, 0146, 0149, 0153, 0169, 0179, 0184, 0185, 0191, 0193, 0201, 0205, 0227, 0228, 0235, 0239, 0241, 0248, 0258, 0262, 0269, 0272, 0277, 0280, 0296, 0304, 0321, 0333, 0342, 0345, 0346, 0355, 0365, 0385, 0387, 0392, 0415, 0417, 0424, 0431, 0432, 0439, 0444, 0447, 0503, 0504, 0505, 0525, 0542, 0546, 0547, 0548, 0554, 0558, 0559, 0565, 0574, 0576, 0579, 0592, 0594, 0597, 0603, 0604, 0605, 0615, 0619, 0632, 0634, 0639, 0641, 0644, 0650,

0656, 0662, 0663, 0665, 0674, 0686, 0689, 0696, 0697, 0700, 0701, 0702, 0707, 0722, 0734, 0735, 0736, 0742, 0755, 0756, 0759, 0767, 0777, 0778, 0784, 0786, 0805, 0811, 0832, 0836, 0839, 0842, 0845, 0850, 0862, 0863, 0866, 0868, 0880, 0885, 0887, 0892, 0926, 0937, 0939, 0952, 0970, 0983, 0986, 0996, 0997, 0998, 0999, 1007, 1016, 1018, 1021, 1029, 1030, 1035, 1048, 1062, 1072, 1078, 1081, 1087, 1104, 1116, 1121, 1126, 1129, 1132, 1141, 1151, 1176, 1182, 1186, 1187, 1197, 1199, 1205, 1208, 1217, 1222, 1224, 1228, 1233, 1237, 1245, 1249, 1252, 1254, 1255, 1269, 1274, 1290, 1293, 1299, 1301, 1307, 1310, 1311, 1323, 1328, 1330, 1333, 1338, 1339, 1341, 1342, 1350, 1351, 1361, 1371, 1379, 1385, 1388, 1392, 1404, 1412, 1414, 1428, 1429, 1435, 1438, 1442, 1450, 1460, 1468, 1494, 1499, 1505, 1508, 1509, 1512, 1514, 1526, 1541, 1544, 1565, 1578, 1586, 1593, 1595, 1597, 1605, 1610, 1627, 1628, 1629, 1636, 1643, 1647, 1648, 1652, 1654, 1661, 1676, 1677, 1686, 1687, 1698, 1701, 1702, 1706, 1708, 1710, 1714, 1724, 1731, 1732, 1738, 1739, 1741, 1750, 1752, 1754, 1757, 1759, 1766, 1767, 1769, 1783, 1785, 1786, 1800, 1803, 1807, 1808, 1814, 1816, 1823, 1828, 1830, 1833, 1837, 1844, 1846, 1851, 1852, 1858, 1861, 1868, 1869, 1871, 1874, 1886, 1889, 1893, 1898, 1899, 1909, 1911, 1912, 1913, 1920, 1922, 1927, 1928, 1948, 1951, 1959, 1961, 1963, 1965, 1966, 1974, 1978, 1983, 1992, 1996, 2002, 2025, 2028, 2034, 2037, 2043, 2051, 2058, 2071, 2100, 2101, 2103, 2108, 2115, 2126, 2129, 2136, 2160, 2166, 2170, 2180, 2182, 2193, 2197, 2203, 2216, 2231, 2242, 2254, 2265, 2269, 2272, 2279, 2280, 2283, 2285, 2289, 2294, 2298, 2299, 2303, 2304, 2308, 2314, 2337, 2346, 2357, 2360, 2362, 2364, 2377, 2380, 2381, 2387, 2395, 2406, 2408, 2410, 2414, 2416, 2419, 2420, 2421, 2422, 2423, 2425, 2431, 2435, 2436, 2459, 2467, 2479, 2492, 2498, 2513, 2529, 2531, 2536, 2539, 2551, 2556, 2557, 2574, 2579, 2582, 2587, 2591, 2604, 2605, 2607, 2609, 2616, 2627, 2634, 2642, 2651, 2672, 2682, 2683, 2687, 2690, 2697, 2716, 2719, 2720, 2721, 2731, 2736, 2784, 2797, 2799, 2815, 2826, 2841, 2842, 2845, 2862, 2863, 2873, 2937, 2945, 3004, 3109.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (d) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any helicopter from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent slippage of the T/R drive, loss of directional control, and subsequent loss of

control of the helicopter, accomplish the following:

(a) Before further flight, install alignment dots as follows: Remove the transparent inspection cover on the tail cone and rotate the T/R blades so that one blade leading edge is aligned with the tail cone centerline. Mark a dot on the tail cone skin aligned with the tip of the blade leading edge. With the same alignment, mark a dot on the centerline of the tail cone skin at the edge of the inspection hole, and mark a corresponding dot on the drive shaft flange (see figure 4).

(b) Conduct the following daily preflight checks for misalignment of the alignment dots until compliance with paragraph (c) of this AD has been accomplished: Check for misalignment of the alignment dots installed on the tail cone skin and the drive shaft flange by rotating the T/R blade so that the alignment dot is visible in the inspection window and the tip of the T/R blade leading edge aligns with the dot on the tail cone skin. Ensure that the drive shaft flange dot is aligned with the dot on the centerline of the tail cone skin at the edge of the inspection window. If any misalignment is detected, before further flight, replace the T/R gearbox with an airworthy one that has been determined to have both the input and output keys installed in accordance with paragraph (c) of this AD or other FAA-approved procedures, or is exempt from the requirements of this AD as listed in the applicability section of this AD. The daily preflight checks required by this AD may be performed by an owner/operator holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with paragraph (b) of this AD, in accordance with sections 43.11 and 91.417(a)(2)(v) of the Federal Aviation Regulations.

(c) Within the next 100 hours time-in-service (TIS) after the effective date of this AD, or at the next annual inspection, whichever occurs first, verify installation of both the input and output shaft keys as follows:

(1) Cut and remove the safety wire securing the chip detector to the sight gage on the T/R gearbox. Place a container under the T/R gearbox to catch the drained oil and remove the chip detector. Remove and discard the gasket on the chip detector.

(2) Remove the T/R gearbox from the helicopter in accordance with the applicable maintenance manual.

(3) Cut and remove the safety wire securing the filler vent plug to the sight gage on the T/R gearbox and remove the filler vent plug and sight gage. Remove and discard the gasket on the filler vent plug and sight gage.

(4) Remove and disassemble the output cartridge, P/N A111-1, from the T/R gearbox case, P/N A109-1 (see figure 1) as follows:

(i) Place a mark across the gear case, P/N A109-1, and output cartridge, P/N A111-1, with a felt pen or grease pencil to ensure proper reassembly.

(ii) Cut and remove the safety wire around the four MS20074-04-06 bolts securing the output cartridge to the gear case. Remove and retain each of the four bolts and their associated AN960-416L washer(s), noting the washer stacks for reassembly. Separate the

output cartridge from the gear case (see figure 1).

(iii) Remove and discard the safety wire, MS16562-24 or 52-022-094-0437 roll pin, and MS14145L6 or LCN6M-624 retaining nut. Remove the AN960-616L washer(s) and the washer, P/N A141-2, noting the washer(s) location for reassembly. Do not damage the output shaft, P/N A107-1, or the shim(s), P/N A118-1 through -6, located next to the flange of the output cartridge when removing the retaining nut.

(iv) Visually inspect for the presence of the output shaft key, P/N A114-2, between the pinion gear, P/N A545-1, and the output shaft (see figure 2).

(v) If the output shaft key is missing, replace the T/R gearbox with an airworthy gearbox that has been determined to have the output key installed. Report any T/R gearbox that has a missing key within 10 days after the inspection to the Manager, Los Angeles Manufacturing Inspection Office, FAA, Northwest Mountain Region, 3960 Paramount Blvd., Lakewood, California 90712, telephone (310) 627-5290, fax (310) 627-5293. Reporting requirements have been approved by the Office of Management and Budget and assigned OMB control number 2120-0056.

(vi) If the output key is installed, reinstall the washer, P/N A141-2, and AN960-616L washer(s). Install an MS14145L6 or LCN6M-624 retaining nut, and torque to 225-275 in.-lbs. Install a MS16562-24 or 52-022-094-0437 roll pin, and safety wire using 0.032-inch stainless steel safety wire. The safety wire pigtail must be wrapped tightly around the retaining nut.

(5) Remove and disassemble the input cartridge, P/N A110-1, from the T/R gear case, P/N A109-1, as follows:

(i) Place two marks across the gear case, P/N A109-1, and input cartridge, P/N A110-1, with a felt pen or grease pencil to ensure proper reassembly.

(ii) Cut and remove the safety wire around the four MS20074-04-06 bolts securing the input cartridge to the gear case. Remove each of the four bolts and their associated AN960-416L washer(s), noting the washer stacks for reassembly. Separate the input cartridge from the gear case (see figure 1).

(iii) Secure the input cartridge to a block of wood through the two bolt holes in the input shaft assembly, P/N A116-1 (see figure 1). Place the block of wood in a vise. Remove and discard the safety wire, roll pin, and retaining nut. Remove the AN960-616L washer(s), and washer, P/N A141-1, noting the washer(s) location for reassembly. Do not damage the input shaft or shim(s), P/N A118-1 through -6, located next to the flange of the input cartridge.

(iv) Visually inspect for the presence of the input shaft key, P/N A114-1, between the gear, P/N A545-2, and the input shaft (see Note on figure 2).

(v) If the input shaft key is missing, replace the T/R gearbox with an airworthy gearbox that has been determined to have the input key installed. Report any T/R gearbox that has a missing key within 10 days after the inspection to the Manager, Los Angeles Manufacturing Inspection District Office, FAA, Northwest Mountain Region, 3960

Paramount Blvd., Lakewood, California 90712, telephone (310) 627-5290, fax (310) 627-5293. Reporting requirements have been approved by the Office of Management and Budget, and assigned OMB control number 2120-0056.

(vi) If the input key is installed, reinstall the AN960-616L washer(s) and washer, P/N A141-1. Install an MS14145L6 or LCN6M-624 retaining nut, and torque to 225-275 in.-lbs. Install a MS16562-24 or 52-022-094-0437 roll pin and safety wire using 0.032-inch stainless steel safety wire. The safety wire pigtail must be wrapped tightly around the retaining nut. Remove the two bolts securing the input shaft assembly to the block of wood. Vibro-etch the final rule AD

number on the input cartridge attachment flange.

(6) Reassemble the input and output cartridges to the T/R case as follows:


(i) Color the "X" marked on the pinion gear, P/N A545-1, (one tooth only) of the output cartridge and on the gear, P/N A545-2, (located on two consecutive teeth) of the input cartridge with a red marker to make reinstallation easier. Note that these three gear teeth may already be colored (see figure 3).

(ii) Visually inspect the edge of the chamfers in the gear case, making sure they are round and smooth so that the O-ring will not be damaged upon installation.

(iii) Remove and discard the O-ring on both the input cartridge and output cartridge. Replace the O-ring with National P/N AS142 B46-70, or Parker P/N 2-142 N674-70 O-ring. Lubricate the replacement O-ring with oil, P/N A257-2, and install an O-ring on each cartridge.


(iv) Reinstall the output cartridge on the gear case with the four MS20074-04-06 bolts and AN960-416L washer stacks that were removed in accordance with paragraph (c)(4)(ii). Reinstall the input cartridge on the gear case with the four MS20074-04-06 bolts and AN960-416L washer stacks that were removed in accordance with paragraph (c)(5)(ii). Do not torque the bolts at this time.

BILLING CODE 4910-13-U



Note: The safety wire has been removed for clarity

Figure 1



Note: The A114-1 Key for the A110-1 Input Cartridge is located similar to the A111-1 Output Cartridge depicted above

Figure 2




Figure 3




Figure 4

(v) Look through the sight gage opening while using a flashlight pointed into the filler vent hole to verify the gears are meshed properly. Gears are properly meshed when the "X" marked on the pinion gear of the output cartridge is between the two "X's" marked on the gear of the input cartridge (see figure 3). Do not torque the MS20074-04-06 bolts until both cartridges are installed on the case and the gears are properly meshed. Torque the output cartridge bolts to 60 in.-lbs. first, then torque the input cartridge bolts to 60 in.-lbs. Safety wire with 0.032-inch stainless steel safety wire.

(vi) Reinstall sight gage with MS35769-11 or AN900-10 gasket. Oil threads to prevent threads from locking up. Torque to 200 in.-lbs.

(vii) Reinstall the chip detector with a MS35769-8 or AN900-9 gasket after lubricating the threads with oil. Torque the chip detector to 150 in.-lbs. Safety wire the sight gage to the chip detector using 0.032-inch stainless steel safety wire.

(viii) Fill the T/R gearbox with oil to the level indicated on the T/R sight glass decal. Reinstall the filler vent plug, P/N A610-1, with a MS35769-9 or AN900-8 gasket, after lubricating the threads with oil.

(ix) Inspect the T/R gearbox assembly to ensure that the shafts and gears rotate freely.

(7) Reinstall the T/R gearbox onto the helicopter in accordance with the applicable maintenance manual. Verify that the oil level of the T/R gearbox is at the recommended mark on the sight glass.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used when approved by the Manager, Los Angeles Aircraft Certification Office, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Los Angeles Aircraft Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles Aircraft Certification Office.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(f) This amendment becomes effective on December 27, 1995.

Issued in Fort Worth, Texas, on November 2, 1995.

Eric Bries,

Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.

[FR Doc. 95-28537 Filed 11-21-95; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

21 CFR Parts 520 and 522

New Animal Drugs; Change of Sponsor

AGENCY: Food and Drug Administration, HHS.

ACTION: Final rule.

SUMMARY: The Food and Drug Administration (FDA) is amending the animal drug regulations to reflect a change of sponsor name for three new animal drug applications (NADA's) from Vet-A-Mix, Inc., to Lloyd, Inc.

EFFECTIVE DATE: November 22, 1995.

FOR FURTHER INFORMATION CONTACT: Benjamin A. Puyot, Center for Veterinary Medicine (HFV-130), Food and Drug Administration, 7500 Standish Pl., Rockville, MD 20855, 301-594-1646.

SUPPLEMENTARY INFORMATION: Vet-A-Mix, Inc., 604 West Thomas Ave., P.O. Box A, Shenandoah, IA 51601, has informed FDA of a change of sponsor name for approved NADA's 92-836 (diethylcarbamazine citrate), 140-866 (yohimbine hydrochloride injectable), and 140-921 (prednisolone tablets) to Lloyd, Inc., 604 West Thomas Ave., Shenandoah, IA 51601. Accordingly, FDA is amending the regulations in 21 CFR 520.622c, 520.1880, and 522.2670 to reflect the change of sponsor name.

List of Subjects in 21 CFR Parts 520 and 522

Animal drugs.

Therefore, under the Federal Food, Drug, and Cosmetic Act and under authority delegated to the Commissioner of Food and Drugs and redelegated to the Center for Veterinary Medicine, 21 CFR parts 520 and 522 are amended as follows:

PART 520—ORAL DOSAGE FORM NEW ANIMAL DRUGS

1. The authority citation for 21 CFR part 520 continues to read as follows:

Authority: Sec. 512 of the Federal Food, Drug, and Cosmetic Act (21 U.S.C. 360b).

§ 520.622c [Amended]

2. Section 520.622c *Diethylcarbamazine citrate chewable tablets* is amended in paragraph (b)(3) by removing "011789" and adding in its place "061690".

§ 520.1880 [Amended]

3. Section 520.1880 *Prednisolone tablets* is amended in paragraph (b) by

removing "011789" and adding in its place "061690".

PART 522—IMPLANTATION OR INJECTABLE DOSAGE FORM NEW ANIMAL DRUGS

4. The authority citation of 21 CFR part 522 continues to read as follows:

Authority: Sec. 512 of the Federal Food, Drug, and Cosmetic Act (21 U.S.C. 360b).

§ 522.2670 [Amended]

5. Section 522.2670 *Yohimbine injectable* is amended in paragraph (b) by removing "032998" and adding in its place "061690".

Dated: November 13, 1995.

Robert C. Livingston,

Director, Office of New Animal Drug Evaluation, Center for Veterinary Medicine.

[FR Doc. 95-28542 Filed 11-21-95; 8:45 am]

BILLING CODE 4160-01-F

21 CFR Part 522

Implantation or Injectable Dosage Form New Animal Drugs; Selenium/Vitamin E Injection

AGENCY: Food and Drug Administration, HHS.

ACTION: Final rule.

SUMMARY: The Food and Drug Administration (FDA) is amending the animal drug regulations to reflect approval of an abbreviated new animal drug application (ANADA) filed by Fort Dodge Laboratories. The ANADA provides for subcutaneous or intramuscular use of a selenium/vitamin E injection for prevention and treatment of selenium/tocopherol deficiency syndrome in weanling calves and breeding beef cattle.

EFFECTIVE DATE: November 22, 1995.

FOR FURTHER INFORMATION CONTACT: Melanie R. Berson, Center for Veterinary Medicine (HFV-135), Food and Drug Administration, 7500 Standish Pl., Rockville, MD 20855, 301-594-1643.

SUPPLEMENTARY INFORMATION: Fort Dodge Laboratories, 800 Fifth St. NW., P.O. Box 518, Fort Dodge, IA 50501, filed ANADA 200-109, which provides for subcutaneous or intramuscular use of Velenium™ (selenium, vitamin E) Injection for prevention and treatment of selenium/tocopherol deficiency syndrome in weanling calves and breeding beef cattle. The drug is limited to use by or on the order of a licensed veterinarian.

Approval of ANADA 200-109 for Fort Dodge's selenium/vitamin E injection is as a generic copy of Schering-Plough's Mu-Se® (selenium/vitamin E) Injection