

airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact on U.S. operators of the inspections currently required is estimated to be \$53,280, or \$2,220 per airplane.

The new modification that is proposed in this AD action would take approximately 241 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$5,603 per airplane. Based on these figures, the cost impact on U.S. operators of the proposed modification requirements of this AD is estimated to be \$481,512, or \$20,063 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the current or proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-8628 (58 FR 39440, July 23, 1993), and by adding a new airworthiness directive (AD), to read as follows:

Airbus Industrie: Docket 95-NM-216-AD. Supersedes AD 93-14-04, Amendment 39-8628.

Applicability: Model A320 series airplanes, manufacturer's serial numbers 002 through 008 inclusive, 010 through 078 inclusive, and 080 through 107 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent reduced structural integrity of the fuselage, accomplish the following:

(a) Prior to the accumulation of 12,000 total landings, or 6 months after August 23, 1993 (the effective date of AD 93-14-04, amendment 39-8628), whichever occurs later, accomplish the requirements of paragraphs (a)(1) and (a)(2) of this AD, in accordance with Airbus Industrie Service Bulletin A320-53-1024, dated September 23, 1992, or Revision 1, dated March 31, 1994. As of the effective date of this new AD, only Revision 1 of this service bulletin shall be used.

(1) Conduct an eddy current inspection to detect cracking around the fastener/bolt holes at the top horizontal flange of the floor beams and side box-beams, at the two sides of the pressure floor, and at the vertical integral stiffener of the side box-beams; and

(2) Conduct a detailed visual inspection to detect cracking around the fastener/bolt holes at the fillet radius and riveted area of the top outboard flange of the side box-beams, and at the flange-corner radius of the slanted inboard flange of the side box-beam and fittings.

(b) If any crack is detected during the inspections required by paragraph (a) of this AD, prior to further flight, repair the crack in accordance with a method approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate.

(c) Modify the pressure floor at section 15 of the fuselage in accordance with Airbus

Service Bulletin A320-53-1023, Revision 3, dated March 18, 1994, at the time specified in either paragraph (c)(1) or (c)(2) of this AD, as applicable. Accomplishment of the modification terminates the requirements of this AD.

(1) For airplanes on which the modification specified in Airbus Service Bulletin A320-53-1023, dated September 23, 1992, as amended by Service Bulletin Change Notice 0A, dated January 20, 1993; Revision 1, dated March 23, 1993; or Revision 2, dated October 22, 1993; has been accomplished: Modify prior to the accumulation of 24,000 total landings, or 6 months after the effective date of this AD, whichever occurs later.

(2) For all other airplanes not subject to paragraph (c)(1) of this AD: Modify prior to the accumulation of 18,000 total landings, or 6 months after the effective date of this AD, whichever occurs later.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on April 9, 1996.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 96-9235 Filed 4-12-96; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-NM-255-AD]

Airworthiness Directives; Beech Model 400, 400A, MU-300-10, and 2000 Airplanes, and Model 200, B200, 300, and B300 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Beech Model 400, 400A, MU-300-10, and 2000 airplanes, and Model 200, B200, 300, and B300 series airplanes. This proposal would require replacement of outflow/safety valves

with serviceable valves. This proposal is prompted by a report of cracking and subsequent failure of outflow safety valves in the pressurization system. The actions specified by the proposed AD are intended to prevent such cracking and subsequent failure of the outflow/safety valves, which could result in rapid decompression of the airplane.

DATES: Comments must be received by May 28, 1996.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-255-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from AlliedSignal Aerospace, Technical Publications, Dept. 65-70, P.O. Box 52170, Phoenix, Arizona 85072-2170. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California.

FOR FURTHER INFORMATION CONTACT: Walter Eierman, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; telephone (310) 627-5336; fax (310) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report

summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 95-NM-255-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-255-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received a report of the failure of a safety valve in the pressurization system on a Learjet Model 31A airplane. Failure of the valve resulted in depressurization of the cabin. Investigation revealed that the poppets of certain outflow/safety valves were cracked. These discrepant valves, including the safety valve installed on the incident airplane, had been manufactured since January 1, 1989. Certain valves manufactured since that date have been found to be susceptible to cracking due to an improper molding process during their manufacture. Cracking in the poppets of the outflow/safety valves in the pressurization system can result in an open valve with an effective flow area of 4.4 square inches; additionally, the valve may close and remain closed. This condition, if not corrected, could result in cracking and subsequent failure of the airflow/safety valves, which could lead to rapid decompression of the airplane.

On September 20, 1995, the FAA issued AD 95-20-03, amendment 39-9381 (60 FR 51709, October 3, 1995), to address this unsafe condition on certain Learjet Model 24, 25, 28, 29, 31, 35, 36, and 55 series airplanes. Subsequently, on December 5, 1995, the FAA issued AD 95-25-10, amendment 39-9456, (60 FR 66484, December 22, 1995), to address the unsafe condition on certain Cessna Model 441, 500, 550, and 560 series airplanes. The outflow/safety valves installed on these Cessna and Learjet airplane models are similar to the valves installed on Beech Model 400, 400A, MU-300-10, and 2000 airplanes, and Model 200, B200, 300, and B300 series airplanes. Therefore, the FAA has determined that the latter airplane models also are subject to the unsafe condition described previously.

The FAA has reviewed and approved Allied Signal Aerospace Service Bulletins 103570-21-4012 (for airplanes equipped with valves having part number 103570-25, 103570-26, or 103570-27) and 103648-21-4022 (for airplanes equipped with valves having part number 103648-1, 103648-3, 103648-4, 103648-5, 103648-6, 103648-7, or 103648-13), both Revision 1, both dated May 30, 1995, which describe procedures for replacement of certain discrepant outflow/safety valves with serviceable valves.

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require replacement of certain discrepant outflow/safety valves with serviceable valves. The actions would be required to be accomplished in accordance with the service bulletins described previously.

Operators should note that Allied Signal Aerospace Service Bulletin 103570-21-4012 recommends accomplishing the replacement within 150 flight hours (after the release of the service bulletin), but no later than June 30, 1996. Allied Signal Aerospace Service Bulletin 103648-21-4022 recommends accomplishing the replacement within 200 flight hours (after the release of the service bulletin), but no later than June 30, 1996. However, the FAA has determined that an interval of 18 months will address the identified unsafe condition in a timely manner. This proposed compliance time of 18 months was determined to be appropriate in consideration of the safety implications, the average utilization rate of the affected fleet, the practical aspects of accomplishment of the replacement during regular maintenance periods, and the availability of required replacement parts.

There are approximately 150 Model 400, 400A, MU-300-10, and 2000 airplanes, and Model 200, B200, 300, and B300 series airplanes of the affected design in the worldwide fleet. The FAA estimates that 105 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 12 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. The parts manufacturer has advised that it will provide replacement parts at no cost to operators. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$75,600, or \$720 per airplane.

The cost impact figure discussed above is based on assumptions that no

operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption "ADDRESSES."

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Beech Aircraft Corporation: Docket 95-NM-255-AD.

Applicability: Model 400, 400A, MU-300-10, and 2000 airplanes, Model 200 and B200 series airplanes having a maximum altitude capability of greater than 31,000 feet, and Model 300 and B300 series airplanes; equipped with Allied Signal outflow/safety valves, as identified in Allied Signal Aerospace Service Bulletins 103570-21-4012 and 103648-21-4022, both Revision 1, both

dated May 30, 1995; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent cracking and subsequent failure of the outflow/safety valves, which could result in rapid decompression of the airplane, accomplish the following:

(a) Within 18 months after the effective date of this AD, replace the outflow/safety valve in accordance with Allied Signal Aerospace Service Bulletin 103570-21-4012 (for airplanes equipped with valves having part number 103570-25, 103570-26, or 103570-27), or 103648-21-4022 (for airplanes equipped with valves having part number 103648-1, 103648-3, 103648-4, 103648-5, 103648-6, 103648-7, or 103648-13), both Revision 1, both dated May 30, 1995, as applicable.

(b) As of the effective date of this AD, no person shall install an outflow/safety valve, having a part number and serial number identified in Allied Signal Aerospace Service Bulletin 103570-21-4012 (for airplanes equipped with valves having part number 103570-25, 103570-26, or 103570-27), or 103648-21-4022 (for airplanes equipped with valves having part number 103648-1, 103648-3, 103648-4, 103648-5, 103648-6, 103648-7, or 103648-13), both Revision 1, both dated May 30, 1995, on any airplane unless that valve is considered to be serviceable in accordance with the applicable service bulletin.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on April 9, 1996.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 96-9234 Filed 4-12-96; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-NM-228-AD]

Airworthiness Directives; Airbus Model A300-600 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Airbus Model A300-600 series airplanes. This proposal would require an inspection to detect cracks of certain attachment holes; and installation of a new fastener and follow-on inspections or repair, if necessary. This proposal is prompted by reports of fatigue cracking found on the forward fitting of frame 47 at the level of the last fastener of the external angle fitting. The actions specified by the proposed AD are intended to prevent such fatigue cracking, which could result in reduced structural integrity of the airframe.

DATES: Comments must be received by May 28, 1996.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-228-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Tim Backman, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2797; fax (206) 227-1149.