

averaged \$.61 per pound, whereas wholesale prices of cut-up broilers averaged \$.66 per pound. Second, the potential for lowering production costs using lower wage employees would be offset by export fees, import fees and increased shipping/transportation costs.

Considering these factors, FSIS does not anticipate any measurable change in market prices for processed poultry products. Because of shipping and transportation costs, FSIS expects most of the change to be limited to firms located relatively close to the Mexican border. For the same reasons, FSIS does not expect to see increases in poultry imports from Mexico processed from birds slaughtered in other countries such as Canada and Great Britain. Currently, Mexico imports very little poultry from other countries. In 1996, Mexico imported approximately 396 million pounds of poultry and poultry products. More than 97 percent was imported from the United States.

FSIS does not believe this rule would offset enough product to affect domestic poultry prices. In 1996, U.S. poultry production was approximately 32.3 billion pounds on a ready-to-cook carcass weight basis. The United States exported approximately 386 million pounds to Mexico. With this rule, exports would likely increase more than imports on a pound basis. However, considering that imports would consist of value-added products, it is possible that the dollar value of imports will increase more than the value of exports.

As noted above, FSIS is requesting comments on the potential effect of this proposal on small entities. While most poultry is cut-up and boned in large firms, there are many small businesses involved in cut-up, boning and further poultry processing operations. Although changes in prices would affect these small businesses, FSIS does not expect measurable price changes for the reasons already discussed.

Paperwork Requirements

No new paperwork requirements are associated with this proposed rule. Foreign countries wanting to export poultry or poultry products to the United States are required to provide information to FSIS certifying that its inspection system provides standards equivalent to those of the United States and that the legal authority for the system and its implementing regulations are equivalent to those of the United States before they may start exporting such product to the United States. FSIS collects this information one time only. FSIS gave Mexico questionnaires asking for detailed information about the country's inspection practices and

procedures to assist the country in organizing its materials. This information collection was approved under OMB number 0583-0094. The proposed rule contains no other paperwork requirements.

List of Subjects 9 CFR Part 381

Imports, Poultry and poultry products.

For the reasons set out in the preamble, 9 CFR part 381 would be amended as follows:

PART 381—POULTRY PRODUCTS INSPECTION REGULATIONS

1. The authority citation for part 381 would continue to read as follows:

Authority: 7 U.S.C. 138f; 7 U.S.C. 450; 21 U.S.C. 451-470; 7 CFR 2.18, 2.53.

§ 381.196 [Amended]

2. Section 381.196 would be amended by adding "Mexico" in alphabetical order to the list of countries in paragraph (b).

Done at Washington, DC, on: November 18, 1997.

Thomas J. Billy,
Administrator.

[FR Doc. 97-31177 Filed 11-24-97; 10:10 am]

BILLING CODE 3410-DM-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-NM-154-AD]

RIN 2120-AA64

Airworthiness Directives; Dornier Model 328-100 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Dornier Model 328 series airplanes. This proposal would require a one-time inspection of the date stamp affixed to the wing deicing boots to determine the cure date, and replacement of the deicing boot with a new boot, if necessary. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent delamination of the wing deicing boots, and resultant inflation of the deicing boots to a

distorted aerodynamic shape during flight, which could result in reduced controllability of the airplane.

DATES: Comments must be received by December 29, 1997.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 97-NM-154-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Dornier Deutsche Aerospace, P.O. Box 1103, D-82230 Wessling, Federal Republic of Germany. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 97-NM-154-AD." The

postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 97-NM-154-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, notified the FAA that an unsafe condition may exist on all Dornier Model 328-100 series airplanes. The LBA advises that it has received two reports indicating that, during routine inspections, a wing deicing boot was found to be delaminated. The cause of the delamination of certain boots (i.e., those having cure dates of January 31, 1994, or earlier) has been attributed to the curing process used during manufacture. This condition, if not detected and corrected in a timely manner, could allow a deicing boot to inflate to a distorted aerodynamic shape during flight, which could result in reduced controllability of the airplane.

Explanation of Relevant Service Information

Dornier has issued Service Bulletin SB-328-30-171, dated September 20, 1996, including Annexes 1 and 2 (undated), which describes procedures for performing a one-time visual inspection of the date stamp affixed to the wing deicing boots to determine the cure date; and replacement of the boot with a new boot, if the cure date is January 31, 1994, or earlier. The LBA classified this service bulletin as mandatory and issued German airworthiness directive 96-320, dated November 7, 1996, in order to assure the continued airworthiness of these airplanes in Germany.

FAA's Conclusions

This airplane model is manufactured in Germany and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LBA has kept the FAA informed of the situation described above. The FAA has examined the findings of the LBA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Cost Impact

The FAA estimates that 50 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$3,000, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption

ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the

Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Dornier: Docket 97-NM-154-AD.

Applicability: All Model 328-100 series airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent delamination of the wing deicing boots and resultant inflation of the deicing boots to a distorted aerodynamic shape during flight, which could result in reduced controllability of the airplane, accomplish the following:

(a) Within 120 days after the effective date of this AD, perform a one-time visual inspection of the date stamp affixed to each wing deicing boot to determine the cure date, in accordance with Dornier Service Bulletin SB-328-30-171, dated September 20, 1996, including Annexes 1 and 2 (undated). If the cure date of any deicing boot is January 31, 1994, or earlier, or if the cure date of the deicing boot cannot be determined, prior to further flight, replace the deicing boot with a new deicing boot having a cure date later than January 31, 1994, in accordance with the service bulletin.

(b) As of the effective date of this AD, no person shall install on any airplane a wing deicing boot having a cure date of January 31, 1994, or earlier.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in German airworthiness directive 96-320, dated November 7, 1996.

Issued in Renton, Washington, on November 20, 1997.

Stewart R. Miller,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 97-31157 Filed 11-26-97; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-NM-231-AD]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica, S.A. (EMBRAER), Model

EMB-120 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain EMBRAER Model EMB-120 series airplanes. This proposal would require deactivation of certain circuit breakers, and a revision to the Airplane Flight Manual (AFM) to provide operational procedures to prevent loss of electrical power following an engine flameout. This proposal also would require modifications of the electrical system, which would terminate the requirement for the AFM revision and allow reactivation of the circuit breakers. This proposal is prompted by the issuance of mandatory continued airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent generator overload conditions that could result in loss of electrical power and failure of certain flight and landing control systems, and to prevent power interruption to the attitude heading reference system (AHRS) that could

result in the display of erroneous heading information.

DATES: Comments must be received by December 29, 1997.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 97-NM-231-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Empresa Brasileira de Aeronautica S/A, Sao Jose dos Campos, Brazil. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia.

FOR FURTHER INFORMATION CONTACT: John W. McGraw, Aerospace Engineer, Systems and Flight Test Branch, ACE-116A, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703-6098; fax (770) 703-6097.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped

postcard on which the following statement is made: "Comments to Docket Number 97-NM-231-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 97-NM-231-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Departamento de Aviacao Civil (DAC), which is the airworthiness authority for Brazil, notified the FAA that an unsafe condition may exist on certain EMBRAER Model EMB-120 series airplanes. The DAC advises that it received a report of one instance of substantial electrical power loss after flameout of the number 1 engine. The power loss was caused by activation of the system overload protection due to excessive loads on the remaining number 2 engine generator, which led to loss of certain flight and landing control systems. The DAC also advises that, due to power interruption for a few milliseconds to the attitude heading reference system (AHRS), erroneous heading information in both electronic horizontal situation indicators (EHSI) may be provided, without warning to the pilots, during an electrical emergency or when the electrical emergency switch is set to the "EMERGENCY" position. This condition, if not corrected, could result in generator overload conditions that could result in loss of electrical power and failure of certain flight and landing control systems, and power interruption to the AHRS that could result in display of erroneous heading information.

Explanation of Relevant Service Information

EMBRAER has issued Service Bulletin 120-24-0008, Change 04, dated October 3, 1995, which describes procedures for modification of the electrical system.

This modification involves revising the electrical connections and wiring in the relay boxes and circuit breaker panels.

EMBRAER has also issued Service Bulletin 120-24-0051, Change 04, dated March 8, 1995, which also describes procedures for modification of the electrical system. This modification involves electrical load redistribution and introduction of a contactor to connect a direct current (DC) bus to the emergency bus.

Accomplishment of the actions specified in these service bulletins is