

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 96–NM–171–AD.

Applicability: Model 747–400, –400D, and –400F series airplanes; as identified in Boeing Alert Service Bulletin 747–21A2381, dated June 27, 1996; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of control of the cabin pressurization system, which could result in rapid depressurization of the airplane and consequent deleterious physiological effects on the passengers and crew; and airplane diversions, which represent an increased risk to the airplane, passengers, and crew; accomplish the following:

(a) Within 180 days after the effective date of this AD: Modify the P212 and P213 panels of the cabin pressure control system as specified in paragraph (a)(1) or (a)(2) of this AD, as applicable, in accordance with Boeing Alert Service Bulletin 747–21A2381, dated June 27, 1996.

(1) For Groups 1 through 7 airplanes, as identified in the alert service bulletin: Change the wiring in the P212 and P213 panels; replace the existing two-pole relays with new four-pole relays; and perform a test of both panels.

(2) For Group 8 airplanes, as identified in the alert service bulletin: Change the wiring in the P212 panel; replace the existing two-pole relays with new four-pole relays; replace the existing P213 panel with a new P213 panel; and perform a test of both panels.

(b) For airplanes having line positions 696 through 1021 inclusive: Within 180 days after the effective date of this AD, accomplish paragraphs (b)(1) and (b)(2), as applicable, of this AD; in accordance with Boeing Service Bulletin 747–24–2193, dated January 25, 1995; as revised by Notices of Status Change (NSC) 747–24–2193 NSC 1, dated April 13, 1995, 747–24–2193 NSC 2, dated October 5, 1995, 747–24–2193 NSC 3, dated November 22, 1995, 747–24–2193 NSC 4, dated December 21, 1995, 747–24–2193 NSC 5, dated May 2, 1996, and 747–24–2193 NSC 6, dated March 13, 1997; or Alert Service Bulletin 747–24A2193, Revision 1, dated June 19, 1997.

(1) For all airplanes: Modify the wiring of the P5, P6, and P7 panels; modify the wiring in the W4701 and W4908 wire bundles; and install diodes in the P6 panel.

(2) For Groups 1 and 2 airplanes identified in paragraph I. of the Accomplishment Instructions of the service bulletin or alert service bulletin: Modify the wiring in the W4703 wire bundle.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on May 5, 1998.

D. L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98–12520 Filed 5–11–98; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97–NM–156–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Model A320 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A320 series airplanes. This proposal would require repetitive inspections to detect cracking in the inner flange of door frame 66, and corrective actions, if necessary. This proposal also would provide for an optional terminating action for the repetitive inspections. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to correct such fatigue cracking, which could result in reduced structural integrity of the airplane.

DATES: Comments must be received by June 11, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 97–NM–156–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–2110; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule.

The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 97–NM–156–AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the

FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-156-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on certain Airbus Model A320 series airplanes. The DGAC advises that, during fatigue testing on a Model A320 test article, between 60,500 and 85,700 flight cycles, three cracks developed on the inner flange of door frame 66 at stringer 18 and stringer 20. The cracks were located around the edges of the gusset plate attachment holes of the inner flange of door frame 66, which, during routine visual inspection, would be hidden by the gusset plates. Such fatigue cracking, if not corrected, could result in reduced structural integrity of the airplane.

Explanation of Relevant Service Information

Airbus has issued Service Bulletin A320-53-1071, dated November 7, 1995, as revised by Change Notice 0A, dated July 5, 1996. This service bulletin describes procedures for repetitive rotating probe eddy current inspections to detect cracking around the edges of the gusset plate attachment holes of the inner flange of door frame 66, left and right, at stringer positions P18, P20, P22, P18', P20', and P22'. The DGAC classified this service bulletin as mandatory and issued French airworthiness directive 96-234-087(B), dated October 23, 1996, in order to assure the continued airworthiness of these airplanes in France. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Airbus also has issued Service Bulletin A320-53-1072, dated November 7, 1995, as revised by Change Notice 0A, dated July 5, 1996. This service bulletin describes procedures for modification of the gusset plate attachment holes. The modification involves cold working the attachment holes of the inner flange of door frame 66, left and right, at stringer positions P18, P20, P22, P18', P20', and P22.. Accomplishment of the modification would eliminate the need for the repetitive inspections. The DGAC has approved this service bulletin.

FAA's Conclusions

This airplane model is manufactured in France and is type certificated for operation in the United States under the

provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in Service Bulletin A320-53-1071 described previously, except as described in the following section. This proposed AD also would provide for optional terminating action for the repetitive inspections.

Operators should note that, in consonance with the findings of the DGAC, the FAA has determined that the repetitive inspections proposed by this AD can be allowed to continue in lieu of accomplishment of a terminating action. In making this determination, the FAA considers that, in this case, long-term continued operational safety will be adequately assured by accomplishing the repetitive inspections to detect cracking before it represents a hazard to the airplane.

Differences Between the Proposed AD and the Foreign Service Information

The proposed AD would differ from the previously described Airbus service bulletins and French airworthiness directive, which specify that Airbus be contacted for a repair solution for cracking detected during an inspection. In the proposed AD, however, repair of any crack would be required to be accomplished in accordance with a method approved by the FAA.

Also, operators should note that, unlike the procedures described in Airbus Service Bulletin A320-53-1071, this proposed AD would not permit further flight if cracks are detected around the edges of the gusset plate attachment holes of the inner flange of door frame 66. The FAA has determined that, because of the safety implications and consequences associated with such cracking, any subject attachment hole that is found to have cracking must be repaired or modified prior to further flight.

Cost Impact

The FAA estimates that 132 airplanes of U.S. registry would be affected by this proposed AD.

It would take approximately 8 work hours per airplane to accomplish the proposed inspection, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the inspection proposed by this AD on U.S. operators is estimated to be \$63,360, or \$480 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Should an operator elect to accomplish the proposed modification, it would take approximately 5 work hours per airplane to accomplish the actions, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the modification proposed by this AD on U.S. operators is estimated to be \$300 per airplane.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation

Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Airbus Industrie: Docket 97–NM–156–AD.

Applicability: Model A320 series airplanes on which Airbus Modification 21778 (reference Airbus Service Bulletin A320–53–1072, dated November 7, 1995, as revised by Change Notice 0A, dated July 5, 1996) has not been accomplished, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To correct fatigue cracking in the inner flange of door frame 66, left and right, which could result in reduced structural integrity of the airplane, accomplish the following:

(a) Prior to the accumulation of 20,000 total flight cycles, or within 1 year after the effective date of this AD, whichever occurs later: Perform a rotating probe eddy current inspection to detect cracking around the edges of the gusset plate attachment holes of the inner flange of door frame 66, left and right, at stringer positions P18, P20, P22, P18', P20', and P22', in accordance with Airbus Service Bulletin A320–53–1071, dated November 7, 1995, as revised by Change Notice 0A, dated July 5, 1996. If any crack is detected, prior to further flight, repair in accordance with a method approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate. Repeat the inspection thereafter at intervals not to exceed 20,000 flight cycles.

(b) Modification of the gusset plate attachment holes of the inner flange of door frame 66, left and right (Airbus Modification 21778), in accordance with Airbus Service Bulletin A320–53–1072, dated November 7, 1995, as revised by Change Notice 0A, dated July 5, 1996, constitutes terminating action for the repetitive inspection requirements of this AD.

(c) An alternative method of compliance or adjustment of the compliance time that

provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in French airworthiness directive 96–234–087(B), dated October 23, 1996.

Issued in Renton, Washington, on May 5, 1998.

John J. Hickey,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98–12518 Filed 5–11–98; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98–NM–37–AD]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 757–200 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 757–200 series airplanes. This proposal would require modifications to the attachment installation of the forward lavatory. This proposal is prompted by a stress analysis report indicating that the forward lavatory could break free from the upper and/or lower attachments during an emergency landing. The actions specified by the proposed AD are intended to prevent failure of the attachment installation of the forward lavatory during an emergency landing, which could result in injury to the crew and passengers.

DATES: Comments must be received by June 26, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport

Airplane Directorate, ANM–114, Attention: Rules Docket No. 98–NM–37–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124–2207.

This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Keith Ladderud, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–2780; fax (425) 227–1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98–NM–37–AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate,