

Rules and Regulations

Federal Register

Vol. 63, No. 99

Friday, May 22, 1998

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-NM-251-AD; Amendment 39-10537; AD 98-11-10]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-9 and DC-9-80 Series Airplanes, Model MD-88 Airplanes, and C-9 (Military) Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model DC-9 and DC-9-80 series airplanes, Model MD-88 airplanes, and C-9 (military) series airplanes, that requires an inspection to determine if the latching lever pin of the speed brake passes an axial force check, and a visual inspection to determine if the staking of the latching lever pin is acceptable; and follow-on corrective action, if necessary. This amendment is prompted by reports that the speed brake handle jammed in the ground spoiler position. The actions specified by this AD are intended to prevent a jammed speed brake handle pin, which could result in retraction of the spoilers and full advancement of the left throttle during a go-around.

DATES: Effective June 26, 1998.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of June 26, 1998.

ADDRESSES: The service information referenced in this AD may be obtained from The Boeing Company, Douglas Products Division, 3855 Lakewood

Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Walter Eierman, Aerospace Engineer, Systems and Equipment Branch, ANM-130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; telephone (562) 627-5336; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model DC-9 and DC-9-80 series airplanes, Model MD-88 airplanes, and C-9 (military) series airplanes was published in the **Federal Register** on February 19, 1998 (63 FR 8371). That action proposed to require an inspection to determine if the latching lever pin of the speed brake passes an axial force check, and a visual inspection to determine if the staking of the latching lever pin is acceptable; and follow-on corrective action, if necessary.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

The commenter supports the proposed rule.

Conclusion

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 2,050 McDonnell Douglas Model DC-9 and DC-9-80 series airplanes, Model MD-88 airplanes, and C-9 (military) series

airplanes of the affected design in the worldwide fleet. The FAA estimates that 1,250 airplanes of U.S. registry will be affected by this AD, that it will take approximately 5 work hours per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$375,000, or \$300 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

98-11-10 McDonnell Douglas: Amendment 39-10537. Docket 97-NM-251-AD.

Applicability: Model DC-9-10, -20, -30, -40, and -50, and DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) series airplanes; Model MD-88 airplanes; and C-9 (military) series airplanes; as listed in McDonnell Douglas Service Bulletin DC9-27-346, Revision 01, dated July 29, 1997; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent a jammed speed brake handle pin, which could result in retraction of the spoilers and full advancement of the left throttle during a go-around, accomplish the following:

(a) Within 12 months after the effective date of this AD, perform an inspection to determine if the latching lever pin of the speed brake passes an axial force check, and a visual inspection to determine if the staking of the latching lever pin is "acceptable", in accordance with McDonnell Douglas Service Bulletin DC9-27-346, Revision 01, dated July 29, 1997.

Note 2: The criteria for determining whether the staking is "acceptable" are defined in Figure 1 of the service bulletin.

(1) Condition 1. If the pin passes the axial force check and the staking is found to be acceptable, no further action is required by this AD.

(2) Condition 2. If the pin passes the axial force check and the staking is found to be unacceptable, accomplish the actions specified in Condition 2, Option 1, or Condition 2, Option 2 of the Accomplishment Instructions of the service bulletin. These actions shall be accomplished at the times specified in paragraph E. "Compliance" of the service bulletin. Accomplishment of the replacement of the speed brake latching lever constitutes terminating action for the repetitive inspection requirements of this AD.

(3) Condition 3. If the pin fails the axial force check and the staking is found to be unacceptable, accomplish the actions specified in Condition 3, Option 1, or Condition 3, Option 2 of the Accomplishment Instructions of the service bulletin. These actions shall be accomplished at the times specified in paragraph E. "Compliance" of the service bulletin. Accomplishment of the replacement of the speed brake latching lever constitutes terminating action for the repetitive inspection requirements of this AD.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The actions shall be done in accordance with McDonnell Douglas Service Bulletin DC9-27-346, Revision 01, dated July 29, 1997. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from The Boeing Company, Douglas Products Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on June 26, 1998.

Issued in Renton, Washington, on May 14, 1998.

John J. Hickey,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 98-13407 Filed 5-21-98; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-NM-165-AD; Amendment 39-10540; AD 98-11-13]

RIN 2120-AA64

Airworthiness Directives; Raytheon Model Hawker 800XP Series Airplanes, and Hawker 800 (U-125A Military Derivative) Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain Raytheon Model Hawker 800XP series airplanes and Hawker 800 (U-125A military derivative) airplanes. This action requires removal of the sealant from the firewall mounting flanges and mounting points of the fire extinguisher assemblies; removal of sealant obstructing the discharge tubes of the fire extinguisher assemblies; cleaning and flushing of the mounting flanges, mounting points, and discharge tubes with solvent; and installation of new gaskets on the firewall mounting flanges and mounting points. This amendment is prompted by reports of excessive sealant applied during manufacture of the firewall mounting flanges and mounting points of the fire extinguisher assemblies, which subsequently entered and obstructed the discharge tubes. The actions specified in this AD are intended to prevent obstructions of the discharge tubes of the fire extinguisher assemblies, which could result in improper distribution of the fire extinguishing agent within the nacelle in the event of a fire.

DATES: Effective June 8, 1998.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of June 8, 1998.

Comments for inclusion in the Rules Docket must be received on or before July 21, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-165-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

The service information referenced in this AD may be obtained from Raytheon Aircraft Company, Manager Service