

performed in accordance with paragraph (a)(1) of this AD.

(b) Remove from service those HPT disks found with a crack indicating a subsurface anomaly and replace with a serviceable part.

(c) For the purposes of this AD, HPT disk piece part accessibility is defined as the separation of the HPT disk from the HPT module.

(d) For engines that do not have a HPT stage 1 or Stage 2 disk installed that has a serial number listed in the Accomplishment Instructions section of PW SB PW2000-72-628, dated January 4, 1999, no inspections are required.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office. Operators shall submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Engine Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Engine Certification Office.

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be accomplished.

Issued in Burlington, Massachusetts, on March 16, 1999.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 99-6979 Filed 3-22-99; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-112-AD]

RIN 2120-AA64

Airworthiness Directives; The New Piper Aircraft, Inc. Models PA-46-310P and PA-46-350P Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes to adopt a new airworthiness directive (AD) that would apply to all The New Piper Aircraft, Inc. (Piper) Models PA-46-310P and PA-46-350P airplanes. The proposed AD would require calibrating the turbine inlet temperature system to assure the accuracy of the existing turbine inlet temperature indicator and wiring for all of the applicable airplanes, and repairing or

replacing any turbine inlet temperature system that fails the calibration test. The proposed AD would also require repetitively replacing the turbine inlet temperature probe on the Model PA-46-350P airplanes, and inserting a copy of this AD into the Pilot's Operating Handbook of certain airplanes. The proposed AD is the result of field reports that indicate service accuracy problems with the existing turbine inlet temperature system. The actions specified by the proposed AD are intended to prevent improper engine operation caused by improperly calibrated turbine inlet temperature indicators or defective turbine inlet temperature probes, which could result in engine damage/failure with consequent loss of control of the airplane.

DATES: Comments must be received on or before May 21, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-112-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from The New Piper Aircraft, Inc., Customer Services, 2926 Piper Drive, Vero Beach, Florida 32960. This information also may be examined at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Mr. Donald J. Young, Aerospace Engineer, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, Suite 450, Atlanta, Georgia 30349; telephone: (770) 703-6079; facsimile: (770) 703-6097; e-mail address: "Donald.Young@faa.gov".

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic,

environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 98-CE-112-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-112-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Discussion

The FAA has received several reports that indicate service accuracy problems with the existing turbine inlet temperature system on Piper Models PA-46-310P and PA-46-350P airplanes. In particular, an accident report cited turbine inlet temperature probe inaccuracy as a contributing factor.

In addition, 9 airplanes were randomly checked for turbine inlet temperature system accuracy. Six of these airplanes revealed turbine inlet temperature system inaccuracy (60 degrees to 110 degrees low at the 1,750-degree test point). More extensive analysis of these systems reveals the following:

- The turbine inlet temperature probe used on the Model PA-46-310P airplanes (part number 471-990) when calibrated correctly is accurate and durable; and
- The turbine inlet temperature probe used on the Model PA-46-350P airplanes (part number 481-392) when calibrated correctly is accurate, but not durable.

The FAA's Determination

After examining the circumstances and reviewing all available information related to the incidents described above, the FAA has determined that:

- the turbine inlet temperature systems on all Piper Models PA-46-310P and PA-46-350P airplanes should be calibrated to assure the accuracy of

- the existing turbine inlet temperature indicator and wiring;
- the turbine inlet temperature probe used on the Model PA-46-350P airplanes (part number 481-392) should be replaced every 250 hours time-in-service (TIS); and
- AD action should be taken to prevent improper engine operation caused by improperly calibrated turbine inlet temperature indicators or defective turbine inlet temperature probes, which could result in engine damage/failure with consequent loss of control of the airplane.

Explanation of the Provisions of the Proposed AD

Since an unsafe condition has been identified that is likely to exist or develop in other Piper Models PA-46-310P and PA-46-350P airplanes of the same type design, the FAA is proposing AD action. The proposed AD would require calibrating the turbine inlet temperature system to assure the accuracy of the existing turbine inlet temperature indicator and wiring for all of the applicable airplanes, and repairing or replacing any turbine inlet temperature system that fails the calibration test. The proposed AD would also require repetitively replacing the turbine inlet temperature probe on the Model PA-46-350P airplanes, and inserting a copy of this AD into the Pilot's Operating Handbook of certain airplanes.

Cost Impact

The FAA estimates that 580 airplanes in the U.S. registry would be affected by the proposed calibration, that it would take approximately 4 workhours per airplane to accomplish the proposed calibration, and that the average labor rate is approximately \$60 an hour. Based on these figures, the total cost impact of the proposed calibration on U.S. operators is estimated to be \$139,200, or \$240 per airplane.

The FAA estimates that it would take approximately 1 workhour per airplane to accomplish the proposed initial turbine inlet temperature probe replacement, and that the average labor rate is approximately \$60 an hour. Parts cost approximately \$518. Based on these figures, the total cost impact of the proposed replacement on U.S. operators is estimated to be \$335,240, or \$578 per airplane. These figures only take into account the initial replacement and do not take into account the cost of subsequent repetitive replacements. The FAA has no way of determining the number of replacements each owner/operator will incur over the life of the affected airplanes.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action has been placed in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD) to read as follows:

The New Piper Aircraft, Inc.: Docket No. 98-CE-112-AD.

Applicability: Models PA-46-310P and PA-46-350P airplanes, all serial numbers, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in

accordance with paragraph (h) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated in the body of this AD, unless already accomplished.

To prevent improper engine operation caused by improperly calibrated turbine inlet temperature indicators or defective turbine inlet temperature probes, which could result in engine damage/failure with consequent loss of control of the airplane, accomplish the following:

(a) For all affected airplanes (Models PA-46-310P and PA-46-350P), within the next 100 hours time-in-service (TIS) after the effective date of this AD, accomplish the Turbine Inlet Temperature Gauge and Probe Cleaning and Inspection, and Turbine Inlet Temperature System Calibration, as follows:

(1) *For Model PA-46-310P airplanes:* Perform the Turbine Inlet Temperature Gauge and Probe Cleaning and Inspection in accordance with the PA-46-310P/350P Maintenance Manual, Chapter 77-20-00 (section A.(1)(d), pages 1 and 2); and accomplish the Turbine Inlet Temperature System Calibration in accordance with the PA-46-310P/350P Maintenance Manual, Chapter 77-20-00 (pages 3 and 4); and

(2) *For Model PA-46-350P airplanes:* Perform the Turbine Inlet Temperature Gauge and Probe Cleaning and Inspection in accordance with the PA-46-350P Maintenance Manual, Chapter 77-20-00 (section 1.C, page 1); and accomplish the Turbine Inlet Temperature System Calibration in accordance with the PA-46-350P Maintenance Manual, Chapter 77-20-00 (section 1.I., pages 4 through 7).

Note 2: Operators of the Model PA-46-350P airplanes with over 150 hours TIS on the currently installed turbine inlet temperature probe will have to replace the probe as required in paragraph (c) of this AD. In this case, the operator may want to accomplish the replacement prior to the Turbine Inlet Temperature Gauge and Probe Cleaning and Inspection, and Turbine Inlet Temperature System Calibration.

(b) For all affected airplanes (Models PA-46-310P and PA-46-350P), if the results of paragraph (a) of this AD cannot be met (the turbine inlet temperature system indicator cannot be calibrated or the turbine inlet temperature probe fails the inspection), prior to further flight, repair or replace the failed parts with serviceable parts of the following part numbers:

(1) Lewis Turbine Inlet Temperature Analog Indicator, part number 471-008.

(2) Lewis Turbine Inlet Temperature Digital Indicator, part number 548-811.

(3) Turbine Inlet Temperature Probe, part number 471-009 for the Model PA-46-310P airplanes and part number 481-392 for the PA-46-350P airplanes.

(4) Only the Lewis Turbine Inlet Temperature Analog Indicator (referenced in paragraph (b)(1) of this AD) has a zero adjustment screw. The Lewis Turbine Inlet Temperature Digital Indicator (referenced in

paragraph (b)(2) of this AD must be returned to the factory for adjustment or replacement.

(c) For the Model PA-46-350P airplanes, upon accumulating 250 hours TIS on the currently installed turbine inlet temperature probe or within the next 100 hours TIS after the effective date of this AD, whichever occurs later, and thereafter at intervals not to exceed 250 hours TIS; replace the part number 481-392 turbine inlet temperature

probe with a new one of the same part number.

(d) For the operators of the airplanes presented in paragraphs (d)(1) and (d)(2) of this AD, within the next 100 hours TIS after the effective date of this AD, incorporate the emergency operation procedures specified in paragraph (e) of this AD for when a turbine inlet temperature system failure occurs while in-flight by inserting a copy of this AD into

the applicable Pilots' Operating Handbook/ Airplane Flight Manual (AFM/POH):

(1) For all operators of the Model PA-46-310P airplanes; and

(2) For those operators of the Model PA-46-350P airplanes that do not have the applicable POH revision incorporated as follows:

POH	Revision/date	Affected serial numbers
VB-1332	16/November 14, 1997	4622001 through 4622200.
VB-1609	1/November 21, 1997	463001 through 4636020.
VB-1602	1/November 28, 1997	4636021 through 4636131.
VB-1446	New/December 3, 1997	all serial numbers beginning with 4636132.

(e) The following are emergency operation procedures for when a turbine inlet temperature system failure occurs while in-flight:

(1) For Model PA-46-310P airplanes:

(i) If the turbine inlet temperature indication fails during takeoff, climb, descent, or landing, maintain FULL RICH mixture to assure adequate fuel flow for engine cooling.

(ii) If the turbine inlet temperature indication fails after cruise power has been set, maintain cruise power setting and lean to 6 gallons per hour (GPH) fuel flow above that specified in the Power Setting Table in Section 5 of the AFM/POH. Continually monitor engine cylinder head and oil temperatures to avoid exceeding temperature limits.

(2) For Model PA-46-350P airplanes:

(i) If the turbine inlet temperature indication fails during takeoff, climb, descent or landing, set power per the POH Section 5 Power Setting Table and then lean to the approximate POH Power Setting Table fuel flow plus 4 GPH.

(ii) If the turbine inlet temperature indication fails after cruise power has been set, maintain the power setting and increase indicated fuel flow by 1 GPH. Continually monitor engine cylinder head and oil temperatures to avoid exceeding temperature limits.

(f) Inserting a copy of this AD into the applicable POH/AFM as required by paragraph (d) of this AD may be performed by the owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7), and must be entered into the aircraft records showing compliance with paragraph (d) of this AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(h) An alternative method of compliance or adjustment of the initial or repetitive compliance times that provides an equivalent level of safety may be approved by the Manager, Atlanta Aircraft Certification Office (ACO), One Crown Center, 1895 Phoenix Boulevard, Suite 450, Atlanta, Georgia 30349.

The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

(i) All persons affected by this directive may obtain copies of the document referred to herein upon request to The New Piper Aircraft, Inc., Customer Services, 2926 Piper Drive, Vero Beach, Florida 32960; or may examine this document at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on March 12, 1999.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-6975 Filed 3-22-99; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-SW-16-AD]

Airworthiness Directives; McDonnell Douglas Helicopter Systems Model 600N Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to McDonnell Douglas Helicopter Systems (MDHS) Model 600N helicopters. This proposal would require applying serial numbers to several life-limited components related to pitch control and removing and replacing the components according to new life-limits. This proposal is prompted by fatigue tests

that indicate a need for shorter service lives for these components. The actions specified by the proposed AD are intended to prevent failure of the collective pitch control tubes, collective stick housings, and collective pitch tube assemblies, which can cause loss of collective pitch control, and subsequent loss of control of the helicopter.

DATES: Comments must be received by May 24, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 98-SW-16-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from McDonnell Douglas Helicopter Systems, Technical Publications, Bldg. 530/B11, 5000 E. McDowell Road, Mesa, Arizona 85205-9797. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas.

FOR FURTHER INFORMATION CONTACT: Frederick A. Guerin, Aerospace Engineer, Airframe Branch, Los Angeles Aircraft Certification Office, 3960 Paramount Blvd., Lakewood, California 90712, telephone (562) 627-5232, fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All