

b. The biological quality of the protein in the alternate protein product must be at least 80 percent that of casein, determined by performing a Protein Digestibility Corrected Amino Acid Score (PDCAAS).

c. The alternate protein product must contain at least 18 percent protein by weight when fully hydrated or formulated. ("When hydrated or formulated" refers to a dry alternate protein product and the amount of water, fat, oil, colors, flavors or any other substances which have been added).

d. Manufacturers supplying an alternate protein product to participating schools or institutions must provide documentation that the product meets the criteria in paragraphs a through c above.

e. Manufacturers should provide information on the percent protein contained in the dry alternate protein product and on an as prepared basis.

f. For an alternate protein product mix, manufacturers provide information on:

- (1) the amount by weight of dry alternate protein product in the package;
- (2) hydration instructions; and
- (3) instructions on how to combine the mix with meat, poultry or seafood.

#### *B. How are Alternate Protein Products Used in the Summer Food Service Program?*

1. Schools, institutions, and service institutions may use alternate protein products to fulfill all or part of the meat/meat alternate component discussed in § 225.20.

2. The following terms and conditions apply:

a. The alternate protein product may be used alone or in combination with other food ingredients. Examples of combination items are beef patties, beef crumbles, pizza topping, meat loaf, meat sauce, taco filling, burritos, and tuna salad.

b. Alternate protein products may be used in the dry form (nonhydrated), partially hydrated or fully hydrated form. The moisture content of the fully hydrated alternate protein product (if prepared from a dry concentrated form) must be such that the mixture will have a minimum of 18 percent protein by weight or equivalent amount for the dry or partially hydrated form (based on the level that would be provided if the product were fully hydrated).

#### *C. How are Commercially Prepared Products Used in the Summer Food Service Program?*

Schools, institutions, and service institutions may use a commercially prepared meat, poultry or seafood product combined with alternate protein products or use a commercially prepared product that contains only alternate protein products.

### **PART 226—CHILD AND ADULT CARE FOOD PROGRAM**

1. The authority citation for 7 CFR 225 continues to read:

**Authority:** Secs. 9, 11, 14, 16, and 17, National School Lunch Act, as amended (42 U.S.C. 1758, 1759a, 1762a, 1765, and 1766).

2. Revise Appendix A to Part 226, entitled Alternate Foods for Meals, to read as follows:

### **Appendix A to Part 226—Alternate Foods for Meals**

#### **Alternate Foods for Meals**

##### *A. What are the Criteria for Alternate Protein Products (APP) Used in the Child and Adult Care Food Program?*

1. An alternate protein product used in meals planned under the provisions in § 226.20 must meet all of the criteria in this section.

2. An alternate protein product whether used alone or in combination with meat, poultry or seafood must meet the following criteria:

a. The alternate protein product must be processed so that some portion of the non-protein constituents of the food is removed. These alternate protein products must be safe and suitable edible products produced from plant or animal sources.

b. The biological quality of the protein in the alternate protein product must be at least 80 percent that of casein, determined by performing a Protein Digestibility Corrected Amino Acid Score (PDCAAS).

c. The alternate protein product must contain at least 18 percent protein by weight when fully hydrated or formulated. ("When hydrated or formulated" refers to a dry alternate protein product and the amount of water, fat, oil, colors, flavors or any other substances which have been added).

d. Manufacturers supplying an alternate protein product to participating schools or institutions must provide documentation that the product meets the criteria in paragraphs a through c above.

e. Manufacturers should provide information on the percent protein contained in the dry alternate protein product and on an as prepared basis.

f. For an alternate protein product mix, manufacturers provide information on:

- (1) the amount by weight of dry alternate protein product in the package;
- (2) hydration instructions; and
- (3) instructions on how to combine the mix with meat, poultry or seafood.

##### *B. How are Alternate Protein Products Used in the Child and Adult Care Food Program?*

1. Schools, institutions, and service institutions may use alternate protein products to fulfill all or part of the meat/meat alternate component discussed in § 226.20.

2. The following terms and conditions apply:

a. The alternate protein product may be used alone or in combination with other food ingredients. Examples of combination items are beef patties, beef crumbles, pizza topping, meat loaf, meat sauce, taco filling, burritos, and tuna salad.

b. Alternate protein products may be used in the dry form (nonhydrated), partially hydrated or fully hydrated form. The moisture content of the fully hydrated alternate protein product (if prepared from a dry concentrated form) must be such that the mixture will have a minimum of 18 percent protein by weight or equivalent amount for the dry or partially hydrated form (based on the level that would be provided if the product were fully hydrated).

##### *C. How are Commercially Prepared Products Used in the Child and Adult Care Food Program?*

Schools, institutions, and service institutions may use a commercially prepared meat, poultry or seafood product combined with alternate protein products or use a commercially prepared product that contains only alternate protein products.

Dated: July 14, 1999.

**Samuel Chambers, Jr.,**

*Administrator, Food and Nutrition Service.*

[FR Doc. 99-18433 Filed 7-19-99; 8:45 am]

BILLING CODE 3410-30-P

## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 39**

[Docket No. 99-NM-92-AD]

RIN 2120-AA64

#### **Airworthiness Directives; Bombardier Model CL-600-2B19 (Regional Jet Series 100) Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Bombardier Model CL-600-2B19 (Regional Jet Series 100) series airplanes. This proposal would require removal of the insulation blankets surrounding the emergency overwing exit hatches. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent the freezing of moisture entrapped in the fiberglass/foam insulation installed on the fuselage structure between the overwing exit door and the fuselage door frame and intercostal, which could interfere with the opening of the overwing emergency exit hatches during an emergency evacuation of the airplane.

**DATES:** Comments must be received by August 19, 1999.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-92-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. The service information referenced in the proposed rule may be

obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington or at the FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York.

**FOR FURTHER INFORMATION CONTACT:** Paolo Farina, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7530; fax (516) 568-2716.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-92-AD." The postcard will be date stamped and returned to the commenter.

**Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-92-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

**Discussion**

Transport Canada Aviation (TCA), which is the airworthiness authority for Canada, recently notified the FAA that an unsafe condition may exist on certain Bombardier Model CL-600-2B19 (Regional Jet Series 100) series airplanes. TCA advises that, during airplane maintenance that was carried out within approximately one hour of the last flight of the day, an operator experienced problems removing the emergency overwing exit hatches on three Model CL-600-2B19 series airplanes. An investigation revealed that the problem was due to the freezing of moisture in the fiberglass/foam insulation installed on the fuselage structure between the overwing exit door and the fuselage door frame and intercostal. This condition, if not corrected, could prevent the opening of the emergency overwing exit hatches during an emergency evacuation of the aircraft.

**Explanation of Relevant Service Information**

Bombardier has issued Canadair Regional Jet Alert Service Bulletin S.B. A601R-25-152, Revision 'A,' dated February 25, 1999, which describes procedures for removal of the insulation blankets surrounding the emergency overwing exit hatches. Accomplishment of the actions specified in the alert service bulletin is intended to adequately address the identified unsafe condition. TCA classified this alert service bulletin as mandatory and issued Canadian airworthiness directive CF-99-01, dated February 9, 1999, in order to assure the continued airworthiness of these airplanes in Canada.

**FAA's Conclusions**

This airplane model is manufactured in Canada and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, TCA has kept the FAA informed of the situation described above. The FAA has examined the findings of TCA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

**Explanation of Requirements of Proposed Rule**

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same

type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the alert service bulletin described previously.

**Cost Impact**

The FAA estimates that 157 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 3 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$28,260, or \$180 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

**Regulatory Impact**

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Safety.

**The Proposed Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Bombardier, Inc.** (Formerly Canadair):  
Docket 99-NM-92-AD.

**Applicability:** Model CL-600-2B19 (Regional Jet Series 100) series airplanes, serial numbers 7003 through 7067 inclusive and 7069 through 7292 inclusive; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent the freezing of moisture entrapped in the fiberglass/foam insulation installed on the fuselage structure between the overwing exit door and the fuselage door frame and intercostal, which could interfere with the opening of the overwing emergency exit hatches during an emergency evacuation of the airplane, accomplish the following:

(a) Within 100 flight hours or 30 days after the effective date of this AD, whichever occurs first, remove the insulation blankets surrounding the emergency overwing exit hatches in accordance with Canadair Regional Jet Alert Service Bulletin S.B. A601R-25-152, Revision 'A,' dated February 25, 1999.

**Note 2:** Removal of the insulation blankets surrounding the emergency overwing exit hatches accomplished in accordance with Canadair Regional Jet Alert Service Bulletin S.B. A601R-25-152, dated December 26, 1998, prior to the effective date of this AD, is considered acceptable for compliance with paragraph (a) of this AD.

### Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA, Engine and Propeller Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

### Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Note 4:** The subject of this AD is addressed in Canadian airworthiness directive CF-99-01, dated February 9, 1999.

Issued in Renton, Washington, on July 14, 1999.

### D.L. Rigglin,

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 99-18413 Filed 7-19-99; 8:45 am]

BILLING CODE 4910-13-U

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 99-NM-89-AD]

RIN 2120-AA64

### Airworthiness Directives; Boeing Model 757-200 and -300 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 757-200 and -300 series airplanes. This proposal would require modification of the slide/raft evacuation system by installing a girt reinforcement chafing patch. This proposal is prompted by reports of holes in the inflatable area of the slide/raft evacuation system. The actions specified by the proposed AD are intended to prevent holes in the inflatable portion of the slide/raft evacuation system, which could result in the slide/raft being unusable as a raft during an emergency water landing.

**DATES:** Comments must be received by September 3, 1999.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-89-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m.,

Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Air Cruisers Company, Technical Publications Department, P.O. Box 180, Belmar, New Jersey 07719-0180. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Keith Ladderud, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2780; fax (425) 227-1181.

### SUPPLEMENTARY INFORMATION:

#### Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-89-AD." The postcard will be date stamped and returned to the commenter.

#### Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-89-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

#### Discussion

The FAA has received reports of holes in the inflatable portion of certain slide/