

therefore is not covered under Executive Order 12866, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Withdrawal

Accordingly, the notice of proposed rulemaking, Docket 97-NM-203-AD, published in the **Federal Register** on April 6, 1998 (63 FR 16715), is withdrawn.

Issued in Renton, Washington, on March 21, 2000.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 00-7460 Filed 3-24-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-354-AD]

RIN 2120-AA64

Airworthiness Directives; Saab Model SAAB 340B and SAAB 2000 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to certain Saab Model SAAB 340B and SAAB 2000 series airplanes, that currently requires an inspection of the fluorescent lamps in the cabin area to ensure correct installation, and correction, if necessary; and an inspection of the lampholders to identify any discrepancies and to ensure the security of the back covers, and replacement of discrepant lampholders with new lampholders; installation of retaining clips on certain Page Aerospace lampholders; and reinspection of the lamps to ensure correct installation after replacement or reinstallation of the lamps or lampholders, and corrections, if necessary. This action would add a requirement for replacement of the electronic light ballasts with improved ballasts, which would terminate the reinspections. This action would also expand the applicability of the existing AD. This proposal is prompted by

issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent electrical arcing between the fluorescent tube pins and the lampholders, which could burn the surrounding area and lead to smoke and fumes in the passenger compartment or lavatory area.

DATES: Comments must be received by April 26, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-354-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from SAAB Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linkoping, Sweden. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-354-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-354-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On June 13, 1997, the FAA issued AD 97-13-06, amendment 39-10052 (62 FR 33545, June 20, 1997), applicable to certain Saab Model SAAB 340B and SAAB 2000 series airplanes, to require an inspection of the fluorescent lamps in the cabin area to ensure correct installation, and corrections, if necessary. That AD also requires an inspection of the lampholders to identify any discrepancies and to ensure the security of the back covers, and replacement of discrepant lampholders with new lampholders; installation of retaining clips on certain Page Aerospace lampholders; and reinspection of the lamps to ensure correct installation after replacement or reinstallation of the lamps or lampholders, and corrections, if necessary. That action was prompted by reports indicating that loose back covers on the lampholders and incorrect lamp installations have led to electrical arcing between fluorescent tube pins and lampholders and consequent charring or melting of the affected areas. The requirements of that AD are intended to prevent such electrical arcing, which could burn the surrounding area and lead to smoke and fumes in the passenger compartment or lavatory area.

Actions Since Issuance of Previous Rule

Since the issuance of that AD, the Luftfartsverket (LFV), which is the airworthiness authority for Sweden, has advised the FAA that additional Model SAAB 340B and SAAB 2000 series airplanes may be subject to fluorescent lampholder charring due to the incorrect installation of fluorescent lamps in their holders. Additionally, the LFV has advised the FAA that a modification is now available that will eliminate the need for reinspecting the fluorescent lamps following each replacement or reinstallation of the lamps or lampholders.

In the preamble to AD 97-13-06, the FAA indicated that the actions required by that AD were considered "interim action" and that further rulemaking action was being considered. The FAA now has determined that further rulemaking action is indeed necessary, and this proposed AD follows from that determination.

Explanation of Relevant Service Information

Saab has issued Service Bulletins 340-33-048, Revision 01, dated January 21, 1999 (for Model SAAB 340B series airplanes), and 2000-33-015 (for Model SAAB 2000 series airplanes), dated January 29, 1999. These service bulletins describe procedures for replacement of the electronic light ballasts with improved ballasts, which would eliminate the need for reinspection of the fluorescent lampholders. Additionally, Service Bulletin 340-33-048, Revision 01, references Service Bulletin 340-33-049, dated January 21, 1999, which describes procedures for concurrent modification of the ballasts to ensure sufficient clearance between the ballast and certain transistors.

Saab also has issued Service Bulletin 340-33-047, Revision 01, dated June 26, 1998. The procedures in Revision 01 are identical to those in the original issue of the service bulletin, which is cited as the appropriate source of service information in AD 97-13-06 for Model SAAB 340B series airplanes. However, Revision 01 specifies additional airplanes in the effectivity of the service bulletin, and adds a reference to Saab Service Bulletin 340-33-048 (Saab Modification No. 2936), which would eliminate the need for reinspections of the lamps.

The LFV classified Service Bulletin 340-33-047, Revision 01, as mandatory, and approved Service Bulletins 340-33-048, Revision 01; 340-33-049; and 2000-33-015; and issued Swedish airworthiness directives 1-113R1 and 1-114R1, both dated September 8, 1998, in order to assure the continued airworthiness of these airplanes in Sweden.

FAA's Conclusions

These airplane models are manufactured in Sweden and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LFV has kept the FAA informed of the situation described above. The FAA has

examined the findings of the LFV, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would supersede AD 97-13-06 to continue to require the actions specified in that AD, and to add a requirement for replacement of the electronic light ballasts with improved ballasts, which would terminate the requirement for reinspections of the lamps. The proposed AD would also expand the applicability of the existing AD to include additional Model SAAB 340B and SAAB 2000 series airplanes that are also subject to the identified unsafe condition. The actions would be required to be accomplished in accordance with the service bulletins described previously, except as discussed below.

Differences Between Proposed Rule and Service Bulletin

Operators should note that this AD proposes to mandate, within 18 months, the replacement of the light ballasts with improved ballasts as terminating action for the reinspections. (Incorporation of the terminating action specified in this service bulletin is optional in Swedish airworthiness directives 1-113R1 and 1-114R1.)

The FAA has determined that long-term continued operational safety will be better assured by design changes to remove the source of the problem, rather than by repetitive inspections. Long-term inspections may not be providing the degree of safety assurance necessary for the transport airplane fleet. This, coupled with a better understanding of the human factors associated with numerous continual inspections, has led the FAA to consider placing less emphasis on inspections and more emphasis on design improvements. The proposed replacement requirement is consistent with these conditions.

Cost Impact

There are approximately 78 airplanes of U.S. registry that would be affected by this proposed AD.

The actions that are currently required by AD 97-13-06 take approximately 7 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Based

on these figures, the cost impact of the currently required actions on U.S. operators is estimated to be \$420 per airplane.

The new actions that are proposed in this AD action would take as much as 9 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Required parts would be provided free of charge by the manufacturer. Based on these figures, the cost impact of the proposed requirements of this AD on U.S. operators is estimated to be \$42,120, or \$540 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-10052 (62 FR 33545, June 20, 1997), and by adding a new airworthiness directive (AD), to read as follows:

SAAB Aircraft AB: Docket 99-NM-354-AD. Supersedes AD 97-13-06, Amendment 39-10052.

Applicability: This AD applies to the following airplanes:

- Model SAAB 340B series airplanes having serial numbers -342 and -359 through -460 inclusive, certificated in any category; except those on which Saab Service Bulletin 340-33-048, Revision 01, dated January 21, 1999 (Saab Modification No. 2936), has been incorporated; and
- Model SAAB 2000 series airplanes having serial numbers -004 through -063 inclusive, certificated in any category; except those on which Saab Service Bulletin 2000-33-015, dated January 29, 1999 (Saab Modification No. 6148), has been incorporated.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent electrical arcing between the fluorescent tube pins and the lampholders, which could burn the surrounding area and lead to smoke and fumes in the passenger compartment or lavatory area, accomplish the following:

Restatement of Requirements of AD 97-13-06

Inspections

(a) For Model SAAB 340B series airplanes having serial numbers -342 and -359

through -439 inclusive; and Model SAAB 2000 series airplanes having serial numbers -004 through -059 inclusive: Within 30 days after July 7, 1997 (the effective date of AD 97-13-06, amendment 39-10052), accomplish the actions required by paragraphs (a)(1), (a)(2), and (a)(3), as applicable.

(1) For all airplanes: Inspect the fluorescent lamps installed in the ceiling/window of the lavatory and passenger compartment to ensure correct installation; and inspect the lampholders for discrepancies such as discoloration, evidence of electrical arcing at the light tube pins, charring or melting, or insecure back covers; in accordance with Saab Service Bulletin 340-33-047, dated May 16, 1997 (for Model SAAB 340B series airplanes); or Saab Service Bulletin 2000-33-014, dated May 16, 1997 (for Model SAAB 2000 series airplanes); as applicable.

(i) If any lamp is installed incorrectly, prior to further flight, install the lamp correctly in accordance with the applicable service bulletin.

(ii) If any discrepancy is found, prior to further flight, replace the lampholder with a new lampholder in accordance with the applicable service bulletin.

(2) For Model SAAB 340B series airplanes on which a Page Aerospace lampholder having part number (P/N) D756-02-001 is installed: Install a retaining clip in accordance with Saab Service Bulletin 340-33-040, Revision 02, dated February 20, 1997.

Note 2: Installation of retaining clips on Page Aerospace lampholders that was accomplished prior to July 7, 1997, in accordance with Saab Service Bulletin 340-33-040, Revision 01, dated January 31, 1997, also is considered acceptable for compliance with the requirement of paragraph (a)(2) of this AD.

(3) For Model SAAB 2000 series airplanes on which a Page Aerospace lampholder having P/N C756-10-001 is installed: Install a retaining clip in accordance with Saab Service Bulletin 2000-33-009, dated June 19, 1996.

Reinspections Following Replacement or Reinstallation

(b) Following the accomplishment of the requirements of paragraph (a) or paragraph (c) of this AD: If any fluorescent lamp or lampholder is replaced or reinstalled, within 7 days after accomplishing such replacement or reinstallation, reinspect the lamp to ensure it is still in the correct position, in accordance with Saab Service Bulletin 340-33-047, dated May 16, 1997, or Revision 01, dated June 26, 1998 (for Model SAAB 340B series airplanes); or Saab Service Bulletin 2000-33-014, dated May 16, 1997 (for Model SAAB 2000 series airplanes); as applicable. If

any lamp is installed incorrectly, prior to further flight, make corrections to ensure correct installation in accordance with the applicable service bulletin.

New Requirements of This AD

Inspections for Additional Airplanes

(c) For airplanes other than those specified in paragraph (a) of this AD: Within 30 days after the effective date of this AD, accomplish the requirements of paragraph (a) of this AD, and thereafter accomplish the requirements of paragraph (b) of this AD.

Terminating Modification

(d) For all airplanes: Within 18 months after the effective date of this AD, accomplish the requirements of paragraph (d)(1) or (d)(2) of this AD, as applicable. Accomplishment of the actions required by the applicable paragraph constitutes terminating action for the requirements of this AD.

(1) For Model SAAB 340B series airplanes: Replace the electronic light ballasts with improved ballasts, in accordance with Saab Service Bulletin 340-33-048, Revision 01, dated January 21, 1999. Concurrent with the replacement, modify the ballasts to ensure sufficient clearance between the ballast and certain transistors, in accordance with Saab Service Bulletin 340-33-049, dated January 21, 1999.

(2) For Model SAAB 2000 series airplanes: Replace the electronic light ballasts with improved ballasts, in accordance with Saab Service Bulletin 2000-33-015, dated January 29, 1999.

Spares

(e) As of the effective date of this AD, no person shall install a fluorescent lampholder having Page Aerospace P/N D756-02-001 or Page Aerospace P/N C756-10-001 on any Model SAAB 340B or SAAB 2000 series airplane, unless the lampholder has been modified in accordance with the requirements of paragraph (a)(2) or (a)(3) of this AD, as applicable.

Alternative Methods of Compliance

(f)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

(2) Alternative methods of compliance, approved previously in accordance with AD 97-13-06, amendment 39-10052, are approved as

alternative methods of compliance with this AD.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 4: The subject of this AD is addressed in Swedish airworthiness directives 1-113R1 and 1-114R1, both dated September 8, 1998.

Issued in Renton, Washington, on March 21, 2000.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-7459 Filed 3-24-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-22-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A320-232 and -233 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A320-232 and -233 series airplanes. This proposal would require replacement of the fuel metering units (FMU) of each engine with new FMU's. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent an inadvertent increase in thrust, which could result in reduced controllability of the airplane during final approach.

DATES: Comments must be received by April 26, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-22-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this

location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NM-22-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-22-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Generale de l'Aviation Civile (DGAC), which is the airworthiness authority for France,

recently notified the FAA that an unsafe condition may exist on certain Airbus Model A320-232 and -233 series airplanes. The DGAC advises that an inadvertent increase of thrust can occur during a critical phase of flight. Investigation revealed that the cause of the inadvertent increase of thrust is due to a malfunction of the high flow fuel metering unit (FMU), which controls the fuel flow to the engines. This condition, if not corrected, could result in reduced controllability of the airplane during final approach.

Explanation of Relevant Service Information

The manufacturer has issued Airbus Service Bulletin A320-73-1067, dated August 11, 1999, which describes procedures for replacement of the FMU of each engine with new FMU's. Accomplishment of the actions specified in the service bulletin will permit the operators with a mixed fleet (Models A319 and A320 series airplanes) to have a single common FMU, which will eliminate the possibility of inadvertent increase of thrust due to a malfunction of the FMU. The DGAC classified this service bulletin as mandatory and issued French airworthiness directive 2000-005-143(B), dated January 12, 2000, in order to assure the continued airworthiness of these airplanes in France.

FAA's Conclusions

This airplane model is manufactured in France and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require replacement of the high flow FMU of each engine with new FMU's. The