

electrical bonding leads or inadequate electrical bonding of the fuel pipe couplings, which could result in fuel ignition and consequent uncontained rupture of the fuel tank, accomplish the following:

(a) Within 36 months after the effective date of this AD, perform a one-time inspection to detect damage (*i.e.*, breakage, fraying, abrasion damage, looseness of the outer metal braid protection in the end crimp, looseness of the outer metal braid protection on the bonding lead inner core, corrosion, or missing leads) of the electrical bonding leads in specified locations of the fuel tanks, in accordance with the Accomplishment Instructions of Airbus Service Bulletins A300-28-0072, Revision 01, dated October 01, 1998, including Appendix 1, dated October 01, 1998, and Appendix 2, dated February 20, 1998 (for Model A300 series airplanes); A310-28-2128, Revision 01, dated October 01, 1998, including Appendix 1, dated October 01, 1998, and Appendix 2, dated February 20, 1998 (for Model A310 series airplanes); or A300-28-6057, Revision 01, dated October 01, 1998, including Appendix 1, dated October 01, 1998, and Appendix 2, dated February 20, 1998 (for Model A300-600 series airplanes); as applicable.

Note 2: Inspection of the area specified in paragraph (a) of this AD accomplished prior to the effective date of this AD in accordance with Airbus Service Bulletins A300-28-0072, A310-28-2128, or A300-28-6057; all dated February 20, 1998; as applicable; is considered acceptable for compliance with the requirements of paragraph (a) of this AD.

(b) If any electrical bonding lead is damaged, prior to further flight, replace the bonding lead with a serviceable bonding lead in accordance with the applicable service bulletin specified in paragraph (a) of this AD.

(c) For airplanes on which Airbus Industrie Modification 11847 (for Model A310 series airplanes) or 11848 (for Model A300/A300-600 series airplanes) has not been accomplished, within 36 months after the effective date of this AD, modify the fuel pipe couplings in the specified locations of the fuel tank in accordance with the Accomplishment Instructions of Airbus Service Bulletins A300-28-0073, Revision 01, dated October 01, 1998 (for Model A300 series airplanes); A310-28-2130, Revision 01, dated October 01, 1998 (for Model A310 series airplanes); or A300-28-6058, Revision 01, dated October 01, 1998 (for Model A300-600 series airplanes); as applicable.

Note 3: Modification of the fuel pipe couplings accomplished prior to the effective date of this AD in accordance with Airbus Service Bulletins A300-28-0073, A310-28-2130, or A300-28-6058; all dated February 20, 1998; as applicable; is considered acceptable for compliance with the requirements of paragraph (c) of this AD.

(d) An alternative method of compliance or adjustment of the compliance time that

provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 5: The subject of this AD is addressed in French airworthiness directive 98-174-248(B), dated April 22, 1998.

Issued in Renton, Washington, on March 20, 2000.

Donald L. Riggin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-7337 Filed 3-24-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-NM-203-AD]

RIN 2120-AA64

Airworthiness Directives; Dornier Model 328-100 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Proposed rule; withdrawal.

SUMMARY: This action withdraws a notice of proposed rulemaking (NPRM) that proposed a new airworthiness directive (AD), applicable to certain Dornier Model 328-100 series airplanes. That action would have required installation of two reinforcing brackets on the keel beam in the lower shell of the main landing gear bay. Since the issuance of the NPRM, the Federal Aviation Administration (FAA) has received new data indicating that the unsafe condition addressed in the NPRM does not exist. Accordingly, the proposed rule is withdrawn.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A

proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to add a new airworthiness directive (AD), applicable to certain Dornier Model 328-100 series airplanes, was published in the **Federal Register** as a Notice of Proposed Rulemaking (NPRM) on April 6, 1998 (63 FR 16715). The proposed rule would have required installation of two reinforcing brackets on the keel beam in the lower shell of the main landing gear bay. That action was prompted by a report of cracking of the keel beam that was discovered during full-scale fatigue testing. The proposed actions were intended to prevent fatigue cracking of the keel beam, which could result in reduced structural integrity of the airplane.

Actions That Occurred Since the NPRM Was Issued

Since the issuance of that NPRM, the manufacturer has provided the FAA with additional information regarding the unsafe condition identified in the proposed AD. The manufacturer states that an analysis has been accomplished that shows that if the cracking addressed by the proposed AD propagated to its maximum limit, the airplane could still withstand ultimate structural loads.

FAA's Conclusions

Upon further consideration, the FAA has determined that fatigue cracking of the keel beam, which was intended to be addressed by the corrective actions required in the proposed AD, does not constitute an unsafe condition. Accordingly, the proposed rule is hereby withdrawn.

Withdrawal of this notice of proposed rulemaking constitutes only such action, and does not preclude the agency from issuing another notice in the future, nor does it commit the agency to any course of action in the future.

Regulatory Impact

Since this action only withdraws a notice of proposed rulemaking, it is neither a proposed nor a final rule and

therefore is not covered under Executive Order 12866, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Withdrawal

Accordingly, the notice of proposed rulemaking, Docket 97-NM-203-AD, published in the **Federal Register** on April 6, 1998 (63 FR 16715), is withdrawn.

Issued in Renton, Washington, on March 21, 2000.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 00-7460 Filed 3-24-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-354-AD]

RIN 2120-AA64

Airworthiness Directives; Saab Model SAAB 340B and SAAB 2000 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to certain Saab Model SAAB 340B and SAAB 2000 series airplanes, that currently requires an inspection of the fluorescent lamps in the cabin area to ensure correct installation, and correction, if necessary; and an inspection of the lampholders to identify any discrepancies and to ensure the security of the back covers, and replacement of discrepant lampholders with new lampholders; installation of retaining clips on certain Page Aerospace lampholders; and reinspection of the lamps to ensure correct installation after replacement or reinstallation of the lamps or lampholders, and corrections, if necessary. This action would add a requirement for replacement of the electronic light ballasts with improved ballasts, which would terminate the reinspections. This action would also expand the applicability of the existing AD. This proposal is prompted by

issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent electrical arcing between the fluorescent tube pins and the lampholders, which could burn the surrounding area and lead to smoke and fumes in the passenger compartment or lavatory area.

DATES: Comments must be received by April 26, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-354-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from SAAB Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linkoping, Sweden. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-354-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-354-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On June 13, 1997, the FAA issued AD 97-13-06, amendment 39-10052 (62 FR 33545, June 20, 1997), applicable to certain Saab Model SAAB 340B and SAAB 2000 series airplanes, to require an inspection of the fluorescent lamps in the cabin area to ensure correct installation, and corrections, if necessary. That AD also requires an inspection of the lampholders to identify any discrepancies and to ensure the security of the back covers, and replacement of discrepant lampholders with new lampholders; installation of retaining clips on certain Page Aerospace lampholders; and reinspection of the lamps to ensure correct installation after replacement or reinstallation of the lamps or lampholders, and corrections, if necessary. That action was prompted by reports indicating that loose back covers on the lampholders and incorrect lamp installations have led to electrical arcing between fluorescent tube pins and lampholders and consequent charring or melting of the affected areas. The requirements of that AD are intended to prevent such electrical arcing, which could burn the surrounding area and lead to smoke and fumes in the passenger compartment or lavatory area.

Actions Since Issuance of Previous Rule

Since the issuance of that AD, the Luftfartsverket (LFV), which is the airworthiness authority for Sweden, has advised the FAA that additional Model SAAB 340B and SAAB 2000 series airplanes may be subject to fluorescent lampholder charring due to the incorrect installation of fluorescent lamps in their holders. Additionally, the LFV has advised the FAA that a modification is now available that will eliminate the need for reinspecting the fluorescent lamps following each replacement or reinstallation of the lamps or lampholders.