

For Model A300–600 Series Airplanes

(3) For Model A300–600 series airplanes on which Airbus Modification 5890 is not installed: Perform the one-time HFEC inspection at the applicable time specified in paragraph (a)(3)(i) or (a)(3)(ii) of this AD.

(i) For airplanes that have accumulated fewer than 10,000 total flight cycles as of the effective date of this AD: Perform the one-time HFEC inspection at the later of the times specified in paragraphs (a)(3)(i)(A) and (a)(3)(i)(B) of this AD.

(A) Prior to the accumulation of 2,500 total flight cycles or 6,400 total flight hours, whichever occurs earlier.

(B) Within 1,500 flight cycles after the effective date of this AD.

(ii) For airplanes that have accumulated 10,000 or more total flight cycles as of the effective date of this AD: Perform the one-time HFEC inspection within 500 flight cycles after the effective date of this AD.

(4) For Model A300–600 series airplanes on which Airbus Modification 5890 is installed: Perform the one-time HFEC inspection at the applicable time specified in paragraph (a)(4)(i) or (a)(4)(ii) of this AD.

(i) For airplanes that have accumulated fewer than 10,000 total flight cycles as of the effective date of this AD: Perform the one-time HFEC inspection at the later of the times specified in paragraph (a)(4)(i)(A) and (a)(4)(i)(B) of this AD.

(A) Prior to the accumulation of 6,500 total flight cycles or 16,700 total flight hours, whichever occurs earlier.

(B) Within 1,500 flight cycles after the effective date of this AD.

(ii) For airplanes that have accumulated 10,000 or more total flight cycles as of the effective date of this AD: Perform the one-time HFEC inspection within 500 flight cycles after the effective date of this AD.

Corrective Actions

(b) If any cracking is detected during the one-time HFEC inspection required by paragraph (a) of this AD, prior to further flight, remove the splice fitting and perform an HFEC inspection to detect cracking in the area surrounding the fastener holes (fastener holes “A” to “N”) on the face of FR47 adjacent to the affected splice fitting, in accordance with Airbus AOT A300–53A0350 (for Model A300 series airplanes) or A300–600–53A6123 (for Model A300–600 series airplanes), each dated October 25, 1999, as applicable.

(1) If no cracking is detected in the area surrounding the fastener holes on the face of FR47, prior to further flight, replace the splice fitting with a new splice fitting in accordance with the applicable AOT.

(2) If any cracking is detected in the area surrounding the fastener holes on the face of FR47, prior to further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate; or the Direction Generale de l’Aviation Civile (DGAC) (or its delegated agent). For a repair method to be approved by the Manager, International Branch, ANM–116, as required by this paragraph, the Manager’s approval letter must specifically reference this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch ANM–116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in French airworthiness directive 1999–515–298(B), dated December 29, 1999.

Issued in Renton, Washington, on March 30, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 00–8389 Filed 4–4–00; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 99–NM–95–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Model A319, A320, and A321 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to certain Airbus Model A320 series airplanes, that currently requires an initial inspection of fastener holes on certain outer frames of the fuselage to detect fatigue cracking, and modification of the area by cold expanding the holes and installing oversized fasteners. This action would revise the applicability to include additional airplanes; require a high frequency eddy current inspection to detect fatigue cracking in the frames and frame feet at fuselage frames FR37 through FR41; and follow-on actions. This proposal also provides for an optional terminating action for the

follow-on repetitive inspections. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent fatigue cracking of the fuselage frames and frame feet, and consequent reduced structural integrity of the fuselage.

DATES: Comments must be received by May 5, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 99–NM–95–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–2110; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA–public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-95-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-95-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On May 12, 1997, the FAA issued AD 97-11-01, amendment 39-10030 (62 FR 28324, May 23, 1997), applicable to certain Airbus Model A320 series airplanes, to require an initial inspection of fastener holes on certain outer frames of the fuselage to detect fatigue cracking, and modification of the area by cold expanding the holes and installing oversized fasteners. That action was prompted by a report from the manufacturer indicating that, during full-scale fatigue testing of the test article, fatigue cracking was detected in the area where the center fuselage joins the wing. The requirements of that AD are intended to prevent fatigue cracking and consequent reduced structural integrity of this area, which could lead to rapid depressurization of the fuselage.

Actions Since Issuance of Previous Rule

The Direction Generale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, has advised the FAA that, during accomplishment of the eddy current rotating probe inspection to detect fatigue cracking of fastener holes on certain outer frames of the fuselage (required by AD 97-11-01), some operators have reported also finding cracks in the frame and frame feet at fuselage frames FR37 through FR41, stringer 23. This condition, if not detected and corrected, could result in reduced structural integrity of the fuselage.

Explanation of Relevant Service Information

Airbus has issued Service Bulletin A320-53-1141, Revision 1, dated October 4, 1999. This service bulletin describes procedures for conducting a high frequency eddy current (HFEC) inspection to detect fatigue cracking in the frames and frame feet at fuselage frames FR37 through FR41, and follow-

on actions. For cases where no cracking is detected, the follow-on actions include one of the following: (1) Repetitive inspections; (2) the modifications specified in Airbus Service Bulletin A320-53-1128 described below; or (3) if applicable, modification of certain fastener holes of the fuselage frames FR37 through FR41 adjacent to stringer 23, and follow-on repetitive inspections. For certain cracking conditions, the follow-on actions involve a bushing repair, or accomplishment of the modifications in Airbus Service Bulletin A320-53-1128. For certain other cracking conditions, the follow-on actions involve simultaneous replacement of the frame segment or frame foot with a new frame segment or frame foot and accomplishment of the modifications in Airbus Service Bulletin A320-53-1128.

Airbus also has issued Service Bulletin A320-53-1128, Revision 01, including Appendix 01, both dated October 4, 1999. This service bulletin describes procedures for a rotating probe eddy current inspection to detect cracks in the fastener holes where the existing fasteners are removed; repair of the fastener hole; installation of four doublers on each frame; cold working of certain fastener holes; installation of new fasteners in the cold-worked holes; and installation of new modified system brackets at fuselage frames FR37 through FR41. These modifications would improve the fatigue strength in the frame and frame feet of left and right fuselage frames FR37 through FR41, and would eliminate the need for the repetitive HFEC inspections in this area.

Accomplishment of the actions specified in the service bulletins is intended to adequately address the identified unsafe condition. The DGAC classified both of these service bulletins as mandatory for certain actions, recommended Airbus Service Bulletin A320-53-1128 for certain other actions, and issued French airworthiness directive 98-509-123(B), dated December 16, 1998, in order to assure the continued airworthiness of these airplanes in France.

FAA's Conclusions

These airplane models are manufactured in France and are type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available

information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would supersede AD 97-11-01 to require an HFEC inspection to detect fatigue cracking in the frames and frame feet of left and right fuselage frames FR37 through FR41; and follow-on actions. This proposal also would allow for an optional terminating action for the follow-on repetitive inspections. The actions would be required to be accomplished in accordance with the service bulletins described previously, except as discussed below.

Differences Between Proposed Rule and Service Bulletin

Operators should note that, unlike the procedures described in Airbus Service Bulletin A320-53-1141, this proposed AD would not permit further flight if cracks are detected in the frame or frame feet. The FAA has determined that, because of the safety implications and consequences associated with such cracking, any subject frames or frame feet that are found to be cracked must be repaired or modified prior to further flight.

Operators also should note that, in consonance with the findings of the DGAC, the FAA has determined that the repetitive inspections proposed by this AD can be allowed to continue in lieu of accomplishment of a terminating action. In making this determination, the FAA considers that, in this case, long-term continued operational safety will be adequately assured by accomplishing the repetitive inspections to detect cracking before it represents a hazard to the airplane.

Cost Impact

There are approximately 198 airplanes of U.S. registry that would be affected by this proposed AD.

The new HFEC inspection that is proposed in this AD action would take approximately 2 work hours per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the proposed requirements of this AD on U.S. operators is estimated to be \$23,760, or \$120 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no

operator has yet accomplished any of the current or proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Should an operator elect to accomplish the optional terminating action rather than continue the repetitive inspections, it would take between 297 and 316 work hours per airplane to accomplish the inspection and modification, at an average labor rate of \$60 per work hour. Required parts would cost between \$40 and \$5,290 per airplane. Based on these figures, the cost impact of this optional terminating action is estimated to be between \$17,860 and \$24,250 per airplane.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39–10030 (62 FR 28324, May 23, 1997), and by adding a new airworthiness directive (AD), to read as follows:

Airbus Industrie: Docket 99–NM–95–AD.

Supersedes AD 97–11–01, Amendment 39–10030.

Applicability: Model A319, A320, and A321 series airplanes, certificated in any category; except those on which Airbus Modification 25896, 25592, or 25593, or Airbus Service Bulletin A320–53–1128, Revision 01, dated October 4, 1999, has been accomplished.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (g) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue cracking of the fuselage frames and frame feet, and consequent reduced structural integrity of the fuselage, accomplish the following:

Inspection

(a) Perform a high frequency eddy current (HFEC) inspection to detect fatigue cracks in the frames and frame feet at fuselage frames FR37 through FR41, adjacent to stringer 23, at the time specified in paragraph (a)(1), (a)(2), or (a)(3), as applicable; in accordance with Airbus Service Bulletin A320–53–1141, Revision 01, dated October 4, 1999.

(1) For Configuration 01 airplanes, as identified in Airbus Service Bulletin A320–53–1141: Within 3,500 flight cycles after the effective date of this AD.

(2) For Configuration 02 airplanes, as identified in Airbus Service Bulletin A320–53–1141: Within 16,000 flight cycles after accomplishment of Airbus Service Bulletin A320–53–1025, Revision 1, dated November 24, 1994, or within 3,500 flight cycles after the effective date of this AD, whichever occurs later.

(3) For Configurations 03, 04, and 05 airplanes, as identified in Airbus Service Bulletin A320–53–1141: Prior to the accumulation of 20,000 total flight cycles, or within 3,500 flight cycles after the effective date of this AD, whichever occurs later.

Repetitive Inspections or Corrective Action(s)

(b) For Configuration 01 airplanes: If no crack is detected during the HFEC inspection required by paragraph (a) of this AD, accomplish the action specified in either paragraph (b)(1) or (b)(2) of this AD.

(1) Repeat the HFEC inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 3,500 flight cycles until accomplishment of paragraph (f) of this AD. Or

(2) Prior to further flight, modify each fastener hole of the outer frame flanges of left and right fuselage frames FR37 through FR41, adjacent to stringer 23, in accordance with Airbus Service Bulletin A320–53–1141, Revision 01, dated October 4, 1999. Within 16,000 flight cycles after accomplishment of this modification, and thereafter at intervals not to exceed 3,500 flight cycles, repeat the HFEC inspection required by paragraph (a) of this AD until accomplishment of paragraph (f) of this AD.

Note 2: Airbus Service Bulletin A320–53–1141, Revision 01, dated October 4, 1999, references Airbus Service Bulletin A320–53–1025, Revision 1, dated November 24, 1994, as an additional source of information for accomplishing the modification required by paragraph (b)(2) of this AD.

Note 3: Accomplishment of the modification in accordance with Airbus Service Bulletin A320–53–1125, dated August 5, 1994, prior to the effective date of this AD, is considered acceptable for compliance with the modification requirements of paragraph (b)(2) of this AD.

(c) For Configurations 02, 03, 04, and 05 airplanes: If no crack is detected during the inspection required by paragraph (a) of this AD, repeat the HFEC inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 3,500 flight cycles until accomplishment of paragraph (f) of this AD.

(d) If any crack less than 0.20 inches (5.0 mm) in length is detected during any HFEC inspection required by this AD, prior to further flight, accomplish the actions specified in either paragraph (d)(1) or (d)(2) of this AD.

(1) Repair in accordance with Airbus Service Bulletin A320–53–1141, Revision 01, dated October 4, 1999. Repeat the HFEC inspection required by paragraph (a) of this AD thereafter at intervals not to exceed 3,500 flight cycles. Or

(2) Accomplish the actions specified in paragraph (f) of this AD.

(e) If any crack is 0.20 inches (5.0 mm) or greater in length, or if more than one crack per frame side is detected during any HFEC inspection required by this AD, prior to further flight, simultaneously accomplish the actions specified in paragraphs (e)(1) and (e)(2) of this AD.

(1) Replace the frame segment and/or frame foot with a new frame segment or frame foot in accordance with Airbus Service Bulletin A320–53–1141, Revision 01, dated October 4, 1999. And

(2) Accomplish the actions specified in paragraph (f) of this AD.

Optional Terminating Action

(f) Modification of the frames and frame feet area at fuselage frames FR37 through FR41 (including the rotating probe eddy current inspection to detect cracks, fastener hole repair, installation of doublers on each frame, cold working of specified fastener

holes, installation of new fasteners in the cold-worked holes, and installation of new modified system brackets), as applicable, in accordance with Airbus Service Bulletin A320-53-1128, Revision 01, including Appendix 01, both dated October 4, 1999, constitutes terminating action for the requirements of this AD.

Note 4: Accomplishment of the modification in accordance with Airbus Service Bulletin A320-53-1128, including Appendix 1, both dated October 3, 1997, prior to the effective date of this AD, is considered acceptable for compliance with the modification requirements of paragraph (f) of this AD.

Alternative Methods of Compliance

(g) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 5: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(h) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 6: The subject of this AD is addressed in French airworthiness directive 98-509-123(B), dated December 16, 1998.

Issued in Renton, Washington, on March 30, 2000.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-8391 Filed 4-4-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-27-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 727-100 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness

directive (AD) that is applicable to certain Boeing Model 727-100 series airplanes. This proposal would require repetitive inspections to detect corrosion of the lower surface of the wing center section and the surrounding area, and follow-on actions. This proposal is prompted by reports of corrosion progression through the lower surface of the wing center section into the center wing fuel tank, and subsequent fuel leakage into the ram air duct. The actions specified by the proposed AD are intended to detect and correct such conditions, which, if combined with a leak in the primary or secondary heat exchanger, could result in the release of fuel vapors into the cabin, and consequent adverse effects on flight crew and passengers.

DATES: Comments must be received by May 22, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-27-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, PO Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Stan Wood, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2772; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of

the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NM-27-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-27-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On November 7, 1985, the FAA issued AD 85-24-02, amendment 39-5170 (50 FR 47356, November 18, 1985), applicable to all Boeing Model 727-200 series airplanes, which requires repetitive inspections for corrosion, and repair, as necessary, of the lower surface of the wing center section, which forms the upper wall of the ram air plenum chambers.

Since the issuance of that AD, the manufacturer has notified the FAA that certain airplanes were inadvertently not included in the effectivity listing in Boeing Service Bulletin 727-51-17, dated April 26, 1974, which was referenced as the appropriate source of service information for accomplishment of the actions required by AD 85-24-02. That service bulletin describes corrosion inspections for Model 727-200 series airplanes having integral fuel cells installed. Model 727-100 series airplanes were not included in the effectivity of that service bulletin, and consequently, in the applicability of the existing AD, due to the fact that bladder-type fuel cells are installed on the majority of those airplanes. However, it has now been determined that there are three Model 727-100 series airplanes having integral fuel cells installed that are subject to the same unsafe condition as the airplanes that are included in the applicability statement of AD 85-24-02. Therefore, the FAA finds that additional rulemaking is necessary to ensure that the unsafe condition is addressed on all affected airplanes.