

Other Inspections

(c) Within 500 flight cycles after completing the actions required by paragraph (b) of this AD: Perform an inspection of the MLG left and right shock struts for nitrogen pressure, visible chrome dimension, and oil leakage, in accordance with Part E of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-32-079, Revision D, dated December 1, 2000. Thereafter, repeat the inspection at intervals not to exceed 500 flight cycles.

Corrective Actions for Certain Inspections

(d) If the chrome extension dimension of the shock strut pressure reading is outside the limits specified in the Airplane Maintenance Manual, Task 32-11-05-220-801, or any oil leakage is found: Prior to further flight, service the MLG shock strut in accordance with Part C (for airplanes on the ground) or Part D (for airplanes on jacks) of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-32-079, Revision D, dated December 1, 2000.

Extension of the Repetitive Interval

(e) After the effective date of this AD: After a total of five consecutive inspections of the MLG shock struts that verify that the shock struts are serviced properly, and a total of five consecutive eddy current inspections of the MLG main fitting has been accomplished that verify there is no cracking of the main fitting, in accordance with Bombardier Alert Service Bulletin A601R-32-079, Revision D, dated December 1, 2000, the repetitive interval for the eddy current inspections required by paragraph (a) of this AD may be extended from every 500 flight cycles to every 1,000 flight cycles.

Reporting Requirement

(f) Within 30 days after each inspection and servicing required by paragraphs (a), (b), and (c) of this AD, report all findings, positive or negative, to: Bombardier Aerospace, Regional Aircraft, CRJ Action Desk, fax number 514-855-8501. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

Alternative Methods of Compliance

(g) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

Special Flight Permits

(h) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to

a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(i) The actions shall be done in accordance with Bombardier Alert Service Bulletin A601R-32-079, Revision D, dated December 1, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Canadian airworthiness directive CF-1999-32R1, dated January 22, 2001.

Effective Date

(j) This amendment becomes effective on December 4, 2001.

Issued in Renton, Washington, on October 22, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-27068 Filed 10-29-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2001-NM-208-AD; Amendment 39-12487; AD 2001-22-08]

RIN 2120-AA64

Airworthiness Directives; Fokker Model F.28 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to all Fokker Model F.28 series airplanes, that requires replacing the main landing gear (MLG) torque link dampers with modified and reidentified dampers. This action is necessary to prevent degradation of the dampers, which could result in MLG high amplitude oscillation in a lateral torsional mode, and consequent MLG damage or separation of the MLG from the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective December 4, 2001.

The incorporation by reference of certain publications listed in the

regulations is approved by the Director of the Federal Register as of December 4, 2001.

ADDRESSES: The service information referenced in this AD may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to all Fokker Model F.28 series airplanes was published in the **Federal Register** on August 17, 2001 (66 FR 43124). That action proposed to require replacing the main landing gear (MLG) torque link dampers with modified and reidentified dampers.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

Allow Use of New-Configuration Dampers

The commenter requests that the FAA revise paragraph (a) of the proposed rule to allow an operator to install a torque link damper with a dash number higher than (23700)-5. The commenter states that it has already modified its entire inventory of torque link dampers to the configuration of part number 23700-7. The commenter states that revising the proposed AD to allow installation of parts modified to a configuration subsequent to that of part number 23700-5 would relieve it and other operators of the need to request approval of alternative methods of compliance (AMOCs).

The FAA partially concurs with the commenter's request. Because we cannot approve installation of dampers that do not exist, we do not concur to revise paragraph (a) of the proposed AD in the specific way the commenter suggests.

However, since the issuance of the proposed rule, we have reviewed Fokker

Service Bulletins SBF28/32-159, dated October 1, 1999 (for Models F.28 Mark 1000 through 4000 series airplanes), and SBF100-32-116, dated February 1, 2000 (for Model F.28 Mark 0070/0100 series airplanes). Those service bulletins specify replacement of existing torque link dampers with modified dampers, and refer to Menasco Aerospace Service Bulletin 23700-32-15, dated September 3, 1999, as an appropriate source of service information for modifying torque link dampers with part number 23700-1, -3, or -5, to part number 23700-7. In consideration of these service bulletins, we have added a new Note 2 to this final rule to state that installation of torque link dampers with part number 23700-7 in accordance with Fokker Service Bulletin SBF28/32-159 or SBF100-32-116, as applicable, is acceptable for compliance with paragraph (a) of this AD.

Operators should note that, for installation of dampers with part numbers other than 23700-5 or -7, they must submit a request for approval of an AMOC in accordance with paragraph (c) of this AD.

Conclusion

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

The FAA estimates that 147 Model F.28 series airplanes of U.S. registry will be affected by this AD, that it will take approximately 6 work hours per airplane to accomplish the required replacement, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$1,910 per airplane. Based on these figures, the cost impact of this AD on U.S. operators is estimated to be \$333,690, or \$2,270 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of

the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the

Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2001-22-08 Fokker Services B.V.:

Amendment 39-12487. Docket 2001-NM-208-AD.

Applicability: All Model F.28 series airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent separation of the main landing gear (MLG) from the airplane due to performance degradation of the torque link damper, accomplish the following:

Modification and Reidentification

(a) Replace MLG torque link dampers having part numbers (P/N) 23700-1 or -3 with dampers having P/N 23700-5, in accordance with the Accomplishment Instructions of Fokker Service Bulletin (SB) SBF28/32-157 (for Models F.28 Mark 1000 through 4000 series airplanes) or Fokker Service Bulletin SBF100-32-114 (for Model F.28 Mark 0070/0100 series airplanes), both dated October 1, 1999, as applicable; at the times specified in the following table:

TABLE 1.—COMPLIANCE TIMES

Fokker F.28 model (mark) designation	MLG manufactured by	MLG mod. status	Compliance required after the effective date of this AD
(1) Mk.0100	Dowty Aerospace; MD	Pre-Mod SB F100-32-50	Within 15 months.
(2) Mk.0100	Dowty Aerospace; MD	Post-Mod SB F100-32-50	Within 21 months.
(3) Mk.0100	Menasco Aerospace	[Reserved]	Within 24 months.
(4) Mk.0070	Menasco Aerospace	[Reserved]	Within 24 months.
(5) Mk.1000 through Mk.4000 series	Dowty Aerospace; MD	[Reserved]	Within 24 months.

Note 2: Installation of torque link dampers with P/N 23700-7 in accordance with Fokker

Service Bulletin SBF28/32-159, dated October 1, 1999 (for Models F.28 Mark 1000

through 4000 series airplanes), or SBF100-32-116, dated February 1, 2000 (for Model

F.28 Mark 0070/0100 series airplanes), as applicable, is acceptable for compliance with paragraph (a) of this AD.

Spares

(b) As of the effective date of this AD, no person shall install torque link damper having P/N 23700-1 or -3, on any airplane.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The actions shall be done in accordance with Fokker Service Bulletin SBF28/32-157, dated October 1, 1999; or Fokker Service Bulletin SBF100-32-114, dated October 1, 1999; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 4: The subject of this AD is addressed in Dutch airworthiness directive 1999-138, dated October 29, 1999.

Effective Date

(f) This amendment becomes effective on December 4, 2001.

Issued in Renton, Washington, on October 22, 2001.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-27069 Filed 10-29-01; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF JUSTICE

28 CFR PART 16

[AAG/A Order No. 246-2001]

Privacy Act of 1974; Implementation

AGENCY: Department of Justice.

ACTION: Final rule.

SUMMARY: The Department of Justice currently exempts the following system of records from subsection (d) of the Privacy Act, pursuant to 5 U.S.C. 552a(j)(2): Controlled Substances Act Nonpublic Records (JUSTICE/JMD-002). This final rule makes changes to reflect the current statutory authority, as well as the primary reason for exempting the system.

EFFECTIVE DATE: This final rule is effective October 30, 2001.

FOR FURTHER INFORMATION CONTACT: Mary Cahill at 202-307-1823.

SUPPLEMENTARY INFORMATION: On July 20, 2001 (66 FR 37939), a proposed rule was published in the **Federal Register** with an invitation to comment. No comments were received.

This order relates to individuals rather than small business entities. Nevertheless, pursuant to the requirements of the Regulatory Flexibility Act, 5 U.S.C. 601-612, this order will not have a significant economic impact on a substantial number of small entities.

List of Subjects in Part 16

Administrative Practices and Procedures, Courts, Freedom of Information Act, Privacy Act, and Government in Sunshine Act.

Pursuant to the authority vested in the Attorney General by 5 U.S.C. 552a and delegated to me by Attorney General Order No. 793-78, 28 CFR part 16 is amended as follows:

PART 16—AMENDED

1. The authority for part 16 continues to read as follows:

Authority: 5 U.S.C. 301, 552, 552a, 552b(g), 553; 18 U.S.C. 4203(a)(1); 28 U.S.C. 509, 510, 534; 31 U.S.C. 3717, 9701.

2. It is proposed to amend 28 CFR 16.76 by revising paragraph (b)(1) as follows:

§ 16.76 Exemption of Justice Management Division.

* * * * *

(b) Exemption from subsection (d) is justified for the following reasons:

(1) Access to and use of the nonpublic records maintained in this system are restricted by law. Section 3607(b) of

Title 18 U.S.C. (enacted as part of the Sentencing Reform Act of 1984, Pub. L. 98-473, Chapter II) provides that the sole purpose of these records shall be for use by the courts in determining whether a person found guilty of violating section 404 of the Controlled Substances Act qualifies:

(i) for the disposition available under 18 U.S.C. 3607(a) to persons with no prior conviction under a Federal or State law relating to controlled substances, or

(ii) for an order, under 18 U.S.C. 3607(c), expunging all official records (except the nonpublic records to be retained by the Department of Justice) of the arrest and any subsequent criminal proceedings relating to the offense.

* * * * *

Dated: October 17, 2001.

Janis A. Sposato,

Acting Assistant Attorney General for Administration.

[FR Doc. 01-27202 Filed 10-29-01; 8:45 am]

BILLING CODE 4410-FB-M

DEPARTMENT OF TRANSPORTATION

Coast Guard

33 CFR Part 165

[COTP San Francisco Bay 01-009]

RIN 2115-AA97

Security Zones; San Francisco Bay, San Francisco, CA and Oakland, CA

AGENCY: Coast Guard, DOT.

ACTION: Temporary final rule; request for comments.

SUMMARY: The Coast Guard is establishing two temporary security zones in areas of the San Francisco Bay adjacent to San Francisco International Airport and Oakland International Airport. These actions are necessary to ensure public safety and prevent sabotage or terrorist acts at these airports. Persons and vessels are prohibited from entering into or remaining in these security zones without permission of the Captain of the Port, or his designated representative.

DATES: This rule is effective from 5 p.m. (PDT) on September 21, 2001 to 4:59 p.m. (PDT) on March 21, 2002. Comments and related material must reach the Coast Guard on or before December 31, 2001.

ADDRESSES: Send comments to: U.S. Coast Guard Marine Safety Office, San Francisco Bay, Coast Guard Island, Alameda, CA 94501. Any comments and material received from the public, as