

(3) Misrepresented any fact affecting a program determination.

(b) Any funds disbursed pursuant to this part to any person or operation engaged in a misrepresentation, scheme, or device, shall be refunded with interest together with such other sums as may become due. Any sheep and lamb operation or person engaged in acts prohibited by this section and any sheep and lamb operation or person receiving payment under this part shall be jointly and severally liable with other persons or operations involved in such claim for benefits for any refund due under this section and for related charges. The remedies provided in this part shall be in addition to other civil, criminal, or administrative remedies that may apply.

§ 784.10 Estates, trusts, and minors.

(a) Program documents executed by persons legally authorized to represent estates or trusts will be accepted only if such person furnishes evidence of the authority to execute such documents.

(b) A minor who is otherwise eligible for assistance under this part must, also:

(1) Establish that the right of majority has been conferred on the minor by court proceedings or by statute;

(2) Show a guardian has been appointed to manage the minor's property and the applicable program documents are executed by the guardian; or

(3) Furnish a bond under which the surety guarantees any loss incurred for which the minor would be liable had the minor been an adult.

§ 784.11 Death, incompetence, or disappearance.

In the case of death, incompetence, disappearance or dissolution of a person that is eligible to receive benefits in accordance with this part, such person or persons specified in 7 CFR part 707 may receive such benefits, as determined appropriate by FSA.

§ 784.12 Maintaining records.

Persons making application for benefits under this program must maintain accurate records and accounts that will document that they meet all eligibility requirements specified herein. Such records and accounts must be retained for 3 years after the date of payment to the sheep and lamb operations under this program. Destruction of the records after such date shall be at the risk of the party undertaking the destruction.

§ 784.13 Refunds; joint and several liability.

(a) In the event there is a failure to comply with any term, requirement, or

condition for payment arising under the application, or this part, and if any refund of a payment to FSA shall otherwise become due in connection with the application, or this part, all payments made under this part to any sheep and lamb operation shall be refunded to FSA together with interest as determined in accordance with paragraph (c) of this section and late payment charges as provided in part 1403 of this title.

(b) All persons signing a sheep and lamb operation's application for payment as having an interest in the operation shall be jointly and severally liable for any refund, including related charges, that is determined to be due for any reason under the terms and conditions of the application or this part with respect to such operation.

(c) Interest shall be applicable to refunds required of any person under this part if FSA determines that payments or other assistance was provided to a person who was not eligible for such assistance. Such interest shall be charged at the rate of interest that the United States Treasury charges the Commodity Credit Corporation for funds, from the date FSA made such benefits available to the date of repayment or the date interest increases as determined in accordance with applicable regulations. FSA may waive the accrual of interest if FSA determines that the cause of the erroneous determination was not due to any action of the person.

(d) Interest determined in accordance with paragraph (c) of this section may be waived at the discretion of FSA alone for refunds resulting from those violations determined by FSA to have been beyond the control of the person committing the violation.

(e) Late payment interest shall be assessed on all refunds in accordance with the provisions of, and subject to the rates prescribed in 7 CFR part 792.

(f) Any excess payments made by FSA with respect to any application under this part must be refunded.

(g) In the event that a benefit under this subpart was provided as the result of erroneous information provided by any person, the benefit must be repaid with any applicable interest.

§ 784.14 Offsets and withholdings.

FSA may offset or withhold any amounts due FSA under this subpart in accordance with the provisions of 7 CFR part 792, or successor regulations, as designated by the Department.

§ 784.15 Assignments.

Any person who may be entitled to a payment may assign his rights to such

payment in accordance with 7 CFR part 1404 or successor regulations as designated by the Department.

§ 784.16 Termination of program.

This program will be terminated after payment has been made to those applications certified as eligible pursuant to the application period established in § 784.4.

Signed at Washington, DC, August 31, 2004.

James R. Little,

Administrator, Farm Service Agency.

[FR Doc. 04-20186 Filed 9-3-04; 8:45 am]

BILLING CODE 3410-05-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-19022; Directorate Identifier 2004-NM-122-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-600, -700, -700C, -800, and -900 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 737-600, -700, -700C, -800, and -900 series airplanes. This proposed AD would require repetitive detailed, low frequency eddy current, and high frequency eddy current inspections of the webs of the aft pressure bulkhead at body station 1016 for cracks, and corrective action if necessary. This proposed AD is prompted by a report of cracks found, during fatigue testing, at several of the fastener rows in the web lap splices at the dome apex of the aft pressure bulkhead. We are proposing this AD to detect and correct fatigue cracks in the webs of the aft pressure bulkhead, which could result in rapid decompression of the airplane.

DATES: We must receive comments on this proposed AD by October 22, 2004.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov>

and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW, Nassif Building, room PL-401, Washington, DC 20590.
- By fax: (202) 493-2251.
- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street SW, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Technical information: Howard Hall, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6430; fax (425) 917-6590.

Plain language information: Marcia Walters, marcia.walters@faa.gov.

SUPPLEMENTARY INFORMATION:

Docket Management System (DMS)

The FAA has implemented new procedures for maintaining AD dockets electronically. As of May 17, 2004, new AD actions are posted on DMS and assigned a docket number. We track each action and assign a corresponding directorate identifier. The DMS AD docket number is in the form "Docket No. FAA-2004-99999." The Transport Airplane Directorate identifier is in the form "Directorate Identifier 2004-NM-999-AD." Each DMS AD docket also lists the directorate identifier ("Old Docket Number") as a cross-reference for searching purposes.

Comments Invited

We invite you to submit any written relevant data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2004-19022; Directorate Identifier 2004-NM-122-AD" in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that website, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You can review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you can visit <http://dms.dot.gov>.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications that affect you. You can get more information about plain language at <http://www.faa.gov/language> and <http://www.plainlanguage.gov>.

Examining the Docket

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the DMS receives them.

Discussion

We have received a report that, during fatigue testing, the manufacturer found cracks at several of the fastener rows in the web lap splices at the dome apex of the aft pressure bulkhead on a Boeing 737-800 series airplane. Cracks were found in three of the seven webs. The single rivet located where each of the webs transition up 0.032 inches over the adjacent web causes pull down loading, which leads to cracks at the rivet holes of the web lap splices. This condition, if not detected and corrected, could result in rapid decompression of the airplane.

The web lap splices on certain Model 737-600, -700, -700C, and -900 series airplanes are identical to those on the affected Model 737-800 series airplanes. Therefore, all of these models may be subject to the same unsafe condition.

Relevant Service Information

We have reviewed Boeing Service Bulletin 737-53-1251, dated June 3, 2004. The service bulletin describes procedures for doing repetitive detailed inspections, low frequency eddy current (LFEC) inspections, and high frequency eddy current (HFEC) inspections of the webs of the aft pressure bulkhead at body station 1016 from the aft side at the dome apex for cracks; and contacting the manufacturer for repair instructions if cracks are found. We have determined that accomplishing the actions specified in the service bulletin will adequately address the unsafe condition.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. Therefore, we are proposing this AD, which would require doing repetitive detailed inspections, LFEC inspections, and HFEC inspections of the webs of the aft pressure bulkhead at body station 1016 from the aft side at the dome apex for cracks, and corrective action if necessary. The corrective action includes repairing any crack found during any inspection in accordance with a method approved by the FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative (DER) who has been authorized by the FAA to make those findings. The proposed AD would require you to use the service information described previously to perform these actions, except as discussed under "Differences Between the Proposed AD and the Service Bulletin."

Differences Between the Proposed AD and the Service Bulletin

Operators should note that, although the service bulletin does not list a grace period in the compliance times, this proposal adds a grace period to the compliance times. The FAA finds that such a grace period will keep airplanes from being grounded unnecessarily.

Operators should also note that although the service bulletin specifies that operators may contact the manufacturer for disposition of certain repair conditions, this proposed AD would require operators to repair those conditions per a method approved by the FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company DER

who has been authorized by the FAA to make those findings.

Costs of Compliance

This proposed AD would affect about 457 airplanes of U.S. registry and 1,166 airplanes worldwide. The proposed actions would take about 8 work hours per airplane, at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$237,640, or \$520 per airplane, per inspection cycle.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA-2004-19022; Directorate Identifier 2004-NM-122-AD.

Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this AD action by October 22, 2004.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 737-600, -700, -700C, -800, and -900 series airplanes, certificated in any category; as listed in Boeing Service Bulletin 737-53-1251, dated June 3, 2004.

Unsafe Condition

(d) This AD was prompted by a report of cracks found, during fatigue testing, at several of the fastener rows in the web lap splices at the dome apex of the aft pressure bulkhead. We are issuing this AD to detect and correct fatigue cracks in the webs of the aft pressure bulkhead, which could result in rapid decompression of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Initial and Repetitive Inspections

(f) Prior to accumulating 26,000 total flight cycles or within 4,000 flight cycles after the effective date of this AD, whichever occurs later: Do a detailed inspection, low frequency eddy current inspection, and high frequency eddy current inspection of the webs of the aft pressure bulkhead at body station 1016 for cracks, in accordance with Boeing Service Bulletin 737-53-1251, dated June 3, 2004. Repeat the inspections thereafter at intervals not to exceed 4,000 flight cycles.

Note 1: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

Corrective Action

(g) If any crack is found during any inspection required by paragraph (f) of this AD: Before further flight, repair per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative (DER) who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved, the approval must specifically reference this AD.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle ACO, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by a Boeing Company DER who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the approval must specifically refer to this AD.

Issued in Renton, Washington, on August 27, 2004.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-20212 Filed 9-3-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-19023; Directorate Identifier 2004-NM-123-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A318, A319, A320, and A321 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus Model A318, A319, A320, and A321 series airplanes. This proposed AD would require removing two maintenance lights in the hydraulics bay, disconnecting the wiring for the lights, and modifying the switches. This proposed AD is prompted by underlying safety issues involved in fuel tank explosions on several large transport airplanes. We are proposing this AD to prevent an ignition source for fuel vapor in the hydraulics bay, which could result in fire or explosion in the adjacent center wing fuel tank.

DATES: We must receive comments on this proposed AD by October 7, 2004.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL-401, Washington, DC 20590.