

MLGs currently equipped with a swinging lever part number (P/N) D56771, we have determined that a swinging lever P/N D56771 could be installed in the future on an airplane not currently equipped with a lever having that part number. Therefore, this proposed AD would be applicable to all Model ATR 42–200, –300, and –320 series airplanes and would prohibit installing a swinging lever having a subject P/N and serial number on any of these airplanes.

Though French airworthiness directive 2003–376(B) specifies that operators shall report certain inspection findings to Messier-Dowty, this proposed AD would not require this.

Though French airworthiness directive 2003–376(B) specifies that operators shall return swinging levers with applicable serial numbers to Messier-Dowty for discard, this proposed AD would not require this.

#### Costs of Compliance

This proposed AD would affect about 24 airplanes of U.S. registry. The proposed inspection would take about 1 work hour per airplane, at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$1,560, or \$65 per airplane.

#### Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Aerospatiale:** Docket No. FAA–2004–19562; Directorate Identifier 2004–NM–73–AD.

##### Comments Due Date

- (a) The Federal Aviation Administration must receive comments on this AD action by December 10, 2004.

##### Affected ADs

- (b) None.

##### Applicability

- (c) This AD applies to all Aerospatiale Model ATR 42–200, –300, and –320 series airplanes; certificated in any category.

##### Unsafe Condition

- (d) This AD was prompted by a report that, on an airplane lined up for takeoff, the swinging lever of the left MLG collapsed when engine power was applied. We are issuing this AD to prevent fracture of the MLG swinging lever, which could result in collapse of the swinging lever and reduced structural integrity and possible collapse of the MLG during operations on the ground.

##### Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

##### Inspection To Determine Part and Serial Numbers

- (f) Within 30 days after the effective date of this AD, inspect to determine the part number (P/N) and serial number (S/N) of the swinging lever of the MLG.

- (1) If the P/N of the swinging lever is not D56771; or if the P/N of the swinging lever is D56771 but the S/N is not from 115 to 151 inclusive; no further action is required by this paragraph.

- (2) If the P/N of the swinging lever is D56771 and the S/N is from 115 to 151 inclusive, within 90 days after the effective date of this AD: Remove the swinging lever and replace it with a new or serviceable lever in accordance with Job Instruction Card 32–11–00 RAI 10030–001, dated February 1, 2000, to the Avions de Transport Regional Aircraft Maintenance Manual.

##### No Reporting Requirement

- (g) Though French airworthiness directive 2003–376(B), dated October 1, 2003, specifies that operators shall report certain inspection

findings to Messier-Dowty, this AD does not require this.

#### Disposition of Swinging Levers

- (h) Though French airworthiness directive 2003–376(B), dated October 1, 2003, specifies that operators shall return swinging levers with applicable serial numbers to Messier-Dowty for discard, this AD does not require this.

#### Parts Installation

- (i) As of the effective date of this AD, no person may install on any airplane an MLG swinging lever, P/N D56771, having a S/N from 115 to 151 inclusive.

#### Alternative Methods of Compliance (AMOCs)

- (j) The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

#### Related Information

- (k) French airworthiness directive 2003–376(B), dated October 1, 2003, also addresses the subject of this AD.

Issued in Renton, Washington, on November 1, 2004.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 04–25032 Filed 11–9–04; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2004–19561; Directorate Identifier 2004–NM–50–AD]

**RIN 2120–AA64**

**Airworthiness Directives; Raytheon Model DH.125, HS.125, and BH.125 Series Airplanes; BAe.125 Series 800A (C–29A and U–125) and 800B Airplanes; and Hawker 800 (Including Variant U–125A) and 800XP Airplanes; Equipped With TFE731 Engines**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Raytheon Model DH.125, HS.125, and BH.125 series airplanes; BAe.125 series 800A (C–29A and U–125) and 800B airplanes; and Hawker 800 (including variant U–125A) and 800XP airplanes. This proposed AD would require installing insulating blankets on the engine compartment firewall and the wire harness passing

through the firewall fairlead. This proposed AD is prompted by a report indicating that insulation on the wire harness passing through the firewall fairlead ignited on the fuselage side of the firewall. We are proposing this AD to prevent a fire in the engine compartment from causing possible ignition of outgassing wire insulation on the fuselage side of the firewall, which could lead to an uncontrollable fire in the fuselage.

**DATES:** We must receive comments on this proposed AD by December 27, 2004.

**ADDRESSES:** Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL-401, Washington, DC 20590.

- By fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Raytheon Aircraft Company, Department 62, PO Box 85, Wichita, Kansas 67201-0085.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC. This docket number is FAA-2004-19561; the directorate identifier for this docket is 2004-NM-50-AD.

**FOR FURTHER INFORMATION CONTACT:**

*Technical information:* Jeff Pretz, Aerospace Engineer, Airframe Branch, ACE-118W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4153; fax (316) 946-4407.

*Plain language information:* Marcia Walters, [marcia.walters@faa.gov](mailto:marcia.walters@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Docket Management System (DMS)**

The FAA has implemented new procedures for maintaining AD dockets electronically. As of May 17, 2004, new AD actions are posted on DMS and assigned a docket number. We track

each action and assign a corresponding directorate identifier. The DMS AD docket number is in the form "Docket No. FAA-2004-99999." The Transport Airplane Directorate identifier is in the form "Directorate Identifier 2004-NM-999-AD." Each DMS AD docket also lists the directorate identifier ("Old Docket Number") as a cross-reference for searching purposes.

**Comments Invited**

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2004-19561; Directorate Identifier 2004-NM-50-AD" in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that website, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You can review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you can visit <http://dms.dot.gov>.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications that affect you. You can get more information about plain language at <http://www.faa.gov/language> and <http://www.plainlanguage.gov>.

**Examining the Docket**

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in

the AD docket shortly after the DMS receives them.

**Discussion**

We have received a report indicating that during certification testing of a new firewall fairlead material, insulation on the wire harness passing through the laboratory test firewall fairlead ignited on the fuselage side of the firewall. The configuration of the test firewall and wire harness was similar to the configuration of the firewall and wire harness found on certain Raytheon Model DH.125, HS.125, and BH.125 series airplanes; BAe.125 series 800A (C-29A and U-125), and 800B airplanes; and Hawker 800 (including variant U-125A) and 800XP airplanes; equipped with TFE731 engines. This condition, if not corrected, could result in a fire in the engine compartment causing possible ignition of outgassing wire insulation on the fuselage side of the firewall, which could lead to an uncontrollable fire in the fuselage.

**Relevant Service Information**

We have reviewed Raytheon Service Bulletin SB 26-3496, dated November 2003. The service bulletin describes procedures for installing insulating blankets on the engine compartment firewall and the wire harness passing through the firewall fairlead. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

**FAA's Determination and Requirements of the Proposed AD**

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. Therefore, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously, except as discussed under "Differences Between the Proposed AD and Service Bulletin."

**Differences Between the Proposed AD and Service Bulletin**

The service bulletin describes procedures for reporting accomplishment of the service bulletin to the manufacturer; however, this proposed AD would not require that action.

**Costs of Compliance**

There are about 804 airplanes of the affected design in the worldwide fleet. This proposed AD would affect about 530 airplanes of U.S. registry. The proposed actions would take about 8

work hours per airplane, at an average labor rate of \$65 per work hour. Required parts would cost about \$1,784 per airplane. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$1,221,120, or \$2,304 per airplane.

### Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Raytheon Aircraft Company:** Docket No. FAA-2004-19561; Directorate Identifier 2004-NM-50-AD.

#### Comments Due Date

- (a) The Federal Aviation Administration (FAA) must receive comments on this AD action by December 27, 2004.

#### Affected ADs

- (b) None.

### Applicability

(c) This AD applies to Raytheon Model DH.125, HS.125, and BH.125 series airplanes; BAe.125 series 800A (C-29A and U-125) and 800B airplanes; and Hawker 800 (including variant U-125A) and 800XP airplanes; certificated in any category; equipped with TFE731 engines; as listed in Raytheon Service Bulletin SB 26-3496, dated November 2003.

### Unsafe Condition

(d) This AD was prompted by a report indicating that insulation on the wire harness passing through the firewall fairlead ignited on the fuselage side of the firewall. We are issuing this AD to prevent a fire in the engine compartment from causing possible ignition of outgassing wire insulation on the fuselage side of the firewall, which could lead to an uncontrollable fire in the fuselage.

### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

### Installation of Insulating Blankets

(f) Within 12 months after the effective date of this AD, install insulating blankets on the engine compartment firewall and the wire harness passing through the firewall fairlead, by doing all the actions in accordance with the Accomplishment Instructions of Raytheon Service Bulletin SB 26-3496, dated November 2003.

### No Reporting Requirement

The service bulletin describes procedures for reporting accomplishment of the service bulletin to the manufacturer; however, this AD does not require that action.

### Alternative Methods of Compliance (AMOCs)

(g) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Issued in Renton, Washington, on November 1, 2004.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 04-25033 Filed 11-9-04; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2004-19564; Directorate Identifier 2004-NM-103-AD]

RIN 2120-AA64

### Airworthiness Directives; Gulfstream Aerospace LP Model Galaxy and Gulfstream 200 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Gulfstream Aerospace LP Model Galaxy and Gulfstream 200 airplanes. This proposed AD would require repetitive inspections for damage of the flexible supply lines of the pilot and copilot oxygen mask boxes, and eventual replacement of the lines with new rigid tubes. This proposed AD is prompted by a report of an oxygen leak in the cockpit mask box. We are proposing this AD to prevent a broken oxygen supply line, which could result in oxygen being unavailable to the flightcrew.

**DATES:** We must receive comments on this proposed AD by December 10, 2004.

**ADDRESSES:** Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL-401, Washington, DC 20590.

- By fax: (202) 493-2251.
- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Gulfstream Aerospace Corporation, PO Box 2206, Mail Station D-25, Savannah, Georgia 31402.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street