

Terminating Action for AWLs Revision

(j) Incorporating AWL No. 28-AWL-07 into the AWLs section of the ICA in accordance with paragraph (g)(3) of AD 2008-10-10, amendment 39-15516, terminates the action required by paragraph (g) of this AD.

AMOCs

(k)(1) The Manager, Seattle Aircraft Certification Office, FAA, ATTN: Georgios Roussos, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 917-6482; fax (425) 917-6590; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(l) You must use Boeing Alert Service Bulletin 737-28A1221, Revision 1, dated November 9, 2007; and Airworthiness Limitation 28-AWL-07 of Section 9 of the Boeing 737-600/700/800/900 Maintenance Planning Data (MPD) Document, D626A001-CMR, Revision March 2007 R2; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on August 12, 2008.

Michael J Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. E8-19367 Filed 8-27-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-0148; Directorate Identifier 2007-NM-299-AD; Amendment 39-15655; AD 2008-17-17]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Boeing Model 747 airplanes. This AD requires a one-time inspection of certain fuselage skins at section 41 to find any external doublers that cover the inspection areas and to identify the external doublers that end on a stringer and those that do not, and related investigative and corrective actions if necessary. This AD results from reports of cracks found at fastener locations in the fuselage skins at section 41. We are issuing this AD to detect and correct fuselage skin cracks at fastener locations along the skin-to-stringer attachments, which could join together and become large and consequently result in rapid decompression of the cabin.

DATES: This AD is effective October 2, 2008.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 2, 2008.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind

Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6437; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an airworthiness directive (AD) that would apply to all Boeing Model 747 airplanes. That NPRM was published in the **Federal Register** on February 8, 2008 (73 FR 7486). That NPRM proposed to require a one-time inspection of certain fuselage skins at section 41 to find any external doublers that cover the inspection areas and to identify the external doublers that end on a stringer and those that do not, and related investigative and corrective actions if necessary.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comments received from the two commenters.

Support for the NPRM

Boeing concurs with the contents of the NPRM.

Request to Either Delay Issuance of the AD or Extend the Compliance Time

Japan Airlines (JAL) requests that we delay issuance of the AD until Boeing has published a revision to Boeing Alert Service Bulletin 747-53A2704, dated October 4, 2007, to extend the compliance time from 16,000 total flight cycles to 25,000 total flight cycles for accomplishing the general visual inspection for external doublers in Areas 2 and 3. If we cannot delay issuance of the AD, then JAL requests that we revise the compliance time accordingly in this AD. JAL states that Boeing has advised that only the inspection of Area 1 must be done before 16,000 total flight cycles, and that Areas 2 and 3 should be inspected together with the high frequency eddy current inspection of the skin-to-stringer attachments before 25,000 total flight cycles. JAL asserts that Boeing will revise the compliance time in the next revision to the service bulletin.

We do not agree to delay issuance of this AD, or to revise the compliance time for inspecting for external doublers in Areas 2 and 3. We have coordinated with Boeing, and Boeing has no plans, at this time, to revise the service bulletin. Boeing also has confirmed that the inspection of Areas 1, 2, and 3 was left at 16,000 total flight cycles for simplicity of the compliance table in the service bulletin. Therefore, we agree that, for Groups 1 through 5 airplanes,

the general visual inspection for external doublers in Areas 2 and 3 may be done before 25,000 total flight cycles, or within 2,000 flight cycles after the effective date of this AD, whichever occurs later. However, due to the unique nature of JAL's request, it would be best to address it using the alternative methods of compliance (AMOC) process, rather than revising this AD. We will consider requests for adjustments to the compliance time, under the provisions of paragraph (h) of this AD, if data are submitted to substantiate that such an adjustment would provide an acceptable level of safety. We have not changed the AD in this regard.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

We estimate that this AD affects 165 airplanes of U.S. registry. We also estimate that it takes up to 64 work-hours per product to comply with this AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$844,800 or \$5,120 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the

distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2008-17-17 Boeing: Amendment 39-15655. Docket No. FAA-2008-0148; Directorate Identifier 2007-NM-299-AD.

Effective Date

(a) This airworthiness directive (AD) is effective October 2, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes, certificated in any category.

Unsafe Condition

(d) This AD results from reports of cracks found at fastener locations in the fuselage skins at section 41. We are issuing this AD to detect and correct fuselage skin cracks at fastener locations along the skin-to-stringer attachments, which could join together and become large and consequently result in rapid decompression of the cabin.

Compliance

(e) Comply with this AD within the compliance times specified, unless already done.

Repetitive Inspections and Related Investigative/Corrective Actions

(f) At the applicable compliance times specified in Tables 1 and 2 of paragraph 1.E. of Boeing Alert Service Bulletin 747-53A2704, dated October 4, 2007: Do a general visual inspection of the fuselage skins at section 41 to find any external doublers that cover the inspection area and to identify the external doublers that end on a stringer in the inspection area and those that do not, and do all the related investigative and corrective actions as applicable, by accomplishing all of the applicable actions specified in the Accomplishment Instructions of the service bulletin, except as provided by paragraph (g) of this AD. Repeat the related investigative actions thereafter at the interval specified in Tables 1 and 2 of the service bulletin, as applicable.

Exceptions to the Service Bulletin

(g) Where Tables 1 and 2 of paragraph 1.E. of Boeing Alert Service Bulletin 747-53A2704, dated October 4, 2007, specify counting the compliance time from " * * * after the date on this service bulletin," this AD requires counting the compliance time from the effective date of this AD. Where Figure 19 of the service bulletin specifies doing a "detailed visual inspection" for any crack at fastener holes common to the stringer, this AD requires doing a detailed inspection. In Figure 3 of the service bulletin, also inspect the areas at stringer 5 (S-5) and S-5A between station (STA) 340 and STA 360 (similar to Figure 8 for the right side). In Figure 15 of the service bulletin, also inspect the area at S-14A between STA 200 and STA 220 (similar to Figure 17 for the right side).

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, ATTN: Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6437; fax (425) 917-6590; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Material Incorporated by Reference

(i) You must use Boeing Alert Service Bulletin 747-53A2704, dated October 4,

2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on August 8, 2008.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E8-19378 Filed 8-27-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-27339; Directorate Identifier 2006-NM-280-AD; Amendment 39-15654; AD 2008-17-16]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-10-10 and DC-10-10F Airplanes, Model DC-10-15 Airplanes, Model DC-10-30 and DC-10-30F (KC-10A and KDC-10) Airplanes, Model DC-10-40 and DC-10-40F Airplanes, Model MD-10-10F and MD-10-30F Airplanes, and Model MD-11 and MD-11F Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain transport category airplanes identified above. This AD requires modifying the fuel boost pumps. This AD results from a fuel boost pump found with blown thermal fuses and a fractured thrust washer. We are issuing this AD to prevent failure of the fuel boost pumps, which could lead to the potential of ignition sources inside fuel tanks. This condition, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

DATES: This AD becomes effective October 2, 2008.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of October 2, 2008.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024).

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Samuel Lee, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5262; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a supplemental notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain McDonnell Douglas Model DC-10-10 and DC-10-10F airplanes, Model DC-10-15 airplanes, Model DC-10-30 and DC-10-30F (KC-10A and KDC-10) airplanes, Model DC-10-40 and DC-10-40F airplanes, Model MD-10-10F and MD-10-30F airplanes, and Model MD-11 and MD-11F airplanes. That supplemental NPRM was published in the **Federal Register** on March 7, 2008 (73 FR 12301). That supplemental NPRM proposed to require modifying the fuel boost pumps.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

Support for the Supplemental NPRM

FedEx agrees with the technical aspects of the supplemental NPRM.

Request to Allow Use of Parts Manufacture Approval (PMA) Parts

Wencor West requests that we revise the supplemental NPRM to allow the use of PMA part numbers (P/Ns) 60-84744WE, 60-06561WE, 60-01317WE, and 60-02927WE as acceptable means of compliance for the replacement of Hydro-Aire fuel boost pumps having P/Ns 60-84744, 60-06561, 60-01317, and 60-02927, respectively. Wencor West states that these PMA parts were developed through the test and computation method governed by section 21.303 ("Replacement and modification parts") of the Federal Aviation Regulations (14 CFR 21.303) and FAA Order 8110-42B. Wencor West also states that the FAA found the PMA parts to be equal to and interchangeable with the Hydro-Aire parts. In addition, Wencor West requests that we clarify that certain other PMA parts, which may be used when doing further maintenance or overhaul of the pump, continue to be approved as equivalents to the original equipment manufacturer parts.

We disagree with revising this AD. Boeing conducted safety assessments of the fuel tank systems approved by the Los Angeles Aircraft Certification Office (ACO). As a result, we issued AD 2008-06-21, amendment 39-15433 (73 FR 14673, March 19, 2008), to require revising the FAA-approved maintenance program to incorporate new Airworthiness Limitations for the fuel tank systems to satisfy the requirements of Special Federal Aviation Regulation No. 88. That AD, in part, addressed maintenance of the fuel boost pumps. Any deviation from the safety assessment conducted by Boeing, including the use of PMA parts on the fuel boost pumps, must be approved by the Manager, Los Angeles ACO. Consequently, all previously approved PMA parts must be re-evaluated to determine whether an equivalent level of safety for each part meets the approved safety assessment. Therefore, engineering design approval of the PMA parts manufactured by Wencor West must be approved as an alternative method of compliance (AMOC) under the provisions of paragraph (h) of this AD. We will consider requests for approval of an AMOC if sufficient data are submitted to substantiate that the design change would provide an acceptable level of safety. We have not changed the AD in this regard.