TABLE—ESTIMATED COSTS

| Action | Action Work hours Average rate per | | Parts | Cost | Number of U.Sregistered airplanes | Fleet cost |
|-------------|------------------------------------|------|----------|----------|---|--------------|
| Replacement | 25 | \$80 | \$60,670 | \$62,670 | 249 | \$15,604,830 |

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866,

2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Boeing: Docket No. FAA-2009-0293; Directorate Identifier 2008-NM-221-AD.

Comments Due Date

(a) We must receive comments by May 18, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 747–100, -100B, -100B SUD, -200B, -200C, -200F, -300, -400, -400D, -400F, and 747SR series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 747–27–2422, dated October 30, 2008.

Subject

(d) Air Transport Association (ATA) of America Code 27: Flight controls.

Unsafe Condition

(e) This AD results from reports of the inboard trailing edge (TE) flaps blowing back due to the failure of a transmission carbon disk no-back brake. The no-back brake did not hold the flaps in the commanded position. The Federal Aviation Administration is issuing this AD to prevent a decrease of the aerodynamic controllability of the airplane, which could adversely affect the airplane's continued safe flight and landing.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Corrective Action

(g) Within 5 years after the effective date of this AD, replace the trailing edge flap transmission no-back brakes with skewed roller no-back brakes at the trailing edge flap transmission, positions 4 and 5, in accordance with Boeing Special Attention Service Bulletin 747–27–2422, dated October 30, 2008.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Douglas Tsuji, Aerospace Engineer, Systems and Equipment Branch, ANM–130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 917–6487; fax (425) 917–6590.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

Issued in Renton, Washington, on March 18, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9–7273 Filed 3–31–09; 8:45 am]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0292; Directorate Identifier 2008-NM-011-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300, A310, and A300–600 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede an existing airworthiness directive (AD) that applies to certain Airbus Model A300 and A310 series airplanes. The existing AD currently requires replacement of the nose landing gear drag strut upper attachment pin. This proposed AD would require revising the Airworthiness Limitations section (ALS)

of the Instructions for Continued Airworthiness (ICA) to require additional life limits and/or replacements for certain main landing gear and nose landing gear components, and would also expand the applicability. This proposed AD results from revisions to the ALS of the ICA to include new or more restrictive life limits and/or replacements. We are proposing this AD to ensure the continued structural integrity of these airplanes.

DATES: We must receive comments on this proposed AD by May 1, 2009.

ADDRESSES: You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to http://www.regulations.gov. Follow the instructions for submitting comments.
 - Fax: 202-493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M– 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- Hand Delivery: U.S. Department of Transportation, Docket Operations, M—30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: account.airworth-eas@airbus.com; Internet: http://www.airbus.com. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221 or 425–227–1152.

Examining the AD Docket

You may examine the AD docket on the Internet at http://www.regulations.gov; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800–647–5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–1622; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the ADDRESSES section. Include "Docket No. FAA-2009-0292; Directorate Identifier 2008-NM-011-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to http://www.regulations.gov, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On July 21, 1987, we issued AD 87–16–06, amendment 39–5692 (52 FR 28241, July 29, 1987), for certain Airbus Model A300 and A310 series airplanes. That AD requires replacement of the nose landing gear drag strut upper attachment pin. That AD resulted from reports of pins which were found to be improperly manufactured. We issued that AD to prevent failure of the pin and collapse of the nose landing gear.

Actions Since Existing AD Was Issued

Since we issued AD 87–16–06, the manufacturer has revised the Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness (ICA) to include new or more restrictive life limits and replacements for the main landing gear and the nose landing gear. These new limits affect the replacement of the upper attachment pin for the nose landing gear drag strut that was the subject of AD 87–16–06.

In addition, European Aviation Safety Agency (EASA) Airworthiness Directive 2007–0293, dated November 29, 2007, which is parallel to this proposed AD, includes Model A300–600 series airplanes. Those airplane models were not included in AD 87–16–06.

Relevant Service Information

Airbus has issued the following revisions to the ALS of the ICA. These documents provide each mandatory replacement time, structural inspection interval, and related structural inspection procedures or other procedures (e.g., modifications).

- For Model A300 Series Airplanes: "Sub-part 1–2: Life Limits," and "Sub-part 1–3: Demonstrated fatigue lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated September 6, 2007.
- For Model A300–600 Series Airplanes: "Sub-part 1–2: Life Limits," and "Sub-part 1–3: Demonstrated fatigue lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated December 21, 2006.
- For Model A310 Series Airplanes: "Sub-part 1–2: Life Limits," and "Sub-part 1–3: Demonstrated fatigue lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated December 21, 2006.

Airbus has also issued Section 05–10–00, Revision 28, dated February 27, 1998, of Chapter 5, "Service Life Limits and Maintenance Checks," of the A300 Aircraft Maintenance Manual. Section 05–10–00 includes life limit values for the nose and main landing gears. This document is an alternate source for the life limits defined in Part 1, "Safe Life Airworthiness Limitation Items," dated September 6, 2007, of the ALS, for Model A300 series airplanes.

Airbus has also issued Service Information Letter (SIL) 32–118, Revision 02, dated October 24, 2007. This SIL gives instructions for calculating the life limit of main or nose landing gear parts where the history of accumulated landings is partial or unknown, or where the history of application details (airplane type, model, weight variant, etc.) is partial or unknown.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. EASA mandated the service information and issued Airworthiness Directive 2007–0292, dated November 29, 2007, to ensure the continued airworthiness of these airplanes in the European Union.

Other Relevant Rulemaking

On January 11, 1984, we issued AD 84–02–04 (49 FR 2746, January 23, 1984), for certain Airbus Model A300 B2 and B4 series airplanes. That AD requires inspection of main landing gear hinge arms for corrosion and cracks, and repair or modifications if needed. That AD also requires replacement of the main landing gear shock absorber sliding rod attachment fitting. That AD resulted from corrosion and cracks found on these components. We issued that AD to prevent landing gear failure.

The actions specified in paragraph (h) of this proposed AD would satisfy the

requirements of paragraph A. of AD 84–02–04. There are no actions in this proposed AD that would satisfy the requirements of paragraphs B. and C. of AD 84–02–04.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

This proposed AD would supersede AD 87–16–06 and would retain the requirements of that existing AD. This proposed AD would also add airplanes to the applicability and require revising the ALS of the ICA to incorporate additional life limits and/or structural inspections for certain main landing gear and nose landing gear components.

Change to Existing AD

This proposed AD would retain the requirements of AD 87–16–06. Since AD 87–16–06 was issued, the AD format has been revised. As a result, the corresponding paragraph identifiers have changed in this proposed AD, and paragraph (g) of this proposed AD corresponds to paragraph A. of AD 87–16–06.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

| Action | Work hours | Average labor rate per hour | Parts | Cost per airplane | Number of U.Sregistered airplanes | Fleet cost |
|--|------------|-----------------------------|---------|----------------------|---|------------|
| Replacement (required by AD 87–16–06) Revision (new proposed action) | 7 | \$80 | \$3,300 | \$3,860 | 94 | \$362,840 |
| | 1 | 80 | 0 | 80 | 238 | 19,040 |

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;

- 2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- 3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. *See* the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by Reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39–5692 (52 FR 28241, July 29, 1987) and adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA-2009-0292; Directorate Identifier 2008-NM-011-AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by May 1, 2009.

Affected ADs

(b) This AD supersedes AD 87-16-06.

Applicability

(c) This AD applies to all Airbus Model A300, A310, and A300–600 series airplanes, certificated in any category.

Subject

(d) Air Transport Association (ATA) of America Code 32: Landing Gear.

Unsafe Condition

(e) This AD results from revisions to the Airworthiness Limitations section (ALS) of the Instructions for Continued Airworthiness (ICA) to include new or more restrictive life limits and/or replacements. We are issuing this AD to ensure the continued structural integrity of these airplanes.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Note 1: This AD requires revisions to certain operator maintenance documents to include new replacements. Compliance with these inspections is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these replacements, the operator may not be able to accomplish the replacements described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (l) of this AD. The request should include a description of changes to the required replacements that will ensure the continued operational safety of the airplane.

Restatement of the Requirements of AD 87–16–06

(g) For Model A300 and A310 Series Airplanes: Prior to the accumulation of 16,000 landings, or within the next 2,000 landings after September 3, 1987 (the effective date of AD 87–16–06), whichever occurs later, replace the nose landing gear drag strut upper attachment pin in accordance with Airbus Service Bulletin A300–32–374, Revision 1, dated July 15, 1986 (applicable to Model A300 airplanes); or A310–32–2023, Revision 2, dated November 14, 1986 (applicable to Model A310 airplanes).

New Requirements of This AD

ALS Revision

- (h) For Model A300, A310, and A300–600 Series Airplanes: Within 3 months after the effective date of this AD, revise the ALS of the ICA to incorporate the applicable document listed in paragraph (h)(1), (h)(2), or (h)(3) of this AD. Accomplishing the actions specified in the applicable document satisfies the requirements of paragraph A. of AD 84–02–04, amendment 39–4795.
- (1) For Model A300 Series Airplanes: Incorporate the document listed in paragraph (h)(1)(i) or (h)(1)(ii) of this AD.
- (i) Section 05–10–00, Revision 28, dated February 27, 1998, of Chapter 5, "Service Life Limits and Maintenance Checks," of the Airbus A300 Aircraft Maintenance Manual, except that the parts listed in Table 1 of this AD are subject to the life limits defined in the document listed in paragraph (h)(1)(ii) of this AD
- (ii) "Sub-part 1–2: Life Limits," and "Sub-part 1–3: Demonstrated fatigue lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated September 6, 2007, of the Airbus A300 ALS.

TABLE 1—PARTS SUBJECT TO THE LIFE LIMITS SPECIFIED IN THE DOCUMENT IDENTIFIED IN PARAGRAPH (H)(1)(II) OF THIS AD

| Part Number (P/N) | Part name |
|-------------------|-----------|
| | |

- (2) For Model A310 Series Airplanes: Incorporate "Sub-part 1–2: Life Limits," and "Sub-part 1–3: Demonstrated fatigue lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated December 21, 2006, of the Airbus A310 ALS.
- (3) For Model A300–600 Series Airplanes: Incorporate "Sub-part 1–2: Life Limits," and "Sub-part 1–3: Demonstrated fatigue lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated December 21, 2006, of the Airbus A300–600 ALS.

Initial Compliance Times and Repetitive Inspections

(i) Do the replacement at the applicable time specified in paragraph (i)(1) or (i)(2) of this AD, except as provided by paragraph (j) of this AD. The replacement must be done thereafter within the interval specified in the applicable document identified in paragraph (h)(1), (h)(2), or (h)(3) of this AD.

- (1) For any life limitation/task that has been complied with before the effective date of this AD in accordance with the applicable document listed in paragraph (h)(1), (h)(2), or (h)(3) of this AD, or in accordance with paragraph (g) of this AD, use the last accomplishment of each limitation/task as a starting point for accomplishing each corresponding limitation/task required by this AD.
- (2) For any life limitation/task that has not been complied with before the effective date of this AD in accordance with the applicable document listed in paragraphs (h)(1), (h)(2), and (h)(3) of this AD, or in accordance with paragraph (g) of this AD, the initial compliance time starts from the date of initial

entry into service as defined in the applicable document.

Special Compliance Times

(j) For any airplane on which the history of accumulated landings is partial or unknown, or where the history of application details (airplane type, model, weight variant, etc.) is partial or unknown, with or without using the information in Airbus Service Information Letter 32–118, Revision 02, dated October 24, 2007: Parts listed in Figure 1 of this AD must be replaced at the associated compliance time. The replacement must be done thereafter at the interval specified in the applicable document(s) specified in paragraphs (h)(1), (h)(2), and (h)(3) of this AD.

BILLING CODE 4910-13-P

Figure 1 – Special Compliance Times

| | Aircraft type ap | plica | bilit | y | | | | |
|----------------------|------------------|-------|-------|------|----------------------|----------|--|--|
| | A300 | X | | | | | liance Time urs first after the "start | |
| Designation | A310 | | X | | Start date | 1 ` | date") | |
| | A300-600 | | | X | | , | | |
| | P/N | | | | | Landings | Calendar Time | |
| | T + 221 +0022200 | | MAI | N LA | NDING GEAR | 12.500 | | |
| | A32140032200xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| | A32140056200xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| | A32140056202xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| Aft pintle pin | A32140057200xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| | A32140057202xx | X | | X | December 13, 2007 | 13,500 | 9 years | |
| | A32140062000xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| | A32140063000xx | X | | X | December 13, 2007 | 13,500 | 9 years | |
| | A32140036200xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| | A32140036202xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| | A32140036204xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| | A32140036206xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| Half ball housing | A32140042200xx | X | | X | December 13, 2007 | 13,500 | 9 years | |
| (Fwd pintle bearing) | A32140042202xx | X | | X | December 13, 2007 | 13,500 | 9 years | |
| | A32140068002xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| | A32140068004xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| | A32140069002xx | X | | X | December 13, 2007 | 13,500 | 9 years | |
| | A32140069004xx | X | | X | December 13, 2007 | 13,500 | 9 years | |
| Ball (Fwd pintle | A32140012202xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| pin) | A32140043202xx | X | | X | December 13, 2007 | 13,500 | 9 years | |

| | Aircraft type ap | | | | nce Times (conti | | | |
|---------------------------------|------------------|---|----|-----|----------------------|---|---------------|--|
| Designation | A300 | X | | | | Compliance Time (whichever occurs first after the "start date") | | |
| | A310 | | X | | Start date | | | |
| 8 | A300-600 | | | X | | | | |
| | P/N | | | | | Landings | Calendar Time | |
| | A53833451200xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| Pin (Multiple link/Frame 50) | A53833451206xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| inik/riame 30) | A53834451200xx | X | | | December 13, 2007 | 13,500 | 9 years | |
| | A53834451202xx | X | | X | April 25, 2007 | 13,500 | 9 years | |
| Pin (Drop link/Frame 50) | A53811122200xx | | X | | April 25, 2007 | 18,000 | 9 years | |
| | T | т | ML | G B | arrel Assembly | T | | |
| | 00-200-402 | X | | | December 13, 2007 | N/A | 30 months | |
| Upper torque link | SL40089 | X | | | December 13, 2007 | N/A | 30 months | |
| pin nut | SL40089P | X | | | December 13, 2007 | N/A | 30 months | |
| | SL40123 | X | | | December 13, 2007 | N/A | 30 months | |
| | SL40123P | X | X | X | April 25, 2007 | N/A | 30 months | |
| | 00-200-358 | X | | | December 13, 2007 | N/A | 30 months | |
| Torque link | SL40114P | X | X | | April 25, 2007 | N/A | 30 months | |
| medium pin nut | SL40132 | X | | | December 13, 2007 | N/A | 30 months | |
| | SL40132P | X | | X | April 25, 2007 | N/A | 30 months | |
| Attaching fitting pin | C62311-1 | X | | | December 13, 2007 | 13,500 | 9 years | |
| Pili | C62311-20 | X | | X | April 25, 2007 | 13,500 | 9 years | |
| | C65815 | X | | | December 13, 2007 | 13,500 | 9 years | |
| | C65815-1 | X | | | December 13, 2007 | 13,500 | 9 years | |
| Pin (Connecting | C65815-20 | X | | | December 13, 2007 | 13,500 | 9 years | |
| rod/Upper rod) | C66472 | X | | | December 13, 2007 | 13,500 | 9 years | |
| | C66472-1 | X | | | December 13, 2007 | 13,500 | 9 years | |
| | C66472-20 | X | | X | April 25, 2007 | 13,500 | 9 years | |
| | D52751 | | X | | April 25, 2007 | 18,000 | 9 years | |

| | Aircraft type ap | | | | ice Times (contin | T | | |
|------------------------------|------------------|--------------|------|----------|----------------------|---|---------------------------|--|
| | A300 | _ | | <u> </u> | | Compliance Time (whichever occurs first after the "start date") | | |
| Designation | | X | | | Stant data | | | |
| Designation | A310 | | X | | Start date | | | |
| | A300-600 | | | X | | | Γ | |
| | P/N | | | | | Landings | Calendar Time | |
| | 1 | ML | G Sh | ock A | Absorber Assembly | T | T | |
| | 00-200-402 | X | | | December 13, 2007 | N/A | 30 months | |
| Lower torque link | SL40089 | X | | | December 13, 2007 | N/A | 30 months | |
| pin nut | SL40089P | X | | | December 13, 2007 | N/A | 30 months | |
| | SL40123 | X | | | December 13, 2007 | N/A | 30 months | |
| | SL40123P | X | X | X | April 25, 2007 | N/A | 30 months | |
| | SL40054 | X | | | December 13, 2007 | at next remov | val / installation (1)(2) | |
| Bogie beam pivot | SL40054P | X | | X | April 25, 2007 | at next remov | val / installation (1)(2) | |
| pin nut | SL40413P | | X | | April 25, 2007 | at next removal / installation (1)(2) | | |
| | l | M | LG | Lock | Link Assembly | | | |
| Lock link medium | C61485-1 | X | | | December 13, 2007 | N/A | 30 months | |
| pin | C61485-20 | X | | X | April 25, 2007 | N/A | 30 months | |
| | | ľ | | | NDING GEAR | | | |
| Pintle pin | A32210079200xx | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| | | - | | esco | pic Strut Assembly | | T | |
| Nut (Cylinder / | C61375 | X | X | | April 25, 2007 | 13,500 | 9 years | |
| Locking cylinder) | D55955 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| Locking sleeve | C61389 | X | X | | December 13, 2007 | 13,200 | 9 years | |
| | C61389-1 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| | | | NLO | G Ba | rrel Assembly | | , | |
| Pin (Clevis / | C62231-1 | X | | | December 13, 2007 | 13,200 | 9 years | |
| Telescopic strut) | C62231-2 | X | | | December 13, 2007 | 13,200 | 9 years | |
| | C62231-20 | | X | | April 25, 2007 | 13,500 | 9 years | |
| | D56530 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| Lowersin | C62268-1 | X | | | December 13, 2007 | 13,200 | 9 years | |
| Lower pin (Link / Clevis) | C62268-2 | X | | | December 13, 2007 | 13,200 | 9 years | |
| | C62268-20 | X | X | | April 25, 2007 | 13,500 | 9 years | |
| Link | C62230-1 | X | X | | April 25, 2007 | 13,500 | 9 years | |
| (Clevis / Barrel) | D56526 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| Linnarnia | C62267-1 | X | | | December 13, 2007 | 13,200 | 9 years | |
| Upper pin (Link / Barrel) | C62267-2 | X | | | December 13, 2007 | 13,200 | 9 years | |
| | C62267-20 | X | X | X | April 25, 2007 | 13,500 | 9 years | |

| | Aircraft type ar | | | | nce Times (conti | | | |
|--|------------------|-----|------|----------|----------------------|------------------------------------|-----------------------------------|--|
| | A300 | X | lity | \sqcap | | Compliance Time | | |
| Designation | | Λ | - | H | Start date | (whichever occi | urs first after the "start | |
| Designation | A310 | | X | | Start date | | date") | |
| | A300-600 | | | X | | | | |
| | P/N | | | | | Landings | Calendar Time | |
| End fitting pin nut | D68062 | X | X | X | December 13, 2007 | 1 | val / installation (2) | |
| End fitting pin nat | MS17825-6 | X | X | X | December 13, 2007 | | val / installation ⁽²⁾ | |
| | AN6-17 | X | X | X | December 13, 2007 | | val / installation (2) | |
| End fitting nin | D61183 | X | X | X | December 13, 2007 | at next remo | val / installation (2) | |
| End fitting pin | D68063 | X | X | X | December 13, 2007 | at next remo | val / installation (2) | |
| | NAS1306-22D | X | X | X | December 13, 2007 | at next removal / installation (2) | | |
| Management of the Control of the Con | C62032 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| End fitting | C62032-1 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| | C61453 | X | | | December 13, 2007 | 13,200 | 9 years | |
| D ! | C61453-1 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| Rack | C61453-20 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| | C61453-40 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| | C61453-41 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| Torque link pin | C62223-1 | X | | | December 13, 2007 | 13,200 | 9 years | |
| (Upper & Lower) | C62223-20 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| Torque link medium pin nut | SL40110P | X | X | X | April 25, 2007 | N/A | 30 months | |
| | | NLG | Sho | ck A | Absorber Assembly | - | | |
| Wheel axle nut | C62879 | X | X | X | April 25, 2007 | 4,000 | 24 months | |
| Upper cam dowel | C62270 | X | X | X | December 13, 2007 | at next rem | oval / installation | |
| Upper cam | C62034-1 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| Lower cam | C62035 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| | C62036 | X | | | December 13, 2007 | 13,200 | 9 years | |
| | C62036-1 | X | | | December 13, 2007 | 13,200 | 9 years | |
| | C62036-2 | X | | | December 13, 2007 | 13,200 | 9 years | |
| Restrictor | C67863 | X | | | December 13, 2007 | 13,200 | 9 years | |
| | C67863-1 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| | C67863-2 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| | C67863-3 | X | | | December 13, 2007 | 13,500 | 9 years | |
| | C67863-4 | X | X | X | April 25, 2007 | 13,500 | 9 years | |
| | | | | | | | | |

| | Aircraft type a | pplicab | oility | | | Compliance Time (whichever occurs first after the "start date") | | |
|------------------|-----------------|---------|--------|---|----------------------|---|---------------|--|
| Designation | A300 | X | | | | | | |
| | A310 | | X | | Start date | | | |
| | A300-600 | | | X | | | | |
| | P/N | | | | | Landings | Calendar Time | |
| Lower cam dowel | C62866 | X | X | X | December 13, 2007 | at next removal / installation (2) | | |
| Nut (C/A/Damal) | C64040 | X | | | December 13, 2007 | at next removal / installation (1)(2) | | |
| Nut (S/A/Barrel) | C64040-1 | X | X | X | December 13, 2007 | at next removal / installation (1)(2) | | |

Alternative Intervals or Limits

(k) Except as provided by paragraph (l) of this AD, after accomplishing the actions specified in paragraphs (h), (i), and (j) of this AD, no alternative replacements, replacement intervals, or limitations may be used.

Alternative Methods of Compliance (AMOCs)

(l)(1) The Manager, Manager, ANM–116, International Branch, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Stafford, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–1622; fax (425) 227–1149.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

Related Information

(m) European Aviation Safety Agency (EASA) Airworthiness Directive 2007–0293, dated November 29, 2007, also addresses the subject of this AD.

Issued in Renton, Washington, on March 12, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. E9–7267 Filed 3–31–09; 8:45 am]

BILLING CODE 4910-13-C

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA-R06-OAR-2008-0509; FRL-8788-7]

Approval and Promulgation of Implementation Plans; New Mexico; Albuquerque/Bernalillo County

AGENCY: Environmental Protection

Agency (EPA).

ACTION: Proposed rule.

SUMMARY: EPA is proposing to approve a revision to the New Mexico Albuquerque/Bernalillo County State Implementation Plan (SIP). This revision replaces Regulation 8, Airborne Particulate Matter, with NMAC 20.11.20, Fugitive Dust Control. This rulemaking action is being taken under section 110 of the Clean Air Act (CAA). DATES: Written comments must be received on or before May 1, 2009.

ADDRESSES: Comments may be mailed to Mr. Guy Donaldson, Chief, Air Planning Section (6PD–L), Environmental Protection Agency, 1445 Ross Avenue, Suite 1200, Dallas, Texas 75202–2733. Comments may also be submitted electronically or through hand delivery/courier by following the detailed instructions in the ADDRESSES section of the direct final rule located in the rules section of this Federal Register.

FOR FURTHER INFORMATION CONTACT: Joe Kordzi, Air Planning Section (6PD–L), Environmental Protection Agency, Region 6, 1445 Ross Avenue, Suite 700, Dallas, Texas 75202–2733, telephone (214) 665–7186; fax number 214–665–7263; e-mail address kordzi.joe@epa.gov.

SUPPLEMENTARY INFORMATION: In the final rules section of this Federal Register, EPA is approving the State's SIP submittal as a direct final rule without prior proposal because the Agency views this as a noncontroversial submittal and anticipates no adverse comments. A detailed rationale for the approval is set forth in the direct final rule. If no adverse comments are received in response to this action rule, no further activity is contemplated. If EPA receives adverse comments, the direct final rule will be withdrawn and all public comments received will be addressed in a subsequent final rule based on this proposed rule. EPA will not institute a second comment period. Any parties interested in commenting on this action should do so at this time. Please note that if EPA receives adverse comment on an amendment, paragraph, or section of this rule and if that provision may be severed from the remainder of the rule, EPA may adopt as final those provisions of the rule that are not the subject of an adverse comment.

For additional information, see the direct final rule which is located in the rules section of this **Federal Register**.

Dated: March 16, 2009.

Lawrence E. Starfield,

Acting Regional Administrator, Region 6. [FR Doc. E9–7297 Filed 3–31–09; 8:45 am]

BILLING CODE 6560-50-P

⁽¹⁾ When the nut is temporarily removed and reinstalled for the purpose of performing maintenance outside a workshop, no replacement is required provided the nut's removal and reinstallation are performed on the same assembly and neither the assembly nor the nut accumulates time in service during the period between the removal and reinstallation.

⁽²⁾ If the removal / installation was done after the start date, but before the effective date of this AD, the compliance time is within 3 months after the effective date of this AD.