

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Saab AB, Saab Aerosystems: Docket No. FAA-2010-0042; Directorate Identifier 2009-NM-010-AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by March 5, 2010.

Affected ADs

(b) None.

Applicability

(c) This AD applies to the Saab AB, Saab Aerosystems airplanes, certificated in any category, identified in paragraphs (c)(1) and (c)(2) of this AD, that have been modified in accordance with Supplemental Type Certificate (STC) SA00244WI-D, ST00146WI-D, or SA984GL-D.

(1) Model SAAB 340A (SAAB/SF340A) airplanes, serial numbers 004 through 159 inclusive.

(2) Model SAAB 340B airplanes, serial numbers 160 through 459 inclusive.

Subject

(d) Air Transport Association (ATA) of America Code 53: Fuselage.

Unsafe Condition

(e) This AD results from a report of a crack found behind the external adapter plate of the antennae during inspection. Similar cracking was found on two additional airplanes, and extensive corrosion was found on one airplane. The Federal Aviation Administration is issuing this AD to detect and correct corrosion and cracking behind the external adapter plate of the antennae of certain safe-life structure, which could result in reduced structural integrity and consequent rapid depressurization of the airplane.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified.

Inspection/Corrective Actions

(g) Within 600 flight cycles after the effective date of this AD: Remove the external adapter plate of the antennae installation and do a general visual inspection of the fuselage surface for corrosion and cracking behind the external adapter plate of the antennae installation. If any corrosion or cracking is found, repair before further flight. If no corrosion or cracking is found, before further flight, ensure that proper corrosion protection has been applied before reinstalling the adapter plate. Do all the actions required by this paragraph in

accordance with a method approved by the Manager, Wichita Aircraft Certification Office (ACO), FAA.

Note 1: For the purposes of this AD, a general visual inspection is: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Reporting Requirement

(h) At the applicable time specified in paragraph (h)(1) or (h)(2) of this AD: Submit a report of the positive findings of the inspections required by paragraph (g) of this AD. Send the report to the Manager, Wichita ACO. The report must contain, at a minimum, the inspection results, a description of any discrepancies found, the airplane serial number, and the number of flight cycles and flight hours on the airplane since installation of the STC. Under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

Special Flight Permit

(i) Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), may be issued to operate the airplane to a location where the requirements of this AD can be accomplished, but concurrence by the Manager, Wichita ACO, FAA, is required prior to issuance of the special flight permit.

Alternative Methods of Compliance (AMOCs)

(j) The Manager, Wichita ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: William Griffith, Aerospace Engineer, Airframe Branch, ACE-118W, FAA, Wichita ACO, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4116; fax (316) 946-4107. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

Related Information

(k) None.

Issued in Renton, Washington, on January 7, 2010.

Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-698 Filed 1-15-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2010-0043; Directorate Identifier 2009-NM-128-AD]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Corporation Model DC-10-10, DC-10-10F, and MD-10-10F Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain McDonnell Douglas Model DC-10-10, DC-10-10F, and MD-10-10F airplanes. This proposed AD would require a one-time high frequency eddy current inspection of fastener holes for cracks at the left and right side wing rear spar lower cap at station Xors=345, and other specified and corrective actions if necessary. This proposed AD results from a report of three instances of Model DC-10-10F airplanes having fuel leaks in the wing rear spar lower cap at station Xors=345. We are proposing this AD to prevent cracks in the spar cap, which if not corrected could lead to cracking of the lower wing skin, fuel leaks, and the inability of the structure to sustain limit load.

DATES: We must receive comments on this proposed AD by March 5, 2010.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m.

and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, California 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; e-mail dse.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Carl Fountain, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5322; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about

this proposed AD. Send your comments to an address listed under the ADDRESSES section. Include "Docket No. FAA-2010-0043; Directorate Identifier 2009-NM-128-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received a report of three instances of Model DC-10-10F airplanes having fuel leaks in the wing rear spar lower cap at station Xors=345. Investigation revealed the fuel leak was due to a crack in the lower cap. This crack extended into all three legs (aft, forward, and vertical) of the spar cap. Analysis of the cracked portion of the spar cap determined that the crack was due to fatigue and began at a fastener hole in the forward leg of the spar cap. This condition, if not corrected, could lead to cracking of the lower wing skin, fuel leaks, and the inability of the structure to sustain limit load.

Relevant Service Information

We have reviewed Boeing Alert Service Bulletin DC10-57A157, dated May 12, 2009. The service bulletin describes procedures for:

- Doing a high frequency eddy current inspection of fastener holes for

cracking at the left and right side wing rear spar lower cap.

- Cold working open holes and installing new second oversize fasteners in the left and right side wing rear spar lower cap if no cracking is found.
- Contacting Boeing for repair instructions and doing the repair if cracking is found.

FAA's Determination and Requirements of This Proposed AD

We are proposing this AD because we evaluated all relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of these same type designs. This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under "Differences Between the Proposed AD and Service Bulletin."

Differences Between the Proposed AD and Service Bulletin

The service bulletin specifies to contact the manufacturer for instructions on how to repair certain conditions, but this proposed AD would require repairing those conditions in one of the following ways:

- Using a method that we approve; or
- Using data that meet the certification basis of the airplane, and that have been approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that we have authorized to make those findings.

Costs of Compliance

We estimate that this proposed AD would affect 68 airplanes of U.S. registry. The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

TABLE—ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Cost per product	Number of U.S.-registered airplanes	Fleet cost
Inspection	2	\$80	\$160	68	\$10,880

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII,

Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on

products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the

distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866,
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

McDonnell Douglas Corporation: Docket No. FAA-2010-0043; Directorate Identifier 2009-NM-128-AD.

Comments Due Date

(a) We must receive comments by March 5, 2010.

Affected ADs

(b) None.

Applicability

(c) This AD applies to McDonnell Douglas Corporation Model DC-10-10, DC-10-10F, and MD-10-10F airplanes, certificated in any category, as specified in Boeing Alert Service Bulletin DC10-57A157, dated May 12, 2009.

Subject

(d) Air Transport Association (ATA) of America Code 57: Wings.

Unsafe Condition

(e) This AD results from a report of three instances of Model DC-10-10F airplanes having fuel leaks in the wing rear spar lower cap at station Xors=345. The Federal Aviation Administration is issuing this AD to prevent cracking in the spar cap, which could lead to cracking of the lower wing skin, fuel leaks, and the inability of the structure to sustain limit load.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection

(g) Within 3,000 flight cycles after the effective date of this AD, do a one-time high frequency eddy current inspection for cracking of fastener holes at the left and right side wing rear spar lower cap at station Xors=345, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin DC10-57A157, dated May 12, 2009.

(1) If no cracking is found, before further flight, cold work open holes and install new second oversize fasteners and nut assemblies in the left and right side wing rear spar lower cap, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin DC10-57A157, dated May 12, 2009.

(2) If any cracking is found during any inspection required by this AD, before further flight, repair the left and right side wing rear spar lower cap using a method approved in accordance with the procedures specified in paragraph (h) of this AD.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Carl Fountain, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5322; fax (562) 627-5210.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane and 14 CFR 25.571, Amendment 45, and the approval must specifically refer to this AD.

Issued in Renton, Washington, on January 8, 2010.

Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-699 Filed 1-15-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 165

[Docket No. USCG-2009-0996]

RIN 1625-AA00

Safety Zones; Hydroplane Races Within the Captain of the Port Puget Sound Area of Responsibility

AGENCY: Coast Guard, DHS.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Coast Guard proposes to establish permanent safety zones for Hydroplane Races to take place on various dates on the waters of Dyes Inlet, Port Angeles and Lake Washington, WA. When these safety zones are activated, and thus subject to enforcement, this rule would limit the movement of non-participating vessels within the established race areas while hydroplane races are taking place. This proposed rule is needed to ensure the safety of the maritime public from inherent dangers associated with high-speed watercraft races on navigable waterways during these events.

DATES: Comments and related material must be received by the Coast Guard on or before March 22, 2010. Requests for public meetings must be received by the Coast Guard on or before 45 days after date of publication in the **Federal Register**.

ADDRESSES: You may submit comments identified by docket number USCG-2009-0996 using any one of the following methods:

(1) *Federal eRulemaking Portal:* <http://www.regulations.gov>.

(2) *Fax:* 202-493-2251.

(3) *Mail:* Docket Management Facility (M-30), U.S. Department of Transportation, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590-0001.

(4) *Hand delivery:* Same as mail address above, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The telephone number is 202-366-9329.

To avoid duplication, please use only one of these four methods. See the "Public Participation and Request for Comments" portion of the **SUPPLEMENTARY INFORMATION** section below for instructions on submitting comments.

FOR FURTHER INFORMATION CONTACT: If you have questions on this proposed rule, call or e-mail ENS Ashley M.