

and Cooperative Agreements to State and Local Governments;

(3) 7 CFR part 3017, Governmentwide Debarment and Suspension (nonprocurement) and Governmentwide Requirements for Drug-Free Workplace (Grants);

(4) 7 CFR part 3018, New Restrictions on Lobbying;

(5) 7 CFR part 3019, Uniform Administrative Requirements for Grants and Agreements with Institutions of Higher Education, Hospitals and Other Non-profit Organizations; and

(6) 7 CFR part 3052, Audits of States, Local Governments and Non-profit Organizations.

(i) *Audit*. Grantees must comply with the audit requirements of 7 CFR part 3052. The audit requirements apply to the years in which grant funds are received and years in which work is accomplished using grant funds.

(j) *Change in scope or objectives*. The Grantee must obtain prior approval from FSA for any change to the scope or objectives of the approved project. Failure to obtain prior approval of changes to the scope of work or budget may result in suspension, termination, or recovery of grant funds.

(k) *Exceptions*. CCC may, in individual cases, make an exception to any requirement or provision of this part, provided that any such exception is not inconsistent with any applicable law or opinion of the Comptroller General, and provided further, that CCC determines that the application of the requirement or provision would adversely affect the Federal Government's interest.

(l) *Enforcement and refunds; liens and schemes or devices*. Grantees must comply with all conditions of the grant and any monies not spent or improperly spent must be returned immediately with interest to run at the normal rate for CCC obligations. Interest charges will be computed from the date of the CCC disbursement. Grantees must insure that parties that receive funds from the grantee comply with the grantee's application and return funds made available by the grantee where there is no such compliance. Any scheme or device to avoid any limits of this part will be considered to be a program violation with respect to any grant to which that scheme or device is related. Grant funds will be made available to the States or Tribes that are grantees under this part without regard to the claims of others, unless CCC determines otherwise.

Signed at Washington, DC, on June 30, 2010.

**Jonathan W. Coppess**,  
*Executive Vice President, Commodity Credit Corporation, and Administrator, Farm Service Agency.*

[FR Doc. 2010-16656 Filed 7-7-10; 8:45 am]

**BILLING CODE 3410-05-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2010-0565; Directorate Identifier 2010-SW-034-AD; Amendment 39-16357; AD 2010-14-12]

RIN 2120-AA64

**Airworthiness Directives; Arrow Falcon Exporters, Inc. (previously Utah State University); AST, Inc. (previously Firefly Aviation Helicopter Services, and Erickson Air-Crane); Rotorcraft Development Corporation (previously Garlick Helicopters, Inc.); Global Helicopter Technology, Inc.; Hagglund Helicopters, LLC (previously Western International Aviation, Inc.); International Helicopters, Inc.; Northwest Rotorcraft, LLC (previously Precision Helicopters, LLC); Robinson Air Crane, Inc.; San Joaquin Helicopters (previously Hawkins & Powers Aviation); S.M. & T. Aircraft (previously US Helicopter Inc., UNC Helicopters, Inc., Southern Aero Corporation, and Wilco Aviation); Smith Helicopters; Southern Helicopter, Inc.; Southwest Florida Aviation International, Inc. (previously Mr. Jamie R. Hill and Southwest Florida Aviation, Inc.); Tamarack Helicopters, Inc. (previously Ranger Helicopter Services, Inc.); US Helicopter, Inc. (previously Williams Helicopter Tech., Southern Aero Corp., Oregon Helicopters and Lenair Corp); West Coast Fabrications; and Overseas Aircraft Support Inc. (previously Williams Helicopter Corporation, Scott Paper Company and Offshores Construction) Model AH-1G, AH-1S, HH-1K, TH-1F, TH-1L, UH-1A, UH-1B, UH-1E, UH-1F, UH-1H, UH-1L, and UH-1P Helicopters; and Southwest Florida Aviation Model UH-1B (SW204 and SW204HP) and UH-1H (SW205) Helicopters**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) for the

Aeronautical Accessories, Inc. (AAI) Low Skid Landing Gear Forward Crosstube (crosstube) installed on the specified helicopters. This action requires replacing certain AAI serial-numbered crosstubes installed on these model helicopters. This amendment is prompted by the discovery of a defect in the raw material used in manufacturing certain crosstubes. The actions specified in this AD are intended to prevent failure of a crosstube and subsequent collapse of the landing gear.

**DATES:** Effective July 23, 2010.

Comments for inclusion in the Rules Docket must be received on or before September 7, 2010.

**ADDRESSES:** Use one of the following addresses to submit comments on this AD:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

You may get the service information identified in this AD from Aeronautical Accessories, Inc., P. O. Box 3689, Bristol, Tennessee 37625-3689, telephone (423) 538-5151 or 1-800-251-7094, fax (423) 538-8469.

*Examining the Docket:* You may examine the docket that contains the AD, any comments, and other information on the Internet at <http://www.regulations.gov>, or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located in Room W12-140 on the ground floor of the West Building at the street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** DOT/FAA Southwest Region, Martin R. Crane, ASW-170, Aviation Safety Engineer, Rotorcraft Directorate, Rotorcraft Certification Office, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5170, fax (817) 222-5783.

**SUPPLEMENTARY INFORMATION:** This amendment adopts a new AD for the specified AAI crosstubes installed on

the specified model helicopters. This action requires replacing certain AAI serial-numbered crosstubes installed on these model helicopters. This amendment is prompted by AAI's discovery of a defect in a batch of raw material used in the manufacture of these crosstubes. Preliminary tests indicate that surface cracking to the inner wall of the tubing was introduced during the manufacturing process. There have been no failures reported in the field. The defect was discovered during the forming operation at AAI. This condition, if not corrected, could result in failure of a crosstube and subsequent collapse of the landing gear.

We have reviewed AAI Alert Service Bulletin No. AA-10012, dated March 5, 2010 (ASB), which advises of a possible defect in the material used to manufacture the crosstube, part number (P/N) 212-320-103, which is also included in AAI Low Skid Gear Assembly Kits, P/N 412-320-500 and 412-320-502. The ASB specifies locating the serial number (S/N) of each crosstube, and replacing, within 25 hours time-in-service (TIS), each crosstube within the S/N range of AA-574 through AA-628, by following the procedures contained in the Instructions for Continued Airworthiness AA-01136.

This unsafe condition is likely to exist or develop on other helicopters of these same type designs with an affected crosstube installed. Therefore, this AD is being issued to prevent failure of a crosstube and subsequent collapse of the landing gear. This AD requires, within 25 hours TIS, replacing any affected crosstube with an airworthy crosstube.

The short compliance time involved is required because the previously described critical unsafe condition can adversely affect the structural integrity of the helicopter. Therefore, replacing an affected crosstube with an airworthy crosstube is required within 25 hours TIS, and this AD must be issued immediately.

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

We estimate that this AD will affect 18 helicopters, and replacing each affected crosstube will take about 5 work hours at an average labor rate of \$85 per work hour. Required parts will cost about \$4,925 per helicopter. Based on these figures, we estimate the total cost impact of the AD on U.S. operators to be \$96,300.

### Comments Invited

This AD is a final rule that involves requirements that affect flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to submit any written data, views, or arguments regarding this AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2010-0565; Directorate Identifier 2010-SW-034-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the AD. We will consider all comments received by the closing date and may amend the AD in light of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this AD. Using the search function of our docket web site, you can find and read the comments to any of our dockets, including the name of the individual who sent the comment. You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78).

### Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed above, I certify that the regulation:*

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this AD. See the AD docket to examine the economic evaluation.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII,

Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

**2010-14-12 Arrow Falcon Exporters, Inc. (Previously Utah State University); AST, Inc. (Previously Firefly Aviation Helicopter Services, and Erickson Air-Crane); Rotorcraft Development Corporation (Previously Garlick Helicopters, Inc.); Global Helicopter Technology, Inc.; Hagglund Helicopters, LLC (Previously Western International Aviation, Inc.); International Helicopters, Inc.; Northwest Rotorcraft, LLC (Previously Precision Helicopters, LLC); Robinson Air Crane, Inc.; San Joaquin Helicopters (Previously Hawkins & Powers Aviation); S.M. & T. Aircraft (Previously Us Helicopter Inc., UNC Helicopters, Inc., Southern Aero Corporation, and Wilco Aviation); Smith Helicopters; Southern Helicopter, Inc.; Southwest Florida Aviation International, Inc. (Previously Mr. Jamie R. Hill and Southwest Florida Aviation, Inc.); Tamarack Helicopters, Inc. (Previously Ranger Helicopter Services, Inc.); Us Helicopter, Inc. (Previously Williams Helicopter Tech., Southern Aero Corp., Oregon Helicopters and Lenair Corp); West Coast Fabrications; and Overseas Aircraft Support Inc. (Previously Williams Helicopter Corporation, Scott Paper Company and**

**Offshores Construction):** Amendment 39–16357. Docket No. FAA–2010–0565; Directorate Identifier 2010–SW–034–AD.

**Applicability:** Model AH–1G, AH–1S, HH–1K, TH–1F, TH–1L, UH–1A, UH–1B, UH–1E, UH–1F, UH–1H, UH–1L, and UH–1P Helicopters; and Southwest Florida Aviation Model UH–1B (SW204 and SW204HP) and UH–1H (SW205) helicopters, certificated in any category, with Aeronautical Accessories, Inc. (AAI), Low Skid Landing Gear Forward Crosstube (crosstube), part number (P/N) 212–320–103, with a serial number (S/N) prefix of “AA” and an S/N of 574 through 628.

**Note 1:** Crosstube, P/N 212–320–103, is also included as part of AAI Low Skid Gear Assembly Kits, P/N 412–320–500 and 412–320–502.

**Note 2:** Crosstube, P/N 212–320–103, is installed on Rotorcraft Development Corporation; S.M.T. Aircraft; Hagglund Helicopters, LLC; and Southwest Florida Aviation International, Inc., Model UH–1B and UH–1H helicopters, based on Supplemental Type Certificate No. SR01924AT.

**Compliance:** Required as indicated, unless done previously.

To prevent failure of a crosstube and subsequent collapse of the landing gear, do the following:

(a) Within 25 hours time-in-service, replace any affected crosstube with an airworthy crosstube.

**Note 3:** AAI Alert Service Bulletin ASB No. AA–10012, dated March 5, 2010, contains guidance that pertains to the subject of this AD and references AAI Instructions for Continued Airworthiness AA–01136, which contains the instructions for replacing the crosstubes.

(b) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Manager, Rotorcraft Certification Office: *Attn:* DOT/FAA Southwest Region, Martin R. Crane, ASW–170, Aviation Safety Engineer, Rotorcraft Directorate, Rotorcraft Certification Office, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222–5170, fax (817) 222–5783, for information about previously approved alternative methods of compliance.

(c) The Joint Aircraft System/Component (JASC) Code is 3250: Landing Gear System.

(d) This amendment becomes effective on July 23, 2010.

Issued in Fort Worth, Texas, on June 25, 2010.

**Mark R. Schilling,**

*Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.*

[FR Doc. 2010–16529 Filed 7–7–10; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA–2010–0599; Airspace Docket No. 10–AWA–3]

RIN 2120–AA66

#### Amendment of Class C Airspace; Flint, MI

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action amends the legal description of the Bishop International Airport, Flint, MI, Class C airspace area by amending the airport reference point (ARP) information for the airport. This amendment is necessitated by the removal of Runway 5/23 and installation of a parallel taxiway along a portion of Runway 9/27, which changed the configuration of the airport and, consequently, changed the ARP. This action is necessary for the safety of aircraft operating in the Flint, MI, airspace area.

**DATES:** Effective date 0901 UTC, September 23, 2010. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

**FOR FURTHER INFORMATION CONTACT:** Colby Abbott, Airspace and Rules Group, Office of System Operations Airspace and AIM, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; *telephone:* (202) 267–8783.

#### SUPPLEMENTARY INFORMATION:

#### History

In the autumn of 2009, a major construction project at Bishop International Airport, Flint, MI, was completed that entailed removing Runway 5/23, which was not an operating runway, and installing a “south parallel” taxiway along the eastern portion of Runway 9/27. Prior to construction, airport runway configuration made it possible for aircraft to mistake the 3,900 foot Runway 23 for the 7,200 foot Runway 27. There was also no capability for an aircraft to taxi to the approach end of Runway 27 from the south side of the airport without either back taxiing on the runway or crossing the runway and taxiing on the north side parallel to the approach end. As a result of the runway removal and taxiway installation, the airport layout changed enough to affect

the ARP location, which defines the Class C airspace area’s center point.

#### The Rule

This action amends Title 14 Code of Federal Regulations (CFR) part 71 by amending the ARP information contained in the legal description of the Bishop International Airport, Flint, MI, Class C airspace area to reflect current National Airspace System data. The correct ARP information, which the Class C airspace area is centered around, is latitude 42°57’56” N., longitude 83°44’41” W. Although the construction project affected the ARP, there are no other changes to the dimensions or altitudes of the Class C airspace area. Therefore, notice and public comment under 5 U.S.C. 553(b) are unnecessary.

Class C airspace areas are published in paragraph 4000 of FAA Order 7400.9T signed August 27, 2009, and effective September 15, 2009, which is incorporated by reference in 14 CFR 71.1. The Class C airspace area listed in this document will be published subsequently in the Order.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority.

This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends Class C airspace at Bishop International Airport, Flint, MI.