

compliance for the requirements in this paragraph of this AD. It is acceptable to operate an airplane with one MLG having a P/N 41141-5 piston installed, and the other MLG having a P/N 41141-3 piston installed, provided all MLG P/N 41141-3 are replaced within the compliance times specified in paragraph (i) of this AD.

#### (j) New Requirement: Parts Installation

After 120 months after the effective date of this AD: No person may install a MLG piston, P/N 41141-3, or a MLG unit equipped with a MLG piston P/N 41141-3, on any airplane.

#### (k) New Requirement: Revising the Airplane Maintenance Program

Within two months after the effective date of this AD: Revise the airplane maintenance program by incorporating Task 321100-01-16, inspection of the MLG piston, and associated thresholds and intervals described in Fokker Engineering Report, MRB Appendix 1, SE-623, Issue 8, dated March 17, 2011. The initial compliance time for Task 321100-01-16 is within two months after the effective date of this AD.

#### (l) No Alternative Actions or Intervals

After accomplishing the revisions required by paragraph (k) of this AD, no alternative actions (e.g., inspections) or intervals may be used other than those specified in Fokker Engineering Report, MRB Appendix 1, SE-623, Issue 8, dated March 17, 2011, unless the actions and intervals are approved as an AMOC in accordance with the procedures specified in paragraph (m)(1) of this AD.

#### (m) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone 425-227-1137; fax 425-227-1149. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

#### (n) Related Information

(1) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2011-0159, dated August 26, 2011; and the service information specified in paragraphs (n)(1)(i) through (n)(1)(iv) of this AD; for related information.

(i) Fokker Service Bulletin SBF100-32-161, dated April 7, 2011.

(ii) Fokker Services Engineering Report, MRB Appendix 1, SE-623, Issue 8, dated March 17, 2011.

(iii) Goodrich Service Bulletin 41000-32-29, dated November 10, 2010.

(iv) Fokker Service Bulletin SBF100-32-158, dated October 2, 2009.

(2) For Fokker service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands; telephone +31 (0)252-627-350; fax +31 (0)252-627-211; email [technicalservices.fokkerservices@stork.com](mailto:technicalservices.fokkerservices@stork.com); Internet <http://www.myfokkerfleet.com>. For Goodrich service information identified in this AD, contact Goodrich, 1400 South Service Road, West Oakville, L6L 5Y7, Ontario, Canada, telephone +1-905-827-7777; fax +1-905-825-1583; Internet <http://www.goodrich.com/TechPubs>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on June 12, 2012.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2012-15166 Filed 6-20-12; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2012-0642; Directorate Identifier 2011-NM-262-AD]

RIN 2120-AA64

#### Airworthiness Directives; BAE SYSTEMS (OPERATIONS) LIMITED Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain BAE SYSTEMS (OPERATIONS) LIMITED Model BAe 146 series airplanes and Model Avro 146-RJ series airplanes. This proposed AD was prompted by hydraulic pipe ruptures in the center of the cabin resulting in

passengers being contaminated with hydraulic fluid. This proposed AD would require installing a hydraulic fluid containment system. We are proposing this AD to prevent harmful or hazardous concentrations of hydraulic fluid or hydraulic vapor from entering the passenger compartment, possibly resulting in injury to the passengers.

**DATES:** We must receive comments on this proposed AD by August 6, 2012.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact BAE SYSTEMS (OPERATIONS) LIMITED, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email [RApublications@baesystems.com](mailto:RApublications@baesystems.com); Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton,

Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2012-0642; Directorate Identifier 2011-NM-262-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

**Discussion**

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2011-0220, dated November 11, 2011 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Cases of hydraulic pipe ruptures in the centre of the cabin of BAe 146 aeroplanes have been reported, which have resulted in the passengers being contaminated with hydraulic fluid. The results of the investigations have shown that the pipe failures were caused by a combination of seam welded pipes, bends in the pipe runs with small bend radii and fatigue damage due to pressure variations.

This condition, if not corrected, could lead to harmful or hazardous concentrations of hydraulic fluid or hydraulic vapour entering the passenger compartment, possibly resulting in injury to the occupants.

For the reasons described above, this [EASA] AD requires the installation of a flexible envelope around the hydraulic pipe group where the failures have occurred to capture and contain any fluid escaping from a burst pipe and channel it below floor level into the forward cargo bay.

You may obtain further information by examining the MCAI in the AD docket.

**Relevant Service Information**

BAE SYSTEMS (OPERATIONS) LIMITED has issued Modification Service Bulletin SB.29-048-30676A, Revision 2, dated December 23, 2010. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

**FAA's Determination and Requirements of This Proposed AD**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

**Costs of Compliance**

Based on the service information, we estimate that this proposed AD would affect about 1 product of U.S. registry. We also estimate that it would take about 8 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$5,079 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$5,759.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a

substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. The FAA amends § 39.13 by adding the following new AD:

**BAE SYSTEMS (OPERATIONS) LIMITED:**  
Docket No. FAA-2012-0642; Directorate Identifier 2011-NM-262-AD.

**(a) Comments Due Date**

We must receive comments by August 6, 2012.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to BAE SYSTEMS (OPERATIONS) LIMITED Model BAe 146-100A, -200A, and -300A airplanes, and Model Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A airplanes; certificated in any category except for airplanes operating in a cargo configuration. The requirements of this AD become applicable at the time an airplane operating in a cargo configuration is converted to a passenger configuration.

**(d) Subject**

Air Transport Association (ATA) of America Code 29, Hydraulic power.

**(e) Reason**

This AD was prompted by hydraulic pipe ruptures in the center of the cabin resulting in passengers being contaminated with hydraulic fluid. We are issuing this AD to prevent harmful or hazardous concentrations of hydraulic fluid or hydraulic vapor from entering the passenger compartment, possibly resulting in injury to the passengers.

**(f) Compliance**

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**(g) Actions**

Within 4,000 flight hours or 24 months after the effective date of this AD, whichever occurs first, install the hydraulic fluid containment system, in accordance with the Accomplishment Instructions of BAE SYSTEMS (OPERATIONS) LIMITED Modification Service Bulletin SB.29-048-30676A, Revision 2, dated December 23, 2010.

**(h) Credit for Previous Actions**

This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD, using the service bulletin specified in paragraph (h)(1) or (h)(2) of this AD.

(1) BAE SYSTEMS (OPERATIONS) LIMITED Modification Service Bulletin SB.29-048-30676A, dated October 18, 2010.

(2) BAE SYSTEMS (OPERATIONS) LIMITED Modification Service Bulletin SB.29-048-30676A, Revision 1, dated November 5, 2010.

**(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required

to assure the product is airworthy before it is returned to service.

**(j) Related Information**

(1) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2011-0220, dated November 11, 2011; and BAE SYSTEMS (OPERATIONS) LIMITED Modification Service Bulletin SB.29-048-30676A, Revision 2, dated December 23, 2010; for related information.

(2) For service information identified in this AD, contact BAE SYSTEMS (OPERATIONS) LIMITED, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email [RApublications@baesystems.com](mailto:RApublications@baesystems.com); Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on June 12, 2012.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2012-15168 Filed 6-20-12; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2012-0641; Directorate Identifier 2011-NM-258-AD]**

**RIN 2120-AA64**

**Airworthiness Directives; Bombardier, Inc. Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL-600-2A12 (CL-601) and CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604 Variants) airplanes. This proposed AD was prompted by reports of jamming/malfunctioning of the left-hand engine thrust control mechanism. This proposed AD would require modifying the left-hand engine upper core-cowl. We are proposing this AD to prevent jamming/malfunctioning of the left-hand engine thrust control mechanism, which could lead to loss of control of the airplane.

**DATES:** We must receive comments on this proposed AD by August 6, 2012.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Mazdak Hobbi, Aerospace Engineer, Propulsion and Services Branch, ANE-173, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Westbury, NY 11590; telephone (516) 228-7330; fax (516) 794-5531.

**SUPPLEMENTARY INFORMATION:****Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2012-0641; Directorate Identifier 2011-NM-258-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy