

in parts 30, 31, 32, 40 and 70 of Title 10 of the *Code of Federal Regulations* (10 CFR) to make requirements for distributors of byproduct material clearer, less prescriptive, and more risk-informed and up to date. In that notice, the NRC also proposed to redefine categories of devices to be used under exemptions, add explicit provisions regarding the sealed source and device registration process, and add flexibility to the licensing of users of sealed sources and devices. The public comment period on the proposed rule closed on September 7, 2010. The NRC received 10 comments on the proposed rule.

The NRC considered these comments in developing a final rule [RIN 3150-AH91; Docket ID NRC-2008-0338], which is being published in the Rules and Regulations Section of this issue of the **Federal Register**. The final rule will affect manufacturers and distributors of certain products and materials containing source material and certain persons using source material under general license and under exemptions from licensing.

In conjunction with the final rule, the NRC has developed interim guidance. The interim guidance document provides guidance to a licensee or applicant for implementation of 10 CFR parts 30, 31, 32, 40 and 70, "Requirements for Distribution of Byproduct Material." It is intended for use by applicants, licensees, Agreement States, and the NRC staff. The interim guidance describes methods acceptable to the NRC staff for implementing the revised regulations. The approaches and methods described in the guidance document are provided for information and use in implementing the revised regulations. Methods and solutions different from those described in the interim guidance are acceptable if they meet the requirements in 10 CFR parts 30, 31, 32, 40, and 70.

At this time, the NRC is announcing the availability for use of "Interim Guidance for Implementation of the Final Rule, Requirements for Distribution of Byproduct Material in 10 CFR Parts 30, 31, 32, 40, and 70." The document provides guidance on implementing the revised provisions of 10 CFR parts 30, 31, 32, 40, and 70. The NRC is also requesting public comment on this interim guidance. Guidance on the revised regulations will be included in the next revision of the relevant volumes in NUREG-1556, "Consolidated Guidance about Materials Licenses." Comments received on this interim guidance will be considered in the updating of those volumes of NUREG-1556.

Dated at Rockville, Maryland, this 25th day of June 2012.

For the Nuclear Regulatory Commission.

Mark A. Satorius,

Director, Office of Federal and State Materials and Environmental Management Programs.

[FR Doc. 2012-17710 Filed 7-19-12; 8:45 am]

BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-0724; Directorate Identifier 2012-NM-043-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to supersede an existing airworthiness directive (AD) that applies to certain Bombardier, Inc. Model DHC-8-400 series airplanes. The existing AD currently requires a modification to trim the edge of the bumper plate, including performing an inspection for damage or cracks of the bumper plate and base fitting, and replacing any damaged or cracked part. That AD also currently requires, for certain airplanes, reidentifying the bumper plate. Since we issued that AD, we have determined that an operational check must be done after reidentifying the bumper plate to ensure the identified unsafe condition is addressed. This proposed AD would require, for airplanes on which the reidentification is done, an operational check of the alternate extension system of the main landing gear (MLG), and repair if necessary. We are proposing this AD to detect and correct failure of the MLG to extend and lock, which could adversely affect the safe landing of the airplane.

DATES: We must receive comments on this proposed AD by September 10, 2012.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

• *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>.

You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7318; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2012-0724; Directorate Identifier 2012-NM-043-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each

substantive verbal contact we receive about this proposed AD.

Discussion

On July 29, 2011, we issued AD 2011–17–04, Amendment 39–16768 (76 FR 50403, August 15, 2011). That AD required actions intended to address an unsafe condition on certain Bombardier, Inc. Model DHC–8–400, –401, and –402 airplanes.

Since we issued AD 2011–17–04, Amendment 39–16768 (76 FR 50403, August 15, 2011), we have determined that an operational check must be done after reidentifying the bumper plate to ensure the identified unsafe condition is addressed. This action is also included in Canadian Airworthiness Directive CF–2010–23, dated July 21, 2010 (referred to after this as “the MCAI”). The MCAI states:

One in-service incident has been reported on [a] DHC–8 Series 400 aeroplane in which the right hand main landing gear (MLG) failed to extend using the alternate gear extension system. Investigation determined that the tread on the outboard tire was catching on the bumper plate located on the outboard MLG door that prevented the MLG door to open following an extension attempt via the alternate extension system. Failure of [the] MLG to extend and lock could adversely affect the safe landing of the aeroplane.

To prevent the potential jam condition between the bumper plate and the MLG tires, Bombardier Aerospace has developed a modification to trim the edge of the bumper plate to eliminate the possibility of interference [Bombardier Modsum 4–113645].

The Modsum includes performing a detailed visual inspection for damage or cracks of the bumper plate and base fitting and replacing any damaged or cracked part with a new part, if necessary. You may obtain further information by examining the MCAI in the AD docket.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 65 products of U.S. registry.

The actions that are required by AD 2011–17–04, Amendment 39–16768 (76 FR 50403, August 15, 2011), and retained in this proposed AD take about 8 work-hours per product, at an average labor rate of \$85 per work hour. Required parts would cost about \$479 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, the cost of the currently required actions is \$1,159 per product.

We estimate that it would take about 1 work-hour per product to comply with the new basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$5,525, or \$85 per product.

We have received no definitive data that would enable us to provide a cost estimate for the on-condition actions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by removing airworthiness directive (AD) 2011–17–04, Amendment 39–16768 (76 FR 50403, August 15, 2011), and adding the following new AD:

Bombardier, Inc.: Docket No. FAA–2012–0724; Directorate Identifier 2012–NM–043–AD.

(a) Comments Due Date

We must receive comments by September 10, 2012.

(b) Affected ADs

This AD supersedes AD 2011–17–04, Amendment 39–16768 (76 FR 50403, August 15, 2011).

(c) Applicability

This AD applies to Bombardier, Inc. Model DHC–8–400, –401, and –402 airplanes, certificated in any category, having serial numbers 4001 through 4247 inclusive.

(d) Subject

(d) Air Transport Association (ATA) of America Code 32: Landing Gear.

(e) Reason

This AD was prompted by one in-service incident reported on a DHC–8–400 airplane in which the right hand main landing gear

(MLG) failed to extend using the alternate gear extension system. We are issuing this AD to detect and correct failure of the MLG to extend and lock, which could adversely affect the safe landing of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Retained Actions for All Airplanes

Within 2,000 flight hours after September 19, 2011 (the effective date of AD 2011-17-04, Amendment 39-16768 (76 FR 50403, August 15, 2011); Incorporate Bombardier Modsum 4-113645, including performing a detailed visual inspection for damage or cracks of the bumper plate and base fitting and replacing any damaged or cracked part, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 84-32-74, Revision A, dated May 17, 2010. Do all applicable replacements before further flight.

Note 1 to paragraphs (g) and (h) of this AD: Bombardier Service Bulletin 84-32-74, Revision A, dated May 17, 2010, includes an operational check of the alternate extension system of the MLG. If the operational check fails, guidance on doing corrective actions can be found in the Bombardier Q400 Dash 8 Aircraft Maintenance Manual.

(h) Retained Actions for Airplanes Having Certain Bumper Plates

For airplanes on which a bumper plate having part number 85424082-101 or 85424082-103 is installed on which the rework specified in Bombardier Repair Drawing 8/4-54-553 has been done: Within 1,000 flight hours after September 19, 2011 (the effective date of AD 2011-17-04, Amendment 39-16768 (76 FR 50403, August 15, 2011), reidentify the bumper plate, in accordance with paragraph 3.B., step (8) of the Accomplishment Instructions of Bombardier Service Bulletin 84-32-74, Revision A, dated May 17, 2010.

(i) Retained Credit for Previous Actions

This paragraph provides credit for the modification required by paragraph (h) of this AD by incorporation of Bombardier Modsum 4-113645 before September 19, 2011 (the effective date of AD 2011-17-04, Amendment 39-16768 (76 FR 50403, August 15, 2011), if the modification was performed using Bombardier Service Bulletin 84-32-74, dated December 23, 2009; and provided the modification is done within the compliance time specified in paragraph (h) of this AD.

(j) New Requirements of This AD: Operational Check for Airplanes on Which the Action Required by Paragraph (h) Is Done

Concurrently with doing the actions required by paragraph (h) of this AD, or within 30 days after the effective date of this AD, whichever occurs later: Perform an operational check of the alternate extension system of the MLG, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 84-32-74, Revision A, dated

May 17, 2010. If the operational check fails, before further flight, repair in accordance with a method approved by either the Manager, New York Aircraft Certification Office (ACO), FAA; or the Transport Canada Civil Aviation (TCCA) (or its delegated agent).

Note 2 to paragraph (j) of this AD: If the operational check fails, guidance on doing the repair can be found in the Bombardier Q400 Dash 8 Aircraft Maintenance Manual.

(k) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD, provided the operational check specified in paragraph (j) of this AD is done within the compliance time specified in paragraph (g) of this AD, or within 30 days after the effective date of this AD, whichever occurs later, using Bombardier Service Bulletin 84-32-74, dated December 23, 2009.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO, ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the New York ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York, 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(m) Related Information

(1) Refer to MCAI Canadian Airworthiness Directive CF-2010-23, dated July 21, 2010; and Bombardier Service Bulletin 84-32-74, Revision A, dated May 17, 2010; for related information.

(2) For service information identified in this proposed AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on July 17, 2012.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-18145 Filed 7-24-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-0723; Directorate Identifier 2011-NM-137-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737-600, -700, -700C, -800, and -900 series airplanes. This proposed AD was prompted by a report of cracks found in the skin at body station (STA) 540 just below stringer S-22L on a Model 737-700 series airplane. This proposed AD would require repetitive detailed and high frequency eddy current inspections for cracking of the skin around the eight fasteners common to the ends of the STA 540 bulkhead chords between stringers S-22 and S-23, left and right sides; and corrective actions and preventive modification if necessary. We are proposing this AD to detect and correct fatigue cracking in the skin, which can result in rapid decompression of the cabin.

DATES: We must receive comments on this proposed AD by September 10, 2012.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing