

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Branch, send it to the attention of the person identified in paragraph (m)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591. Attn: Information Collection Clearance Officer, AES-200.

(4) *Required for Compliance (RC)*: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA

Airworthiness Directive 2016-0079, dated April 21, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9574.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-2125; fax: 425-227-1149.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(3) and (n)(4) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A300-52-0180, Revision 01, dated October 14, 2014.

(ii) Airbus Service Bulletin A300-52-6084, Revision 01, dated October 16, 2014.

(iii) Airbus Service Bulletin A310-52-2076, Revision 01, dated October 14, 2014.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: account.airworth-eas@airbus.com; Internet: <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 2, 2017.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-12286 Filed 6-19-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2015-3148; Directorate Identifier 2014-NM-254-AD; Amendment 39-18928; AD 2017-12-13]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Airbus Model A320-212, -214, -232, and -233 airplanes. This AD was prompted by a report of a crack found during an inspection of the pocket radius of the fuselage frame. This AD requires repetitive low frequency eddy current inspections or repetitive high frequency eddy current inspections of this area, and repair if necessary. The repair terminates the repetitive inspections. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD becomes effective July 25, 2017.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 25, 2017.

ADDRESSES: For service information identified in this final rule, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3148; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory

evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to Airbus Model A320-212, -214, -232, and -233 airplanes. The NPRM published in the **Federal Register** on August 27, 2015 (80 FR 51968) (“the NPRM”).

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2014-0278, dated December 19, 2014 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus Model A320-212, -214, -232, and -233 airplanes. The MCAI states:

An operator reported finding a crack during an inspection in accordance with the instructions of Airbus Alert Operators Transmission (AOT) A53N007-14. What was found, a 170 mm through-thickness crack in the pocket radius between frame 36 and 37 above stringer 6 on left hand (LH) side lap joint, was not the aim of the AOT inspection. Prior to this finding, the operator reported noise in the affected area during several weeks.

This condition, if not detected and corrected, could lead to in-flight decompression of the aeroplane, possibly resulting in injury to occupants.

To address this unsafe condition, Airbus published AOT A53N009-14 to provide inspection and repair instructions to detect and prevent crack propagation.

EASA decided to agree on a sampling inspection to determine whether additional aeroplanes need to be inspected.

For the reasons described above, this [EASA] AD requires, for the selected aeroplanes, repetitive Low Frequency Eddy Current (LFEC) or High Frequency Eddy Current (HFEC) inspections of the pocket

radii [for cracks] located between fuselage frames 35 and 40, above stringer 6 on both LH and right hand (RH) sides and, depending on findings, accomplishment of repair instructions.

This [EASA] AD is considered an interim action and further [EASA] AD action may follow.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3148.

Comments

We gave the public the opportunity to participate in developing this AD. We have considered the comment received. The following presents the comment received on the NPRM and the FAA’s response.

Request To Withdraw the Proposed Rule

Delta (DAL) requested that we withdraw the proposed rule. DAL commented that a review of the manufacturing records for the cracked skin panel noted rework in the discrepant area, which could have contributed to cracking. DAL also stated that the effectivity specified in Airbus AOT A53N009-14, dated December 17, 2014, was limited to airplanes fitted with reworked panels and manufactured with the same chemical milling process. DAL commented that, in addition, there were scratch-like indications near the cracked area which may have been due to the manufacturing process. DAL stated that further research is in work with nothing confirmed.

DAL stated since the issuance of Airbus AOT A53N009-14, dated December 17, 2014, all 7 applicable airplanes mentioned in the proposed rule have completed the initial inspections with no findings. DAL stated that over half the airplanes were inspected from the inside using the HFEC inspection, which is capable of detecting very small cracks. DAL also commented that the inspection results have been provided to Airbus for review. DAL also stated that Airbus conducted a study that showed an undetected crack would not result in an explosive decompression but rather a partial opening of the skin causing flapping with a slow loss of cabin pressure. DAL noted that further testing is in work to determine what final action, if any, is required.

DAL also stated that EASA is considering cancellation of AD 2014-0278, dated December 19, 2014, pending the outcome of the investigations.

DAL stated that the proposed rule is premature and should be cancelled based on the available data and recent inspection results.

We disagree with the commenter’s request. The EASA, as the State of Design Authority for Airbus products, has determined that cancellation of AD 2014-0278, dated December 19, 2014, is warranted. However, if new information becomes available to justify revising or removing this AD, we will consider further rulemaking. We have not changed this AD in this regard.

Conclusion

We reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this AD as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 14 CFR Part 51

We reviewed Airbus AOT A53N009-14, Rev 00, dated December 17, 2014. The service information describes procedures for repetitive inspections of the pocket radii located between fuselage frames 35 and 40, above stringer 6 on both the left- and right-hand sides, and repair if necessary. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 1 airplane of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	3 work-hours × \$85 per hour = \$255 per inspection cycle.	\$0	\$255 per inspection cycle.	\$255 per inspection cycle.

We have received no definitive data that will enable us to provide cost estimates for the on-condition actions specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2017-12-13 Airbus: Amendment 39-18928; Docket No. FAA-2015-3148; Directorate Identifier 2014-NM-254-AD.

(a) Effective Date

This AD becomes effective July 25, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Airbus Model A320-212 airplane having manufacturer serial number (MSN) 1011; Airbus Model A320-214 airplanes having MSNs 1009, 1026 and 1030; the Airbus Model A320-232 airplane having MSN 0977; and Airbus Model A320-233 airplanes having MSNs 1007 and 1013; certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by a report of a crack found during an inspection of the pocket radius of the fuselage frame. We are issuing this AD to detect and correct any cracking of the pocket radius, which could lead to in-flight decompression of the airplane and possible injury to the passengers.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections

Within 750 flight cycles or 4 months, whichever occurs first after the effective date of this AD: Do a low frequency eddy current (LFEC) inspection or a high frequency eddy current (HFEC) inspection for cracking of the pocket radii located between fuselage frames 35 and 40, above stringer 6 on both the left and right-hand sides, in accordance with the

instructions of Airbus Alert Operators Transmission (AOT) A53N009-14, Rev 00, dated December 17, 2014. Repeat the inspection, thereafter, at intervals not to exceed the times specified in paragraphs (g)(1) and (g)(2) of this AD.

(1) For the LFEC inspection performed on the outside: Repeat the inspection at intervals not to exceed 1,000 flight cycles.

(2) For the HFEC inspection performed on the inside: Repeat the inspection at intervals not to exceed 2,000 flight cycles.

(h) Corrective Action

If, during any inspection required by paragraph (g) of this AD, any crack is found, before further flight, accomplish the repair in accordance with the instructions of Airbus AOT A53N009-14, Rev 00, dated December 17, 2014; except if the crack is beyond the structural repair manual limits as specified in Airbus AOT A53N009-14, Rev 00, dated December 17, 2014, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

(i) Terminating Action

Repair of an airplane as required by paragraph (h) of this AD terminates the repetitive inspections required by paragraph (g) of this AD for the repaired area only.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0278, dated December 19, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3148.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Alert Operators Transmission A53N009-14, Rev 00, dated December 17, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus, Airworthiness Office—ELIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 6, 2017.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-12289 Filed 6-19-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2016-8944; Airspace Docket No. 16-AGL-21]

Amendment of and Establishment of Air Traffic Service (ATS) Routes; Northcentral United States

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action modifies one jet route (J-25) and five VHF Omnidirectional Range (VOR) Federal airways (V-55, V-82, V-161, V-218, and V-413), and establishes three Area Navigation (RNAV) T-routes (T-330, T-354, and T-383) in the northcentral United States. The FAA is taking this action due to the planned decommissioning of the Brainerd, MN (BRD), VHF Omnidirectional Range/Tactical Air Navigation (VORTAC) navigation aid (NAVAID), which provides navigation guidance for portions of the ATS routes amended by this action. The RNAV T-routes established by this action mitigate potential issues to the National Airspace System (NAS) route structure caused by the Jet route and VOR Federal airway amendments. This action enhances the safe and efficient management of aircraft operating within the NAS.

DATES: Effective date 0901 UTC, August 17, 2017.

The Director of the Federal Register approves this incorporation by reference action under Title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.11A, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11A at NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal-regulations/ibr_locations.html.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT: Colby Abbott, Airspace Policy Group, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:**Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code.

Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it modifies the NAS route structure as necessary to preserve the safe and efficient flow of air traffic within the NAS.

History

On January 19, 2017, the FAA published in the **Federal Register** a notice of proposed rulemaking (NPRM) (82 FR 6353), Docket No. FAA-2016-8944, to amend Jet route J-25; amend VOR Federal airways V-55, V-82, V-161, V-218, and V-413; and establish RNAV T-routes T-330, T-354, and T-383 due to the planned decommissioning of the Brainerd VORTAC. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal. One comment was received.

Discussion of Comments

The commenter stated that the NPRM listed only the regulatory body [aeronautical] changes in the proposal and that an additional study to be conducted was an environmental impact study. The commenter stated the only environmental concerns would be any potential for aircraft noise changes in the affected areas, due to the changing routes, and the associated impact to the local populace and/or wildlife, depending on the degree of the changes. The FAA completed an environmental review of the ATS route amendments and RNAV route establishments in this action and determined that this action qualifies for categorical exclusion from further environmental impact review actions under the National Environmental Policy Act in accordance with FAA Order 1050.1F, Environmental Impacts: Policies and Procedures, paragraph 5-6.5a. This airspace action is not expected to cause any potentially significant environmental impacts and no extraordinary circumstances exist that warrant preparation of an environmental assessment or environmental impact study.

Jet routes are published in paragraph 2004, VOR Federal airways are published in paragraph 6010(a), and