

(1) The substituted intermediary is eligible to receive the assistance approved for the original intermediary;

(2) The substituted intermediary bears a close and genuine relationship to the original intermediary; and

(3) The need for and scope of the project and the purposes for which Agency IRP loan funds will be used remain substantially unchanged.

§ 4274.352 Loan documentation for ultimate recipients.

(a) *Agency IRP loans.* Prior Agency concurrence is required when an intermediary makes loans to an ultimate recipient from its Agency IRP loan funds (this applies to each Agency IRP loan received). A request for Agency concurrence in approval of a proposed loan to an ultimate recipient, whether made directly or through a loan participation purchase, must contain or comply with, as appropriate, the items identified in paragraph (b)(1) through (5) of this section and must include information listed in the IRP Revolving Loan Fund File Checklist, on the Agency website at the USDA Rural Development Intermediary Relending Program website:

(1) Certification by the intermediary that:

(i) The ultimate recipient is eligible for the loan;

(ii) The loan is for an eligible purpose;

(iii) Agency IRP loan funds are not more than 75 percent of the total project costs;

(iv) The loan complies with all applicable statutes and regulations;

(v) The ultimate recipient is unable to finance the proposed project through commercial credit or other Federal, State, or local programs at reasonable rates and terms; and

(vi) The intermediary and its principal officers (including immediate family) hold no legal or financial interest or influence in the ultimate recipient, and the ultimate recipient and its principal officers (including immediate family) hold no legal or financial interest or influence in the intermediary. The interest and influence of a cooperative member when the intermediary is a cooperative is an allowable exception to this paragraph.

(2) A completed and executed request for environmental information on a form provided by the Agency for projects that meet the criteria for a NEPA review categorical exclusion, NEPA environmental assessment or NEPA environmental impact statement in accordance with § 4274.305(b)(2).

(3) All comments obtained in accordance with § 4274.305(a) regarding intergovernmental consultation (if required).

(4) Copies of sufficient material from the ultimate recipient's application and the intermediary's related files to allow the Agency to determine the:

(i) Name, address, DUNS number, Federal ID number, and North American Classification System (NAICS) Code of the ultimate recipient;

(ii) Loan purpose;

(iii) Interest rate and term;

(iv) Location, nature, and scope of the project being financed;

(v) Uses and sources of funds; and

(vi) Nature and lien priority of the collateral.

(5) Such other information as the Agency may request.

(b) *Revolved IRP loan funds.* An intermediary may use revolved funds to make loans to ultimate recipients in accordance with § 4274.320(b) without obtaining prior Agency concurrence as required in § 4274.352(a) and are also exempted from completion of items required by paragraphs (a)(2) and (3) of this section.

§ 4274.353–§ 4274.359 [Reserved]

Karama Neal,

Administrator, Rural Business-Cooperative Service.

[FR Doc. 2021–27522 Filed 12–20–21; 8:45 am]

BILLING CODE 3410–XY–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–1065; Project Identifier MCAI–2021–01264–T; Amendment 39–21858; AD 2021–25–14]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A319–111, –112, –113, –114, –115, –131, –132, and –133 airplanes; Model A320–211, –212, –214, –216, –231, –232, and –233 airplanes; and Model A321–111, –112, –131, –211, –212, –213, –231, and –232 airplanes. This AD was prompted by the determination that fatigue cracking may occur at the wing manhole access panel attachment holes at certain wing skin panels on airplanes with Sharklets or its structural reinforcements installed. This AD requires repetitive inspections for

cracking of the area, and corrective action if necessary, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD becomes effective January 5, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 5, 2022.

The FAA must receive comments on this AD by February 4, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

• *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

• *Fax:* 202–493–2251.

• *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–1065.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–1065; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Sanjay Ralhan, Aerospace Engineer,

Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223; email Sanjay.Ralhan@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2021-1065; Project Identifier MCAI-2021-01264-T” at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223; email Sanjay.Ralhan@faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European

Union, has issued EASA AD 2021-0256, dated November 16, 2021 (EASA AD 2021-0256) (also referred to as the MCAI), to correct an unsafe condition for all Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-211, -212, -214, -215, -216, -231, -232, and -233 airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes. Model A320-215 airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this AD therefore does not include those airplanes in the applicability.

This AD was prompted by the determination that fatigue cracking may occur at the left-hand and right-hand wing manhole access panel attachment holes in the bottom wing skin panels 2, between rib 13 and rib 23, on airplanes with Sharklets or its structural reinforcements installed. The FAA is issuing this AD to address this condition, which could lead to crack propagation, possibly resulting in reduced structural integrity of the wings. See the MCAI for additional background information.

Related Service Information Under 1 CFR Part 51

EASA AD 2021-0256 specifies procedures for repetitive detailed visual inspections to detect discrepancies (cracking) of the left-hand and right-hand wing manhole access panel attachment holes in the bottom wing skin panels 2, between rib 13 and rib 23. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI described above. The FAA is issuing this AD after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type designs.

Requirements of This AD

This AD requires accomplishing the actions specified in EASA AD 2021-0256 described previously, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, EASA AD 2021-0256 is incorporated by reference in this AD. This AD requires compliance with EASA AD 2021-0256 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using common terms that are the same as the heading of a particular section in EASA AD 2021-0256 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2021-0256. Service information required by EASA AD 2021-0256 for compliance will be available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1065 after this AD is published.

Interim Action

The FAA considers this AD interim action. If final action is later identified, the FAA might consider further rulemaking then.

FAA’s Justification and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies forgoing notice and comment prior to adoption of this rule because fatigue cracking at the wing

manhole access panel attachment holes in the bottom wing skin panels 2, between rib 13 and rib 23, on airplanes with Sharklets or its structural reinforcements are installed, could lead to crack propagation, possibly resulting in reduced structural integrity of the wings. In addition, the compliance time for the required action is shorter than the time necessary for the public to comment and for publication of the final rule. Accordingly, notice and opportunity for prior public comment

are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b)(3)(B).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forgo notice and comment.

Regulatory Flexibility Act (RFA)

The requirements of the RFA do not apply when an agency finds good cause

pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 1,463 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS *

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
14 work-hours × \$85 per hour = \$1,190	\$0	\$1,190	\$1,740,970 per inspection cycle.

* Table does not include estimated costs for reporting inspection results.

The FAA estimates that it takes 1 work-hour per product to comply with the reporting requirement in this AD. The average labor rate is \$85 per hour. Based on these figures, the FAA estimates the cost of reporting the inspection results on U.S. operators to be \$124,355, or \$85 per product, per inspection cycle.

The FAA has received no definitive data on which to base the cost estimates for the on-condition actions specified in this AD.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a currently valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to take approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021-25-14 Airbus SAS: Amendment 39-21858; Docket No. FAA-2021-1065; Project Identifier MCAI-2021-01264-T.

(a) Effective Date

This airworthiness directive (AD) is effective January 5, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS airplanes identified in paragraphs (c)(1) through (3) of this AD and certificated in any category.

- (1) Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes.
- (2) Model A320-211, -212, -214, -216, -231, -232, and -233 airplanes.
- (3) Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by the determination that fatigue cracking may occur at the left-hand and right-hand wing manhole access panel attachment holes in the bottom wing skin panels 2, between rib 13 and rib 23, on airplanes with Sharklets or its structural reinforcements installed. The FAA is issuing this AD to address this condition, which could lead to crack propagation, possibly resulting in reduced structural integrity of the wings.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021–0256, dated November 16, 2021 (EASA AD 2021–0256).

(h) Exceptions to EASA AD 2021–0256

(1) Where EASA AD 2021–0256 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph (1) of EASA AD 2021–0256 requires “a DET [detailed visual inspection] of the affected areas,” this AD requires a detailed visual inspection to detect discrepancies (cracking) of the affected areas.

(3) Where paragraph (2) of EASA AD 2021–0256 specifies to “contact Airbus for approved instructions and . . . accomplish [the specified] instructions accordingly” if discrepancies are detected, for this AD if any cracking is detected, the cracking must be repaired before further flight using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(4) Paragraph (3) of EASA AD 2021–0256 specifies to report inspection results to Airbus within a certain compliance time. For this AD, report inspection results at the applicable time specified in paragraph (h)(4)(i) or (ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(5) The “Remarks” section of EASA AD 2021–0256 does not apply to this AD.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending

information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (i)(2) of this AD, if any service information referenced in EASA AD 2021–0256 that contains paragraphs that are labeled as RC, the instructions in RC paragraphs, including subparagraphs under an RC paragraph, must be done to comply with this AD; any paragraphs, including subparagraphs under those paragraphs, that are not identified as RC are recommended. The instructions in paragraphs, including subparagraphs under those paragraphs, not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the instructions identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to instructions identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223; email Sanjay.Ralhan@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021–0256, dated November 16, 2021.

(ii) [Reserved]

(3) For EASA AD 2021–0256, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADS@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 3, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–27707 Filed 12–17–21; 11:15 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2021–1064; Project Identifier MCAI–2021–01028–T; Amendment 39–21856; AD 2021–25–12]

RIN 2120–AA64

Airworthiness Directives; De Havilland Aircraft of Canada Limited (Type Certificate Previously Held by Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2017–19–09, which applied to certain De Havilland Aircraft of Canada Limited (Type Certificate Previously Held by Bombardier, Inc.) Model DHC–8–400 series airplanes. AD 2017–19–09 required modifying the nose landing gear (NLG) shock strut assembly. This new AD requires repetitive lubrications of the trailing arm of the NLG. This new AD also requires revising the existing maintenance or inspection program to include new and revised airworthiness limitations (life limits for certain bolts). This AD was prompted by reports of a certain bolt being found missing or having stress corrosion cracking. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 5, 2022.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of January 5, 2022.

The FAA must receive comments on this AD by February 4, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods: