

(c) Applicability

This AD applies to all Airbus SAS airplanes, certificated in any category, identified in paragraphs (c)(1) through (4) of this AD.

- (1) Model A318–111 and –112 airplanes.
- (2) Model A319–111, –112, –113, –114, –115, –131, –132, and –133 airplanes.
- (3) Model A320–211, –212, –214, –216, –231, –232, and –233 airplanes.
- (4) Model A321–111, –112, –131, –211, –212, –213, –231, and –232 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/furnishings.

(e) Reason

This AD was prompted by reports of damaged lower lateral fittings of the 80VU rack, and reports of new damage on airplanes on which certain optional service information had been accomplished. The FAA is issuing this AD to address damage or cracking of the 80VU fittings and supports, which could lead to possible disconnection of the cable harnesses to one or more computers, and if occurring during a critical phase of flight, could result in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021–0172, dated July 20, 2021 (EASA AD 2021–0172).

(h) Exceptions to EASA AD 2021–0172

- (1) Where EASA AD 2021–0172 refers to its effective date, this AD requires using the effective date of this AD.
- (2) The remarks section of EASA AD 2021–0172 does not apply to this AD.
- (3) Where paragraph (3) of EASA AD 2021–0172 specifies “any discrepancy,” for this AD “any discrepancy” includes broken fittings, missing bolts, an electronics rack FIN 80VU that is in contact with structure, any bush that has migrated, burred material, and cracks.

(i) Method of Compliance for Paragraphs (1), (2), and (3) of EASA AD 2021–0172

Accomplishing inspections and correctives actions in accordance with the Accomplishment Instruction of Airbus Service Bulletin A320–25–1BKJ, Revision 02, dated April 9, 2020, with corrections referenced in the Airbus Technical Adaptation 80827186/024/2020, Issue 1, dated September 18, 2020, is an acceptable method of compliance for the inspections and corrective actions specified in paragraphs (1), (2), and (3) of EASA AD 2021–0172.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (j)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(k) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223; email sanjay.ralhan@faa.gov.

(l) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.
 - (i) Airbus Service Bulletin A320–25–1BKJ, Revision 02, dated April 9, 2020.
 - (ii) Airbus Technical Adaptation 80827186/024/2020, Issue 1, dated September 18, 2020.
 - (iii) European Union Aviation Safety Agency (EASA) AD 2021–0172, dated July 20, 2021.
- (3) For EASA AD 2021–0172, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999

000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. For Airbus service information identified in this AD, contact Airbus SAS, Airworthiness Office—ELAS, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; internet <https://www.airbus.com>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 8, 2022.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–05617 Filed 3–21–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2021–1178; Project Identifier MCAI–2021–00986–R; Amendment 39–21986; AD 2022–06–20]

RIN 2120–AA64

Airworthiness Directives; Bell Textron Canada Limited (Type Certificate Previously Held by Bell Helicopter Textron Canada Limited) Helicopters

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2020–20–06, which applied to certain Bell Helicopter Textron Canada Limited (now Bell Textron Canada Limited) Model 429 helicopters. AD 2020–20–06 required repetitive inspections of certain cyclic and collective assembly bearings. This AD was prompted by new bellcrank assemblies, which have been upgraded with corrosion resistant steel bearings. This AD retains certain requirements of AD 2020–20–06, and depending on the inspection results, requires removing certain parts from service and installing the upgraded cyclic and collective bellcrank

assemblies. This AD also requires installing the upgraded collective and cyclic bellcrank assemblies on certain helicopters if not already installed, and prohibits installing certain bellcrank assemblies. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 26, 2022.

ADDRESSES: For service information identified in this final rule, contact Bell Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J 1R4, Canada; telephone 1-450-437-2862 or 1-800-363-8023; fax 1-450-433-0272; email productsupport@bellflight.com; or at <https://www.bellflight.com/support/contact-support>. You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1178; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the Transport Canada AD, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email andrea.jimenez@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2020-20-06, Amendment 39-21262 (85 FR 60356, September 25, 2020) (AD 2020-20-06). AD 2020-20-06 applied to Bell Helicopter Textron Canada Limited Model 429 helicopters with a bellcrank assembly part number (P/N) 429-001-523-101, 429-001-523-103, 429-001-532-101, or 429-001-532-103 installed. The NPRM published in the **Federal Register** on January 14, 2022 (87 FR 2362). In the NPRM, the FAA proposed

to retain some of the requirements of AD 2020-20-06, and proposed to require, for certain serial-numbered helicopters, within 12 months after the helicopter was manufactured or 30 days, whichever occurs later, and thereafter at intervals not to exceed 6 months, disconnecting certain parts, stowing certain parts to prevent binding, and moving the cyclic stick and the collective stick to inspect for roughness in the flight control system and binding in the collective, lateral, and longitudinal arm assemblies. If any of these conditions exist, the NPRM proposed to require, before further flight, removing certain parts from service and installing upgraded bellcrank assemblies.

Additionally, the NPRM proposed to require, for certain serial-numbered helicopters that do not have the upgraded bellcrank assemblies installed, within 24 months, installing the upgraded bellcrank assemblies, which would provide a terminating action for the recurring inspections. Finally, the NPRM proposed to prohibit installing any affected bellcrank assembly on any helicopter.

The NPRM was prompted by Transport Canada AD CF-2016-11R3, dated August 30, 2021 (Transport Canada AD CF-2016-11R3), issued by Transport Canada, which is the aviation authority for Canada, to correct an unsafe condition for Bell Textron Canada Limited Model 429 helicopters, all serial numbers. Transport Canada advises of new collective and cyclic bellcrank assemblies which have been upgraded with corrosion resistant steel bearings. This condition, if not addressed, could result in restrictions in the collective, directional, or pitch control systems, and subsequent loss of helicopter control.

Accordingly, Transport Canada AD CF-2016-11R3 requires for certain serial-numbered helicopters, within 12 months from the helicopter manufacture date, or for helicopters that have exceeded the age threshold of 12 months from the helicopter manufacturer date, within 30 days, and thereafter at intervals not to exceed 6 months, performing a functional check of the flight controls to detect roughness in the pivot bearings and binding of the collective, lateral, or longitudinal arm end bearings of the bellcrank assemblies. If any roughness or binding is detected, Transport Canada AD CF-2016-11R3 requires replacement of each affected bellcrank assembly before further flight. Transport Canada AD CF-2016-11R3 also requires, within 24 months, installing the upgraded collective and cyclic bellcrank

assemblies and considers this action a terminating action to the recurring inspections. Finally, Transport Canada AD CF-2016-11R3 prohibits an affected bellcrank assembly from being installed on any helicopter.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Conclusion

These helicopters have been approved by the aviation authority of Canada and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with Canada, Transport Canada, its technical representative, has notified the FAA of the unsafe condition described in its AD. The FAA reviewed the relevant data, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these helicopters. This AD is adopted as proposed in the NPRM.

Related Service Information

The FAA reviewed Bell Technical Bulletin 429-18-58, Revision B, dated August 23, 2021 (TB 429-18-58 Rev B), which specifies procedures to upgrade certain part-numbered bellcrank assemblies to the bellcrank assemblies that utilize the corrosion resistant steel bearings.

The FAA also reviewed Bell Helicopter Alert Service Bulletin 429-15-21, Revision C, dated August 23, 2021 (ASB 429-15-21 Rev C), which specifies moving the cyclic stick fore, aft, and laterally, and the collective stick up and down from stop to stop to detect deteriorated pivot bearings. ASB 429-15-21 Rev C also specifies inspecting to determine whether the bearings in the collective, lateral, and longitudinal arm assemblies rotate freely. If discrepant arm bearings are found, ASB 429-15-21 Rev C specifies contacting Bell Product Support Engineering to report the findings and replacing the discrepant parts with serviceable parts.

Differences Between This AD and Transport Canada AD CF-2016-11R3

Transport Canada AD CF-2016-11R3 provides requirements if the most recent functional check was performed using a hydraulic test stand as an alternate procedure. This AD provides no such alternate procedure. Transport Canada AD CF-2016-11R3 provides requirements for helicopters that have exceeded the age threshold of 12 months from the helicopter

manufacturer date to complete the initial functional check within 30 days from the effective date of its AD. This AD requires the initial inspection within 12 months after the helicopter was manufactured or 30 days after the effective date of this AD, whichever occurs later. Transport Canada AD CF-2016-11R3 allows credit for the corrective actions of Part I if the initial functional check was accomplished prior to the effective date of Transport Canada AD CF-2016-11R3, whereas this AD does not.

Costs of Compliance

The FAA estimates that this AD affects 64 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this AD.

Inspecting the cyclic and the collective bellcrank assemblies for roughness in the pivot bearings and binding in the collective, lateral, and longitudinal arm end bearings takes about 3 work-hours for an estimated cost of \$255 per inspection cycle.

Installing the upgraded collective and cyclic bellcrank assemblies takes about 18 work-hours and parts cost about \$1,750 for an estimated cost of \$3,280 per upgrade installation.

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order

13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 Amended

- 2. The FAA amends § 39.13 by:
 - a. Removing Airworthiness Directive 2020-20-06, Amendment 39-21262 (85 FR 60356, September 25, 2020); and
 - b. Adding the following new airworthiness directive:

AD 2022-06-20 Bell Textron Canada Limited (Type Certificate Previously Held by Bell Helicopter Textron Canada Limited): Amendment 39-21986; Docket No. FAA-2021-1178; Project Identifier MCAI-2021-00986-R.

(a) Effective Date

This airworthiness directive (AD) is effective April 26, 2022.

(b) Affected ADs

This AD replaces AD 2020-20-06, Amendment 39-21262 (85 FR 60356, September 25, 2020) (AD 2020-20-06).

(c) Applicability

This AD applies to Bell Textron Canada Limited (type certificate previously held by Bell Helicopter Textron Canada Limited) Model 429 helicopters, certificated in any category, with a bellcrank assembly part number (P/N) 429-001-523-101, 429-001-523-103, 429-001-532-101, or 429-001-532-103 installed.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 2700, Flight Control System.

(e) Unsafe Condition

This AD was prompted by new bellcrank assemblies, which have been upgraded with corrosion resistant steel bearings. The FAA is issuing this AD to prevent corrosion of the bearings due to pooling at the bellcrank assembly from precipitation in the forward portion of the roof structure. The unsafe condition, if not addressed, could result in restrictions in the collective, directional, or pitch control systems, and subsequent loss of helicopter control.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For Model 429 helicopters serial number (S/N) 57001 through 57296 inclusive, within 12 months after the helicopter was manufactured or 30 days after the effective date of this AD, whichever occurs later, and thereafter at intervals not to exceed 6 months:

(i) Disconnect the forward ends of the collective control tube, longitudinal stability and control augmentation system (SCAS) actuator, and lateral SCAS actuator. Stow the collective control tube and each SCAS actuator to prevent binding.

(ii) Move the cyclic stick fore, aft, and laterally, and the collective stick up and down from stop to stop to determine if there is any roughness. If there is any roughness in the flight control system, before further flight, remove each pivot bearing P/N MS27646-41, each arm assembly bearing P/N MS27643-4, and each sleeve P/N 120-13-4A from service and install bellcrank assemblies P/N 429-001-523-101FM and 429-001-532-101FM; or 429-001-523-107FM and 429-001-532-107FM; or 429-001-523-107 and 429-001-532-107.

(iii) Inspect the collective arm assembly P/N 429-001-525-101, the lateral arm assembly P/N 429-001-527-101, and the longitudinal arm assembly P/N 429-001-530-101, by rotating each bearing and determining whether each bearing rotates freely. If there is any binding in any arm end bearing or on the longitudinal bellcrank assembly, before further flight, remove each pivot bearing P/N MS27646-41, each arm assembly bearing P/N MS27643-4, and each sleeve P/N 120-13-4A from service and install bellcrank assemblies P/N 429-001-523-101FM and 429-001-532-101FM; or 429-001-523-107FM and 429-001-532-107FM; or 429-001-523-107 and 429-001-532-107.

(2) For Model 429 helicopters S/N 57001 through 57296 inclusive, unless already accomplished by following paragraphs (g)(1)(ii) or (iii) of this AD, within 24 months after the effective date of this AD, install bellcrank assemblies P/N 429-001-523-101FM and 429-001-532-101FM; or 429-001-523-107FM and 429-001-532-107FM; or 429-001-523-107 and 429-001-532-107.

(3) As of the effective date of this AD, installing bellcrank assemblies P/N 429-001-523-101FM and 429-001-532-101FM; or 429-001-523-107FM and 429-001-532-107FM; or 429-001-523-107 and 429-001-

532–107, constitutes a terminating action for the recurring inspections required by paragraph (g)(1) of this AD.

(4) As of the effective date of this AD, do not install any bellcrank assembly P/N 429–001–523–101, 429–001–523–103, 429–001–532–101, or 429–001–532–103 on any helicopter.

(h) Special Flight Permits

Special flight permits are prohibited.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228–7330; email andrea.jimenez@faa.gov.

(2) For service information identified in this AD, contact Bell Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7 1R4, Canada; telephone 1–450–437–2862 or 1–800–363–8023; fax 1–450–433–0272; email productsupport@bellflight.com; or at <https://www.bellflight.com/support/contact-support>. You may view this referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(3) The subject of this AD is addressed in Transport Canada AD CF–2016–11R3, dated August 30, 2021. You may view the Transport Canada AD on the internet at <https://www.regulations.gov> in Docket No. FAA–2021–1178.

(k) Material Incorporated by Reference

None.

Issued on March 10, 2022.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–05664 Filed 3–21–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2021–0816; Airspace Docket No. 21–ANM–27]

RIN 2120–AA66

Modification of Class D and Class E Airspace, and Establishment of Class E Airspace; Southwest Oregon Regional Airport, OR; Correction

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting a final rule that appeared in the **Federal Register** on March 3, 2022. The rule modified the Class D and Class E surface airspace, established Class E airspace designated as an extension to Class D & E surface areas, Class E airspace beginning at 700 feet above the surface, removed navigational aids (NAVAIDs) from text headers, and made administrative changes to the legal descriptions at Southwest Oregon Regional Airport, North Bend, OR. The Final Rule did not explain the purposeful removal of Class E airspace beginning at 1,200 feet above the surface, nor did it properly exclude the Sunnyside Airport cut-out. This action adds verbiage explaining the removal of Class E airspace beginning at 1,200 feet above the surface, and corrects the legal description for the newly established Class E airspace designated as an extension to Class D & E surface areas to properly exclude Sunnyside Airport, OR.

DATES: Effective 0901 UTC, May 19, 2022. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Nathan A. Chaffman, Federal Aviation Administration, Western Service Center, Operations Support Group, 2200 S 216th Street, Des Moines, WA 98198; telephone (206) 231–3460.

SUPPLEMENTARY INFORMATION:

History

The FAA published a final rule in the **Federal Register** (87 FR 11955; March 3, 2022) for Docket FAA–2021–0816, which modified the Class D and Class E surface airspace, established Class E airspace designated as an extension to Class D & E surface areas, modified the Class E airspace beginning at 700 feet

above the surface, removed navigational aids (NAVAIDs) from text headers, and made administrative changes to the legal descriptions at Southwest Oregon Regional Airport, North Bend, OR. Subsequent to publication, the FAA identified that the removal of Class E airspace beginning at 1,200 feet above the surface at the airport was not disclosed. This airspace was removed as it is not needed at Southwest Oregon Regional Airport. The Bend E6 en route domestic airspace area beginning at 1,200 feet above the surface provides sufficient containment to accommodate arriving instrument flight rules (IFR) operations at 1,500 feet and higher above the surface and departing IFR operations from the point they reach 1,200 feet above the surface.

Additionally, it was discovered after publication of the Final Rule that the legal description for the Class E airspace designated as an extension to Class D & E surface areas did not properly exclude the Sunnyside Airport, OR cut-out. This action corrects those errors.

Class D, Class E2, Class E4, and Class E5 airspace designations are published in paragraphs 5000, 6002, 6004, and 6005, respectively, of FAA Order JO 7400.11F, dated August 10, 2021, and effective September 15, 2021, which is incorporated by reference in 14 CFR 71.1. The Class D and Class E airspace designations listed in this document will be published subsequently in FAA Order JO 7400.11.

Correction to Final Rule

Accordingly, pursuant to the authority delegated to me, Amendment of Class D and Class E airspace, and Establishment of Class E airspace; Southwest Oregon Regional Airport, North Bend, OR, published in the **Federal Register** of March 3, 2022 (87 FR 11955), FR Doc. 2022–04326, is corrected as follows:

§ 71.1 [Corrected]

■ 1. On page 11957, in the first column, beginning on line 8, the legal description for ANM OR E4 is corrected to read:

ANM OR E4 North Bend, OR [New]

Southwest Oregon Regional Airport, OR
(Lat. 43°25'01" N, long. 124°14'49" W)
Sunnyside Airport, OR
(Lat. 43°28'59" N, long. 124°12'10" W)

That airspace extending upward from the surface within 3.6 miles north and 3.5 miles south of the 092° bearing from the airport, extending from the Southwest Oregon Regional Airport Class D 4.2-mile radius to 11.7 miles east of the airport, excluding that airspace within a 0.9-mile radius of Sunnyside Airport, and within 2.0 miles southeast and 2.1 miles northwest of the 242°