

of its failure that may accumulate in hazardous quantities within the airplane.

4. Meet the requirements of § 25.863.

5. Not damage surrounding structure or adjacent systems, equipment, or electrical wiring from corrosive fluids or gases that may escape in such a way as to cause a major or more-severe failure condition.

6. Have provisions to prevent any hazardous effect on airplane structure or systems caused by the maximum amount of heat it can generate due to any failure of it or its individual cells.

7. Have a failure sensing and warning system to alert the flight crew if its failure affects safe operation of the airplane.

8. Have a monitoring and warning feature that alerts the flightcrew when its charge state falls below acceptable levels if its function is required for safe operation of the airplane.

9. Have a means to automatically disconnect from its charging source in the event of an over-temperature condition, cell failure or battery failure.

Note: A battery system consists of the battery, battery charger, and any protective monitoring and alerting circuitry or hardware inside or outside of the battery. It also includes vents (where necessary) and packaging. For the purpose of these special conditions, a battery and the battery system is referred to as a battery.

Issued in Kansas City, Missouri, on April 1, 2022.

Patrick R. Mullen,

Manager, Technical Innovation Policy Branch, Policy and Innovation Division, Aircraft Certification Service.

[FR Doc. 2022-07255 Filed 4-5-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0018; Project Identifier MCAI-2021-00853-R; Amendment 39-21997; AD 2022-07-09]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus Helicopters Model AS33L2 and EC225LP helicopters. This AD was prompted by a discrepancy in the

rotorcraft flight manual (RFM) where the rotorcraft stay-up flying capabilities for Category B operation were provided through performance data only, not as airworthiness limitations that are dependent upon on the number of passengers on board. This AD requires revising the existing RFM for your helicopter, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products. **DATES:** This AD is effective May 11, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 11, 2022.

ADDRESSES: For EASA material incorporated by reference (IBR) in this final rule, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0018.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0018; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the EASA AD, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email andrea.jimenez@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

EASA, which is the Technical Agent for the Member States of the European

Union, has issued EASA AD 2021-0174, dated July 21, 2021 (EASA AD 2021-0174), to correct an unsafe condition for Airbus Helicopters, formerly Eurocopter, Eurocopter France, and Aerospatiale, Model AS 332 L2 and EC 225 LP helicopters.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Helicopters Model AS332L2 and EC225LP helicopters. The NPRM published in the **Federal Register** on January 31, 2022 (87 FR 4820). The NPRM was prompted by a discrepancy in the RFM where the rotorcraft stay-up flying capabilities for Category B operation were provided through performance data only, not as airworthiness limitations that are dependent upon on the number of passengers on board. The NPRM proposed to require revising the existing RFM for your helicopter, as specified in EASA AD 2021-0174.

The FAA is issuing this AD to address this discrepancy in the RFM, which, if not addressed, could lead to incorrect determination of the stay-up flying capabilities of the helicopter, resulting in reduced control of the helicopter. See EASA AD 2021-0174 for additional background information.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Conclusion

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its AD. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these helicopters. Except for minor editorial changes, this AD is adopted as proposed in the NPRM.

Related Service Information Under 14 CFR Part 51

EASA AD 2021-0174 requires amending (revising) the Limitation Section of the applicable RFM by incorporating new weight limitations that are dependent upon the number of passengers on board.

This material is reasonably available because the interested parties have access to it through their normal course

of business or by the means identified in the **ADDRESSES** section.

Differences Between This AD and the EASA AD

EASA AD 2021–0174 requires operators to “inform all flight crew” of revisions to the RFM and, thereafter, to “operate the helicopter accordingly.” However, this AD does not specifically require those actions.

14 CFR 91.9 requires that no person may operate a civil aircraft without complying with the operating limitations specified in the RFM. Therefore, including a requirement in this AD to operate the helicopter according to the revised RFM would be redundant and unnecessary. Further, compliance with such a requirement in an AD would be impracticable to demonstrate or track on an ongoing basis; therefore, a requirement to operate the helicopter in such a manner would be unenforceable.

This AD allows the owner/operator (pilot) holding at least a private pilot certificate to revise the existing RFM for your helicopter and do the logbook entry, whereas EASA AD 2021–0174 does not specify this. This AD requires these actions to be entered into the aircraft records showing compliance with this AD in accordance with 14 CFR 43.9(a)(1) through (4) and 14 CFR 91.417(a)(2)(v), and the record to be maintained as required by 14 CFR 91.417 or 135.439.

Costs of Compliance

The FAA estimates that this AD affects 38 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this AD.

Revising the existing RFM for your helicopter takes about 0.50 work-hour for an estimated cost of \$42.50 per helicopter and \$1,615 for the U.S. fleet.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds

necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022–07–09 Airbus Helicopters:

Amendment 39–21997; Docket No. FAA–2022–0018; Project Identifier MCAI–2021–00853–R.

(a) Effective Date

This airworthiness directive (AD) is effective May 11, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus Helicopters Model AS332L2 and EC225LP helicopters, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 7600, Engine Controls.

(e) Unsafe Condition

This AD was prompted by a discrepancy in the rotorcraft flight manual (RFM) where the rotorcraft stay-up flying capabilities for Category B operation were provided through performance data only, not as airworthiness limitations that are dependent upon the number of passengers on board. The FAA is issuing this AD to address this discrepancy in the RFM, which, if not addressed, could lead to incorrect determination of the stay-up flying capabilities of the helicopter, resulting in reduced control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021–0174, dated July 21, 2021 (EASA AD 2021–0174).

(h) Exceptions to EASA AD 2021–0174

(1) Where EASA AD 2021–0174 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph (1) of EASA AD 2021–0174 specifies to “inform all flight crew and, thereafter, operate the helicopter accordingly,” this AD does not require those actions.

(3) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021–0174.

(4) Where paragraph (2) of EASA AD 2021–0174 specifies an acceptable compliance method, replace the text “which includes information of equal effect to that presented” with “which includes information identical to that presented.”

(5) The action required by paragraphs (1) and (2) of EASA AD 2021–0174 may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with 14 CFR 43.9(a)(1) through (4) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417 or 135.439.

(i) Special Flight Permit

Special flight permits may be permitted provided that there are no passengers on board.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email andrea.jimenez@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0174, dated July 21, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0174, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0018.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 31, 2022.

Derek Morgan,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-07174 Filed 4-5-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0008; Project Identifier MCAI-2021-00882-R; Amendment 39-21985; AD 2022-06-19]

RIN 2120-AA64

Airworthiness Directives; Leonardo S.p.a. Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Leonardo S.p.a. Model AW109SP helicopters. This AD was prompted by reports of corrosion inside the hoist support assembly (boom assembly) (affected part) that affects both the huck bolt heads (blind bolt fasteners) and the support surface. This AD requires repetitive inspections of the external and internal surfaces of each affected part for cracking and corrosion and, depending on the findings, accomplishment of corrective actions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective May 11, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 11, 2022.

ADDRESSES: For EASA material incorporated by reference (IBR) in this final rule, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0008.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0008; or in person at Docket Operations between 9 a.m. and 5 p.m.,

Monday through Friday, except Federal holidays. The AD docket contains this final rule, the EASA AD, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email andrea.jimenez@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021-0179, dated July 27, 2021 (EASA AD 2021-0179), to correct an unsafe condition for Leonardo S.p.a. Helicopters, formerly Finmeccanica S.p.A., AgustaWestland S.p.A., and Agusta S.p.A., Model AW109SP helicopters, all serial numbers.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Leonardo S.p.a. Model AW109SP helicopters. The NPRM published in the **Federal Register** on January 21, 2022 (87 FR 3241). The NPRM was prompted by reports of corrosion inside the hoist support assembly affecting both the huck bolt heads and the support surface. Investigation of the root cause for the corrosion is ongoing. The NPRM proposed to require repetitive inspections of the external and internal surfaces of each affected part for cracking and corrosion and, depending on the findings, accomplishment of corrective actions, as specified in EASA AD 2021-0179.

The FAA is issuing this AD to address corrosion on the hoist support assembly. This condition, if not addressed, could affect the structural integrity of the hoist support assembly, leading to in-flight detachment of the hoist support and consequent damage to the helicopter, and injury to hoisted persons. See EASA AD 2021-0179 for additional background information.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.