

contact information will not be publicly viewable except for your first and last names, organization name (if any), and submitter representative name (if any). If your comment is not processed properly because of technical difficulties, DOE will use this information to contact you. If DOE cannot read your comment due to technical difficulties and cannot contact you for clarification, DOE may not be able to consider your comment.

However, your contact information will be publicly viewable if you include it in the comment itself or in any documents attached to your comment. Any information that you do not want to be publicly viewable should not be included in your comment, nor in any document attached to your comment. Otherwise, persons viewing comments will see only first and last names, organization names, correspondence containing comments, and any documents submitted with the comments.

Do not submit to <https://www.regulations.gov> information for which disclosure is restricted by statute, such as trade secrets and commercial or financial information (hereinafter referred to as Confidential Business Information (“CBI”). Comments submitted through <https://www.regulations.gov> cannot be claimed as CBI. Comments received through the website will waive any CBI claims for the information submitted. For information on submitting CBI, see the Confidential Business Information section.

DOE processes submissions made through <https://www.regulations.gov> before posting. Normally, comments will be posted within a few days of being submitted. However, if large volumes of comments are being processed simultaneously, your comment may not be viewable for up to several weeks. Please keep the comment tracking number that <https://www.regulations.gov> provides after you have successfully uploaded your comment.

Submitting comments via email, hand delivery/courier, or postal mail.

Comments and documents submitted via email, hand delivery/courier, or postal mail also will be posted to <https://www.regulations.gov>. If you do not want your personal contact information to be publicly viewable, do not include it in your comment or any accompanying documents. Instead, provide your contact information in a cover letter. Include your first and last names, email address, telephone number, and optional mailing address. The cover letter will not be publicly

viewable as long as it does not include any comments

Include contact information each time you submit comments, data, documents, and other information to DOE. If you submit via postal mail or hand delivery/courier, please provide all items on a CD, if feasible, in which case it is not necessary to submit printed copies. No telefacsimiles (“faxes”) will be accepted.

Comments, data, and other information submitted to DOE electronically should be provided in PDF (preferred), Microsoft Word or Excel, WordPerfect, or text (ASCII) file format. Provide documents that are not secured, that are written in English, and that are free of any defects or viruses. Documents should not contain special characters or any form of encryption and, if possible, they should carry the electronic signature of the author.

Campaign form letters. Please submit campaign form letters by the originating organization in batches of between 50 to 500 form letters per PDF or as one form letter with a list of supporters’ names compiled into one or more PDFs. This reduces comment processing and posting time.

Confidential Business Information. Pursuant to 10 CFR 1004.11, any person submitting information that he or she believes to be confidential and exempt by law from public disclosure should submit via email two well-marked copies: one copy of the document marked “confidential” including all the information believed to be confidential, and one copy of the document marked “non-confidential” with the information believed to be confidential deleted. DOE will make its own determination about the confidential status of the information and treat it according to its determination.

It is DOE’s policy that all comments may be included in the public docket, without change and as received, including any personal information provided in the comments (except information deemed to be exempt from public disclosure).

V. Approval of the Office of the Secretary

The Secretary of Energy has approved publication of this notification of the availability of the preliminary technical support document and request for comment.

Signing Authority

This document of the Department of Energy was signed on June 24, 2022, by Kelly J. Speakes-Backman, Principal Deputy Assistant Secretary for Energy Efficiency and Renewable Energy,

pursuant to delegated authority from the Secretary of Energy. That document with the original signature and date is maintained by DOE. For administrative purposes only, and in compliance with requirements of the Office of the Federal Register, the undersigned DOE Federal Register Liaison Officer has been authorized to sign and submit the document in electronic format for publication, as an official document of the Department of Energy. This administrative process in no way alters the legal effect of this document upon publication in the **Federal Register**.

Signed in Washington, DC, on June 24, 2022.

Treana V. Garrett,

Federal Register Liaison Officer, U.S. Department of Energy.

[FR Doc. 2022–13957 Filed 6–29–22; 8:45 am]

BILLING CODE 6450–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2022–0807; Project Identifier AD–2022–00214–R]

RIN 2120–AA64

Airworthiness Directives; Bell Textron Canada Limited Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2021–26–08, which applies to certain Bell Textron Canada Limited Model 206, 206A, 206A–1, 206B, 206B–1, 206L, 206L–1, 206L–3, and 206L–4 helicopters. AD 2021–26–08 requires removing certain nuts from service; installing newly designed nuts; applying a specific torque, and a torque stripe to each newly installed nut; after the installation of each newly designed nut, inspecting the torque; and depending on the inspection results, either applying a torque stripe, or performing further inspections and removing certain parts from service. AD 2021–26–08 also prohibits installing any affected nut on any tail rotor drive shaft (TRDS) disc pack (Thomas) coupling. Since the FAA issued AD 2021–26–089, the FAA determined certain torque values and part numbers (P/Ns) need to be revised. This proposed AD would require removing certain nuts from service; installing newly designed nuts; applying torque and a torque stripe; and

additional corrective actions if necessary. This proposed AD would also prohibit installing any affected nut on any TRDS Thomas coupling, as specified in a Transport Canada AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by August 15, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For Transport Canada material that is proposed for IBR in this NPRM, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario, K1A 0N5, CANADA; telephone 888-663-3639; email TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca; internet <https://tc.canada.ca/en/aviation>. You may find the Transport Canada material on the Transport Canada website at <https://tc.canada.ca/en/aviation>. For Air Comm Corporation service information identified in this NPRM, contact Air Comm Corporation, 1575 West 124th Ave. #210, Westminster, CO 80234; telephone (303) 440-4075; email service@aircommcorp.com; or at <https://www.aircommcorp.com>. For Bell service information identified in this NPRM, contact Bell Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J 1R4, Canada; telephone 1-450-437-2862 or 1-800-363-8023; fax 1-450-433-0272; email productsupport@bellflight.com; or at <https://www.bellflight.com/support/contact-support>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. The Transport Canada material is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0807.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0807; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the Transport Canada AD, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Matt Fuller, AD Program Manager, General Aviation & Rotorcraft Unit, Airworthiness Products Section, Operational Safety Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email matthew.fuller@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2022-0807; Project Identifier AD-2022-00214-R" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential

under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Matt Fuller, AD Program Manager, General Aviation & Rotorcraft Unit, Airworthiness Products Section, Operational Safety Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email matthew.fuller@faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued AD 2021-26-08, Amendment 39-21867 (86 FR 72833, December 23, 2021) (AD 2021-26-08) for Bell Textron Canada Limited Model 206, 206A, 206A-1, 206B, 206B-1, 206L, 206L-1, 206L-3, and 206L-4 helicopters, with nut P/N MS21042L4 or P/N MS21042L5 installed on the TRDS Thomas couplings. AD 2021-26-08 requires removing certain nuts from service, installing newly designed nuts, and applying a specific torque and a torque stripe to each newly installed nut. AD 2021-26-08 also requires, after the installation of each newly designed nut, inspecting the torque and, depending on the inspection results, either applying a torque stripe or performing further inspections and removing certain parts from service. Finally, AD 2021-26-08 prohibits installing any affected nut on any TRDS Thomas coupling. The FAA issued AD 2021-26-08 to prevent failure or loss of a nut on any TRDS Thomas coupling.

AD 2021-26-08 was prompted by Transport Canada AD CF-2020-15, dated May 13, 2020 (Transport Canada AD CF-2020-15). Transport Canada, which is the aviation authority for Canada, issued Transport Canada AD CF-2020-15 to correct an unsafe condition for Bell Textron Canada Limited Model 206, 206A, 206A-1, 206B, 206B-1, 206L, 206L-1, 206L-3, and 206L-4 helicopters, all serial numbers. Transport Canada AD CF-2020-15 specifies for certain model helicopters, newly designed nuts cannot be installed because Supplemental Type Certificate (STC) SH2750NM and Transport Canada STC SH99-202 install a pulley at the Thomas coupling location causing insufficient clearance. Transport Canada advises, for certain model helicopters with STC SH2750NM or Transport Canada STC SH99-202 installed, different part-numbered nuts may be installed and are now required to be replaced with a new part-numbered nut that is not vulnerable to the unsafe condition.

Actions Since AD 2021–26–08 Was Issued

Since the FAA issued AD 2021–26–08, the FAA determined that certain P/Ns and certain torque values in paragraph (g) of AD 2021–26–08 need to be revised. The FAA advises that the 50–70 in lb torque values are only applicable to certain bolts and nuts, and a 150–180 in lb torque value is required for other bolts and nuts that are required to be installed by this proposed AD. The FAA also advises that certain part-numbered nuts that are required to be installed according to AD 2021–26–08 need to be removed from service and replaced due to a certain pulley configuration.

This proposed AD was prompted by reports of cracked or missing nuts installed on the TRDS Thomas couplings. The FAA is proposing this AD to prevent failure or loss of a nut on the TRDS Thomas couplings, which if not addressed could result in loss of the tail rotor and subsequent loss of control of the helicopter. See Transport Canada AD CF–2020–15 for additional background information.

Related Service Information Under 1 CFR Part 51

Transport Canada AD CF–2020–15 requires the replacement of certain part-numbered nuts with newly designed nuts at each TRDS Thomas coupling and prohibits installing any affected nut on any TRDS Thomas coupling. The replacement includes applying torque, and a torque stripe.

The FAA reviewed Air Comm Corporation Service Bulletin SB 206EC–092619, Revision NC, dated September 26, 2019, which also specifies procedures for replacing the affected nuts with the newly designed corrosion-resistant nuts, but explains that affected helicopters equipped with Air Comm Corporation air conditioning systems installed under STC SH2750NM use the affected nut to attach a pulley onto the TRDS, which causes clearance issues for the nuts to be installed at the coupling. Therefore, this service bulletin specifies replacing the nut with a lower profile nut.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Other Related Service Information

The FAA also reviewed Bell Alert Service Bulletin (ASB) 206–19–136, dated August 27, 2019, for FAA-certificated Model 206, 206A-series, and 206B-series helicopters, and non FAA-

certificated Model TH–67 helicopters; and Bell ASB 206L–19–181, dated August 27, 2019, and Revision A, dated August 29, 2019, for Model 206L, 206L–1, 206L–3, and 206L–4 helicopters. This service information specifies procedures for replacing the affected nuts with the newly designed corrosion-resistant nuts. Revision A of Bell ASB 206L–19–181 corrects a typographical error.

Additionally, the FAA reviewed Bell Service Instruction BHT–206–SI–2052, Revision 1, dated October 14, 2010. This service information specifies procedures to upgrade Model 206L–1 and 206L–3 helicopters to allow operations at an increased internal gross weight.

Differences Between This Proposed AD and Transport Canada AD CF–2020–15

Transport Canada AD CF–2020–15 requires compliance with certain actions within 600 hours air time or within the next 24 months, whichever occurs first, whereas this proposed AD would require compliance within 600 hours time-in-service only. Service information referenced in Transport Canada AD CF–2020–15 specifies if any P/N MS21042L4 nuts are found loose or damaged, reporting the location and providing the information to Bell, whereas this proposed AD would require if any P/N MS21042L4 nuts are found loose or damaged, inspecting each TRDS Thomas coupling, including each bolt, nut, and washer, for any elongated holes, fretting on the fasteners, and damaged fasteners, and depending on the results of the inspection, removing from service each affected part and replacing it with an airworthy part.

FAA’s Determination

These helicopters have been approved by the aviation authority of Canada and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with Canada, Transport Canada, its technical representative, has notified the FAA of the unsafe condition described in its AD. The FAA is proposing this AD after evaluating all known relevant information and determining that the unsafe condition described previously is likely to exist or develop on other helicopters of these same type designs.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in Transport Canada AD CF–2020–15, described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this proposed AD and

except as discussed under “Differences Between this Proposed AD and Transport Canada AD CF–2020–15.”

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate Transport Canada AD CF–2020–15 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with Transport Canada AD CF–2020–15 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in Transport Canada AD CF–2020–15 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “corrective actions,” compliance with this AD requirement is not limited to the section titled “Corrective Actions” in Transport Canada AD CF–2020–15. Service information referenced in Transport Canada AD CF–2020–15 for compliance will be available at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2022–0807 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 1,359 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this proposed AD.

Replacing each affected nut with the newly designed nut and applying torque and a torque stripe would take about 4 work-hours, and parts would cost about \$75 for an estimated cost of \$415 per nut replacement and \$563,985 per nut replacement for the U.S. fleet.

In addition, the costs of the actions that are part of the required replacement are as follows:

If required due to loose or damaged nuts found, inspecting each TRDS Thomas coupling, and each bolt, nut, and washer for elongated holes and fretting on the fasteners would take about 0.5 work-hour for an estimated cost of \$43 per inspection.

If required, replacing each TRDS Thomas coupling would take about 4 work-hours, and parts would cost about \$4,000 for an estimated cost of \$4,340 per TRDS Thomas coupling replacement.

If required, replacing a bolt or washer would take a minimal amount of time and parts would cost a nominal amount.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by:

■ a. Removing Airworthiness Directive 2021–26–08, Amendment 39–21867 (86 FR 72833, December 23, 2021); and

■ b. Adding the following new airworthiness directive:

Bell Textron Canada Limited: Docket No. FAA–2022–0807; Project Identifier AD–2022–00214–R.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by August 15, 2022.

(b) Affected ADs

This AD replaces AD 2021–26–08, Amendment 39–21867 (86 FR 72833, December 23, 2021) (AD 2021–26–08).

(c) Applicability

This AD applies to Bell Textron Canada Limited Model 206, 206A, 206A–1, 206B, 206B–1, 206L, 206L–1, 206L–3, and 206L–4 helicopters, all serial numbers, certificated in any category.

Note 1 to paragraph (c): Helicopters with an OH–58A designation are Model 206A–1 helicopters.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6510, Tail Rotor Drive Shaft.

(e) Unsafe Condition

This AD was prompted by reports of cracked or missing nuts installed on the tail rotor drive shaft (TRDS) disc pack (Thomas) couplings. The FAA is issuing this AD to prevent failure or loss of a nut on the TRDS Thomas couplings. The unsafe condition, if not addressed, could result in loss of the tail rotor and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Transport Canada AD CF–2020–15, dated May 13, 2020 (Transport Canada AD CF–2020–15).

(h) Exceptions to Transport Canada AD CF–2020–15

(1) Where Transport Canada AD CF–2020–15 requires compliance in terms of air time, this AD requires using hours time-in-service (TIS).

(2) Where Transport Canada AD CF–2020–15 refers to the effective dates specified in paragraphs (h)(2)(i) and (ii) of this AD, this

AD requires using the effective date of this AD.

(i) October 9, 2019 (the effective date of Transport Canada AD CF–2019–34, dated September 25, 2019).

(ii) The effective date of Transport Canada AD CF–2020–15.

(3) Where Transport Canada AD CF–2020–15 defines Group 1 helicopters as those models "that have not been modified by installing STC SH2750NM or STC SH99–202," replace "that have not been modified by installing STC SH2750NM or STC SH99–202" with "that have not been modified by installing STC SH2750NM."

(4) Where Transport Canada AD CF–2020–15 defines Group 4 helicopters as those models "that have been modified by installing STC SH2750NM or STC SH99–202," replace "that have been modified by installing STC SH2750NM or STC SH99–202" with "that have been modified by installing STC SH2750NM."

(5) Where Transport Canada AD CF–2020–15 requires compliance within 600 hours air time or 24 months, whichever occurs first, this AD requires compliance within 600 hours TIS only and does not allow a compliance time of 24 months.

(6) Where any paragraph of Transport Canada AD CF–2020–15 specifies to replace part number (P/N) MS21042 nuts with P/N NAS9926 nuts, this AD requires removing P/N MS21042 nuts from service and replacing with P/N NAS9926 nuts.

(7) Where any paragraph of any service information referenced in Transport Canada AD CF–2020–15 specifies to replace P/N MS21042L4 nuts with P/N 90–132L4 nuts, this AD requires removing P/N MS21042L4 nuts from service and replacing with P/N 90–132L4 nuts, in accordance with Air Comm Corporation Service Bulletin SB 206EC–092619, Revision NC, dated September 26, 2019 (SB 206EC–092619 Rev NC).

(8) Where any paragraph of any service information referenced in Transport Canada AD CF–2020–15 specifies to replace P/N MS21042L5 nuts with P/N 90–132L5 nuts, this AD requires removing P/N MS21042L5 nuts from service and replacing with P/N 90–132L5 nuts, in accordance with SB 206EC–092619 Rev NC.

(9) Where any paragraph of any service information referenced in Transport Canada AD CF–2020–15 specifies if any P/N MS21042L4 nuts are found loose or damaged, report at which location and provide the information to Product Support Engineering at productsupport@bellflight.com, this AD requires if any P/N MS21042L4 nuts are found loose or damaged, before further flight, inspecting each TRDS Thomas coupling, including each bolt, nut, and washer, for any elongated holes, fretting on the fasteners, and damaged fasteners. If there is any elongated hole, fretting on the fasteners, or damaged fasteners, this AD requires before further flight, removing from service each affected part and replacing it with an airworthy part.

(i) No Reporting Requirement

Although the service information referenced in Transport Canada AD CF–2020–15 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

(1) For Transport Canada AD CF-2020-15, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario, K1A 0N5, CANADA; telephone 888-663-3639; email TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca; internet <https://tc.canada.ca/en/aviation>. You may find the Transport Canada material on the Transport Canada website at <https://tc.canada.ca/en/aviation>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0807.

(2) For more information about this AD, contact Matt Fuller, AD Program Manager, General Aviation & Rotorcraft Unit, Airworthiness Products Section, Operational Safety Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email matthew.fuller@faa.gov.

(3) For Air Comm Corporation service information identified in this AD, contact Air Comm Corporation, 1575 West 124th Ave. #210, Westminster, CO 80234; telephone (303) 440-4075; email service@aircommcorp.com; or at <https://www.aircommcorp.com>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N 321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

Issued on June 23, 2022.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-13858 Filed 6-29-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2022-0805; Project Identifier MCAI-2021-00951-R]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus Helicopters Model AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters. This proposed AD was prompted by the identification of certain parts needing maintenance actions, including life limits and maintenance tasks. This proposed AD would require incorporating into maintenance records requirements (airworthiness limitations), as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by August 15, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For EASA material that is proposed for IBR in this NPRM, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>. For Airbus Helicopters service information identified in this NPRM, contact Airbus Helicopters, 2701 North Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-

0323; fax (972) 641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. The EASA material is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0805.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0805; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the EASA AD, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Kristi Bradley, Program Manager, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5110; email kristin.bradley@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2022-0805; Project Identifier MCAI-2021-00951-R" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act