

occurs first, replace rudder T-yoke axle part number (P/N) LN 9037–M6x90 with rudder T-yoke axle P/N D60–5320–00–32 in accordance with the Instructions, section III, in Diamond Aircraft Work Instruction WI–RSB 42–139 and WI–RSB 42NG–081, Revision 1, dated October 24, 2019 (issued as one document) attached to Diamond Aircraft Recommended Service Bulletin DAI RSB 42–139 and DAI RSB 42NG–081, dated October 21, 2019.

(2) As of the effective date of this AD, do not install rudder T-yoke axle P/N LN 9037–M6x90 on any airplane.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Additional Information

(1) For more information about this AD, contact Penelope Trease, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 26805 E 68th Avenue, Denver, CO 80249; phone: (303) 342–1094; email: penelope.trease@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2019–0302, dated December 13, 2019, for related information. This EASA AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2021–1070.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Diamond Aircraft Recommended Service Bulletin DAI RSB 42–139 and DAI RSB 42NG–081, dated October 21, 2019 (issued as one document), published with DAI Work Instruction WI–RSB 42–139 and WI–RSB 42NG–081, Revision 1, dated October 24, 2019 (issued as one document) attached.

(ii) [Reserved]

(3) For service information identified in this AD, contact Diamond Aircraft Industries GmbH, N.A. Otto-Straße 5, A–2700 Wiener Neustadt, Austria; phone: +43 2622 26700; fax: +43 2622 26780; email: office@diamond-air.at; website: diamondaircraft.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust,

Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on October 7, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–24370 Filed 11–8–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2022–0982; Project Identifier MCAI–2021–00787–T; Amendment 39–22202; AD 2022–21–03]

RIN 2120–AA64

Airworthiness Directives; Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus Canada Limited Partnership Model BD–500–1A10 and BD–500–1A11 airplanes. This AD was prompted by reports that the engine feed pressure switches were installed with no secondary locking mechanism and can become loose and cause a fuel leak. This AD requires initial and repetitive inspections at the engine feed pressure switch locations and installation of a flange adaptor with lockwire to terminate the repetitive inspections, as specified in a Transport Canada Civil Aviation (TCCA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 14, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 14, 2022.

ADDRESSES:

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2022–0982; or in person at Docket Operations between 9 a.m. and

5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building, Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For material incorporated by reference in this AD, contact TCCA, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888–663–3639; email AD-CN@tc.gc.ca; website tc.canada.ca/en/aviation.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2022–0982.

FOR FURTHER INFORMATION CONTACT:

Joseph Catanzaro, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7366; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus Canada Limited Partnership Model BD–500–1A10 and BD–500–1A11 airplanes. The NPRM published in the **Federal Register** on July 29, 2022 (87 FR 45712). The NPRM was prompted by AD CF–2021–50, dated December 21, 2021, issued by TCCA, which is the aviation authority for Canada (referred to after this as the MCAI). The MCAI states that certain fuel system pressure switches have been installed on the left-hand and right-hand wings without a secondary locking feature (lockwire). This condition may allow the fuel pressure switches to become loose and allow fuel to leak in the affected areas, creating a fire hazard.

In the NPRM, the FAA proposed to require initial and repetitive inspections at the engine feed pressure switch locations and installation of a flange adaptor with lockwire to terminate the repetitive inspections, as specified in TCCA AD CF–2021–50. The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA-2022-0982.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described

in the MCAI referenced above. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Related Service Information Under 1 CFR Part 51

TCCA AD CF-2021-50 specifies procedures for repetitive general visual inspections of the torque identification stripes, torquing of the fuel pressure switches, and installation of lockwire at

the two alternating current (AC) boost pump cartridges; repetitive general visual inspections of the torque identification stripes and torquing of the fuel pressure switches at the two engine feed pressure switches; and installation of a new flange adaptor and lockwire, which terminates the repetitive inspections. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Costs of Compliance

The FAA estimates that this AD affects 60 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

| Labor cost | Parts cost | Cost per product | Cost on U.S. operators |
|---|------------|---------------------|------------------------|
| Up to 27 work-hours × \$85 per hour = \$2,295 | \$811 | Up to \$2,295 | \$137,700 |

The FAA estimates the following costs to do any necessary on-condition actions that would be required based on

the results of any required actions. The FAA has no way of determining the

number of aircraft that might need these on-condition action:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

| Labor cost | Parts cost | Cost per product |
|---|------------|------------------|
| 14 work-hours × \$85 per hour = \$1,190 | \$0 | \$1,190 |

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or

develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022-21-03 Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.): Amendment 39-22202; Docket No. FAA-2022-0982; Project Identifier MCAI-2021-00787-T.

(a) Effective Date

This airworthiness directive (AD) is effective December 14, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Canada Limited Partnership Model BD-500-1A10 and BD-500-1A11 airplanes, certificated in any category, as identified in Transport Canada Civil Aviation (TCCA) AD CF-2021-50, dated December 21, 2021 (TCCA AD CF-2021-50).

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

(e) Unsafe Condition

This AD was prompted by reports that the engine feed pressure switches were installed with no secondary locking mechanism and can become loose and cause a fuel leak. The FAA is issuing this AD to address the absence of a secondary locking feature (lockwire) on the fuel pressure switches, which may allow them to become loose and allow fuel to leak in the affected areas, creating a fire hazard.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, TCCA AD CF-2021-50.

(h) Exception to TCCA AD CF-2021-50

(1) Where TCCA AD CF-2021-50 refers to hours air time, this AD requires using flight hours.

(2) Where TCCA AD CF-2021-50 refers to its effective date, or 14 July 2021, the effective date of TCCA AD CF-2021-21, this AD requires using the effective date of this AD.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or TCCA; or Airbus Canada Limited

Partnership's TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Additional Information

For more information about this AD, contact Joseph Catanzaro, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7366; email 9-avs-nyacos@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Transport Canada Civil Aviation (TCCA) AD CF-2021-50, dated December 21, 2021.

(ii) [Reserved]

(3) For TCCA AD CF-2021-50, contact TCCA, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888-663-3639; email AD-CN@tc.gc.ca; website tc.canada.ca/en/aviation.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on September 28, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-24311 Filed 11-8-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2022-0986; Project Identifier MCAI-2021-01440-T; Amendment 39-22201; AD 2022-21-02]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2000-20-

15, which applied to certain Airbus SAS Model A300 and A300-600 series airplanes. AD 2000-20-15 required a high frequency eddy current (HFEC) inspection to detect cracking of the rear fittings of fuselage frame FR40 at stringer 27, and repetitive inspections or repair, as applicable. In lieu of accomplishing the repetitive inspections, AD 2000-20-15 provided a modification that would allow the inspection to be deferred for a certain period of time. This AD was prompted by cracking of the rear fittings of fuselage frame FR40 at stringer 27, and a determination that reduced compliance times are necessary. This AD removes airplanes from the applicability, and continues to require the actions in AD 2000-20-15, but at reduced compliance times, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 14, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 14, 2022.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2022-0986; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For material incorporated by reference in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this IBR material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at regulations.gov under Docket No. FAA-2022-0986.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, Large