to the manager of the International Validation Branch, mail it to ATTN: Program Manager, Continuing Operational Safety, at the address identified in paragraph (k)(2) of this AD or email to: 9-avs-nyaco-cos@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada or Bombardier, Inc.'s Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

#### (k) Additional Information

- (1) Refer to Transport Canada AD CF–2022–55, dated September 21, 2022, for related information. This Transport Canada AD may be found in the AD docket at regulations.gov under Docket No. FAA–2023–0439.
- (2) For more information about this AD, contact Chirayu Gupta, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email 9-avs-nyaco-cos@faa.gov.
- (3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (1)(3) and (4) of this AD.

# (l) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.
- (i) Bombardier Service Bulletin 100–27–20, Revision 01, dated December 1, 2020.
- (ii) Bombardier Service Bulletin 350–27–009, Revision 01, dated December 1, 2020.
- (3) For service information identified in this AD, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–2999; email ac.yul@aero.bombardier.com; website bombardier.com.
- (4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.
- (5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibrlocations.html.

Issued on June 7, 2023.

#### Ross Landes

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-12934 Filed 6-15-23; 8:45 am]

BILLING CODE 4910-13-P

#### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 39

[Docket No. FAA-2023-0425; Project Identifier MCAI-2022-00980-A; Amendment 39-22458; AD 2023-11-12]

#### RIN 2120-AA64

Airworthiness Directives; DAHER AEROSPACE (Type Certificate Previously Held by SOCATA) Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain DAHER AEROSPACE (type certificate previously held by SOCATA) Model TBM 700 airplanes. This AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as interference between the emergency exit trim panel and the upholstery panel, which could result in additional effort required to open the emergency exit door. This AD requires modification of the gripping strap, which maintains the upholstery panel on the emergency exit trim panel. The FAA is issuing this AD to address the unsafe condition on these products. DATES: This AD is effective July 21, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 21, 2023.

# ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2023–0425; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the MCAI, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For service information identified in this final rule, contact DAHER AEROSPACE, Customer Support, Airplane Business Unit, Tarbes Cedex 9, France 65921; phone: (833) 826–2273; email: tbmcare@daher.com; website: daher.com
- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110. It is also available at regulations.gov under Docket No. FAA–2023–0425.

FOR FURTHER INFORMATION CONTACT: Fred Guerin, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 206–231–2346; email: fred.guerin@faa.gov.

#### SUPPLEMENTARY INFORMATION:

#### **Background**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain DAHER AEROSPACE Model TBM 700 airplanes. The NPRM published in the **Federal Register** on March 8, 2023 (88 FR 14301). The NPRM was prompted by AD 2022–0149, dated July 21, 2022 (referred to after this as "the MCAI"), issued by the European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union.

The MCAI was prompted by a report that, due to interference between the emergency exit trim panel and the upholstery panel, additional effort may be required to open the emergency exit door. An investigation revealed that the gripping strap, which maintains the upholstery panel on the emergency exit trim panel, is not properly sized. The MCAI requires inserting a temporary revision (TR) into the emergency procedures section of the applicable pilot's operating handbook (POH), informing all flight crews, operating the airplane accordingly, and modifying the gripping strap, at which time the TR can be removed from the POH. The unsafe condition, if not addressed, could lead to failure of the emergency exit door to perform its intended function during an emergency opening, possibly resulting in reduced evacuation capacity from the airplane and injury to occupants.

In the NPRM, the FAA proposed to require modification of the gripping strap, which maintains the upholstery panel on the emergency exit trim panel. The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2023–0425.

# Discussion of Final Airworthiness Directive

#### Comments

The FAA received no comments on the NPRM or on the determination of the costs.

#### Conclusion

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM.

# **Related Service Information Under 1 CFR Part 51**

The FAA reviewed Daher Aerospace Service Bulletin SB 70–304, dated July 2022, which specifies procedures for modifying the gripping strap on the emergency exit trim panel.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

# Differences Between This AD and the MCAI

The MCAI requires inserting a TR into the emergency procedures section of the applicable POH, informing all flight crews, and thereafter, operating the airplane accordingly until the modification of the gripping strap, at which time the TR can be removed from the POH. This AD requires modifying the gripping strap because FAA regulations mandate compliance with only the operating limitations section of the POH and not the emergency procedures section.

#### **Costs of Compliance**

The FAA estimates that this AD affects 841 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

#### **ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Modification of the gripping strap	1 work-hour × \$85 per hour = \$85	\$300	\$385	\$323,785

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

# **Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

# Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the

distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866.
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

# PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for Part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2023–11–12 DAHER AEROSPACE (Type Certificate Previously Held by SOCATA): Amendment 39–22458; Docket No. FAA–2023–0425; Project Identifier MCAI–2022–00980–A.

#### (a) Effective Date

This airworthiness directive (AD) is effective July 21, 2023.

# (b) Affected ADs

None.

# (c) Applicability

This AD applies to DAHER AEROSPACE (type certificate previously held by SOCATA) Model TBM 700 airplanes, serial numbers 434 through 1424 inclusive, except serial numbers 1408 and 1420, certificated in any category.

#### (d) Subject

Joint Aircraft System Component (JASC) Code 5220, Emergency Exits.

# (e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as interference between the emergency exit trim panel and the upholstery panel, which could result in additional effort required to open the emergency exit door. The FAA is issuing this AD to address this condition. The unsafe condition, if not addressed, could lead to failure of the emergency exit door to perform its intended function during an emergency opening, resulting in reduced evacuation capacity from the airplane and injury to occupants.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

Within 12 months after the effective date of this AD, modify the gripping strap on the emergency exit trim panel by following, as applicable for your serial-numbered airplane, sections A, B, and C in the Description of Accomplishment Instructions in Daher Aerospace Service Bulletin SB 70-304, dated July 2022 (Daher SB 70-304), except where Daher SB 70-304 specifies to discard certain parts, this AD requires removing those parts from service. If the operational check of the emergency exit fails, before further flight, remodify the gripping strap on the emergency exit trim panel by following, as applicable for your serial-numbered airplane, sections A, B, and C in the Description of Accomplishment Instructions in Daher SB 70-304 until it passes this operational check, except where Daher SB 70-304 specifies to discard certain parts, this AD requires removing those parts

# (h) Alternative Methods of Compliance (AMOCs)

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in § 39.19. In accordance with § 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (i)(2) of this AD or email to: 9-AVS-AIR-730-AMOC@ faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

# (i) Additional Information

- (1) Refer to European Union Aviation Safety Agency (EASA) AD 2022–0149, dated July 21, 2022, for related information. This EASA AD may be found in the AD docket at regulations.gov under Docket No. FAA– 2023–0425.
- (2) For more information about this AD, contact Fred Guerin, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 206–231–2346; email: fred.guerin@faa.gov.

# (j) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.
- (i) Daher Aerospace Service Bulletin SB 70–304, dated July 2022.
  - (ii) [Reserved]
- (3) For service information identified in this AD, contact DAHER AEROSPACE,

Customer Support, Airplane Business Unit, Tarbes Cedex 9, France 65921; phone: (833) 826–2273; email: tbmcare@daher.com; website: daher.com.

- (4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110.
- (5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibrlocations.html.

Issued on June 12, 2023.

#### Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–12914 Filed 6–15–23; 8:45 am]

BILLING CODE 4910-13-P

### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 71

[Docket No. FAA-2023-0503; Airspace Docket No. 23-ASO-07]

RIN 2120-AA66

# Amendment of Class D and Class E Airspace; Huntsville, AL

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

SUMMARY: This action amends the Class D and Class E surface airspace and Class E airspace extending upward from 700 feet above the surface in Huntsville, AL, as the result of a biennial airspace evaluation. This action extends the Class E airspace extending upward from 700 feet above the surface surrounding Redstone Army Airfield (AAF) and Huntsville Executive Tom Sharp Jr. Field. The FAA will also update terminology in the Class D and Class E surface airspace descriptions for Redstone AAF.

**DATES:** Effective date 0901 UTC, October 5, 2023. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

**ADDRESSES:** A copy of the Notice of Proposed Rulemaking (NPRM), all comments received, this final rule, and all background material may be viewed online at *www.regulations.gov* using the FAA Docket number. Electronic

retrieval help and guidelines are available on the website. It is available 24 hours a day, 365 days a year.

FAA Order JO 7400.11G, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at www.faa.gov/air\_traffic/publications/. You may also contact the Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

# FOR FURTHER INFORMATION CONTACT:

Jennifer Ledford, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Ave., College Park, GA 30337; Telephone: (404) 305–5649.

#### SUPPLEMENTARY INFORMATION:

### **Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as controlled airspace is necessary for the safety and management of instrument flight rules (IFR) operations in the area.

#### History

The FAA published a notice of proposed rulemaking for Docket No. FAA 2023–0503 in the **Federal Register** (88 FR 21141; April 10, 2023), amending Class E airspace extending upward from 700 feet above the surface at Redstone AAF and Huntsville Executive Tom Sharp Field in Huntsville, AL. This action also updates terminology in the Class D and Class E surface airspace descriptions for Redstone AAF. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

#### **Incorporation by Reference**

Class D and E airspace designations are published in paragraphs 5000, 6002, and 6005 of FAA Order JO 7400.11, Airspace Designations and Reporting Points, which is incorporated by reference in 14 CFR 71.1 annually. This document amends the current version of