

# Proposed Rules

Federal Register

Vol. 88, No. 132

Wednesday, July 12, 2023

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2023-1404; Project Identifier MCAI-2023-00451-T]

RIN 2120-AA64

#### Airworthiness Directives; Airworthiness Directives; MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.) Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all MHI RJ Aviation ULC Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. This proposed AD was prompted by a report of missing insulation in the engine pylon area. This proposed AD would require, for certain airplanes, inspecting the engine pylon structure for discrepancies and repair if necessary. This proposed AD would also require revising the existing maintenance or inspection program, as applicable, to incorporate a new certification maintenance requirement (CMR) task. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by August 28, 2023.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1404; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

*Material Incorporated by Reference:*

- For service information identified in this NPRM, contact MHI RJ Aviation Group, Customer Response Center, 3655 Ave. des Grandes-Tourelles, Suite 110, Boisbriand, Québec J7H 0E2 Canada; North America toll-free telephone 833-990-7272 or direct-dial telephone 450-990-7272; email: [thd.crj@mhirj.com](mailto:thd.crj@mhirj.com); website: [mhirj.com](https://www.mhirj.com).

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

**FOR FURTHER INFORMATION CONTACT:** Fatin Saumik, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2023-1404; Project Identifier MCAI-2023-00451-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to

[regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

#### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Fatin Saumik, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

#### Background

Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF-2023-19, dated March 13, 2023 (Transport Canada AD CF-2023-19) (also referred to after this as the MCAI), to correct an unsafe condition on all MHI RJ Aviation ULC Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes. The MCAI states there was a report of a missing 12-inch piece of insulation in the 14th stage bleed ducts installed in both left hand (LH) and right hand (RH) engine pylon areas.

The FAA is proposing this AD to address missing insulation in the engine pylon area. The unsafe condition, if not addressed, could result in the bleed duct to radiate heat to the surrounding structure and, if not corrected, could lead to the loss of the structural integrity of the engine pylon and possible loss of the engine. You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1404.

**Related Service Information Under 14 CFR Part 51**

The FAA reviewed MHI RJ Service Bulletin 601R-54-006, Revision A, dated May 24, 2023. This service information specifies procedures for doing a detailed visual inspection of spar FS654.50, spar FS672.20, and the firewall for discrepancies, including corrosion, cracks, web waviness or flatness and damaged fasteners.

The FAA reviewed MHI RJ Temporary Revision 2A-76, dated September 29, 2022. This service information specifies a new or more restrictive CMR task, number C36-12-133-01, "Detailed Visual Inspection for missing insulation/heat shield on the 14th stage bleed duct, running through the pylon area between FS654 and FS672."

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**FAA's Determination**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the

FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

**Proposed AD Requirements in This NPRM**

This proposed AD would require, for certain airplanes, inspecting the engine pylon structure for discrepancies and repair if necessary. This proposed AD would also require revising the existing maintenance or inspection program, as applicable, to incorporate a new CMR task.

This proposed AD would require revisions to certain operator maintenance documents to include new actions (e.g., inspections). Compliance with these actions is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this proposed AD, the operator may not be able to accomplish the actions described in the

revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (k)(1) of this proposed AD.

**Differences Between This NPRM and the MCAI or Service Information**

Part I of the Transport Canada AD does not include a corrective action requirement for the inspection of the spars and firewall specified in MHI RJ Service Bulletin 601R-54-006, Revision A, dated May 24, 2023. Paragraph 3.B.(2) of MHI RJ Service Bulletin 601R-54-006, Revision A, dated May 24, 2023, only specifies contacting the manufacturer and that the manufacturer will provide additional action. Therefore, this proposed AD specifies that corrective actions must be done if any discrepancies are found during the inspection required by paragraph (g) of the proposed AD.

**Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 338 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS \*

| Labor cost                                 | Parts cost | Cost per product | Cost on U.S. operators |
|--|------------|------------------|------------------------|
| 6 work-hours × \$85 per hour = \$510 ..... | \$0        | \$510            | \$172,380              |

\* This table does not include the cost of revising the existing maintenance or inspection program.

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, the agency estimates the average total cost per operator to be \$7,650 (90 work-hours × \$85 per work-hour).

The FAA has received no definitive data on which to base the cost estimates for the on-condition repairs specified in this proposed AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more

detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.):**  
Docket No. FAA–2023–1404; Project Identifier MCAI–2023–00451–T.

#### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by August 28, 2023.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all MHI RJ Aviation ULC (Type Certificate previously held by Bombardier, Inc.) Model CL–600–2B19 (Regional Jet Series 100 & 440) airplanes, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code: 36, Pneumatic.

#### (e) Unsafe Condition

This AD was prompted by a report of missing insulation in the engine pylon area. The FAA is issuing this AD to address missing insulation in the engine pylon area. The unsafe condition, if not addressed, could result in the bleed duct to radiate heat to the surrounding structure and, if not corrected, could lead to the loss of the structural integrity of the engine pylon and possible loss of the engine.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Detailed Visual Inspection

For airplanes having serial numbers 7031, 7045, 7069, 7078, 7089, 7102, 7110, 7168, 7188, 7203, 7212, 7217, 7229, 7231, 7236, 7243, 7257, 7258, 7269, 7271, 7276, 7284, 7290, 7302, 7304, 7306, 7310, 7328, 7339, 7342, 7355, 7358, 7360, 7401, 7404, 7437, 7441, 7448, 7458, 7474, 7476, 7479, 7495, 7502, 7503, 7517, 7527, 7530, 7532, 7548, 7551, 7574, 7575, 7579, 7582, 7586, 7588, 7599, 7600, 7606, 7609, 7623, 7632, 7648, 7657, 7658, 7664, 7667, 7674, 7681, 7682, 7683, 7687, 7715, 7727, 7743, 7748, 7749, 7750, 7758, 7760, 7769, 7780, 7810, 7817, 7818, 7821, 7822, 7857, 7859, 7871, 7873, 7889, 7892, 7895, 7909, 7912, 7913, 7920, 7922, 7923, 7926, 7929, 7932, 7935, 7937, 7954, 7961, 7964, and 8011: Within 48 months or 6,600 flight hours, whichever occurs first after the effective date of this AD, do a detailed visual inspection for discrepancies of spar FS654.50, spar FS672.20, and the firewall, in accordance

with Section 2.B. of the Accomplishment Instructions of MHI RJ Service Bulletin 601R–54–006, Revision A, dated May 24, 2023. If any discrepancies are found, before further flight, repair using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada or MHI RJ Aviation ULC's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

#### (h) Maintenance or Inspection Program Revision

Within 60 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in MHI RJ Temporary Revision 2A–76, dated September 29, 2022, for certification maintenance requirements task number C36–12–133–01. The initial compliance time for doing the task is within 48 months or 6,600 flight hours, whichever occurs first after the effective date of this AD.

#### (i) No Alternative Actions or Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (h) of this AD, no alternative actions (*e.g.*, inspections) or intervals may be used unless the actions and intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (k)(1) of this AD.

#### (j) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using MHI RJ Service Bulletin 601R–54–006, dated September 13, 2022.

#### (k) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager, International Validation Branch, mail it to the address identified in paragraph (l)(2) of this AD or email to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada or MHI RJ Aviation ULC's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

#### (l) Additional Information

(1) Refer to Transport Canada AD CF–2023–19, dated March 13, 2023, for related information. This Transport Canada AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–1404.

(2) For more information about this AD, contact Fatin Saumik, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

#### (m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) MHI RJ Service Bulletin 601R–54–006, Revision A, dated May 24, 2023.

(ii) MHI RJ Temporary Revision 2A–76, dated September 29, 2022.

(3) For service information identified in this AD, contact MHI RJ Aviation Group, Customer Response Center, 3655 Ave. des Grandes-Tourelles, Suite 110, Boisbriand, Québec J7H 0E2 Canada; North America toll-free telephone 833–990–7272 or direct-dial telephone 450–990–7272; email: [thd.crj@mhirj.com](mailto:thd.crj@mhirj.com); website: [mhirj.com](http://mhirj.com).

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: [www.archives.gov/federal-register/cfr/ibr-locations.html](http://www.archives.gov/federal-register/cfr/ibr-locations.html).

Issued on July 6, 2023.

**Michael Linegang,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2023–14616 Filed 7–11–23; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2023–1405; Project Identifier MCAI–2023–00381–T]

RIN 2120–AA64

#### Airworthiness Directives; Dassault Aviation Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).