

- a. Removing Airworthiness Directive (AD) 2021–09–06, Amendment 39–21519 (86 FR 23595, May 4, 2021), and
- b. Adding the following new AD:

**The Boeing Company:** Docket No. FAA–2024–0028; Project Identifier AD–2023–00919–T.

**(a) Comments Due Date**

The FAA must receive comments on this airworthiness directive (AD) by March 1, 2024.

**(b) Affected ADs**

This AD replaces AD 2021–09–06, Amendment 39–21519 (86 FR 23595, May 4, 2021) (AD 2021–09–06).

**(c) Applicability**

This AD applies to all The Boeing Company Model 737–600, –700, –700C, –800, –900, and –900ER series airplanes, certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 53, Fuselage.

**(e) Unsafe Condition**

This AD was prompted by reports of cracking in the station (STA) 663.75 frame fitting outboard chords and failsafe straps adjacent to the stringer S–18A area and a determination that additional inspections are needed to address the unsafe condition. The FAA is issuing this AD to address cracking in the STA 663.75 frame fitting outboard chords and failsafe straps adjacent to the stringer S–18A straps, which could result in failure of a Principal Structural Element (PSE) to sustain limit load. The unsafe condition, if not addressed, could adversely affect the structural integrity of the airplane and result in loss of control of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737–53A1414 RB, Revision 1, dated November 20, 2023, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737–53A1414 RB, Revision 1, dated November 20, 2023.

**Note 1 to paragraph (g):** Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737–53A1414, Revision 1, dated November 20, 2023, which is referred to in Boeing Alert Requirements Bulletin 737–53A1414 RB, Revision 1, dated November 20, 2023.

**(h) Exceptions to Service Information Specifications**

(1) Where the Condition and Compliance Time columns of the tables in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737–53A1414 RB,

Revision 1, dated November 20, 2023, use the phrase “the original issue date of Requirements Bulletin 737–53A1414 RB,” or “the Revision 1 date of Requirements Bulletin 737–53A1414 RB,” this AD requires using “the effective date of this AD.”

(2) Where Boeing Alert Requirements Bulletin 737–53A1414 RB, Revision 1, dated November 20, 2023, specifies contacting Boeing for repair instructions: This AD requires doing the repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR–520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

**(j) Related Information**

(1) For more information about this AD, contact Owen Bley-Male, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3992; email [owen.f.bley-male@faa.gov](mailto:owen.f.bley-male@faa.gov).

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (4) of this AD.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 737–53A1414 RB, Revision 1, dated November 20, 2023.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600;

telephone 562–797–1717; website [myboeingfleet.com](http://myboeingfleet.com).

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on January 5, 2024.

**Victor Wicklund,**

*Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2024–00345 Filed 1–12–24; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA–2024–0031; Project Identifier MCAI–2022–01307–T]**

**RIN 2120–AA64**

**Airworthiness Directives; MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.) Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain MHI RJ Aviation ULC Model CL–600–2C10 (Regional Jet Series 700, 701 & 702); CL–600–2C11 (Regional Jet Series 550); CL–600–2D15 (Regional Jet Series 705); and CL–600–2D24 (Regional Jet Series 900) airplanes. This proposed AD was prompted by a determination that a potential crack of the tombstone fitting lug cannot be detected as the bushings remaining in place during accomplishment of the special detailed inspection (SDI) required by a certain airworthiness limitation (ALI) task. This proposed AD would require inspecting the tombstone fitting lug with a new SDI sub-surface ultrasound procedure when accomplishing the ALI task, as specified in a Transport Canada AD, which is proposed for incorporation by reference (IBR). This proposed AD would also require corrective actions if necessary. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by March 1, 2024.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at *regulations.gov* under Docket No. FAA-2024-0031; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

*Material Incorporated by Reference:*

- For material that is proposed for IBR in this AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888-663-3639; email *TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca*. You may find this material on the Transport Canada website at *tc.canada.ca/en/aviation*. It is also available at *regulations.gov* under Docket No. FAA-2024-0031.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

**FOR FURTHER INFORMATION CONTACT:** Yaser Osman, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email *9-avs-nyaco-cos@faa.gov*.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2024-0031; Project Identifier MCAI-2022-01307-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include

supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

##### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Yaser Osman, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email *9-avs-nyaco-cos@faa.gov*. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

##### Background

Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF-2022-54R1, dated October 4, 2022 (Transport Canada AD CF-2022-54R1) (also referred to after this as the MCAI), to correct an unsafe condition for certain MHI RJ Aviation ULC Model CL-600-2C10 (Regional Jet Series 700, 701 & 702); CL-600-2C11 (Regional Jet Series 550); CL-600-2D15 (Regional Jet Series 705); and CL-600-2D24 (Regional Jet Series 900) airplanes. Transport Canada AD CF-2022-54R1 superseded Transport Canada AD CF-2022-54, dated September 13, 2022 (Transport Canada AD CF-2022-54), to correct a reference to an incorrect maintenance requirements manual number.

Transport Canada AD CF-2022-54R1 states that MHI RJ discovered that the

MHI RJ Non-Destructive Testing Manual (NDTM) Part 6, Procedure 53-61-121-250, associated with ALI Task 53-61-121, is not adequate to detect a potential crack of the tombstone fitting lug before the critical crack size is reached as the bushings remain in place during the SDI. Transport Canada AD CF-2022-54R1 mandates the use of new ultrasonic MHI RJ NDTM Part 4, Procedure 53-61-121-270, in conjunction with NDTM Part 6, Procedure 53-61-121-250, during accomplishment of the SDIs required by ALI Task 53-61-121.

The FAA is proposing this AD to address the undetected cracking of the tombstone fitting lug. If the crack is not detected, the tombstone fitting lug will eventually fail. The failure will cause a transfer of load to other engine attachment points, which will then be overloaded and compromised in their structural integrity. This can lead to a rapid failure mode, potentially resulting in the loss of the engine. You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA-2024-0031.

##### Related Service Information Under 1 CFR Part 51

Transport Canada AD CF-2022-54R1 specifies procedures for accomplishing a special detailed inspection for cracks of the engine forward support frame’s tombstone top and bottom fitting lugs at frame fuselage station (FS) 1051.30, during the accomplishment of the SDIs required by ALI Task 53-61-121. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in

##### ADDRESSES.

##### FAA’s Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

##### Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in Transport Canada AD CF-2022-54R1 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD,

and except as discussed under “Difference Between this Proposed AD and the MCAI.”

**Explanation of Required Compliance Information**

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and

CAAs. As a result, the FAA proposes to incorporate Transport Canada AD CF–2022–54R1 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with Transport Canada AD CF–2022–54R1 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Service information required by Transport Canada AD CF–2022–54R1 for compliance will be available at regulations.gov under Docket No. FAA–2024–0031 after the FAA final rule is published.

**Difference Between This NPRM and the MCAI**

Transport Canada AD CF–2022–54R1 did not specify any corrective action for cracking found during the required inspection. This proposed AD would require repairing all cracks before further flight.

**Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 597 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
2 work-hours × \$85 per hour = \$170 (per interval) .....	\$0	\$170 (per interval) .....	\$101,490 (per interval).

The FAA has received no definitive data on which to base the cost estimates for the repairs specified in this proposed AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.):**  
Docket No. FAA–2024–0031; Project Identifier MCAI–2022–01307–T.

**(a) Comments Due Date**

The FAA must receive comments on this airworthiness directive (AD) by March 1, 2024.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.) Model CL–600–2C10 (Regional Jet Series 700, 701 & 702); CL–600–

2C11 (Regional Jet Series 550); CL–600–2D15 (Regional Jet Series 705); and CL–600–2D24 (Regional Jet Series 900) airplanes, certificated in any category, as identified in Transport Canada AD CF–2022–54R1, dated October 4, 2022 (Transport Canada AD CF–2022–54R1).

**(d) Subject**

Air Transport Association (ATA) of America 53, Fuselage.

**(e) Unsafe Condition**

This AD was prompted by a determination that the MHI RJ Non-Destructive Testing Manual (NDTM) Part 6, Procedure 53–61–121–250, associated with Airworthiness Limitations (ALI) Task 53–61–121, is not adequate to detect a potential crack of the tombstone fitting lug as the bushings remain in place during the special detailed inspection (SDI). The FAA is issuing this AD to address the undetected cracking of the tombstone fitting lug. If the crack is not detected, the tombstone fitting lug will eventually fail. The failure will cause a transfer of load to other engine attachment points, which will then be overloaded and compromised in their structural integrity. This can lead to a rapid failure mode, potentially resulting in the loss of the engine.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as required by paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Transport Canada CF–2022–54R1.

**(h) Exceptions to Transport Canada CF–2022–54R1**

(1) Where Transport Canada AD CF–2022–54R1 refers to the effective date of AD CF–2022–54 (September 27, 2022), this AD requires using the effective date of this AD.

(2) Where paragraph A. of Transport Canada AD CF-2022-54R1 specifies inspecting “For aeroplanes that, as of the effective date of AD CF-2022-54 (27 September 2022), have not been inspected as required by MRM CSP B-053 Part 2 ALI Task 53-61-121,” this AD requires replacing those words with “For all airplanes.”

(3) This AD does not adopt paragraph B. of Transport Canada AD CF-2022-54R1.

(4) Where paragraph A. of Transport Canada AD CF-2022-54R1 specifies inspecting “within the intervals in MRM CSP B-053 Part 2 for ALI Task 53-61-121,” for this AD, the initial compliance time for the task is within the “threshold” specified in the service information identified in paragraph A. Transport Canada AD CF-2022-54R1 or within 90 days after the effective date of this AD, whichever occurs later.

#### (i) Crack Repair

If any cracking is found during the actions required by paragraph (g) of this AD, repair the cracking before further flight using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada; or MHI RJ Aviation ULC's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DOA-authorized signature.

#### (j) No Reporting Requirement

Although the service information referenced in Transport Canada AD CF-2022-54R1 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

#### (k) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (l) of this AD. Information may be emailed to: [9-AVS-NYACO-COS@faa.gov](mailto:9-AVS-NYACO-COS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada; or MHI RJ Aviation ULC's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

#### (l) Additional Information

For more information about this AD, contact Yaser Osman, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite

410, Westbury, NY 11590; telephone 516-228-7300; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

#### (m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Transport Canada AD CF-2022-54R1, dated October 4, 2022.

(ii) [Reserved]

(3) For Transport Canada AD CF-2022-54R1, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888-663-3639; email [TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca](mailto:TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca). You may find this Transport Canada AD on the Transport Canada website at [tc.canada.ca/en/aviation](http://tc.canada.ca/en/aviation).

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on January 6, 2024.

**Caitlin Locke,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2024-00493 Filed 1-12-24; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2023-2482; Airspace Docket No. 23-AAL-26]

RIN 2120-AA66

#### Modification of Class E Airspace; Edward G. Pitka Sr. Airport, Galena, AK

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to modify the Class E airspace designated as a surface area and modify the Class E airspace extending upward from 700 feet above the surface at Edward G. Pitka Sr. Airport, Galena, AK. Additionally, this action proposes administrative amendments to update the airport's geographic coordinates in

the legal description to match the FAA database. These actions would support the safety and management of instrument flight rules (IFR) operations at the airport.

**DATES:** Comments must be received on or before March 1, 2024.

**ADDRESSES:** Send comments identified by FAA Docket No. FAA-2023-2482 and Airspace Docket No. 23-AAL-26 using any of the following methods:

\* *Federal eRulemaking Portal:* Go to [www.regulations.gov](http://www.regulations.gov) and follow the online instructions for sending your comments electronically.

\* *Mail:* Send comments to Docket Operations, M-30; U.S. Department of Transportation, 1200 New Jersey Avenue SE, Room W12-140, West Building Ground Floor, Washington, DC 20590-0001.

\* *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

\* *Fax:* Fax comments to Docket Operations at (202) 493-2251.

*Docket:* Background documents or comments received may be read at [www.regulations.gov](http://www.regulations.gov) at any time. Follow the online instructions for accessing the docket or go to the Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FAA Order JO 7400.11H, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). You may also contact the Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

**FOR FURTHER INFORMATION CONTACT:** Keith T. Adams, Federal Aviation Administration, Western Service Center, Operations Support Group, 2200 S 216th Street, Des Moines, WA 98198; telephone (206) 231-2428.

#### SUPPLEMENTARY INFORMATION:

##### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority