

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

(1) Within 125 flight cycles (FCs) after the effective date of this AD and thereafter at intervals not to exceed 125 FCs, calculate the NSV data in accordance with the Accomplishment Instructions, paragraphs 5.A.(1) and 5.A.(3), or 5.B.(1) and 5.B.(3) of CFM SB LEAP-1A-72-00-0504-01A-930A-D, Issue 002.

(2) If, during any calculation required by paragraph (g)(1) of this AD, the NSV data exceeds the limits specified in the Accomplishment Instructions, paragraph 5.A.(4)(a)1 or 5.B.(4)(a)1 of CFM SB LEAP-1A-72-00-0504-01A-930A-D, Issue 002, discontinue the calculations required by paragraph (g)(1) of this AD and within 150 FCs of the flight when these limits are exceeded:

(i) Remove from service the No. 3 bearing spring finger housing having P/N 2629M62G01 and a serial number identified in Table 1 or Table 2 of CFM SB LEAP-1A-72-00-0504-01A-930A-D, Issue 002, and replace with a part eligible for installation.

(ii) Inspect the stage 2 high-pressure turbine (HPT) nozzle assembly honeycomb for rubs in accordance with the Accomplishment Instructions, paragraphs 5.A.(4)(a)3b1 or 5.B.(4)(a)3b1 of CFM SB LEAP-1A-72-00-0504-01A-930A-D, Issue 002.

(iii) Inspect the HPT stator stationary seal honeycomb for rubs in accordance with the Accomplishment Instructions, paragraphs 5.A.(4)(a)3b2 or 5.B.(4)(a)3b2 of CFM SB LEAP-1A-72-00-0504-01A-930A-D, Issue 002.

(3) If, during the inspection required by paragraph (g)(2)(ii) of this AD, the stage 2 HPT nozzle assembly honeycomb fails to meet the serviceability criteria referenced in the Accomplishment Instructions, paragraphs 5.A.(4)(a)3b1 or 5.B.(4)(a)3b1 of CFM SB LEAP-1A-72-00-0504-01A-930A-D, Issue 002, before further flight, replace the stage 2 HPT nozzle assembly honeycomb.

(4) If, during the inspection required by paragraph (g)(2)(iii) of this AD, the HPT stator stationary seal honeycomb fails to meet the serviceability criteria referenced in the Accomplishment Instructions, paragraphs 5.A.(4)(a)3b2 or 5.B.(4)(a)3b2 of CFM SB LEAP-1A-72-00-0504-01A-930A-D, Issue 002, before further flight, replace the HPT stator stationary seal.

(5) At the next piece-part exposure after the effective date of this AD, but before exceeding 9,900 cycles since new, replace the No. 3 bearing spring finger housing having P/N 2629M62G01 and a serial number identified in Table 1 of CFM SB LEAP-1A-72-00-0504-01A-930A-D, Issue 002, with a part eligible for installation.

**(h) Terminating Action**

Replacement of the No. 3 bearing spring finger housing having P/N 2629M62G01 and a serial number identified in Table 1 or Table 2 of CFM SB LEAP-1A-72-00-0504-01A-930A-D, Issue 002 with a part eligible for

installation, as specified in paragraphs (g)(2)(i) and (g)(5) of this AD, constitutes terminating action for the calculations required by paragraph (g)(1) of this AD.

**(i) Definition**

For the purpose of this AD, a “part eligible for installation” is a No. 3 bearing spring finger housing that does not have P/N 2629M62G01 and a serial number identified in Table 1 or Table 2 of CFM SB LEAP-1A-72-00-0504-01A-930A-D, Issue 002.

**(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, AIR-520 Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the Manager, AIR-520 Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (k) of this AD and email it to: [ANE-AD-AMOC@faa.gov](mailto:ANE-AD-AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) For service information that contains steps that are labeled as Required for Compliance (RC), the following provisions apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, that are required by paragraph (g) of this AD must be done to comply with this AD. An AMOC is required for any deviations to RC steps required by paragraph (g) of this AD, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

**(k) Additional Information**

For more information about this AD, Mehdi Lamnyi, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (781) 238-7743; email: [mehdi.lamnyi@faa.gov](mailto:mehdi.lamnyi@faa.gov).

**(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) CFM International, S.A. Service Bulletin LEAP-1A-72-00-0504-01A-930A-D, Issue 002, dated October 17, 2023.

(ii) [Reserved]

(3) For service information, contact CFM International, S.A., GE Aviation Fleet Support, 1 Neumann Way, M/D Room 285,

Cincinnati, OH 45215; phone: (877) 432-3272; email: [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com).

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locationsoremailfr.inspection@nara.gov](http://www.archives.gov/federal-register/cfr/ibr-locationsoremailfr.inspection@nara.gov).

Issued on March 29, 2024.

**Victor Wicklund,**

*Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2024-09110 Filed 4-26-24; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2024-0771; Project Identifier AD-2023-01251-E; Amendment 39-22720; AD 2024-06-15]**

**RIN 2120-AA64**

**Airworthiness Directives; General Electric Company Engines**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain General Electric Company (GE) Model GE90-110B1 and GE90-115B engines. This AD was prompted by a report of an aborted takeoff due to left engine failure caused by liberation of the interstage high-pressure turbine (HPT) rotor seal rim. This AD requires repetitive ultrasonic inspections (USIs) of the interstage HPT rotor seal for cracks and removal from service if necessary. As a mandatory terminating action to the repetitive USIs of the interstage HPT rotor seal, this AD also requires replacement of the interstage HPT rotor seal. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective May 14, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 14, 2024.

The FAA must receive comments on this AD by June 13, 2024.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR

11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal*: Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax*: (202) 493-2251.

- *Mail*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery*: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket*: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-0771; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The street address for Docket Operations is listed above.

*Material Incorporated by Reference*:

- For service information identified in this final rule, contact General Electric Company, 1 Neumann Way, Cincinnati, OH 45215; phone: (513) 552-3272; email: [aviation.fleetsupport@ae.ge.com](mailto:aviation.fleetsupport@ae.ge.com); website: [ge.com](https://www.ge.com).

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-0771.

**FOR FURTHER INFORMATION CONTACT:** Alexander Thickstun, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (202) 267-8292; email: [alexander.m.thickstun@faa.gov](mailto:alexander.m.thickstun@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under **ADDRESSES**. Include “FAA-2024-0771 Project Identifier AD-2023-01251-E” at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR

11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

**Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Alexander Thickstun, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Background**

On October 19, 2019, a The Boeing Company Model 777 airplane, powered by GE Model GE90-115B engines, experienced an engine failure, which resulted in an aborted takeoff. A manufacturer investigation determined that the engine failure was caused by rim liberation of the interstage HPT rotor seal. Additional root cause analysis determined that rim liberation was the result of high cycle fatigue cracks initiating at the interstage seal web holes occurring from atypical intermittent operating conditions with short durations. As a result, the FAA issued Emergency AD 2019-21-51, Amendment 39-19798 (84 FR 64195, November 21, 2019) for certain GE GE90-115B model turbofan engines; Emergency AD 2020-01-55, Amendment 39-19838 (85 FR 8386, February 14, 2020) for certain GE GE90-115B model turbofan engines; and AD 2020-10-04, Amendment 39-21122 (85 FR 27909, May 12, 2020) for all GE GE90-110B1 and GE90-115B model turbofan engines with a certain interstage HPT rotor seal installed to remove affected parts from engines that had accumulated high flight cycles (FCs). Since the FAA issued those three ADs, the affected engines have

continued to accumulate FCs, and the manufacturer has identified additional parts for inspection and removal. This condition, if not addressed, could result in uncontained HPT failure, release of high-energy debris, damage to the engine, damage to the airplane, and possible loss of the airplane. The FAA is issuing this AD to address the unsafe condition on these products.

**FAA’s Determination**

The FAA is issuing this AD because the agency has determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

**Related Service Information Under 1 CFR Part 51**

The FAA reviewed GE GE90-100 Service Bulletin (SB) 72-0908 R00, dated July 7, 2023. The SB specifies procedures for performing a USI of the interstage HPT rotor seal. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

**AD Requirements**

This AD requires repetitive USIs of the interstage HPT rotor seal for cracks and removal from service if necessary. As a mandatory terminating action to the repetitive USIs of the interstage HPT rotor seal, this AD requires replacement of the interstage HPT rotor seal.

**Interim Action**

The FAA considers this AD to be an interim action. The unsafe condition is still under investigation by the manufacturer and, depending on the results of that investigation, the FAA may consider further rulemaking action.

**Justification for Immediate Adoption and Determination of the Effective Date**

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

The FAA justifies waiving notice and comment prior to adoption of this rule because no domestic operators use this

product. It is unlikely that the FAA will receive any adverse comments or useful information about this AD from any U.S. operator. Accordingly, notice and opportunity for prior public comment are unnecessary, pursuant to 5 U.S.C. 553(b)(3)(B). In addition, for the foregoing reason(s), the FAA finds that good cause exists pursuant to 5 U.S.C.

553(d) for making this amendment effective in less than 30 days.

**Regulatory Flexibility Act**

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because FAA has determined that it has good cause to

adopt this rule without prior notice and comment, RFA analysis is not required.

**Costs of Compliance**

The FAA estimates that this AD affects 0 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Remove interstage HPT rotor seal .....	100 work-hours × \$85 per hour = \$8,500 .....	\$540,000	\$548,500	\$0
Perform USI of interstage HPT rotor seal .....	2 work-hours × \$85 per hour = \$170 .....	0	170	0

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2024–06–15 General Electric Company:**  
Amendment 39–22720; Docket No. FAA–2024–0771; Project Identifier AD–2023–01251–E.

**(a) Effective Date**

This airworthiness directive (AD) is effective May 14, 2024.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to General Electric Company (GE) Model GE90–110B1 and GE90–115B engines with an installed interstage high-pressure turbine (HPT) rotor seal having a part number and serial number listed in Table 1 or Table 2 of GE GE90–100 Service Bulletin (SB) 72–A0908 R00, dated July 7, 2023 (GE SB 72–A0908).

**(d) Subject**

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

**(e) Unsafe Condition**

This AD was prompted by a report of an aborted takeoff due to left engine failure caused by liberation of the interstage HPT rotor seal rim. The FAA is issuing this AD to prevent failure of the HPT. The unsafe condition, if not addressed, could result in uncontained HPT failure, release of high-energy debris, damage to the engine, damage

to the airplane, and possible loss of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

(1) Perform an ultrasonic inspection (USI) of the interstage HPT rotor seal in accordance with the Accomplishment Instructions, paragraph 3.B.(2), of GE SB 72–A0908, as follows:

(i) Perform an initial USI before reaching the part cycles since new limit listed in Table 1 or Table 2, as applicable, of GE SB 72–A0908, or within 10 flight cycles after the effective date of this AD, whichever occurs later; and

(ii) Repeat the USI thereafter within every 100 cycles or 175 cycles, as applicable, as listed in Table 1 or Table 2 of GE SB 72–A0908, since the last inspection.

(2) If, during any USI required by paragraph (g)(1)(i) or (ii) of this AD, a non-serviceable indication is found, as defined in paragraph 3.B.(2)(b) of GE SB 72–A0908, before further flight, remove the interstage HPT rotor seal from service.

**(h) Mandatory Terminating Action**

As a terminating action to the repetitive USI required by paragraph (g)(1)(i) or (ii) of this AD, at the next engine shop visit after the effective date of this AD, remove the affected interstage HPT rotor seal from service.

**(i) Definition**

For the purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine case flanges, except separation of engine flanges solely for the purposes of transportation of the engine without subsequent maintenance, which does not constitute an engine shop visit.

**(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, AIR–520 Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if

requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the AIR-520 Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: *ANE-AD-AMOC@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (k) Additional Information

For more information about this AD, contact Alexander Thickstun, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (202) 267-8292; email: *alexander.m.thickstun@faa.gov*.

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) General Electric Company GE90-100 Service Bulletin 72-0908 R00, dated July 7, 2023.

(ii) [Reserved]

(3) For service information identified in this AD, contact General Electric Company, 1 Newman Way, Cincinnati, OH 45215; phone: (513) 552-3272; email: *aviation.fleetsupport@ae.ge.com*; website: *ge.com*.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit *www.archives.gov/federal-register/cfr/ibr-locations* or email *fr.inspection@nara.gov*.

Issued on March 25, 2024.

#### Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2024-09109 Filed 4-26-24; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2024-0044; Project Identifier MCAI-2023-00629-A; Amendment 39-22736; AD 2024-08-03]

RIN 2120-AA64

#### Airworthiness Directives; Britten-Norman Aircraft, Ltd. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all Britten-Norman Aircraft, Ltd. Model BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B27, BN-2T, BN2T-4R, and BN2T-4S airplanes; and Model BN2A MK. III, BN2A MK. III-2, and BN2A MK. III-3 airplanes. This AD is prompted by reports of electrical cable (Kooled Kord) and flight control cables interference with the control column. This AD requires inspecting for interference between the control column, rudder pedal adjuster cable, and any wiring (including the Kooled Kord) concurrently with performing a flight control full and free movement inspection, and taking corrective actions if necessary. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective June 3, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 3, 2024.

#### ADDRESSES:

**AD Docket:** You may examine the AD docket at *regulations.gov* under Docket No. FAA-2024-0044; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### Material Incorporated by Reference:

- For service information, contact Britten-Norman Aircraft Ltd., Bembridge Airport, Bembridge, Isle of Wight, PO35 5PR United Kingdom; phone: +44 20 3371 4000; email: *customer.support@*

*britten-norman.com*; website: *britten-norman.com/approvals-technical-publications*.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at *regulations.gov* under Docket No. FAA-2024-0044.

#### FOR FURTHER INFORMATION CONTACT:

Penelope Trease, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (303) 342-1094; email: *penelope.trease@faa.gov*.

#### SUPPLEMENTARY INFORMATION:

#### Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Britten-Norman Aircraft, Ltd. Model BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN-2T, BN2T-4R, and BN2T-4S airplanes; and Model BN2A MK. III, BN2A MK. III-2, and BN2A MK. III-3 airplanes. The NPRM published in the **Federal Register** on February 1, 2024 (89 FR 6452). The NPRM was prompted by AD G-2022-0017, dated September 20, 2022 (also referred to as the MCAI), issued by the Civil Aviation Authority (CAA), which is the aviation authority for the United Kingdom (UK). The MCAI states that there have been occurrences of flight control restriction in pitch during the pilot's full and free flight control checks prior to take-off. Investigations into these occurrences revealed interference between the routing of the Kooled Kord, flight control cables, and control column, which could restrict the full and free movement of the flight controls. An incorrectly routed Kooled Kord could snag the rudder pedal adjustment cable, draw it towards the control column tube where it could snag the aileron control stop, and restrict movement of the control column tube. This increased load on the rudder pedal adjustment cable could unlock the adjustment mechanism, permitting the rudder pedals to freely move forward and aft. One of the investigations also revealed that a correctly routed Kooled Kord was entangled with an incorrectly routed rudder pedal adjustment cable, which resulted in snagging the aileron control stop. In order to address this condition, the MCAI requires an inspection using Britten-Norman