

d. Any legal or market impediment or regulatory requirement that must be addressed or satisfied in order to implement the option.

5. *Escalation procedures.* A recovery plan should clearly outline the process for escalating decision-making to senior management or the board of directors (or an appropriate committee of the board of directors), as appropriate, in response to the breach of any trigger. The recovery plan should also identify the departments and persons responsible for executing the decisions of senior management or the board of directors (or an appropriate committee of the board of directors).

6. *Management reports.* A recovery plan should require reports that provide senior management or the board of directors (or an appropriate committee of the board of directors) with sufficient data and information to make timely decisions regarding the appropriate actions necessary to respond to the breach of a trigger.

7. *Communication procedures.* A recovery plan should provide that the covered bank notify the OCC of any significant breach of a trigger and any action taken or to be taken in response to such breach and should explain the process for deciding when a breach of a trigger is significant. A recovery plan also should address when and how the covered bank will notify persons within the organization and other external parties of its action under the recovery plan. The recovery plan should specifically identify how the covered bank will obtain required regulatory or legal approvals.

8. *Other information.* A recovery plan should include any other information that the OCC communicates in writing directly to the covered bank regarding the covered bank's recovery plan.

C. *Relationship to other processes; coordination with other plans.* The covered bank should integrate its recovery plan into its risk governance functions. The covered bank also should align its recovery plan with its other plans, such as its strategic; operational (including business continuity and resilience program); contingency; capital (including stress testing); liquidity; and resolution planning. The covered bank's recovery plan should be specific to that covered bank. The covered bank also should coordinate its recovery plan with any recovery and resolution planning efforts by the covered bank's holding company, so that the plans are consistent with and do not contradict each other.

D. *Testing.* Each covered bank should test its recovery plan periodically but not less than annually. The test should validate the effectiveness of the recovery plan, including each element set forth in paragraph II.B. of this appendix. Each covered bank should revise its recovery plan as appropriate following completion of the test.

\* \* \* \* \*

Michael J. Hsu,

Acting Comptroller of the Currency.

[FR Doc. 2024-13960 Filed 7-2-24; 8:45 am]

BILLING CODE 4810-33-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2024-1881; Project Identifier MCAI-2024-00160-T]

RIN 2120-AA64

#### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus SAS Model A350-941 and -1041 airplanes. This proposed AD was prompted by reports that engine nacelle anti-icing (NAI) forward bulkheads have been found with elongated locating holes. This proposed AD would require a one-time detailed inspection of the engine NAI forward bulkhead locating holes for elongation and loose fasteners and applicable corrective actions, and would also prohibit the installation of affected parts under certain conditions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by August 19, 2024.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-1881; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

*Material Incorporated by Reference:*

- For EASA material, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](https://easa.europa.eu). You may find this material on the EASA website [ad.easa.europa.eu](https://ad.easa.europa.eu). It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-1881.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

**FOR FURTHER INFORMATION CONTACT:** Dat Le, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7317; email [dat.v.le@faa.gov](mailto:dat.v.le@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2024-1881; Project Identifier MCAI-2024-00160-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

##### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such

marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Dat Le, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7317; email [dat.v.le@faa.gov](mailto:dat.v.le@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Background**

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2024-0060R1, dated April 16, 2024 (EASA AD 2024-0060R1) (also referred to as the MCAI), to correct an unsafe condition on all Airbus SAS Model A350-941 and -1041 airplanes. The MCAI states that certain engine NAI forward bulkheads may have elongated locating holes. These holes are used in the manufacturing process and closed with fasteners before delivery. It has been determined that these fasteners, if loose, may vibrate and cause further elongation of the locating holes, which, eventually, can reduce the NAI performance. This condition, if not detected and corrected, could lead to the undetected loss of NAI protection on both engines, possibly resulting in loss of control of the airplane.

The FAA is proposing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-1881.

**Related Material Under 1 CFR Part 51**

EASA AD 2024-0060R1 specifies procedures for a one-time detailed inspection of the engine NAI forward bulkhead location holes for discrepancies, including elongation and

loose fasteners. Depending on the inspection results, EASA 2024-0060R1 also specifies corrective action, including obtaining and following instructions if any discrepancy is identified. EASA AD 2024-0060R1 also requires reporting of the inspection results to Collins Aerospace. EASA AD 2024-0060R1 also prohibits the installation of an affected part on any airplane unless it is a serviceable part and is inspected before installation. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**FAA’s Determination**

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

**Proposed AD Requirements in This NPRM**

This proposed AD would require accomplishing the actions specified in EASA AD 2024-0060R1 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD and except as discussed under “Differences Between this NPRM and the MCAI.”

**Explanation of Required Compliance Information**

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA)

ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2024-0060R1 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2024-0060R1 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2024-0060R1 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2024-0060R1. Material required by EASA AD 2024-0060R1 for compliance will be available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-1881 after the FAA final rule is published.

**Differences Between This NPRM and the MCAI**

EASA 2024-0060R1 requires to report inspection results (including no findings) to Collins Aerospace, and this proposed AD would not require reporting the inspection results because the root cause is known, and additional data obtained from operators would not provide information to suggest different or additional rulemaking.

**Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 31 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
7.5 work-hours × \$85 per hour = \$638 .....	\$10	\$648	\$20,088

The FAA has received no definitive data on which to base the cost estimates for the on-condition repairs specified in this proposed AD.

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this proposed AD may be covered under warranty, thereby

reducing the cost impact on affected operators.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more

detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and

procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Airbus SAS:** Docket No. FAA–2024–1881; Project Identifier MCAI–2024–00160–T.

#### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by August 19, 2024.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all Airbus SAS Model A350–941 and –1041 airplanes, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code 54, Nacelles/pylons.

#### (e) Unsafe Condition

This AD was prompted by reports that engine nacelle anti-icing (NAI) forward bulkheads may have elongated locating holes. The FAA is issuing this AD to address elongated locating holes. The unsafe condition, if not addressed, could result in the fasteners, if loose, to vibrate and cause further elongation of the locating holes, which, eventually, can reduce the NAI performance. This condition, if not detected and corrected, could lead to the undetected loss of NAI protection on both engines, possibly resulting in loss of control of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2024–0060R1, dated April 16, 2024 (EASA AD 2024–0060R1).

#### (h) Exceptions to EASA AD 2024–0060R1

(1) Where EASA AD 2024–0060R1 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph (2) of EASA AD 2024–0060R1 specifies if “any discrepancy is detected, before next flight, contact Collins Aerospace for approved corrective action instructions and, within the compliance time identified therein accomplish those instructions accordingly,” this AD requires replacing that text with if “any discrepancy is detected, the discrepancy must be repaired before further flight using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.”

(3) This AD does not adopt the “Remarks” section of EASA AD 2024–0060R1.

#### (i) No Reporting Required

Although EASA AD 2024–0060R1 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

#### (j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or

lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (h)(2) of this AD, if any material contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (k) Additional Information

For more information about this AD, contact Dat Le, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7317; email [dat.v.le@faa.gov](mailto:dat.v.le@faa.gov).

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2024–0060R1, dated April 16, 2024.

(ii) [Reserved]

(3) For EASA AD 2024–0060R1, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find this EASA AD on the EASA website [ad.easa.europa.eu](http://ad.easa.europa.eu).

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations), or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on June 27, 2024.

#### Suzanne Masterson,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2024–14566 Filed 7–2–24; 8:45 am]

**BILLING CODE 4910–13–P**