

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

95-17-10 Jetstream Aircraft Limited:

Amendment 39-9340; Docket No. 91-CE-85-AD.

Applicability: Jetstream Model 3101 airplanes, all serial numbers, and Jetstream Model 3201 airplanes, serial numbers 790 through 950, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (d) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required within the next 200 hours time-in-service after the effective date of this AD, unless already accomplished.

To prevent failure of a diode in the central annunciator panel test button circuit, which could result in inadvertent engine shutdown while in flight if the central annunciator panel test button is pressed, accomplish the following:

(a) Modify the central annunciator panel test button circuit (Amendment JA 911045) by removing diodes from the engine stop circuit and configuring a minor wiring change in accordance with PART 2 of the ACCOMPLISHMENT INSTRUCTIONS section of Jetstream Alert Service Bulletin 80-A-JA 911045, Revision 1, dated November 1, 1991.

(b) As noted in Jetstream Alert Service Bulletin 80-A-JA 911045, Revision 1, dated November 1, 1991, terminals may be linked using 22 AWA cable and terminal tags, provided the following is accomplished:

(1) For airplanes without roof panel plug breaks, identify the cables as WQ69 and WQ70.

(2) For airplanes with roof panel plug breaks, identify the cables as WQ71 and WQ72.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Brussels Aircraft Certification Office (ACO), Europe, Africa, Middle East office, FAA, c/o American Embassy, B-1000 Brussels, Belgium. The

request should be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Brussels ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Brussels ACO.

(e) The modification required by this AD shall be done in accordance with Jetstream Alert Service Bulletin 80-A-JA 911045, Revision 1, dated November 1, 1991. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Jetstream Aircraft Limited, Manager Product Support, Prestwick Airport, Ayrshire, KA9 2RW Scotland; or Jetstream Aircraft Inc., Librarian, P.O. Box 16029, Dulles International Airport, Washington, DC, 20041-6029. Copies may be inspected at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., 7th Floor, suite 700, Washington, DC.

(f) This amendment (39-9340) becomes effective on October 3, 1995. Issued in Kansas City, Missouri, on August 10, 1995.

Gerald W. Pierce,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-20277 Filed 8-22-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 73

[Airspace Docket No. 95-ASW-3]

Amendment of Restricted Areas R-6302B and R-6302E, Fort Hood, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: This document contains a correction to the final rule published on July 20, 1995. The airspace designation for "R-6203E Fort Hood, TX," was in error. This correction changes "R-6203E Fort Hood, TX" to read "R-6302E Fort Hood, TX."

EFFECTIVE DATE: August 23, 1995.

FOR FURTHER INFORMATION CONTACT: Pete Magarelli, Military Operations Program Office (ATM-420), Office of Air Traffic System Management, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-7130.

SUPPLEMENTARY INFORMATION: On July 20, 1995, the FAA published a final rule that amended the descriptions of R-6302B and R-6302E Fort Hood, TX. The airspace designation for "R-6203E Fort Hood, TX," was in error. This correction

changes "R-6203E Fort Hood, TX" to read "R-6302E Fort Hood, TX." [95-ASW-3] 2

Correction of Final Rule

Accordingly, pursuant to the authority delegated to me, the title of the airspace designation for "R-6203E Fort Hood, TX" published in the **Federal Register** on July 20, 1995 (60 FR 37331; **Federal Register** Document 95-17901, Column 3) is corrected as follows:

* * * * *

On page 37331, Column 3, the title for the airspace designation is revised to read as "R-6302E Fort Hood, TX."

* * * * *

Issued in Washington, DC, on August 14, 1995.

Harold W. Becker,

Manager, Airspace-Rules and Aeronautical Information Division.

[FR Doc. 95-20839 Filed 8-22-95; 8:45 am]

BILLING CODE 4910-13-P

14 CFR Part 73

[Airspace Docket No. 95-AGL-7]

Alteration of R-3403A and Revocation of Restricted Area R-3403C, Jefferson Proving Ground, IN

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action removes Restricted Area R-3403C Jefferson Proving Ground, IN. As a result of the annual restricted area review, the Department of the Army has determined that there is no longer a requirement for a separate continuous use restricted area. Additionally, R-3403A is being amended to remove reference to R-3403C.

EFFECTIVE DATE: 0901 UTC, November 9, 1995.

FOR FURTHER INFORMATION CONTACT: Jim Robinson, Military Operations Program Office (ATM-420), Office of Air Traffic System Management, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 493-4050.

SUPPLEMENTARY INFORMATION:

The Rule

This amendment to part 73 of the Federal Aviation Regulations removes Restricted Area R-3403C, Jefferson