

most Federal motor vehicle safety standards.

Champagne submitted information with its petition intended to demonstrate that non-U.S. certified 1995–1999 Mercedes-Benz S600 passenger cars, as originally manufactured, conform to many Federal motor vehicle safety standards in the same manner as their U.S. certified counterparts, or are capable of being readily altered to conform to those standards.

Specifically, the petitioner claims that non-U.S. certified 1995–1999 Mercedes-Benz S600 passenger cars are identical to their U.S.-certified counterparts with respect to compliance with Standard Nos. 102 *Transmission Shift Lever Sequence* * * *, 103 *Defrosting and Defogging Systems*, 104 *Windshield Wiping and Washing Systems*, 105 *Hydraulic Brake Systems*, 106 *Brake Hoses*, 109 *New Pneumatic Tires*, 113 *Hood Latch Systems*, 116 *Brake Fluid*, 124 *Accelerator Control Systems*, 201 *Occupant Protection in Interior Impact*, 202 *Head Restraints*, 204 *Steering Control Rearward Displacement*, 205 *Glazing Materials*, 207 *Seating Systems*, 209 *Seat Belt Assemblies*, 210 *Seat Belt Assembly Anchorages*, 212 *Windshield Retention*, 216 *Roof Crush Resistance*, 219 *Windshield Zone Intrusion*, and 302 *Flammability of Interior Materials*.

Additionally, the petitioner states that non-U.S. certified 1995–1999 Mercedes-Benz S600 passenger cars comply with the Bumper Standard found in 49 CFR part 581, and with the Theft Prevention Standard found in 49 CFR part 541.

Petitioner also contends that the vehicles are capable of being readily altered to meet the following standards, in the manner indicated:

Standard No. 101 *Controls and Displays*: (a) Substitution of a lens marked "Brake" for a lens with a noncomplying symbol on the brake failure indicator lamp; (b) installation of a seat belt warning lamp that displays the appropriate symbol; (c) recalibration of the speedometer/odometer from kilometers to miles per hour.

Standard No. 108 *Lamps, Reflective Devices and Associated Equipment*: (a) Installation of U.S.-model headlamp assemblies that incorporate headlamps with DOT markings; (b) installation of U.S.-model front and rear sidemarker/reflector assemblies; (c) installation of U.S.-model taillamp assemblies; (d) installation of a center high mounted

stop lamp if the vehicle is not already so equipped.

Standard No. 110 *Tire Selection and Rims*: installation of a tire information placard.

Standard No. 111 *Rearview Mirror*: replacement of the passenger side rearview mirror with a U.S.-model component.

Standard No. 114 *Theft Protection*: installation of a warning buzzer microswitch in the steering lock assembly and a warning buzzer.

Standard No. 118 *Power Window Systems*: rewiring of the power window system so that the window transport is inoperative when the ignition is switched off.

Standard No. 206 *Door Locks and Door Retention Components*: replacement of the rear door locks and the rear door locking buttons with U.S.-model components.

Standard No. 208 *Occupant Crash Protection*: (a) Installation of a U.S.-model seat belt in the driver's position, or a belt webbing-actuated microswitch inside the driver's seat belt retractor; (b) installation of an ignition switch-actuated seat belt warning lamp and buzzer; (c) replacement of the driver's and passenger's side air bags and knee bolsters with U.S.-model components if the vehicle is not already so equipped. The petitioner states that the vehicles are equipped with combination lap and shoulder restraints that adjust by means of an automatic retractor and release by means of a single push button at both front designated seating positions, with combination lap and shoulder restraints that release by means of a single push button at both rear outboard designated seating positions, and with a lap belt at the rear center designated seating position.

Standard No. 214 *Side Impact Protection*: installation of reinforcing beams if the vehicle is not already so equipped.

Standard No. 301 *Fuel System Integrity*: installation of a rollover valve in the fuel tank vent line between the fuel tank and the evaporative emissions collection canister.

The petitioner states that a vehicle identification number plate must be affixed to all non-U.S. certified 1995–1999 Mercedes-Benz S600 passenger cars to meet the requirements of 49 CFR Part 565.

Interested persons are invited to submit comments on the petition

described above. Comments should refer to the docket number and be submitted to: Docket Section, National Highway Traffic Safety Administration, Room 5109, 400 Seventh Street, SW, Washington, DC 20590. It is requested but not required that 10 copies be submitted.

All comments received before the close of business on the closing date indicated above will be considered, and will be available for examination in the docket at the above address both before and after that date. To the extent possible, comments filed after the closing date will also be considered. Notice of final action on the petition will be published in the **Federal Register** pursuant to the authority indicated below.

Authority: 49 U.S.C. 30141(a)(1)(A) and (b)(1); 49 CFR 593.8; delegations of authority at 49 CFR 1.50 and 501.8.

Issued on: April 9, 1999.

Marilynne Jacobs,

Director, Office of Vehicle Safety Compliance.

[FR Doc. 99–9332 Filed 4–13–99; 8:45 am]

BILLING CODE 4910–59–P

MORRIS K. UDALL SCHOLARSHIP AND EXCELLENCE IN NATIONAL ENVIRONMENTAL POLICY FOUNDATIONS

Sunshine Act Meeting

The Board of Trustees of the Morris K. Udall Scholarship & Excellence in National Environmental Policy Foundation will hold a meeting beginning at 9:00 a.m. on Thursday, April 22, 1999 at the offices of the U.S. Institute for Environmental Conflict Resolution, 110 South Church, Ste. 3350, Tucson, AZ 85701.

The matters to be considered will include (1) A report on the U.S. Institute of Environmental Conflict Resolution, and (2). A report from the Udall Center for Studies and Public Policy and (3) Program Reports. The meeting is open to the public.

Contact Person for More Information:

Christopher L. Helms, 110 South Church, Ste. 3350, Tucson, Arizona 85701. Telephone (520) 670–5608.

Dated this 9th day of April, 1999.

Christopher L. Helms,

Director.

[FR Doc. 99–9380 Filed 4–12–99; 12:05 pm]

BILLING CODE 6820–FN–M