

to be publicly viewable should not be included in your comment, nor in any document attached to your comment. Otherwise, persons viewing comments will see only first and last names, organization names, correspondence containing comments, and any documents submitted with the comments.

Do not submit to *www.regulations.gov* information for which disclosure is restricted by statute, such as trade secrets and commercial or financial information (hereinafter referred to as Confidential Business Information (“CBI”). Comments submitted through *www.regulations.gov* cannot be claimed as CBI. Comments received through the website will waive any CBI claims for the information submitted. For information on submitting CBI, see the Confidential Business Information section.

DOE processes submissions made through *www.regulations.gov* before posting. Normally, comments will be posted within a few days of being submitted. However, if large volumes of comments are being processed simultaneously, your comment may not be viewable for up to several weeks. Please keep the comment tracking number that *www.regulations.gov* provides after you have successfully uploaded your comment.

**Submitting comments via email.** Comments and documents submitted via email also will be posted to *www.regulations.gov*. If you do not want your personal contact information to be publicly viewable, do not include it in your comment or any accompanying documents. Instead, provide your contact information in a cover letter. Include your first and last names, email address, telephone number, and optional mailing address. The cover letter will not be publicly viewable as long as it does not include any comments.

Include contact information each time you submit comments, data, documents, and other information to DOE. No telefacsimiles (“faxes”) will be accepted.

Comments, data, and other information submitted to DOE electronically should be provided in PDF (preferred), Microsoft Word or Excel, WordPerfect, or text (ASCII) file format. Provide documents that are not secured, that are written in English, and that are free of any defects or viruses. Documents should not contain special characters or any form of encryption and, if possible, they should carry the electronic signature of the author.

**Campaign form letters.** Please submit campaign form letters by the originating

organization in batches of between 50 to 500 form letters per PDF or as one form letter with a list of supporters’ names compiled into one or more PDFs. This reduces comment processing and posting time.

**Confidential Business Information.** Pursuant to 10 CFR 1004.11, any person submitting information that he or she believes to be confidential and exempt by law from public disclosure should submit via email two well-marked copies: One copy of the document marked “confidential” including all the information believed to be confidential, and one copy of the document marked “non-confidential” with the information believed to be confidential deleted. DOE will make its own determination about the confidential status of the information and treat it according to its determination.

It is DOE’s policy that all comments may be included in the public docket, without change and as received, including any personal information provided in the comments (except information deemed to be exempt from public disclosure).

#### X. Approval of the Office of the Secretary

The Secretary of Energy has approved publication of this supplemental notice of proposed rulemaking; reopening of comment period and notification of data availability.

#### Signing Authority

This document of the Department of Energy was signed on October 19, 2021, by Kelly Speakes-Backman, Principal Deputy Assistant Secretary and Acting Assistant Secretary for Energy Efficiency and Renewable Energy, pursuant to delegated authority from the Secretary of Energy. That document with the original signature and date is maintained by DOE. For administrative purposes only, and in compliance with requirements of the Office of the Federal Register, the undersigned DOE Federal Register Liaison Officer has been authorized to sign and submit the document in electronic format for publication, as an official document of the Department of Energy. This administrative process in no way alters the legal effect of this document upon publication in the **Federal Register**.

Signed in Washington, DC, on October 20, 2021.

**Treana V. Garrett,**

*Federal Register Liaison Officer, U.S. Department of Energy.*

[FR Doc. 2021–23188 Filed 10–25–21; 8:45 am]

**BILLING CODE 6450–01–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2021–0881; Project Identifier AD–2020–01062–T]

RIN 2120–AA64

#### Airworthiness Directives; Gulfstream Aerospace Corporation Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to supersede Airworthiness Directive (AD) 2020–12–06, which applies to all Gulfstream Aerospace Corporation (Gulfstream) Model G–IV airplanes. AD 2020–12–06 requires replacing the nose wheel steering servo valve manifold, incorporating revised operating procedures into the airplane flight manual (AFM), doing a records inspection for any incidents of uncommanded nose wheel steering turns, and reporting the results to the FAA. Since the FAA issued AD 2020–12–06, the FAA determined that a typographical error was made in a citing one of the AFM documents. This proposed AD would retain the actions of AD 2020–12–06 and would correct the citation to the AFM. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by December 10, 2021.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Gulfstream Aerospace Corporation, P.O. Box 2206, Savannah, GA 31402; phone: (800) 810–4853; email: [pubs@gulfstream.com](mailto:pubs@gulfstream.com); website: <https://www.gulfstream.com/en/customer-support/>. You may view this service information at the FAA, Airworthiness Products Section,

Operational Safety Branch, FAA, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

### Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0881; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

**FOR FURTHER INFORMATION CONTACT:** Samuel Belete, Aviation Safety Engineer, Systems and Equipment Section, FAA, Atlanta ACO Branch, 1701 Columbia Avenue, College Park, GA 30337; phone: (404) 474-5580; fax: (404) 474-5606; email: [samuel.belete@faa.gov](mailto:samuel.belete@faa.gov).

### SUPPLEMENTARY INFORMATION:

#### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2021-0881; Project Identifier AD-2020-01062-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this proposed AD.

#### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial

information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Samuel Belete, Aviation Safety Engineer, Systems and Equipment Section, FAA, Atlanta ACO Branch, 1701 Columbia Avenue, College Park, GA 30337. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

#### Background

The FAA issued AD 2020-12-06, Amendment 39-21141 (85 FR 36143, June 15, 2020) (AD 2020-12-06), for all Gulfstream Model G-IV airplanes. AD 2020-12-06 was prompted by reports of un-commanded nose wheel steering turns. AD 2020-12-06 requires replacing the nose wheel steering servo valve manifold, incorporating revised operating procedures into the AFM, doing a records inspection for any incidents of un-commanded nose wheel steering turns, and reporting the results to the FAA. The agency issued AD 2020-12-06 to prevent moisture from entering the nose steering wheel servo valve, which could freeze and cause an un-commanded nose wheel steering position during touchdown.

#### Actions Since AD 2020-12-06 Was Issued

Since the FAA issued AD 2020-12-06, a typographical error was found in the title of the AFM required by paragraph (g)(3) of AD 2020-12-06. The paragraph incorrectly references the document number as "FAC-AC-G400-OPS-0001" instead of "GAC-AC-G400-OPS-0001."

#### FAA's Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

#### Related Service Information Under 1 CFR Part 51

This proposed AD would require Gulfstream IV Customer Bulletin Number 244, dated March 12, 2018;

Gulfstream G300 Customer Bulletin 244, dated March 12, 2018; Gulfstream G400 Customer Bulletin 244, dated March 12, 2018; Gulfstream IV Airplane Flight Manual, Gulfstream Aerospace Document Number GAC-AC-GIV-OPS-0001, Revision 52, dated October 30, 2017; Gulfstream G300 Airplane Flight Manual, Gulfstream Aerospace Document Number GAC-AC-G300-OPS-0001, Revision 20, dated October 30, 2017; and Gulfstream G400 Airplane Flight Manual, Gulfstream Aerospace Document Number GAC-AC-G400-OPS-0001, Revision 20, dated October 30, 2017; which the Director of the Federal Register approved for incorporation by reference as of July 20, 2020 (85 FR 36143, June 15, 2020).

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

#### Proposed AD Requirements in This NPRM

This proposed AD would retain most of the requirements of AD 2020-12-06. This proposed AD would require revising the AFM (with the correct title of the AFM document for G400 airplanes) and replacing the nose wheel steering servo valve manifold. This proposed AD would also require doing a records inspection for any incidents of un-commanded nose wheel steering turns and reporting all recorded occurrences of un-commanded nose wheel steering turns to the FAA.

#### Differences Between This Proposed AD and the Service Information

The Gulfstream customer bulletins require reporting compliance with the bulletins to Gulfstream. This proposed AD does not contain that requirement; however, this proposed AD would require reporting any known occurrences of un-commanded nose wheel steering turns to the FAA.

The Gulfstream customer bulletins include a compliance time of 48 months beginning on March 12, 2018. The compliance time for this proposed AD is 36 months after July 20, 2020 (the effective date of AD 2020-12-06).

#### Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 425 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

## ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Incorporate AFM revision .....	1 work-hour × \$85 per hour = \$85 .....	\$0	\$85	\$36,125
Replace nose wheel steering servo valve .....	7 work-hours × \$85 per hour = \$595 .....	63,624	64,219	27,293,075
Review records .....	1 work-hour × \$85 per hour = \$85 .....	0	85	36,125
Report results .....	1 work hour × \$85 per hour = \$85 .....	0	85	36,125

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators.

### Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a currently valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Parkway, Fort Worth, TX 76177-1524.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce.

This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
  - a. Removing Airworthiness Directive 2020-12-06, Amendment 39-21141 (85 FR 36143, June 15, 2020); and
  - b. Adding the following new airworthiness directive:

**Gulfstream Aerospace Corporation:** Docket No. FAA-2021-0881; Project Identifier AD-2020-01062-T.

### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by December 10, 2021.

### (b) Affected ADs

This AD replaces AD 2020-12-06, Amendment 39-21141 (85 FR 36143, June 15, 2020) (AD 2020-12-06).

### (c) Applicability

This AD applies to all Gulfstream Aerospace Corporation Model G-IV airplanes, certificated in any category.

### (d) Subject

Joint Aircraft System Component (JASC) Code 3200, Landing Gear System.

### (e) Unsafe Condition

This AD was prompted by reports of uncommanded nose wheel steering turns. The FAA is issuing this AD to prevent moisture from entering the nose steering wheel servo valve, which could freeze and cause an uncommanded nose wheel steering position during touchdown. The unsafe condition, if not addressed, could result in a lateral runway departure.

### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

### (g) Retained Airplane Flight Manual Revisions for Certain Airplanes

This paragraph restates the requirements of paragraph (g)(1) and (2) of AD 2020-12-06. Within 30 days after July 20, 2020 (the effective date of AD2020-12-06), revise your airplane flight manual (AFM) by incorporating the revision applicable to your airplane configuration as listed in paragraphs (g)(1) and (2) of this AD:

- (1) Gulfstream IV Airplane Flight Manual, Gulfstream Aerospace Document Number GAC-AC-GIV-OPS-0001, Revision 52, dated October 30, 2017; or
- (2) Gulfstream G300 Airplane Flight Manual, Gulfstream Aerospace Document Number GAC-AC-G300-OPS-0001, Revision 20, dated October 30, 2017.

### (h) Correction to AFM Revision for Certain Airplanes

Within 30 days after the effective date of this AD, revise your AFM by incorporating Gulfstream G400 Airplane Flight Manual, Gulfstream Aerospace Document Number GAC-AC-G400-OPS-0001, Revision 20, dated October 30, 2017, if applicable to your airplane configuration.

**(i) Retained Replacement of Nose Wheel Steering Servo Valve Manifold With No Changes**

The paragraph restates the requirements of paragraph (h) of AD 2020–12–06 with no changes. Within 36 months after July 20, 2020 (the effective date of AD2020–12–06), replace the nose wheel steering servo valve manifold with nose wheel steering servo valve manifold part number 5100–11 or 5105–5 in accordance with the Accomplishment Instructions of the customer bulletin that applies to your airplane configuration as listed in paragraphs (i)(1) through (3) of this AD, except you are not required to comply with step H:

- (1) Gulfstream IV Customer Bulletin Number 244, dated March 12, 2018;
- (2) Gulfstream G300 Customer Bulletin 244, dated March 12, 2018; or
- (3) Gulfstream G400 Customer Bulletin 244, dated March 12, 2018.

**(j) Retained Records Inspection and Report of Results with No Changes**

This paragraph restates the requirements of paragraph (i) of AD 2020–12–06 with no changes.

(1) Between 12 months and 24 months after the replacement of the nose wheel steering valve manifold assembly required in paragraph (i) of this AD, inspect all aircraft records for entries of an un-commanded nose wheel steering turn.

(2) Within 10 days after the records inspection required in paragraph (j)(1) of this AD, report the results of the inspection, regardless of whether the inspection found any entries, to the FAA by either email: [9-ASO-ATLCOS-Reporting@faa.gov](mailto:9-ASO-ATLCOS-Reporting@faa.gov); or by mail: Attn: Continued Operational Safety, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, GA 30337. The report must include as much of the information listed in paragraphs (j)(2)(i) through (vii) of this AD as is known about the event:

- (i) Date of records inspection;
- (ii) Date and time of all un-commanded occurrences (if any);
- (iii) Airplane serial number;
- (iv) Weather and runway conditions at the time of each occurrence;
- (v) Copy of the pilot's report of the occurrence (if available);
- (vi) Maintenance entry of the root cause of the un-commanded deflection (if available); and
- (vii) Any other information pertinent to the occurrence.

**(k) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Atlanta ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager

of the local flight standards district office/certificate holding district office.

**(l) Related Information**

(1) For more information about this AD, contact Samuel Belete, Aviation Safety Engineer, Systems and Equipment Section, FAA, Atlanta ACO Branch, 1701 Columbia Avenue, College Park, GA 30337; phone: (404) 474–5580; fax: (404) 474–5606; email: [samuel.belete@faa.gov](mailto:samuel.belete@faa.gov).

(2) For service information identified in this AD, Gulfstream Aerospace Corporation, P.O. Box 2206, Savannah, GA 31402; phone: (800) 810–4853; email: [pubs@gulfstream.com](mailto:pubs@gulfstream.com); website: <https://www.gulfstream.com/en/customer-support/>. You may view this referenced service information at the FAA Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Issued on October 13, 2021.

**Lance T. Gant,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2021–23013 Filed 10–25–21; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

**[Docket No. FAA–2021–0867; Airspace Docket No. 21–AAL–39]**

**RIN 2120–AA66**

**Proposed Establishment of United States Area Navigation (RNAV) Route T–435; Sand Point, AK**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to establish United States Area Navigation (RNAV) route T–435 in the vicinity of Sand Point, AK in support of a large and comprehensive T-route modernization project for the state of Alaska.

**DATES:** Comments must be received on or before December 10, 2021.

**ADDRESSES:** Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE, West Building Ground Floor, Room W12–140, Washington, DC 20590; telephone: 1(800) 647–5527, or (202) 366–9826. You must identify FAA Docket No. FAA–2021–0867; Airspace Docket No. 21–AAL–39 at the beginning of your comments. You may also submit comments through the internet at <https://www.regulations.gov>.

FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [https://www.faa.gov/air\\_traffic/publications/](https://www.faa.gov/air_traffic/publications/). For further information, you can contact the Rules and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order JO 7400.11F at NARA, email: [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov) or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

**FOR FURTHER INFORMATION CONTACT:**

Christopher McMullin, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783

**SUPPLEMENTARY INFORMATION:****Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would expand the availability of RNAV routing in Alaska and improve the efficient flow of air traffic within the National Airspace System (NAS) by lessening the dependency on ground based navigation.

**Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA–2021–0867; Airspace Docket No. 21–