

using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or De Havilland Aircraft of Canada Limited's TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) TCCA AD CF-2021-12, dated April 14, 2021, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0656.

(2) For more information about this AD, contact Chirayu Gupta, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531; email 9-avs-nyacos@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) De Havilland Aircraft of Canada Limited Service Bulletin 84-26-20, Revision A, dated March 9, 2021.

(ii) [Reserved]

(3) For service information identified in this AD, contact De Havilland Aircraft of Canada Limited, Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd@dehavilland.com; internet <https://dehavilland.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 26, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-26109 Filed 11-30-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0568; Project Identifier MCAI-2021-00446-T; Amendment 39-21798; AD 2021-22-25]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A330-200, -200 Freighter, -300, and -900 series airplanes; and Model A340-200, -300, -500, and -600 series airplanes. This AD was prompted by a report that during the frame of flight test clearance process, a detailed analysis of air data reference (ADR) failure scenarios led to the identification that compliance requirements for loads and handling qualities throughout the flight envelope could be impaired in case of dispatch with one ADR inoperative (master minimum equipment list (MMEL) item 34-10-01) during the maximum interval allowed by the current MMEL. This AD requires revising the operator's existing FAA-approved minimum equipment list (MEL) for the air data/inertial reference system, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products. **DATES:** This AD is effective January 5, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 5, 2022.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South

216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0568.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0568; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax: 206-231-3229; email vladimir.ulyanov@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021-0103, dated April 13, 2021 (EASA AD 2021-0103) (also referred to as the MCAI), to correct an unsafe condition for all Airbus SAS Model A330-200, -200 Freighter, -300, and -900 series airplanes; Model A340-200 and -300 series airplanes; and Model A340-541, -542, -642, and -643 airplanes. Model A340-542 and -643 airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this AD therefore does not include those airplanes in the applicability.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus SAS Model A330-200, -200 Freighter, -300, and -900 series airplanes; and Model A340-200, -300, -500, and -600 series airplanes. The NPRM published in the **Federal Register** on July 28, 2021 (86 FR 40373). The NPRM was prompted by a report that during the frame of flight test clearance process, a detailed analysis of ADR failure scenarios led to the identification that compliance requirements for loads and handling qualities throughout the flight envelope

could be impaired in case of dispatch with one ADR inoperative (MMEL item 34–10–01) during the maximum interval allowed by the current MMEL. The NPRM proposed to require revising the operator’s existing FAA-approved MEL for the air data/inertial reference system, as specified in EASA AD 2021–0103.

The FAA is issuing this AD to address the possibility of in-flight loss of a second ADR combined with erroneous low speed data provided by the remaining functional ADR, which could result in loss of control of the airplane. See the MCAI for additional background information.

Discussion of Final Airworthiness Directive

Comments

The FAA received a comment from the Air Line Pilots Association, International (ALPA) who supported the NPRM without change.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety requires adopting this AD as proposed. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator. Accordingly, the FAA is issuing this AD

to address the unsafe condition on these products.

Related Service Information Under 1 CFR Part 51

EASA AD 2021–0103 describes procedures for revising the air data/inertial reference system for MMEL item 34–10–01. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Costs of Compliance

The FAA estimates that this AD affects 130 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
2 work-hours × \$85 per hour = \$170	\$0	\$170	\$22,100

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–22–25 Airbus SAS: Amendment 39–21798; Docket No. FAA–2021–0568; Project Identifier MCAI–2021–00446–T.

(a) Effective Date

This airworthiness directive (AD) is effective January 5, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS airplanes specified in paragraphs (c)(1)

through (8) of this AD, certificated in any category.

- (1) Model A330–201, –202, –203, –223, and –243 airplanes.
- (2) Model A330–223F and –243F airplanes.
- (3) Model A330–301, –302, –303, –321, –322, –323, –341, –342, and –343 airplanes.
- (4) Model A330–941 airplanes.
- (5) Model A340–211, –212, and –213 airplanes.
- (6) Model A340–311, –312, and –313 airplanes.
- (7) Model A340–541 airplanes.
- (8) Model A340–642 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

(e) Reason

This AD was prompted by a report that during the frame of flight test clearance process, a detailed analysis of air data reference (ADR) failure scenarios led to the identification that compliance requirements for loads and handling qualities throughout the flight envelope could be impaired in case of dispatch with one ADR inoperative (master minimum equipment list (MMEL) item 34–10–01) during the maximum interval allowed by the current MMEL. The FAA is issuing this AD to address the possibility of in-flight loss of a second ADR combined with erroneous low speed data provided by the remaining functional ADR, which could result in loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in

accordance with, European Union Aviation Safety Agency (EASA) AD 2021–0103, dated April 13, 2021 (EASA AD 2021–0103).

(h) Exceptions to EASA AD 2021–0103

(1) Where EASA AD 2021–0103 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2021–0103 specifies to implement certain information in “the MMEL MER” into the “operational documentation,” this AD requires revising the operator’s existing FAA-approved minimum equipment list (MEL) to incorporate that information.

(3) Where EASA AD 2021–0103 specifies to “inform all flight crews, and, thereafter, operate the aeroplane accordingly,” this AD does not require those actions as those actions are already required by existing FAA operating regulations.

(4) The “Remarks” section of EASA AD 2021–0103 does not apply to this AD.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (i)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax: 206–231–3229; email vladimir.ulyanov@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021–0103, dated April 13, 2021.

(ii) [Reserved]

(3) For EASA AD 2021–0103, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 25, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–26110 Filed 11–30–21; 8:45 am]

BILLING CODE 4910–13–P

SECURITIES AND EXCHANGE COMMISSION

17 CFR Part 211

[Release No. SAB 120]

Staff Accounting Bulletin No. 120

AGENCY: Securities and Exchange Commission.

ACTION: Publication of Staff Accounting Bulletin.

SUMMARY: This staff accounting bulletin expresses the views of the staff regarding the estimation of the fair value of share-based payment transactions in accordance with Financial Accounting

Standards Board (“FASB”) Accounting Standards Codification (“ASC”) Topic 718, *Compensation—Stock Compensation* (“Topic 718”), when a company is in possession of material non-public information, and modifies portions of the interpretive guidance included in the Staff Accounting Bulletin Series (“Series”) in order to make the relevant interpretive guidance consistent with current authoritative accounting guidance, specifically, to update the Series to bring existing guidance into conformity with Topic 718.

DATES: Effective December 1, 2021.

FOR FURTHER INFORMATION CONTACT: Dan Janiak, Professional Accounting Fellow, Office of the Chief Accountant at (202) 551–5300 or Todd E. Hardiman, Associate Chief Accountant, Division of Corporation Finance at (202) 551–3400, Securities and Exchange Commission, 100 F Street NE, Washington, DC 20549.

SUPPLEMENTARY INFORMATION: The statements in staff accounting bulletins are not rules or interpretations of the Commission, nor are they published as bearing the Commission’s official approval. They represent interpretations and practices followed by the Division of Corporation Finance and the Office of the Chief Accountant in administering the disclosure requirements of the federal securities laws.

Dated: November 24, 2021.

J. Matthew DeLesDernier,
Assistant Secretary.

PART 211—[AMENDED]

Accordingly, Part 211 of Title 17 of the Code of Federal Regulations is amended as follows:

PART 211—INTERPRETATIONS RELATING TO FINANCIAL REPORTING MATTERS

■ 1. The authority citation for 17 CFR 211 continues to read as follows:

Authority: 15 U.S.C. 77g, 15 U.S.C. 77s(a), 15 U.S.C. 77aa(25) and (26), 15 U.S.C. 78c(b), 17 CFR 78l(b) and 13(b), 17 CFR 78m(b) and 15 U.S.C. 80a–8, 30(e) 15 U.S.C. 80a–29(e), 15 U.S.C. 80a–30, and 15 U.S.C. 80a–37(a).

■ 2. Amend the table in subpart B by adding an entry for Staff Accounting Bulletin No. 120 at the end of the table to read as follows:

Subpart B—Staff Accounting Bulletins