

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022-06-19 Leonardo S.p.a.: Amendment 39-21985; Docket No. FAA-2022-0008; Project Identifier MCAI-2021-00882-R.

(a) Effective Date

This airworthiness directive (AD) is effective May 11, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Leonardo S.p.a. Model AW109SP helicopters, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 2560, Emergency Equipment.

(e) Unsafe Condition

This AD was prompted by reports of corrosion inside the hoist support assembly (boom assembly) (affected part) that affects both the huck bolt heads (blind bolt fasteners) and the support surface. The FAA is issuing this AD to address corrosion on the hoist support assembly. This condition, if not addressed, could affect the structural integrity of the hoist support assembly, leading to in-flight detachment of the hoist support and consequent damage to the helicopter, and injury to hoisted persons.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021-0179, dated July 27, 2021 (EASA AD 2021-0179).

(h) Exceptions to EASA AD 2021-0179

(1) Where EASA AD 2021-0179 requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(2) Where EASA AD 2021-0179 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where the service information referenced in EASA AD 2021-0179 specifies discarding parts, this AD requires removing those parts from service.

(4) Where the service information referenced in EASA AD 2021-0179 specifies returning a part to the manufacturer, this AD requires removing that part from service.

(5) Where the service information referenced in EASA AD 2021-0179 specifies submitting photographs to the manufacturer, this AD does not require that action.

(6) Where the service information referenced in EASA AD 2021-0179 specifies attaching a label to the hoist support assembly, this AD does not require that action.

(7) Where paragraph (2) of EASA AD 2021-0179 specifies contacting Leonardo S.p.a. for corrective action instructions, this AD requires replacing or repairing before further flight using a method approved by the Manager, General Aviation and Rotorcraft Section, International Validation Branch, FAA; or EASA; or Leonardo S.p.a.'s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(8) This AD does not mandate compliance with the "Remarks" section of EASA AD 2021-0179.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2021-0179 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits may be permitted provided that there are no passengers on board.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7330; email andrea.jimenez@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0179, dated July 27, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0179, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0008.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 10, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-07263 Filed 4-5-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 97**

[Docket No. 31420; Amdt. No. 4001]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This rule establishes, amends, suspends, or removes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures (ODPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational

facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective April 6, 2022. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 6, 2022.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For Examination

1. U.S. Department of Transportation, Docket Ops-M30. 1200 New Jersey Avenue SE, West Bldg., Ground Floor, Washington, DC 20590-0001.

2. The FAA Air Traffic Organization Service Area in which the affected airport is located;

3. The office of Aeronautical Information Services, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Availability

All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit the National Flight Data Center at nfdc.faa.gov to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from the FAA Air Traffic Organization Service Area in which the affected airport is located.

FOR FURTHER INFORMATION CONTACT:

Thomas J. Nichols, Flight Procedures and Airspace Group, Flight Technologies and Procedures Division, Flight Standards Service, Federal Aviation Administration. Mailing Address: FAA Mike Monroney Aeronautical Center, Flight Procedures and Airspace Group, 6500 South MacArthur Blvd., Registry Bldg. 29, Room 104, Oklahoma City, OK 73169. Telephone (405) 954-4164.

SUPPLEMENTARY INFORMATION: This rule amends 14 CFR part 97 by establishing, amending, suspending, or removes SIAPs, Takeoff Minimums and/or ODPS. The complete regulatory

description of each SIAP and its associated Takeoff Minimums or ODP for an identified airport is listed on FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR part 97.20. The applicable FAA Forms 8260-3, 8260-4, 8260-5, 8260-15A, 8260-15B, when required by an entry on 8260-15A, and 8260-15C.

The large number of SIAPs, Takeoff Minimums and ODPs, their complex nature, and the need for a special format make publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, Takeoff Minimums or ODPs, but instead refer to their graphic depiction on charts printed by publishers or aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP, Takeoff Minimums and ODP listed on FAA form documents is unnecessary. This amendment provides the affected CFR sections and specifies the typed of SIAPs, Takeoff Minimums and ODPs with their applicable effective dates. This amendment also identifies the airport and its location, the procedure, and the amendment number.

Availability and Summary of Material Incorporated by Reference

The material incorporated by reference is publicly available as listed in the **ADDRESSES** section.

The material incorporated by reference describes SIAPs, Takeoff Minimums and/or ODPs as identified in the amendatory language for part 97 of this final rule.

The Rule

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP, Takeoff Minimums and ODP as amended in the transmittal. Some SIAP and Takeoff Minimums and textual ODP amendments may have been issued previously by the FAA in a Flight Data Center (FDC) Notice to Airmen (NOTAM) as an emergency action of immediate flights safety relating directly to published aeronautical charts.

The circumstances that created the need for some SIAP and Takeoff Minimums and ODP amendments may require making them effective in less than 30 days. For the remaining SIAPs and Takeoff Minimums and ODPs, an effective date at least 30 days after publication is provided.

Further, the SIAPs and Takeoff Minimums and ODPs contained in this amendment are based on the criteria

contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these SIAPs and Takeoff Minimums and ODPs, the TERPS criteria were applied to the conditions existing or anticipated at the affected airports. Because of the close and immediate relationship between these SIAPs, Takeoff Minimums and ODPs, and safety in air commerce, I find that notice and public procedure under 5 U.S.C. 553(b) are impracticable and contrary to the public interest and, where applicable, under 5 U.S.C. 553(d), good cause exists for making some SIAPs effective in less than 30 days.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Lists of Subjects in 14 CFR Part 97

Air traffic control, Airports, Incorporation by reference, Navigation (air).

Issued in Washington, DC, on March 18, 2022.

Thomas J. Nichols,

Aviation Safety, Flight Standards Service, Manager, Standards Section, Flight Procedures & Airspace Group, Flight Technologies & Procedures Division.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me, Title 14, Code of Federal Regulations, Part 97 (14 CFR part 97) is amended by establishing, amending, suspending, or removing Standard Instrument Approach Procedures and/or Takeoff Minimums and Obstacle Departure Procedures effective at 0901 UTC on the dates specified, as follows:

PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

■ 1. The authority citation for part 97 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44701, 44719, 44721-44722.

■ 2. Part 97 is amended to read as follows:

Effective 19 May 2022

Colorado Springs, CO, KCOS, ILS OR LOC RWY 35L, ILS RWY 35L (SA CAT II), Amdt 40

Colorado Springs, CO, KCOS, NDB RWY 35L, Amdt 28

Dublin, GA, KDBN, ILS OR LOC RWY 2, Amdt 3

Idaho Falls, ID, KIDA, ILS OR LOC RWY 21, Amdt 12A

Idaho Falls, ID, KIDA, RNAV (GPS) Y RWY 3, Amdt 2A

Idaho Falls, ID, KIDA, RNAV (GPS) Y RWY 21, Amdt 2A

Idaho Falls, ID, KIDA, RNAV (RNP) Z RWY 3, Amdt 1A

Idaho Falls, ID, KIDA, RNAV (RNP) Z RWY 21, Amdt 1A

Pocatello, ID, KPIH, ILS OR LOC RWY 21, Amdt 27

Pocatello, ID, KPIH, RNAV (GPS) RWY 3, Amdt 2

Pocatello, ID, KPIH, RNAV (GPS) RWY 21, Amdt 2

Galesburg, IL, KGBG, RNAV (GPS) RWY 3, Orig-C

Galesburg, IL, KGBG, RNAV (GPS) RWY 21, Orig-C

Frankfort, IN, KFKR, RNAV (GPS) RWY 27, Amdt 1B

Kokomo, IN, KOKK, ILS OR LOC RWY 23, Amdt 11

Kokomo, IN, KOKK, RNAV (GPS) RWY 5, Amdt 1A

Kokomo, IN, KOKK, RNAV (GPS) RWY 23, Amdt 1D

Kokomo, IN, KOKK, VOR RWY 32, Amdt 21, CANCELLED

Marion, IN, KMZZ, ILS OR LOC RWY 4, Amdt 8A

Old Town, ME, KOLD, RNAV (GPS) RWY 12, Amdt 1

Old Town, ME, KOLD, RNAV (GPS) RWY 22, Amdt 1

Old Town, ME, KOLD, RNAV (GPS) RWY 30, Amdt 1

Old Town, ME, Dewitt Fld/Old Town Muni, Takeoff Minimums and Obstacle DP, Amdt 1

Battle Creek, MI, KBTL, ILS OR LOC RWY 23R, Amdt 20

Ludington, MI, Mason County, Takeoff Minimums and Obstacle DP, Amdt 7

Sturgis, MI, KIRS, NDB RWY 18, Amdt 6

Sturgis, MI, KIRS, NDB RWY 24, Amdt 11

Twin Bridges, MT, KRVF, RNAV (GPS) RWY 17, Amdt 1

Twin Bridges, MT, KRVF, RNAV (GPS) RWY 35, Amdt 1

Silver City, NM, K SVC, RNAV (GPS) RWY 8, Amdt 1

Silver City, NM, K SVC, RNAV (GPS) RWY 26, Amdt 1

Tulsa, OK, KTUL, ILS OR LOC RWY 18R, Amdt 8

Tulsa, OK, KTUL, RADAR-1, Amdt 19

Tulsa, OK, KTUL, RNAV (GPS) RWY 18L, Amdt 2

Tulsa, OK, KTUL, RNAV (GPS) RWY 18R, Amdt 2

Tulsa, OK, KTUL, RNAV (GPS) RWY 36L, Amdt 1

Vancouver, WA, K VUO, LDA-A, Amdt 2, CANCELLED

Vancouver, WA, K VUO, RNAV (GPS)-B, Orig *RESCINDED*: On March 14, 2022 (87 FR 14165), the FAA published an Amendment in Docket No. 31418, Amdt No. 3999, to Part 97 of the Federal Aviation Regulations under section 97.29, 97.33 and 97.37. The following entries for Rangeley, ME, Detroit, MI, and Troy, MI, effective May 19, 2022, are hereby rescinded in their entirety:

Rangeley, ME, 8B0, RNAV (GPS) RWY 14, Orig

Rangeley, ME, 8B0, RNAV (GPS) RWY 32, Orig

Detroit, MI, KYIP, ILS OR LOC RWY 5, Orig

Detroit, MI, KYIP, ILS OR LOC RWY 5R, Amdt 16, CANCELLED

Detroit, MI, KYIP, ILS OR LOC RWY 23, Orig

Detroit, MI, KYIP, ILS OR LOC RWY 23L, Amdt 8, CANCELLED

Detroit, MI, KYIP, RNAV (GPS) RWY 5, Orig

Detroit, MI, KYIP, RNAV (GPS) RWY 5R, Amdt 2, CANCELLED

Detroit, MI, KYIP, RNAV (GPS) RWY 23, Orig

Detroit, MI, KYIP, RNAV (GPS) RWY 23L, Amdt 2, CANCELLED

Detroit, MI, Willow Run, Takeoff Minimums and Obstacle DP, Amdt 11

Troy, MI, KVLL, RNAV (GPS) RWY 10, Amdt 3A

Troy, MI, KVLL, Takeoff Minimums and Obstacle DP, Amdt 4B

[FR Doc. 2022-07202 Filed 4-5-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 31421; Amdt. No. 4002]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This rule amends, suspends, or removes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide for the safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective April 6, 2022. The compliance date for each

SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 6, 2022.

ADDRESSES: Availability of matter incorporated by reference in the amendment is as follows:

For Examination

1. U.S. Department of Transportation, Docket Ops-M30, 1200 New Jersey Avenue SE, West Bldg., Ground Floor, Washington, DC 20590-0001;

2. The FAA Air Traffic Organization Service Area in which the affected airport is located;

3. The office of Aeronautical Information Services, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,

4. The National Archives and Records Administration (NARA).

For information on the availability of this material at NARA, email fr.inspection@nara.gov or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Availability

All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit the National Flight Data Center online at nfdc.faa.gov to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from the FAA Air Traffic Organization Service Area in which the affected airport is located.

FOR FURTHER INFORMATION CONTACT:

Thomas J. Nichols, Flight Procedures and Airspace Group, Flight Technologies and Procedures Division, Flight Standards Service, Federal Aviation Administration. Mailing Address: FAA Mike Monroney Aeronautical Center, Flight Procedures and Airspace Group, 6500 South MacArthur Blvd., Registry Bldg. 29, Room 104, Oklahoma City, OK 73169. Telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This rule amends 14 CFR part 97 by amending the referenced SIAPs. The complete regulatory description of each SIAP is listed on the appropriate FAA Form 8260, as modified by the National Flight Data Center (NFDC)/Permanent Notice to Airmen (P-NOTAM), and is incorporated by reference under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR 97.20. The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register**