describes the unsafe condition as free play in the trim tab actuator and trim tab surface. The FAA is issuing this AD to detect and correct free play in the trim tab connection, which could lead to reduced airplane control.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

### (g) Trim Tab Surface Free Play Inspection and Maintenance

Within 100 hours time-in-service (TIS) after the effective date of this AD and thereafter at intervals not to exceed 100 hours TIS, measure the trim tab surface for free play in accordance with Appendix A, Accomplishment Instructions, section 2 (Step 1—Trim Tab surface free play measurement) on pages 3 and 4 of Tecnam Service Bulletin 398-CS-Edition 2, Rev. 1, dated August 17, 2020 (Tecnam SB 398-CS-Edition 2, Rev. 1). If there is free play that exceeds the allowable tolerance, before further flight, measure the trim tab actuator for free play and take any corrective actions in accordance with Appendix A, Accomplishment Instructions, section 3 (Step 2-Trim Actuator free play measurement) on page 5 of Tecnam SB 398-CS-Edition 2, Rev 1.

### (h) Credit for Previous Actions

You may take credit for the initial inspection required by paragraph (g) of this AD if you performed that action before the effective date of this AD using Tecnam Service Bulletin 398–CS–Edition 2, Rev. 0, dated August 5, 2020.

### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office.

## (j) Related Information

(1) For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329–4165; email: jim.rutherford@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2021–0119, dated April 30, 2021, for more information. You may examine the EASA AD in the AD docket at *https://www.regulations.gov* by searching for and locating Docket No. FAA–2022–0151.

### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Tecnam Service Bulletin 398–CS– Edition 2, Rev. 1, dated August 17, 2020. (ii) [Reserved]

(3) For service information identified in this AD, contact Costruzioni Aeronautiche Tecnam S.P.A., Airworthiness Office, Via S. D'acquisto 62, Boscotrecase, 80042, Italy; phone: +39 0823 997538; email: traveller.support@Tecnam.com; website: https://www.Tecnam.com.

(4) You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: https://www.archives.gov/federal-register/cfr/ ibr-locations.html.

Issued on June 4, 2022.

#### Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service. [FR Doc. 2022–12762 Filed 6–13–22; 8:45 am]

BILLING CODE 4910-13-P

### **DEPARTMENT OF TRANSPORTATION**

## **Federal Aviation Administration**

#### 14 CFR Part 71

[Docket No. FAA-2022-0306; Airspace Docket No. 22-AGL-16]

## RIN 2120-AA66

## Amendment of Class E Airspace; Baldwin, MI

**AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule.

**SUMMARY:** This action amends the Class E airspace at Baldwin, MI. The FAA is finalizing this action due to an airspace review conducted as part of the decommissioning of the White Cloud very high frequency (VHF) omnidirectional range (VOR) as part of the VOR Minimal Operational Network (MON) Program. The geographic coordinates of the airport are also being updated to coincide with the FAA's aeronautical database.

**DATES:** Effective 0901 UTC, September 8, 2022. The Director of the Federal

Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at *https:// www.faa.gov/air\_traffic/publications/*. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

## FOR FURTHER INFORMATION CONTACT:

Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222–5711.

## SUPPLEMENTARY INFORMATION:

### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends the Class E airspace extending upward from 700 feet above the surface at Baldwin Municipal Airport, Baldwin, MI, to support instrument flight rule operations at this airport.

### History

The FAA published a notice of proposed rulemaking in the **Federal Register** (87 FR 21062; April 11, 2022) for Docket No. FAA–2022–0306 to amend the Class E airspace at Baldwin, MI. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6005 of FAA Order JO 7400.11F, dated August 10, 2021, and effective September 15, 2021, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in FAA Order JO 7400.11. 35896

## Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021. FAA Order JO 7400.11F is publicly available as listed in the **ADDRESSES** section of this document. FAA Order JO 7400.11F lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

### The Rule

This amendment to 14 CFR part 71 amends the Class E airspace extending upward from 700 feet above the surface at Baldwin Municipal Airport, Baldwin, MI, by removing the White Cloud VOR and associated extension from the airspace legal description; and updates the geographic coordinates of the airport to coincide with the FAA's aeronautical database.

This action is due to an airspace review conducted as part of the decommissioning of the White Cloud VOR, which provided navigation information for the instrument procedures at this airport, as part of the VOR MON Program.

FAA Order JŎ 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

## **Regulatory Notices and Analyses**

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) is not a 'significant regulatory action'' under Executive Order 12866; (2) is not a "significant rule" under DOT **Regulatory Policies and Procedures (44** FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### **Environmental Review**

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, Environmental Impacts: Policies and Procedures, paragraph 5– 6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

### Lists of Subjects in 14 CFR 71

Airspace, Incorporation by reference, Navigation (air).

## Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

## PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

## §71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021, is amended as follows:

Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth. \* \* \* \* \* \*

### AGL MI E5 Baldwin, MI [Amended]

Baldwin Municipal Airport, MI

(Lat. 43°52′32″N, long. 85°50′31″W) That airspace extending upward from 700 feet above the surface within a 6.5-mile radius of the Baldwin Municipal Airport.

Issued in Fort Worth, Texas, on June 8, 2022.

#### Martin A. Skinner,

Acting Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. 2022–12696 Filed 6–13–22; 8:45 am] BILLING CODE 4910–13–P

## DEPARTMENT OF TRANSPORTATION

#### **Federal Aviation Administration**

## 14 CFR Part 71

[Docket No. FAA-2022-0311; Airspace Docket No. 22-ASW-7]

## RIN 2120-AA66

## Amendment of Class E Airspace; Graham, TX

**AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule. **SUMMARY:** This action amends the Class E airspace at Graham, TX. The FAA is finalizing this action due to an airspace review conducted as part of the decommissioning of the Graham non-directional beacon (NDB). The geographic coordinates of the airport are also being updated to coincide with the FAA's aeronautical database.

**DATES:** Effective 0901 UTC, September 8, 2022. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at *https:// www.faa.gov/air\_traffic/publications/*. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

# FOR FURTHER INFORMATION CONTACT:

Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222–5711.

# SUPPLEMENTARY INFORMATION:

#### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends the Class E airspace extending upward from 700 feet above the surface at Graham Municipal Airport, Graham, TX, to support instrument flight rule operations at this airport.

## History

The FAA published a notice of proposed rulemaking in the **Federal Register** (87 FR 21066; April 11, 2022) for Docket No. FAA–2022–0311 to amend the Class E airspace at Graham, TX. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the