

Rules and Regulations

Federal Register

Vol. 88, No. 10

Tuesday, January 17, 2023

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-1302; Project Identifier MCAI-2022-00062-E; Amendment 39-22301; AD 2023-01-07]

RIN 2120-AA64

Airworthiness Directives; GE Aviation Czech s.r.o. (Type Certificate Previously Held by WALTER Engines a.s., Walter a.s., and MOTORLET a.s.) Turboprop Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all GE Aviation Czech s.r.o. (GEAC) H75-100, H75-200, H80, H80-100, H80-200, H85-100, and H85-200 model turboprop engines. This AD is prompted by the manufacturer revising the airworthiness limitations section (ALS) of the existing engine maintenance manual (EMM) to introduce updated coefficients for the calculation of the cyclic life and safe life for the main shaft. This AD requires revising the ALS of the existing EMM and the operator's existing approved maintenance or inspection program, as applicable, to incorporate the updated coefficients and recalculate the cycles accumulated on critical parts. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective February 21, 2023.

ADDRESSES:

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2022-1302; or in person at Docket Operations between 9 a.m. and

5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Barbara Caufield, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7146; email: barbara.caufield@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all GEAC H75-100, H75-200, H80, H80-100, H80-200, H85-100, and H85-200 model turboprop engines. The NPRM published in the **Federal Register** on October 24, 2022 (87 FR 64175). The NPRM was prompted by AD 2022-0008, dated January 19, 2022, issued by the European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union (referred to after this as the MCAI). The MCAI states that the airworthiness limitations for H series engine models, which are approved by EASA, are currently defined and published in the ALS of the GEAC EMM. These instructions have been identified as mandatory for continued airworthiness. Failure to accomplish these instructions could result in an unsafe condition. The MCAI explains that recently GEAC published a revision to the ALS, introducing updated coefficients for the calculation of the cyclic life and safe life for the main shaft.

In the NPRM, the FAA proposed to require revising the ALS of the existing EMM and the operator's existing approved maintenance or inspection program, as applicable, to incorporate the updated coefficients and recalculate the cycles accumulated on critical parts. An owner/operator (pilot) holding at least a private pilot certificate may

revise the ALS of the existing EMM, and the owner/operator must enter compliance with the applicable paragraphs of the AD into the aircraft records in showing compliance with this AD in accordance with 14 CFR 43.9(a) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417, 121.380, or 135.439. This is an exception to the FAA's standard maintenance regulations. The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2022-1302.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Conclusion

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM.

Related Service Information

The FAA reviewed the ALS of the GEAC EMM, Part No: 0983402, Rev. 22, dated December 18, 2020. This service information provides updated coefficients for the calculation of the cyclic life and safe life for the main shaft.

Costs of Compliance

The FAA estimates that this AD affects 33 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Revise the ALS of the EMM and the operator's existing approved maintenance or inspection program.	1 work-hour × \$85 per hour = \$85.	\$0	\$85	\$2,805

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,

- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2023-01-07 GE Aviation Czech s.r.o (Type Certificate previously held by WALTER Engines a.s., Walter a.s., and MOTORLET a.s.): Amendment 39-22301; Docket No. FAA-2022-1302; Project Identifier MCAI-2022-00062-E.

(a) Effective Date

This airworthiness directive (AD) is February 21, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to GE Aviation Czech s.r.o. (Type Certificate previously held by WALTER Engines a.s., Walter a.s., and MOTORLET a.s.) H75-100, H75-200, H80, H80-100, H80-200, H85-100, and H85-200 model turboprop engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7200, Engine (Turbine/Turboprop).

(e) Unsafe Condition

This AD was prompted by the manufacturer revising the airworthiness limitations section (ALS) of the existing engine maintenance manual (EMM) to introduce updated coefficients for the calculation of the cyclic life and safe life for the main shaft. The FAA is issuing this AD to prevent failure of the engine. The unsafe condition, if not addressed, could result in uncontained release of a critical part, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

- (1) Within 90 days of the effective date of this AD, revise the ALS of the existing EMM and the existing approved maintenance or inspection program, as applicable, to incorporate the information in Table 1 to paragraph (g)(1) of this AD and recalculate the cycles accumulated on critical parts.

TABLE 1 TO PARAGRAPH (g)(1)—EQUIVALENT CYCLIC LIFE (N) AND SAFE LIFE OF CRITICAL PARTS

Description	Drawing No.	Abbreviated flight cycle coefficient		Flight mission coefficient	Equivalent cyclic life limit
		A _V	A _P	L	N
Main Shaft	M601-1017.75	0.47		1.05	16,000

(2) After performing the action required by paragraph (g)(1) of this AD, except as provided in paragraph (h) of this AD, no alternative life limits may be approved.

(3) The action required by paragraph (g)(1) of this AD may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with §§ 43.9(a) and 91.417(a)(2)(v). The record must be

maintained as required by § 91.417, 121.380, or 135.439.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in § 39.19. In accordance with § 39.19, send your request to your principal inspector or local Flight Standards District Office, as

appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(2) of this AD and email to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Additional Information

(1) Refer to European Union Aviation Safety Agency (EASA) AD 2022–0008, dated January 19, 2022, for related information. This EASA AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2022–1302.

(2) For more information about this AD, contact Barbara Caufield, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7146; email: barbara.caufield@faa.gov.

(j) Material Incorporated by Reference

None.

Issued on January 6, 2023.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–00490 Filed 1–13–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA–2022–1225; Airspace Docket No. 22–AGL–31]

RIN 2120–AA66

Amendment of Class E Airspace; Plymouth and Winamac, IN

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends the Class E airspace at Plymouth and Winamac, IN. This action is due to airspace reviews conducted as part of the decommissioning of the Knox very high frequency (VHF) omnidirectional range (VOR) as part of the VOR Minimal Operational Network (MON) Program. The geographic coordinates of Plymouth Municipal Airport are also being updated to coincide with the FAA’s aeronautical database.

DATES: Effective 0901 UTC, April 20, 2023. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order JO 7400.11G, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

FOR FURTHER INFORMATION CONTACT:

Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222–5711.

SUPPLEMENTARY INFORMATION:**Authority for This Rulemaking**

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends the Class E airspace extending upward from 700 feet above the surface at Plymouth Municipal Airport, Plymouth, IN, and Arens Field, Winamac, IN, to support instrument flight rule operations at these airports.

History

The FAA published a notice of proposed rulemaking in the **Federal Register** (87 FR 66627; November 4, 2022) for Docket No. FAA–2022–1225 to amend the Class E airspace at Plymouth and Winamac, IN. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6005 of FAA Order JO 7400.11G, dated August 19, 2022, and effective September 15, 2022, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in FAA Order JO 7400.11.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order JO 7400.11G, Airspace Designations and Reporting Points, dated August 19, 2022, and effective September 15, 2022. FAA Order JO 7400.11G is publicly available as listed in the **ADDRESSES** section of this document. FAA Order JO 7400.11G lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This amendment to 14 CFR part 71: Amends the Class E airspace extending upward from 700 feet above the surface to within a 6.4-mile (increased from a 6.3-mile) radius of Plymouth Municipal Airport, Plymouth, IN; and updates the geographic coordinates of the airport to coincide with the FAA’s aeronautical database; And amends the Class E airspace extending upward from 700 feet above the surface to within a 6.4-mile (decreased from a 7-mile) radius of Arens Field, Winamac, IN; and removes the city associated with the airport in the airspace legal description header to comply with changes to FAA Order JO 7400.2N, Procedures for Handling Airspace Matters.

This action is due to airspace reviews conducted as part of the decommissioning of the Knox VOR, which provided navigation information for the instrument procedures at this airport, as part of the VOR MON Program.

FAA Order JO 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, “Environmental Impacts: Policies and Procedures,” paragraph 5–6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist