

(2) FCSIC, as receiver, will immediately apply the funds in a borrower's uninsured account(s) as payment against the outstanding balance of the borrower's loan(s).

(e) *Final discharge and release of the receiver.* The receivership terminates after FCSIC makes a final distribution of the assets of the liquidated institution. Then, the Farm Credit Administration Board will completely and finally release and discharge the receiver.

#### Subpart D—Voluntary Liquidation

##### § 627.2795 [Redesignated as § 627.40]

■ 7. Redesignate § 627.2795 as § 627.40.

##### § 627.40 [Amended]

■ 8. In newly redesignated § 627.40, in paragraph (a), remove “subpart B” and add “subpart C” in its place.

##### § 627.2797 [Redesignated as § 627.41]

■ 9. Redesignate § 627.2797 as § 627.41.

■ 10. In newly redesignated § 627.41, revise the last sentence in paragraph (a) to read as follows:

##### § 627.41 Preservation of equity.

(a) \* \* \* In the event the resolution to liquidate is approved by the stockholders of the Farm Credit institution and the liquidation plan is approved by the Farm Credit Administration Board, the liquidation plan shall govern disposition of the equities of the Farm Credit institution.

\* \* \* \* \*

Dated: November 15, 2023.

Ashley Waldron,

Secretary, Farm Credit Administration Board.

[FR Doc. 2023–25652 Filed 11–22–23; 8:45 am]

BILLING CODE 6705–01–P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2023–1722; Project Identifier MCAI–2023–00493–T; Amendment 39–22597; AD 2023–22–13]

RIN 2120–AA64

#### Airworthiness Directives; Dassault Aviation Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is superseding Airworthiness Directive (AD) 2023–04–15, which applied to certain Dassault Aviation Model FALCON 7X airplanes. AD 2023–04–15 required revising the

existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This AD continues to require the actions in AD 2023–04–15 and requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective December 29, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 29, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of May 10, 2023 (88 FR 20062, April 5, 2023).

#### ADDRESSES:

**AD Docket:** You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–1722; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### Material Incorporated by Reference:

- For material incorporated by reference in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADS@easa.europa.eu](mailto:ADS@easa.europa.eu); website [easa.europa.eu](https://easa.europa.eu). You may find this material on the EASA website at [ad.easa.europa.eu](https://ad.easa.europa.eu).

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–1722.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 206–231–3226; email: [tom.rodriguez@faa.gov](mailto:tom.rodriguez@faa.gov).

## SUPPLEMENTARY INFORMATION:

### Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2023–04–15, Amendment 39–22362 (88 FR 20062, April 5, 2023) (AD 2023–04–15). AD 2023–04–15 applied to certain Dassault Aviation Model FALCON 7X airplanes. AD 2023–04–15 required revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA issued AD 2023–04–15 to address reduced structural integrity and reduced control of the airplane due to the failure of system components. AD 2023–04–15 specified that accomplishing the revision required by that AD terminates the requirements of paragraph (q) of AD 2014–16–23, Amendment 39–17947 (79 FR 52545, September 4, 2014) (AD 2014–16–23). This AD therefore continues to allow that terminating action.

The NPRM published in the **Federal Register** on August 29, 2023 (88 FR 59473). The NPRM was prompted by AD 2023–0063, dated March 20, 2023, issued by EASA, which is the Technical Agent for the Member States of the European Union (EASA AD 2023–0063) (also referred to as the MCAI). The MCAI states that new or more restrictive airworthiness limitations have been developed.

In the NPRM, the FAA proposed to continue to require the actions in AD 2023–04–15 and to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in EASA AD 2023–0063. The FAA is issuing this AD to address reduced structural integrity and reduced control of the airplane due to the failure of system components.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–1722.

### Discussion of Final Airworthiness Directive

#### Comments

The FAA received no comments on the NPRM or on the determination of the cost to the public.

#### Conclusion

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data and

determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

#### Related Service Information Under 1 CFR Part 51

The FAA reviewed EASA AD 2023–0063. This service information specifies new or more restrictive airworthiness limitations for airplane structures and safe life limits.

This AD also requires EASA AD 2022–0142, dated July 7, 2022, which the Director of the Federal Register approved for incorporation by reference as of May 10, 2023 (88 FR 20062, April 5, 2023).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

#### Costs of Compliance

The FAA estimates that this AD affects 122 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

The FAA estimates the total cost per operator for the retained actions from AD 2021–09–12 to be \$7,650 (90 work-hours × \$85 per work-hour).

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate.

The FAA estimates the total cost per operator for the new actions to be \$7,650 (90 work-hours × \$85 per work-hour).

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA

with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
  - a. Removing Airworthiness Directive (AD) 2023–04–15, Amendment 39–22362 (88 FR 20062, April 5, 2023); and
  - b. Adding the following new AD:

#### 2023–22–13 Dassault Aviation:

Amendment 39–22597; Docket No. FAA–2023–1722; Project Identifier MCAI–2023–00493–T.

#### (a) Effective Date

This airworthiness directive (AD) is effective December 29, 2023.

#### (b) Affected ADs

- (1) This AD replaces AD 2023–04–15, Amendment 39–22362 (88 FR 20062, April 5, 2023) (AD 2023–04–15).

- (2) This AD affects AD 2014–16–23, Amendment 39–17947 (79 FR 52545, September 4, 2014) (AD 2014–16–23).

#### (c) Applicability

This AD applies to Dassault Aviation Model FALCON 7X airplanes, certificated in any category, with an original airworthiness certificate or original export certificate of airworthiness issued on or before September 7, 2022.

**Note 1 to paragraph (c):** Model FALCON 7X airplanes with modification M1000 incorporated are commonly referred to as “Model FALCON 8X” airplanes as a marketing designation.

#### (d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

#### (e) Unsafe Condition

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address reduced structural integrity and reduced control of the airplane due to the failure of system components.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Retained Revision of the Existing Maintenance or Inspection Program, With No Changes

This paragraph restates the requirements of paragraph (j) of AD 2023–04–15, with no changes. For airplanes with an original airworthiness certificate or original export certificate of airworthiness issued on or before June 7, 2021, except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2022–0142, dated July 7, 2022 (EASA AD 2022–0142). Accomplishing the revision of the existing maintenance or inspection program required by paragraph (j) of this AD terminates the requirements of this paragraph.

#### (h) Retained Exceptions to EASA AD 2022–0142, With No Changes

This paragraph restates the exceptions specified in paragraph (k) of AD 2023–04–15, with no changes.

(1) The requirements specified in paragraphs (1) and (2) of EASA AD 2022–0142 do not apply to this AD.

(2) Paragraph (3) of EASA AD 2022–0142 specifies revising “the approved AMP” within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after May 10, 2023 (the effective date of AD 2023–04–15).

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2022–0142 is at the applicable “limitations” and “associated thresholds” as incorporated by the requirements of paragraph (3) of EASA AD 2022–0142, or within 90 days after May 10, 2023 (the

effective date of this AD 2023–04–15), whichever occurs later.

(4) The provisions specified in paragraphs (4) and (5) of EASA AD 2022–0142 do not apply to this AD.

(5) The “Remarks” section of EASA AD 2022–0142 does not apply to this AD.

**(i) Retained Restrictions on Alternative Actions, Intervals, and Critical Design Configuration Control Limitations (CDCCLs), With a New Exception**

This paragraph restates the requirements of paragraph (l) of AD 2023–04–15, with a new exception. Except as required by paragraph (j) of this AD, after the maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, or CDCCLs are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2022–0142.

**(j) New Revision of the Existing Maintenance or Inspection Program**

Except as specified in paragraph (k) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2023–0063, dated March 20, 2023 (EASA AD 2023–0063). Accomplishing the revision of the existing maintenance or inspection program required by this paragraph terminates the requirements of paragraph (g) of this AD.

**(k) Exceptions to EASA AD 2023–0063**

(1) This AD does not adopt the requirements specified in paragraphs (1) and (2) of EASA AD 2023–0063.

(2) Paragraph (3) of EASA AD 2023–0063 specifies revising “the approved AMP [aircraft maintenance program]” within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after the effective date of this AD.

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2023–0063 is at the applicable “limitations” and “associated thresholds” as incorporated by the requirements of paragraph (3) of EASA AD 2023–0063, or within 90 days after the effective date of this AD, whichever occurs later.

(4) This AD does not adopt the provisions specified in paragraphs (4) and (5) of EASA AD 2023–0063.

(5) This AD does not adopt the “Remarks” section of EASA AD 2023–0063.

**(l) New Provisions for Alternative Actions, Intervals, and CDCCLs**

After the existing maintenance or inspection program has been revised as required by paragraph (j) of this AD, no alternative actions (e.g., inspections), intervals, and CDCCLs are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2023–0063.

**(m) Terminating Action for Certain Requirements in AD 2014–16–23**

Accomplishing the actions required by paragraphs (g) or (j) of this AD terminates the

requirements of paragraph (q) of AD 2014–16–23.

**(n) Additional AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (o) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Dassault Aviation’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

**(o) Additional Information**

For more information about this AD, contact Tom Rodriguez, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206–231–3226; email: [tom.rodriguez@faa.gov](mailto:tom.rodriguez@faa.gov).

**(p) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on December 29, 2023.

(i) European Union Aviation Safety Agency (EASA) AD 2023–0063, dated March 20, 2023.

(ii) [Reserved]

(4) The following service information was approved for IBR on May 10, 2023 (88 FR 20062, April 5, 2023).

(i) European Union Aviation Safety Agency (EASA) AD 2022–0142, dated July 7, 2022.

(ii) [Reserved]

(5) For EASA ADs 2023–0063 and 2022–0142, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find these EASA ADs on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu).

(6) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(7) You may view this material at the National Archives and Records

Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on November 16, 2023.

**Ross Landes,**

*Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2023–25833 Filed 11–22–23; 8:45 am]

BILLING CODE 4910–13–P

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 71**

[Docket No. FAA–2023–1296; Airspace Docket No. 23–ANE–2]

RIN 2120–AA66

**Amendment of Canadian Area Navigation Routes Q–907 and Q–951, and Establishment of United States Area Navigation (RNAV) Route T–739; Eastern United States**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action amends high altitude Canadian Area Navigation routes Q–907 and Q–951; and establishes United States (U.S.) Area Navigation (RNAV) route T–739, in support of the FAA’s Very High Frequency Omnidirectional Range (VOR) Minimum Operational Network (MON) Program. The purpose is to enhance the efficiency of the National Airspace System (NAS) by transitioning from ground-based navigation aids to a satellite-based navigation system.

**DATES:** Effective date 0901 UTC, January 25, 2024. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

**ADDRESSES:** A copy of the Notice of Proposed Rulemaking (NPRM), all comments received, this final rule, and all background material may be viewed online at [www.regulations.gov](http://www.regulations.gov) using the FAA Docket number. Electronic retrieval help and guidelines are available on the website. It is available 24 hours each day, 365 days each year.

FAA Order JO 7400.11H, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). You may also contact the Rules and Regulations Group, Office of Policy, Federal Aviation