

Proposed Rules

Federal Register

Vol. 90, No. 23

Wednesday, February 5, 2025

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2025-0020; Project Identifier MCAI-2024-00604-R]

RIN 2120-AA64

Airworthiness Directives; Leonardo S.p.a. Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Leonardo S.p.a. Model A109E, A109S, and AW109SP helicopters. This proposed AD was prompted by reports of incorrect installation of the motor (MTR) cables and the bonding braids connected to the engine fire extinguisher bottles. This proposed AD would require inspecting the cables and bonding braids installation and, depending on the results, accomplishing corrective action, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by March 24, 2025.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-0020; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For EASA material identified in this proposed AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu; website: easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-0020.

FOR FURTHER INFORMATION CONTACT:

Peter Schmitt, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (206) 231-3377; email: Peter.A.Schmitt@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2025-0020; Project Identifier MCAI-2024-00604-R” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each

substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Peter Schmitt, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (206) 231-3377; email: Peter.A.Schmitt@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2024-0193, dated October 11, 2024 (EASA AD 2024-0193) (also referred to as the MCAI), to correct an unsafe condition on certain serial-numbered Leonardo S.p.a. Model A109E, A109LUH, A109S, and AW109SP helicopters. The MCAI states that reports were received of incorrect installation of the MTR cables and the bonding braids connected to the engine fire extinguisher bottles. This condition, if not detected and corrected, could lead to reduced performance of the engine fire extinguishing system during an engine fire and subsequent loss of control of the helicopter. The FAA is proposing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-0020.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed EASA AD 2024-0193, which requires inspecting the left-

hand and right-hand side MTR cables and bonding braids for correct installation and, depending on the findings, accomplishing corrective action (disconnecting and properly reinstalling the affected MTR cable(s) and bonding braid(s)) in accordance with “the ASB” as defined within. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of these same type designs.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2024–0193, described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this proposed AD and except as discussed under “Differences Between this Proposed AD and the MCAI.”

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2024–0193 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2024–0193 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2024–0193 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,”

compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2024–0193. Material referenced in EASA AD 2024–0193 for compliance will be available at *regulations.gov* under Docket No. FAA–2025–0020 after the FAA final rule is published.

Differences Between This Proposed AD and the MCAI

EASA AD 2024–0193 applies to Model A109LUH helicopters; however, this proposed AD would not because that model is not FAA type-certificated.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 101 helicopters of U.S. registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with the proposed AD.

Inspecting the engine fire extinguisher bottle electrical connections would take 1 work-hour for an estimated cost of \$85 per helicopter and \$8,585 for the U.S. fleet.

Disconnecting and reinstalling the MTR cable(s) and bonding braid(s) would take up to 1 work-hour for an estimated cost of up to \$85 per helicopter.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or

on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Leonardo S.p.a.: Docket No. FAA–2025–0020; Project Identifier MCAI–2024–00604–R.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by March 24, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Leonardo S.p.a. Model A109E, A109S, and AW109SP helicopters, certificated in any category, as identified in European Union Aviation Safety Agency AD 2024–0193, dated October 11, 2024 (EASA AD 2024–0193).

(d) Subject

Joint Aircraft System Component (JASC) Code 2620, Extinguishing System.

(e) Unsafe Condition

This AD was prompted by reports of incorrect installation of the motor (MTR) cables and the bonding braids connected to the engine fire extinguisher bottles. The FAA is issuing this AD to detect and correct incorrect installation of the MTR cables and the bonding braids to the engine fire extinguisher bottles, which could lead to reduced performance of the engine fire extinguishing system during an engine fire and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2024–0193.

(h) Exceptions to EASA AD 2024–0193

(1) Where EASA AD 2024–0193 requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(2) Where EASA AD 2024–0193 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where paragraph (2) of EASA AD 2024–0193 states “any discrepancy,” this AD requires replacing that text with “an improper installation.”

(4) This AD does not adopt the “Remarks” section of EASA AD 2024–0193.

(i) No Reporting Requirement

Although the material referenced in EASA AD 2024–0193 specifies to submit certain information to the manufacturer, this AD does not require that action.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Peter Schmitt, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (206) 231–3377; email: Peter.A.Schmitt@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2024–0193, dated October 11, 2024.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu; website: easa.europa.eu. You may find the

EASA material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on January 30, 2025.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025–02221 Filed 2–4–25; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF THE TREASURY**Internal Revenue Service****26 CFR Part 1**

[REG–116017–24]

RIN 1545–BR36

Administrative Requirements for an Election To Exclude Applicable Unincorporated Organizations From the Application of Subchapter K; Hearing Cancellation

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Cancellation of a notice of public hearing on a proposed rulemaking and notice of public hearing.

SUMMARY: This document contains proposed regulations that would provide certain administrative requirements for unincorporated organizations taking advantage of modifications to the rules governing elections to be excluded from the application of partnership tax rules.

DATES: The public hearing scheduled for February 7, 2025, at 10 a.m. Eastern Standard Time (EST) is cancelled.

FOR FURTHER INFORMATION CONTACT: Martina Greene of the Publications and Regulations Section, Associate Chief Counsel (Procedure and Administration) at (202) 317–6901 (not a toll-free number).

SUPPLEMENTARY INFORMATION: A notice of proposed rulemaking and a notice of public hearing that appeared in the **Federal Register** on November 20, 2024 (89 FR 91617) announced that a public hearing being held in person and by teleconference was scheduled for February 7, 2025, at 10 a.m. EST. The

subject of the public hearing is under 26 CFR part 1.

The public comment period for these regulations expired on January 21, 2025. The notice of proposed rulemaking and notice of public hearing instructed those interested in testifying at the public hearing to submit a request to testify and an outline of the topics to be addressed. We did not receive a request to testify at the Public Hearing. Therefore, the public hearing scheduled for February 7, 2025, at 10 a.m. EST is cancelled.

Oluwafunmilayo A. Taylor,

Section Chief, Publications and Regulations Section, Associate Chief Counsel, (Procedure & Administration).

[FR Doc. 2025–02251 Filed 2–4–25; 8:45 am]

BILLING CODE 4830–01–P

POSTAL SERVICE**39 CFR Part 111****Optional 5-Digit/3-Digit/ADC Sortation**

AGENCY: Postal Service™.

ACTION: Proposed rule.

SUMMARY: The Postal Service is proposing to amend *Mailing Standards of the United States Postal Service*, Domestic Mail Manual (DMM®) to change the standards for First Class Mail® and USPS Marketing Mail® flats from a “required” 5-digit, 3-digit, and ADC preparation to an “optional” preparation.

DATES: Submit comments on or before March 7, 2025.

ADDRESSES: Mail or deliver written comments to the Director, Product Classification, U.S. Postal Service, 475 L’Enfant Plaza SW, Room 4446, Washington, DC 20260–5015. If sending comments by email, include the name and address of the commenter and send to PCFederalRegister@usps.gov, with a subject line of “Optional 5-Digit/3-Digit/ADC Sortation”. Faxed comments are not accepted.

You may inspect and photocopy all written comments, by appointment only, at USPS® Headquarters Library, 475 L’Enfant Plaza SW, 11th Floor North, Washington, DC 20260. These records are available for review on Monday through Friday, 9 a.m.–4 p.m., by calling 202–268–2906.

FOR FURTHER INFORMATION CONTACT: Dale Kennedy at (202) 268–6592 or Doriane Harley at (202) 268–2537.

SUPPLEMENTARY INFORMATION: All submitted comments and attachments are part of the public record and subject to disclosure. Do not enclose any