

symbol on the seat belt warning lamp; (c) recalibration of the speedometer/odometer from kilometers to miles per hour.

Standard No. 108 Lamps, Reflective Devices and Associated Equipment: (a) installation of U.S.-model headlamp assemblies and front sidemarkers; (b) installation of U.S.-model taillamp assemblies and rear sidemarkers; (c) installation of a high mounted stop lamp.

Standard No. 110 Tire Selection and Rims: installation of a tire information placard.

Standard No. 111 Rearview Mirror: replacement of the passenger side rearview mirror with a U.S.-model component.

Standard No. 114 Theft Protection: installation of a warning buzzer microswitch and a warning buzzer in the steering lock assembly.

Standard No. 115 Vehicle Identification Number: installation of a VIN plate that can be read from outside the left windshield pillar, and a VIN reference label on the edge of the door or latch post nearest the driver.

Standard No. 118 Power Window Systems: rewiring of the power window system so that the window transport is inoperative when the ignition is switched off.

Standard No. 208 Occupant Crash Protection: installation of a seat belt warning buzzer. The petitioner states that the vehicles are equipped with Type 2 seat belts in both designated seating positions. The petitioner further states that vehicles manufactured before September 1993 are equipped with driver's side air bags and knee bolsters and that vehicles manufactured after September 1993 are equipped with both driver's and passenger's side air bags and knee bolsters.

Standard No. 214 Side Impact Protection: installation of reinforcing beams.

Standard No. 301 Fuel System Integrity: installation of a rollover valve in the fuel tank vent line between the fuel tank and the evaporative emissions collection canister.

Additionally, the petitioner states that the bumpers on the non-U.S. certified 1992 and 1993 Mercedes-Benz 320SL must be reinforced to comply with the Bumper Standard found in 49 CFR Part 581.

Interested persons are invited to submit comments on the petition described above. Comments should refer to the docket number and be submitted to: Docket Section, National Highway Traffic Safety Administration, Room 5109, 400 Seventh Street, SW., Washington, DC 20590. It is requested

but not required that 10 copies be submitted.

All comments received before the close of business on the closing date indicated above will be considered, and will be available for examination in the docket at the above address both before and after that date. To the extent possible, comments filed after the closing date will also be considered. Notice of final action on the petition will be published in the Federal Register pursuant to the authority indicated below.

Authority: 49 U.S.C. 30141(a)(1)(A) and (b)(1); 49 CFR 593.8; delegations of authority at 49 CFR 1.50 and 501.8.

Issued on: October 24, 1995.

Marilynne Jacobs,

Director, Office of Vehicle Safety Compliance.
[FR Doc. 95-26813 Filed 10-27-95; 8:45 am]

BILLING CODE 4910-59-M

DEPARTMENT OF THE TREASURY

Public Information Collection Requirements Submitted to OMB for Review

October 16, 1995.

The Department of Treasury has submitted the following public information collection requirement(s) to OMB for review and clearance under the Paperwork Reduction Act of 1980, Public Law 96-511. Copies of the submission(s) may be obtained by calling the Treasury Bureau Clearance Officer listed. Comments regarding this information collection should be addressed to the OMB reviewer listed and to the Treasury Department Clearance Officer, Department of the Treasury, Room 2110, 1425 New York Avenue, NW., Washington, DC 20220.

Special Request: In order to conduct the survey described below in a timely manner, the Department of Treasury is requesting Office of Management and Budget (OMB) review and approval of this information collection by October 27, 1995. To obtain a copy of this survey, please write to the IRS Clearance Officer at the address listed below.

Internal Revenue Service (IRS)

OMB Number: 1545-1349

Project Number: SOI-13

Type of Review: Revision

Title: 1996 Automated TeleFile

Customer Satisfaction Survey

Description: Building on 1994 written and 1995 automated survey data from TeleFile users we plan to administer an automated survey data from TeleFile users, we plan to administer

an automated survey to a random systematic sample of taxpayers who successfully file their tax return January 1 through April 15, 1996 using TeleFile. The 1996 automated survey will obtain an overall measure of satisfaction and collect data to determine if one of the primary target populations for TeleFile, namely students, are using the service.

Respondents: Individuals or households

Estimated Number of Respondents:

Spanish Speaking—4,000

Non-Spanish Speaking—4,714

Estimated Burden Hours Per Respondent:

Spanish Speaking—2 minutes

Non-Spanish Speaking—2 minutes

Frequency of Response: Other

Estimated Total Reporting Burden: 247 hours

Clearance Officer: Garrick Shear (202) 622-3869, Internal Revenue Service, Room 5571, 1111 Constitution Avenue, N.W., Washington, DC 20224

OMB Reviewer: Milo Sunderhauf (202) 395-7340, Office of Management and Budget, Room 10226, New Executive Office Building, Washington, DC 20503

Lois K. Holland,

Departmental Reports Management Officer.
[FR Doc. 95-26855 Filed 10-27-95; 8:45 am]

BILLING CODE 4830-01-P

OFFICE OF THE UNITED STATES TRADE REPRESENTATIVE

Generalized System of Preferences; Expedited Review of Products That Are Eligible for a "De Minimis" Waiver Based on 1994 Import Statistics

AGENCY: Office of the United States Trade Representative.

ACTION: Notice and opportunity for public comment.

SUMMARY: This notice invites public comments on whether any "de minimis" waivers should be granted to eligible articles from beneficiary countries that exceed the 50-percent competitive need limit in 1994, but which are eligible for "de minimis" waivers because total U.S. imports of the products in 1994 did not exceed the "de minimis" limit.

FOR FURTHER INFORMATION CONTACT:

GSP Subcommittee, Office of the United States Trade Representative, 600 17th Street, N.W., Room 518, Washington, D.C. 20508. The telephone number is (202) 395-6971.

SUPPLEMENTARY INFORMATION:**I. The GSP Program**

The GSP program grants duty-free treatment to designated eligible articles that are imported from designated beneficiary developing countries. The GSP program is authorized by Title V of the Trade Act of 1974, as amended ("Trade Act") (19 U.S.C. 2461 *et seq.*), and was implemented by Executive Order 11888 of November 24, 1975, and modified by subsequent Executive Orders and Presidential Proclamations. The GSP regulations provide for an annual GSP review, unless otherwise specified by Federal Register notice (15 CFR 2007.3).

The GSP program expired on July 31, 1995 (see section 505(a) of the Trade Act (19 U.S.C. 2465(a))). A bill to renew the program is pending in Congress. This notice solicits public comments on whether to grant any so-called "de minimis" waivers, but the Administration cannot take any action unless and until the GSP program is reauthorized.

II. Competitive Need Limits

Section 504(c) of the Trade Act (19 U.S.C. 2464(c)) provides, in part, that any country, which has exported to the United States a quantity of an eligible article equal to or exceeding 50 percent of the appraised value of the total U.S. imports of the article during the most recent calendar year, shall lose GSP privileges for that article not later than July 1 of the next calendar year.

III. "De Minimis" Waivers

Section 504(d)(2) of the Trade Act (19 U.S.C. 2464(d)(2)) provides, however,

that the President may disregard the 50-percent limit with respect to any eligible article if the value of the total U.S. imports of the article during the most recent calendar year did not exceed \$5 million, indexed to the nominal growth of U.S. GNP since 1979. The "de minimis" limit for 1994 is \$13,346,358.

The countries/products in the annex to this notice exceeded the 50-percent limit in 1994, but total U.S. imports were less than the "de minimis" limit. In accordance with section 504(c) of the Trade Act, all such countries/products lost GSP on July 1, 1995 because the Administration did not conduct an annual GSP review for 1994 and the President did not grant any "de minimis" waivers (see 60 FR 28184).

The Administration has now decided to solicit public comments and to consider "de minimis" waivers on the merits. This notice invites public comments on whether "de minimis" waivers should be granted to the eligible articles from the beneficiary countries that are set forth in the annex to this notice. The Administration will not take any action unless and until the GSP program is reauthorized by the Congress.

IV. Public Comments

All written comments on whether "de minimis" waivers should be granted to the countries/products that are set forth in the annex to this notice should be addressed to: GSP Subcommittee, Office of the U.S. Trade Representative, 600 17th Street, N.W., Room 518, Washington, D.C. 20508. All submissions must be in English and should conform to the information requirements of 15 CFR 2007.

Furthermore, each party providing comments should indicate on the first page of the submission its name, the relevant subheading of the Harmonized Tariff Schedule of the United States and the relevant beneficiary country.

A party must provide fourteen copies of its statement which must be received by the Chairman of the GSP Subcommittee no later than 5 p.m., Wednesday, November 22. Comments received after the deadline will not be accepted. If the comments contain business confidential information, fourteen copies of a non-confidential version must also be submitted. A justification as to why the information contained in the submission should be treated confidentially must be included in the submission. In addition, the submissions containing confidential information should be clearly marked "confidential" at the top and bottom of each page of the submission. The version that does not contain confidential information should also be clearly marked, at the top and bottom of each page, "public version" or "non-confidential".

Written comments submitted in connection with these decisions, except for information granted "business confidential" status pursuant to 15 CFR 2007.7, will be available for public inspection shortly after the filing deadline by appointment only with the staff of the USTR Public Reading Room. Other requests and questions should be directed to the GSP Information Center at USTR by calling (202) 395-6971.

Frederick L. Montgomery,
Chairman, Trade Policy Staff Committee.

ANNEX.—GSP COUNTRIES EXCEEDING THE 50-PERCENT COMPETITIVE NEED LIMIT IN 1994 AND TOTAL U.S. IMPORTS WERE LESS THAN \$13,346.358

HTSUS	Partner	Description
0304.20.50	Argentina	Hake fillets.
0703.10.20	Chile	Onion sets.
0708.10.20	Guatemala	Peas.
0708.10.40	Guatemala	Peas.
0709.10.00	Chile	Artichokes.
0709.20.10	Peru	Asparagus.
0710.22.15	Guatemala	Lima beans.
0710.29.05	Turkey	Chickpeas.
0710.29.30	Dominican Republic	Pigeon peas.
0710.80.50	Dominican Republic	Tomatoes.
0710.80.65	Guatemala	Brussels sprouts.
0710.80.93	Guatemala	Okra.
0711.30.00	Turkey	Capers.
0711.40.00	Sri Lanka (Ceylon)	Cucumbers.
0714.10.00	Costa Rica	Cassava.
0714.20.00	Dominican Republic	Sweet potatoes.
0714.90.10	Costa Rica	Fresh dasheens.
0802.50.20	Turkey	Pistachios.
0802.50.40	Turkey	Pistachios.
0804.50.80	Thailand	Guavas, mangoes.
0811.20.20	Chile	Raspberries.

ANNEX.—GSP COUNTRIES EXCEEDING THE 50-PERCENT COMPETITIVE NEED LIMIT IN 1994 AND TOTAL U.S. IMPORTS WERE LESS THAN \$13,346.358—Continued

HTSUS	Partner	Description
0811.20.40	Chile	Blackberries.
0811.90.50	Costa Rica	Pineapples.
0811.90.55	Guatemala	Melons.
0813.30.00	Argentina	Apples.
0813.40.10	Thailand	Papayas.
0813.40.80	Thailand	Tamarinds.
1106.30.20	Ecuador	Banana flour.
1301.90.40	Brazil	Turpentine gum.
1519.11.00	Malaysia	Stearic acid.
1519.12.00	Malaysia	Oleic acid.
1601.00.40	Brazil	Sausages.
1604.14.50	Thailand	Tunas, skipjack.
1604.16.30	Morocco	Anchovies.
1604.30.20	Russia	Caviar.
1605.10.05	Thailand	Crab products.
1701.99.05	Colombia	Cane/beet sugar.
1701.99.10	Colombia	Cane/beet sugar.
1702.90.35	Belize	Invert molasses.
1703.90.30	Lebanon	Molasses.
1902.11.40	Thailand	Uncooked pasta.
2005.80.00	Thailand	Sweet corn.
2007.99.40	Thailand	Pineapple jam.
2009.99.48	Argentina	Apple pastes.
2008.19.30	Turkey	Pignolia.
2008.50.20	Argentina	Apricot pulp.
2008.99.28	Turkey	Figs.
2008.99.35	Thailand	Lychees.
2106.90.52	Philippines	Juice.
2202.90.36	Colombia	Juice.
2202.90.37	Dominican Republic	Mixed juices.
2207.10.30	Ecuador	Ethyl alcohol.
2208.90.10	Trinidad and Tobago	Bitters.
2208.90.70	Russia	Vodka.
2309.90.70	Hungary	Vitamin B12 feed.
2401.10.21	Dominican Republic	Wrapper tobacco.
2401.10.29	Honduras	Tobacco.
2401.20.45	Indonesia	Tobacco.
2401.20.55	Indonesia	Tobacco.
2516.90.00	South Africa	Building stone.
2804.29.00	Ukraine	Rare gases.
2805.40.00	Russia	Mercury.
2825.30.00	South Africa	Vanadium oxides.
2825.70.00	Chile	Molybdenum oxides.
2840.11.00	Turkey	Refined borax.
2843.21.00	Chile	Silver nitrate.
2903.14.00	Brazil	Carbon tetrachloride.
2903.23.00	Brazil	Tetrachloro.
2907.15.10	Russia	alpha-Naphthol.
2907.23.00	Brazil	Bisphenol.
2908.90.24	India	4,6-Dinitro.
2910.20.00	Brazil	Methyloxirane.
2915.34.00	Venezuela	Isobutyl aceta.
2915.35.00	Venezuela	2-Ethoxyethyl.
2917.14.10	Brazil	Maleic anhydrid.
2917.32.00	Brazil	Diocetyl ortho.
2917.37.00	Romania	Dimethyl tereph.
2921.42.21	India	Metanilic acid.
2922.29.25	India	Fast color bases.
2933.40.08	Hungary	4,7-Dichlor.
2938.10.00	Brazil	Rutoside.
3301.24.00	India	Essential oils.
3806.30.00	Argentina	Ester gums.
3920.93.00	India	Plates, sheets.
4006.10.00	Brazil	Rubber.
4104.31.20	Thailand	Buffalo leather.
4106.19.30	Pakistan	Goat leather.
4106.20.30	India	Goat leather.
4106.20.60	Pakistan	Goat leather.
4109.00.70	Brazil	Patent leather.
4202.22.35	Philippines	Handbags.
4205.00.60	Argentina	Reptile leather.

ANNEX.—GSP COUNTRIES EXCEEDING THE 50-PERCENT COMPETITIVE NEED LIMIT IN 1994 AND TOTAL U.S. IMPORTS WERE LESS THAN \$13,346.358—Continued

HTSUS	Partner	Description
4411.19.20	Brazil	Fiberboard.
4412.12.15	Brazil	Plywood.
4412.19.10	Brazil	Plywood.
4412.19.30	Russia	Plywood.
4412.19.40	Indonesia	Plywood.
4412.29.40	Brazil	Plywood.
4412.99.10	Brazil	Plywood.
4412.99.40	Indonesia	Plywood.
4417.00.60	Brazil	Wooden brush.
4421.90.10	Honduras	Wood dowel pins.
4802.60.10	Brazil	Writing paper.
4823.90.20	Philippines	Papier-mache.
5208.31.20	India	Cotton fabrics.
5208.32.10	India	Cotton fabrics.
5208.41.20	India	Cotton fabrics.
5208.42.10	India	Cotton fabrics.
5208.51.20	India	Cotton fabrics.
5208.52.10	India	Cotton fabrics.
5209.31.30	India	Cotton fabrics.
5209.41.30	India	Cotton fabrics.
5209.51.30	India	Cotton fabrics.
5307.20.00	India	Yarn of jute.
5607.30.20	Philippines	Twine, cordage.
5609.00.20	Philippines	Article of Yarn.
5702.20.10	India	Floor coverings.
5702.99.20	India	Carpets.
5703.90.00	India	Carpets.
6304.99.25	India	Wall hangings.
6501.00.60	Czech Republic	Hat forms.
7002.10.20	Malaysia	Glass in balls.
7109.00.00	Chile	Base metals.
7113.20.21	Oman	Rope necklace.
7114.19.00	Chile	Goldsmith wares.
7202.21.10	Macedonia (Skopje)	Ferrosilicon.
7308.20.00	Brazil	Steel towers.
7319.20.00	Malaysia	Safety pins.
7403.12.00	Peru	Wire bars.
7407.29.15	Chile	Copper profiles.
7603.10.00	Bahrain	Aluminum powders.
7614.10.50	Brazil	Stranded wire.
7614.90.20	Venezuela	Electrical cable.
7614.90.50	Venezuela	Stranded wire.
8107.90.00	Bulgaria	Cadmium.
8112.11.60	Kazakhstan	Berryllium.
8112.91.50	Chile	Rhenium.
8213.00.60	Brazil	Pinking shears.
8402.20.00	Colombia	Water boilers.
8414.90.30	Slovenia	Stators, rotors.
8450.90.40	Brazil	Furniture.
8483.50.40	Malaysia	Awning pulleys.
8519.21.00	Malaysia	Record players.
8519.31.00	Malaysia	Turntables.
8528.10.04	Hungary	TV receivers.
8528.10.34	Malaysia	TV receivers.
8546.10.00	Brazil	Electrical insulators.
8802.50.90	Russia	Spacecraft.
9018.11.60	Argentina	Circuit assemblies.
9102.29.04	Philippines	Wrist watthead.
9303.90.80	Russia	Firearms.
9401.90.15	Czech Republic	Parts of seats.
9506.61.00	Philippines	Lawn-tennis balls.
9606.29.20	Thailand	Button of resin.
9614.20.60	Turkey	Smoking pipes.
9614.20.80	Turkey	Smoking pipes.