# PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### §39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

### **Dornier Luftfahrt GMBH:** Docket 2001-NM–174-AD.

Applicability: Model 328–300 series airplanes, on which a forward engine mount vibration isolator has been removed or reinstalled since the date of manufacture of the airplane, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the engine mount, which could result in separation of the engine from the airplane, accomplish the following:

### **One-Time Inspection**

(a) For airplanes on which a forward engine mount vibration isolator has been removed or reinstalled prior to the effective date of this AD: Within 2,500 flight cycles after the first removal or reinstallation of a forward engine mount vibration isolator, or within 30 days after the effective date of this AD, whichever comes later, do a one-time torque test (inspection) of the attachment bolts of the forward engine mount vibration isolators on the left- and right-hand sides of the airplane to determine if the bolts are adequately torqued, according to Dornier Service Bulletin SB-328J-71-109, dated March 26, 2001, including Aircraft Maintenance Manual (AMM) Temporary Revision (TR) 71-130, dated March 8, 2001.

### Replacement of Bolts

(b) During the inspection required by paragraph (a) of this AD, if the torque value of any attachment bolt is found to be outside the limits specified in Dornier Service Bulletin SB–328J–71–109, dated March 26, 2001, including AMM TR 71–130, dated March 8, 2001: Before further flight, do all actions associated with replacing all bolts on the vibration isolator on which the improperly torqued bolt was found (including performing a detailed visual inspection to determine the condition of

components of the vibration isolator and replacement of any damaged components with new components, removing the existing bolts and washers that attach the forward engine mount vibration isolators to the engine, installing new bolts to reattach the forward engine mount vibration isolators to the engine, and torquing the new bolts to adequate torque values), according to the service bulletin.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

#### **Torque Requirements**

(c) For all airplanes: As of the effective date of this AD, no one may install an attachment bolt on the forward engine mount vibration isolators on any airplane, unless the attachment bolt is torqued within the limits specified in Dornier 328–300 AMM TR 71–130, dated March 8, 2001.

### **Alternative Methods of Compliance**

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

### **Special Flight Permits**

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Note 4:** The subject of this AD is addressed in German airworthiness directive 2001–163, dated June 14, 2001.

Issued in Renton, Washington, on September 7, 2001.

### Vi L. Lipski,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01–23070 Filed 9–13–01; 8:45 am]

BILLING CODE 4910-13-U

### FEDERAL COMMUNICATIONS COMMISSION

### 47 CFR Part 73

[DA 01-2088, MM Docket No. 01-222, RM-10240]

# Digital Television Broadcast Service; Charleston, SC

**AGENCY:** Federal Communications Commission.

**ACTION:** Proposed rule.

**SUMMARY:** The Commission requests comments on a petition filed by WCIV, LLC, licensee of station WCIV(TV), NTSC channel 4, Charleston, South Carolina, proposing the substitution of DTV channel 34 for DTV channel 53. DTV Channel 34 can be allotted to Charleston, South Carolina, in compliance with the principle community coverage requirements of Section 73.625(a) at reference coordinates (32-55-28 N. and 79-41-58 W.). As requested, we propose to allot DTV Channel 34 with a power of 340 and a height above average terrain (HAAT) of 597 meters.

**DATES:** Comments must be filed on or before October 29, 2001, and reply comments on or before November 13, 2001.

ADDRESSES: Federal Communications Commission, 445 12th Street, SW., Room TW-A325, Washington, DC 20554. In addition to filing comments with the FCC, interested parties should serve the petitioner, or its counsel or consultant, as follows: Thomas P. Van Wazer, Sidley & Austin, 1722 Eye Street, NW., Washington, DC 20006 (Counsel for WCIV, LLC).

FOR FURTHER INFORMATION CONTACT: Pam Blumenthal, Mass Media Bureau, (202) 418–1600.

**SUPPLEMENTARY INFORMATION:** This is a synopsis of the Commission's Notice of Proposed Rule Making, MM Docket No. 01-222, adopted September 5, 2001, and released September 7, 2001. The full text of this document is available for public inspection and copying during regular business hours in the FCC Reference Information Center, Portals II, 445 12th Street, SW., Room CY-A257, Washington, DC, 20554. This document may also be purchased from the Commission's duplicating contractor, Qualex International, Portals II, 445 12th Street, SW., Room CY-B402, Washington, DC, 20554, telephone 202-863-2893, facsimile 202-863-2898, or via-e-mail qualexint@aol.com.

Provisions of the Regulatory Flexibility Act of 1980 do not apply to this proceeding. Members of the public should note that from the time a Notice of Proposed Rule Making is issued until the matter is no longer subject to Commission consideration or court review, all *ex parte* contacts are prohibited in Commission proceedings, such as this one, which involve channel allotments. See 47 CFR 1.1204(b) for rules governing permissible *ex parte* contacts.

For information regarding proper filing procedures for comments, see 47 CFR 1.415 and 1.420.

### List of Subjects in 47 CFR Part 73

Television, Digital television broadcasting.

For the reasons discussed in the preamble, the Federal Communications Commission proposes to amend 47 CFR part 73 as follows:

## PART 73—TELEVISION BROADCAST SERVICES

1. The authority citation for part 73 continues to read as follows:

**Authority:** 47 U.S.C. 154, 303, 334, and 336.

### §73.622 [Amended]

2. Section 73.622(b), the Table of Digital Television Allotments under South Carolina is amended by removing DTV Channel 53 and adding DTV Channel 34 at Charleston.

Federal Communications Commission.

### Barbara A. Kreisman,

Chief, Video Services Division, Mass Media Bureau.

[FR Doc. 01–23059 Filed 9–13–01; 8:45 am] BILLING CODE 6712–01–P

### FEDERAL COMMUNICATIONS COMMISSION

### 47 CFR Part 73

[DA 01-2048, MM Docket No. 01-208, RM-10205]

# Digital Television Broadcast Service; Harrisburg, PA

**AGENCY:** Federal Communications Commission.

**ACTION:** Proposed rule.

SUMMARY: The Commission requests comments on a petition filed by Harrisburg Television, Inc., licensee of station WHTM—TV, NTSC channel 27, Harrisburg, Pennsylvania, proposing the substitution of DTV channel 10 for station WHTM—TV's assigned DTV channel 57. DTV Channel 57 can be allotted to Harrisburg, Pennsylvania, in compliance with the principle community coverage requirements of

Section 73.625(a) at reference coordinates (40–18–57 N. and 76–57–02 W.). As requested, we propose to allot DTV Channel 10 to Harrisburg with a power of 14.0 and a height above average terrain (HAAT) of 346 meters. However, since the community of Harrisburg is located within 400 kilometers of the U.S.-Canadian border, concurrence from the Canadian government must be obtained for this allotment.

**DATES:** Comments must be filed on or before October 29, 2001, and reply comments on or before November 13, 2001.

ADDRESSES: Federal Communications Commission, 445 12th Street, SW., Room TW-A325, Washington, DC 20554. In addition to filing comments with the FCC, interested parties should serve the petitioner, or its counsel or consultant, as follows: Thomas P. Van Wazer, Sidney, Austin, Brown & Wood, 1722 Eye Street, NW., Washington, DC 20006 (Counsel for Harrisburg Television, Inc.).

FOR FURTHER INFORMATION CONTACT: Pam Blumenthal, Mass Media Bureau, (202) 418–1600.

**SUPPLEMENTARY INFORMATION:** This is a synopsis of the Commission's Notice of Proposed Rule Making, MM Docket No. 01-208, adopted August 30, 2001, and released September 5, 2001. The full text of this document is available for public inspection and copying during regular business hours in the FCC Reference Information Center, Portals II, 445 12th Street, SW., Room CY-A257, Washington, DC, 20554. This document may also be purchased from the Commission's duplicating contractor, Qualex International, Portals II, 445 12th Street, SW., Room CY-B402, Washington, DC, 20554, telephone 202-863-2893, facsimile 202-863-2898, or via-e-mail qualexint@aol.com.

Provisions of the Regulatory Flexibility Act of 1980 do not apply to this proceeding.

Members of the public should note that from the time a Notice of Proposed Rule Making is issued until the matter is no longer subject to Commission consideration or court review, all ex parte contacts are prohibited in Commission proceedings, such as this one, which involve channel allotments. See 47 CFR 1.1204(b) for rules governing permissible ex parte contacts.

For information regarding proper filing procedures for comments, see 47 CFR 1.415 and 1.420.

### List of Subjects in 47 CFR Part 73

Television, Digital television broadcasting.

For the reasons discussed in the preamble, the Federal Communications Commission proposes to amend 47 CFR part 73 as follows:

# PART 73—TELEVISION BROADCAST SERVICES

1. The authority citation for part 73 continues to read as follows:

**Authority:** 47 U.S.C. 154, 303, 334, and

#### §73.622 [Amended]

2. Section 73.622(b), the Table of Digital Television Allotments under Pennsylvania is amended by removing DTV Channel 57 and adding DTV Channel 10 at Harrisburg.

Federal Communications Commission. **Barbara A. Kreisman**,

Chief, Video Services Division, Mass Media Bureau

[FR Doc. 01–23054 Filed 9–13–01; 8:45 am] **BILLING CODE 6712–01–P** 

### FEDERAL COMMUNICATIONS COMMISSION

#### 47 CFR Part 73

[DA 01-2049, MM Docket No. 01-207, RM-10206]

### Digital Television Broadcast Service; Alexandria, MN

**AGENCY:** Federal Communications Commission.

**ACTION:** Proposed rule.

**SUMMARY:** The Commission requests comments on a petition filed by KSAX-TV, Inc., licensee of station KSAX(TV), NTSC channel 42, Alexandria, Minnesota, proposing the substitution of DTV channel 36 for station KSAX(TV)'s assigned DTV channel 14. DTV Channel 36 can be allotted to Alexandria, Minnesota, in compliance with the principle community coverage requirements of Section 73.625(a) at reference coordinates (45-41-59 N. and 95-10-35 W.). As requested, we propose to allot DTV Channel 36 to Alexandria with a power of 1000 and a height above average terrain (HAAT) of 340 meters. However, since the community Alexandria is located 400 kilometers from the U.S.-Canadian border, concurrence from the Canadian government must be obtained for this allotment.

**DATES:** Comments must be filed on or before October 29, 2001, and reply comments on or before November 13, 2001

**ADDRESSES:** Federal Communications Commission, 445 12th Street, SW.,