

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022-08-07 Embraer S.A. (Type Certificate Previously Held by Yaborã Indústria Aeronáutica S.A.): Amendment 39-22010 ; Docket No. FAA-2022-0451; Project Identifier AD-2022-00265-T.

(a) Effective Date

This airworthiness directive (AD) is effective April 26, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Embraer S.A. airplanes identified in paragraphs (c)(1) through (4) of this AD, certificated in any category.

(1) Model ERJ 170-100 STD, -100 LR, -100 SU, and -100 SE airplanes.

(2) Model ERJ 170-200 STD, -200 LR, and -200 SU airplanes.

(3) Model ERJ 190-100 STD, -100 LR, -100 IGW, and -100 ECJ airplanes.

(4) Model ERJ 190-200 STD, -200 LR, and -200 IGW airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 56, Windows.

(e) Unsafe Condition

This AD was prompted by a report of the failure of the inner pane of the passenger window to meet maximum operating pressure and lack of fail-safe design. The FAA is issuing this AD to address this condition, which could result in possible serious injury to a passenger near the window due to rapid decompression, and consequent reduced ability of the flightcrew to maintain the safe flight and landing of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definition of Affected Parts

Affected parts are NORDAM passenger windows having part number NP00038-3.

(h) Identification of Affected Parts

Before further flight, determine whether any affected part is installed on the airplane. A review of the airplane maintenance records

is acceptable, if the manufacturer and part number of the installed windows can be conclusively determined from that review.

Note 1 to paragraph (h): Guidance for the actions required by paragraph (h) of this AD can be found in NORDAM Alert Service Bulletin ERJ 56-A01, dated January 18, 2022.

(1) *If any affected part is installed:* Before further flight, do a visual inspection of the outer window pane for cracking, and do the applicable action specified in paragraph (h)(1)(i) or (ii) of this AD.

(i) If any cracking is found, before further flight, replace the affected part with a serviceable window.

(ii) If no cracking is found, repeat the inspection thereafter before each flight, until the affected part is replaced, as specified in paragraph (h)(2) of this AD.

(2) Within 90 days after the effective date of this AD: Replace all affected parts installed on the airplane with serviceable windows.

(i) Terminating Action for Repetitive Inspections

Replacement of an affected part, as specified in paragraph (h)(2) of this AD, terminates the repetitive inspection requirements specified in paragraph (h)(1)(ii) of this AD for that part.

(j) Parts Installation Prohibition

As of the effective date of this AD, no person may install a NORDAM passenger window, part number (P/N) NP00038-3, on any airplane.

(k) Alternative Methods of Compliance (AMOCs).

(1) The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(l) Related Information

For more information about this AD, contact Jacob Fitch, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-4130; email jacob.fitch@faa.gov.

(m) Material Incorporated by Reference

None.

Issued on April 4, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-07708 Filed 4-6-22; 4:15 pm]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2021-1146; Airspace Docket No. 21-AGL-36]

RIN 2120-AA66

Amendment of Class E Airspace; Hallock, MN

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends the Class E airspace at Hallock, MN. This action due to an airspace review conducted as part of the decommissioning of the Humbolt very high frequency (VHF) omnidirectional range (VOR) as part of the VOR Minimal Operational Network (MON) Program.

DATES: Effective 0901 UTC, July 14, 2022. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

FOR FURTHER INFORMATION CONTACT: Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5711.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends the Class E airspace extending upward from

700 feet above the surface at Hallock Municipal Airport, Hallock, MN, to support instrument flight rule operations at this airport.

History

The FAA published a notice of proposed rulemaking (NPRM) in the **Federal Register** (86 FR 73203; December 27, 2021) for Docket No. FAA–2021–1146 to amend the Class E airspace at Hallock, MN. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6005 of FAA Order JO 7400.11F, dated August 10, 2021, and effective September 15, 2021, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in FAA Order JO 7400.11.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021. FAA Order JO 7400.11F is publicly available as listed in the **ADDRESSES** section of this document. FAA Order JO 7400.11F lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

Differences From the NPRM

Subsequent to publication, the FAA discovered a typographical error in the title of the NPRM, “Proposed Establishment of Class E Airspace; Hallock, MN” should have been “Proposed Amendment of Class E Airspace; Hallock, MN”. As this error was only in the title and does not impact the actual airspace being amended, it has been corrected in this action.

The Rule

This amendment to 14 CFR part 71 amends the Class E airspace extending upward from 700 feet above the surface at Hallock Municipal Airport, Hallock, MN, by removing the extension to the southeast of the airport as it is no longer needed.

This action is due to an airspace review conducted as part of the decommissioning of the Humbolt VOR, which provided navigation information for the instrument procedures at these airports, as part of the VOR MON Program.

FAA Order JO 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, “Environmental Impacts: Policies and Procedures,” paragraph 5–6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

- 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

71.1 [Amended]

- 2. The incorporation by reference in 14 CFR 71.1 of FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and

effective September 15, 2021, is amended as follows:

Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.

* * * * *

AGL MN E5 Hallock, MN [Amended]

Hallock Municipal Airport, MN
(Lat. 48°45′10″ N, long. 96°56′35″ W)

That airspace extending upward from 700 feet above the surface within a 6.4-mile radius of the Hallock Municipal Airport.

Issued in Fort Worth, Texas, on April 5, 2022.

Martin A. Skinner,

*Acting Manager, Operations Support Group,
ATO Central Service Center.*

[FR Doc. 2022–07590 Filed 4–8–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2021–1147; Airspace Docket No. 21–AGL–37]

RIN 2120–AA66

Amendment of Class E Airspace; Pembina, ND

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends the Class E airspace at Pembina, ND. This action is due to an airspace review conducted as part of the decommissioning of the Humbolt very high frequency (VHF) omnidirectional range (VOR) as part of the VOR Minimal Operational Network (MON) Program. The geographic coordinates of the airport are also being updated to coincide with the FAA’s aeronautical database.

DATES: Effective 0901 UTC, July 14, 2022. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

FOR FURTHER INFORMATION CONTACT: Jeffrey Claypool, Federal Aviation