

Figure 1 to paragraph (g) – Service Information References

| Airplane Model | Service Information |
|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|
| Model CL-600-2A12 | Bombardier Service Bulletin 601-0644, Revision 1, dated January 29, 2019 |
| Model CL-600-2B16 | Bombardier Service Bulletin 601-0644, Revision 1, dated January 29, 2019; or Bombardier Service Bulletin 604-30-007, Revision 1, dated January 29, 2019 |

(h) Required Actions for Airplanes Not Listed in the Service Information

For airplanes with a serial number that is not listed in section 1.A of the service information specified in figure 1 to paragraph (g) of this AD, and for Bombardier Model CL-600-1A11 airplanes: Within 6 years after the effective date of this AD, do applicable actions including an inspection for discrepancies of the potable water-line ribbon heater and repair of any discrepant potable water-line ribbon heaters using a method approved in accordance with the procedures specified in paragraph (i)(2) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Transport Canada AD CF-2021-13, dated April 1, 2021, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0090.

(2) For more information about this AD, contact Thomas Niczky, Aerospace Engineer,

Avionics and Electrical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7347; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 601-0644, Revision 1, dated January 29, 2019.

(ii) Bombardier Service Bulletin 604-30-007, Revision 1, dated January 29, 2019.

(3) For service information identified in this AD, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-2999; email ac.yul@aero.bombardier.com; internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 11, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-08824 Filed 4-25-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2021-0918; Airspace Docket No. 21-ACE-11]

RIN 2120-AA66

Amendment of United States Area Navigation (RNAV) Route T-251; Central United States

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends United States Area Navigation (RNAV) route T-251 in the central United States due to the decommissioning of the Malden, MO, (MAW) VHF Omnidirectional Range Tactical Air Navigation (VORTAC). This amendment supports the VHF Omnidirectional Range (VOR) Minimum Operational Network (MON) program for improved efficiency of the National Airspace System (NAS) while reducing the dependency on ground based navigational systems.

DATES: Effective date 0901 UTC, July 14, 2022. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Rules and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence

Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it modifies the route structure as necessary to preserve the safe and efficient flow of air traffic within the NAS.

History

The FAA published a notice of proposed rulemaking for Docket No. FAA-2021-0918, in the **Federal Register** (86 FR 60185; November 1, 2021), amending T-251. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal. One person submitted two comments, but no specifics pertaining to the proposal were included.

United States RNAV T-routes are published in paragraph 6011 of FAA Order JO 7400.11F, dated August 10, 2021, and effective September 15, 2021, which is incorporated by reference in 14 CFR 71.1. The RNAV routes listed in this document would be subsequently published in FAA Order JO 7400.11.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021. FAA Order JO 7400.11F is publicly available as listed in the **ADDRESSES** section of this document. FAA Order JO 7400.11F lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This action amends 14 CFR part 71 by amending RNAV route T-251 to extend the route further south in the central United States expanding the availability of RNAV routing in the NAS.

T-251: T-251 currently extends from the Farmington, MO, (FAM) VORTAC, north to the KOETZ, WI, waypoint (WP). This amendment extends T-251 by 69 nautical miles to the south of the Farmington, MO, VORTAC, to the new FRNIA, MO, WP. The FRNIA WP replaces the Malden, MO, VORTAC, which is scheduled to be decommissioned. As amended, T-251 extends between the FRNIA, MO, WP, and the KOETZ, WI, WP.

FAA Order JO 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action of amending RNAV route T-251, in support of efforts transitioning the NAS from ground-based to satellite-based navigation, qualifies for categorical exclusion under the National Environmental Policy Act (42 U.S.C. 4321 *et seq.*) and its implementing regulations at 40 CFR part 1500, and in accordance with FAA Order 1050.1F, Environmental Impacts: Policies and Procedures, paragraph 5-6.5a, which categorically excludes from further

environmental impact review rulemaking actions that designate or modify classes of airspace areas, airways, routes, and reporting points (see 14 CFR part 71, Designation of Class A, B, C, D, and E Airspace Areas; Air Traffic Service Routes; and Reporting Points); and paragraph 5-6.5b, which categorically excludes from further environmental impact review "Actions regarding establishment of jet routes and Federal airways (see 14 CFR 71.15, *Designation of jet routes and VOR Federal airways*) . . .". As such, this action is not expected to result in any potentially significant environmental impacts. In accordance with FAA Order 1050.1F, paragraph 5-2 regarding Extraordinary Circumstances, the FAA has reviewed this action for factors and circumstances in which a normally categorically excluded action may have a significant environmental impact requiring further analysis. Accordingly, the FAA has determined that no extraordinary circumstances exist that warrant preparation of an environmental assessment or environmental impact study.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021, is amended as follows:

Paragraph 6011 United States Area Navigation Routes

* * * * *

T-251 FRNIA, MO to KOETZ, WI [Amended]

| | | |
|----------------------|--------|----------------------------------------------|
| FRNIA, MO | WP | (Lat. 36°33'18.69" N, long. 089°54'40.47" W) |
| Farmington, MO (FAM) | VORTAC | (Lat. 37°40'24.46" N, long. 090°14'02.62" W) |
| Foristell, MO (FTZ) | VORTAC | (Lat. 38°41'39.60" N, long. 090°58'16.57" W) |
| RIVRS, IL | Fix | (Lat. 39°25'21.41" N, long. 090°55'56.70" W) |
| KAYUU, MO | WP | (Lat. 40°19'05.81" N, long. 091°41'36.59" W) |
| MERKR, IA | WP | (Lat. 40°49'16.02" N, long. 092°08'26.88" W) |
| AGENS, IA | Fix | (Lat. 41°01'43.78" N, long. 092°20'50.25" W) |

| | | |
|--------------------|---------|----------------------------------------------|
| PICRA, IA | WP | (Lat. 41°35'00.72" N, long. 092°32'34.29" W) |
| HAVOS, IA | WP | (Lat. 42°04'16.32" N, long. 092°28'29.38" W) |
| Waterloo, IA (ALO) | VOR/DME | (Lat. 42°33'23.39" N, long. 092°23'56.13" W) |
| ZEZDU, IA | Fix | (Lat. 42°49'29.02" N, long. 092°04'58.05" W) |
| FALAR, MN | Fix | (Lat. 43°34'26.04" N, long. 091°30'18.32" W) |
| KOETZ, WI | WP | (Lat. 44°13'15.00" N, long. 091°28'14.00" W) |

* * * * *

Issued in Washington, DC, on April 20, 2022.

Scott M. Rosenbloom,

Manager, Airspace Rules and Regulations.

[FR Doc. 2022-08786 Filed 4-25-22; 8:45 am]

BILLING CODE 4910-13-P

CONSUMER PRODUCT SAFETY COMMISSION

16 CFR Part 1235

[Docket No. CPSC-2016-0023]

Safety Standard for Baby Changing Products

AGENCY: Consumer Product Safety Commission.

ACTION: Direct final rule.

SUMMARY: In June 2018, the U.S. Consumer Product Safety Commission (CPSC or Commission) published a consumer product safety standard for baby changing products under section 104 of the Consumer Product Safety Improvement Act of 2008 (CPSIA). The standard incorporated by reference the 2018 ASTM International (ASTM) voluntary standard for baby changing products that was in effect at the time. The CPSIA sets forth a process for updating mandatory standards for durable infant or toddler products that are based on a voluntary standard, when a voluntary standards organization revises the standard. Consistent with the CPSIA update process, this direct final rule updates the mandatory standard for baby changing products to incorporate by reference ASTM's 2021 version of the voluntary standard.

DATES: The rule is effective on July 31, 2022, unless CPSC receives a significant adverse comment by May 26, 2022. If CPSC receives such a comment, it will publish a notification in the **Federal Register**, withdrawing this direct final rule before its effective date. The incorporation by reference of the publication listed in this rule is approved by the Director of the Federal Register as of July 31, 2022.

ADDRESSES: You can submit comments, identified by Docket No. CPSC-2016-0023, by any of the following methods:

Electronic Submissions: Submit electronic comments to the Federal eRulemaking Portal at: [https://](https://www.regulations.gov)

www.regulations.gov. Follow the instructions for submitting comments. CPSC does not accept comments submitted by electronic mail (email), except through <https://www.regulations.gov>, and as described below. CPSC encourages you to submit electronic comments by using the Federal eRulemaking Portal, as described above.

Mail/hand delivery/courier Written Submissions: Submit comments by mail/hand delivery/courier to: Division of the Secretariat, Consumer Product Safety Commission, 4330 East-West Highway, Bethesda, MD 20814; telephone: (301) 504-7479.

Alternatively, as a temporary option during the COVID-19 pandemic, you may email such submissions to: cpsc-os@cpsc.gov.

Instructions: All submissions must include the agency name and docket number for this direct final rule. CPSC may post all comments without change, including any personal identifiers, contact information, or other personal information provided, to: <https://www.regulations.gov>. Do not submit electronically: Confidential business information, trade secret information, or other sensitive or protected information that you do not want to be available to the public. If you wish to submit such information, please submit it according to the instructions for mail/hand delivery/courier written submissions.

Docket: For access to the docket to read background documents or comments received, go to: <https://www.regulations.gov>, and insert the docket number, CPSC-2016-0023, into the "Search" box, and follow the prompts.

FOR FURTHER INFORMATION CONTACT: Keysha Walker, Compliance Officer, U.S. Consumer Product Safety Commission, 4330 East-West Highway, Bethesda, MD 20814; telephone: (301) 504-6820; email: KWalker@cpsc.gov.

SUPPLEMENTARY INFORMATION:

A. Background

1. Statutory Authority

Section 104(b)(1) of the CPSIA requires the Commission to assess the effectiveness of voluntary standards for durable infant or toddler products and adopt mandatory standards for those products. 15 U.S.C. 2056a(b)(1). The mandatory standard must be

"substantially the same as" the voluntary standard, or it may be "more stringent than" the voluntary standard, if the Commission determines that more stringent requirements would further reduce the risk of injury associated with the product. *Id.*

Section 104(b)(4)(B) of the CPSIA specifies the process for updating the Commission's rules when a voluntary standards organization revises a standard that the Commission incorporated by reference under section 104(b)(1). First, the voluntary standards organization must notify the Commission of the revision. Once the Commission receives this notification, the Commission may reject or accept the revised standard. The Commission may reject the revised standard by notifying the voluntary standards organization, within 90 days of receiving notice of the revision, that it has determined that the revised standard does not improve the safety of the consumer product and that it is retaining the existing standard. If the Commission does not take this action to reject the revised standard, the revised voluntary standard will be considered a consumer product safety standard issued under section 9 of the Consumer Product Safety Act (15 U.S.C. 2058), effective 180 days after the Commission received notification of the revision or on a later date specified by the Commission in the **Federal Register**. 15 U.S.C. 2056a(b)(4)(B).

2. Safety Standard for Baby Changing Products

Under section 104(b)(1) of the CPSIA, the Commission adopted a mandatory rule for baby changing products, codified in 16 CFR part 1235. The rule incorporated by reference ASTM F2388-18, *Standard Consumer Safety Specification for Baby Changing Products for Domestic Use*, with no modifications. 83 FR 29672 (June 26, 2018). At the time the Commission published the final rule, ASTM F2388-18 was the current version of the voluntary standard.

On February 1, 2022, ASTM notified CPSC that it had revised the voluntary standard for baby changing products, approving ASTM F2388-21 on November 15, 2021.¹ As discussed below, based on CPSC staff's review of

¹ ASTM published ASTM F2388-21 in January 2022.