

rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022–08–09 Pilatus Aircraft Ltd.:

Amendment 39–22012; Docket No. FAA–2022–0084; Project Identifier MCAI–2020–01312–A.

(a) Effective Date

This airworthiness directive (AD) is effective June 14, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Pilatus Aircraft Ltd. Model PC–24 airplanes, all serial numbers, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 2200, Auto Flight System; 2400, Electrical Power System; 3140, Central Computers (EICAS); 3500, Oxygen System; and 4500, Central Maint, Computer.

(e) Unsafe Condition

This AD was prompted by a failure of the dual ethernet communication channel on a dual-channel data concentration and processing unit, which triggered the opening of electronic circuit breakers that caused several unintended system activations. The FAA is issuing this AD to prevent failure of the dual ethernet communication channel on a dual-channel data concentration and processing unit. The unsafe condition, if not addressed, could result in increased pilot workload and reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For Group 1 airplanes as defined under the "Definitions" section in European Union Aviation Safety Agency AD 2020–0200, dated September 21, 2020 (EASA AD 2020–0200): Install the build 7.3 standard software upgrade to the utility management system software in accordance with paragraph 1 and the "Ref. Publications" section of EASA AD 2020–0200, except you are required to comply within 30 days after the effective date of this AD. After updating the software, do not install on that airplane utility management system software that is earlier than version 7.3.

(2) For Group 2 airplanes as defined under the "Definitions" section in EASA AD 2020–0200: As of the effective date of this AD, do not install utility management system software that is earlier than version 7.3 on any airplane.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i) of this AD and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector,

or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

For more information about this AD, contact Doug Rudolph, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329–4059; email: doug.rudolph@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2020–0200, dated September 21, 2020.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2022–0084.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 3, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–09815 Filed 5–9–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2022–0043; Airspace Docket No. 21–ASW–25]

RIN 2120–AA66

Amendment of Class E Airspace; Weatherford, OK

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends the Class E airspace at Weatherford, OK. This action as the result of an airspace review caused by the decommissioning of the Weatherford non-directional beacon (NDB). The geographic coordinates of the airport are also being updated to coincide with the FAA's aeronautical database.

DATES: Effective 0901 UTC, July 14, 2022. The Director of the Federal Register approves this incorporation by reference action under 1 CFR 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

FOR FURTHER INFORMATION CONTACT: Rebecca Shelby, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5857.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends the Class E airspace extending upward from 700 feet above the surface at Thomas P. Stafford Airport, Weatherford, OK, to support instrument flight rule operations at this airport.

History

The FAA published a notice of proposed rulemaking in the **Federal Register** (87 FR 8992; February 17, 2022) for Docket No. FAA-2022-0043 to amend the Class E airspace at Weatherford, OK. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA.

No comments were received. Class E airspace designations are published in paragraph 6005 of FAA Order JO 7400.11F, dated August 10, 2021, and effective September 15, 2021, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in FAA Order JO 7400.11.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021. FAA Order JO 7400.11F is publicly available as listed in the **ADDRESSES** section of this document. FAA Order JO 7400.11F lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This amendment to 14 CFR part 71 amends the Class E airspace extending upward from 700 feet above the surface to within a 6.5-mile (reduced from a 7.1-mile) radius at Thomas P. Stafford Airport, Weatherford, OK, by removing the Weatherford NDB and updates the geographic coordinates of the airport to coincide with the FAA's aeronautical database, removing the city associated with the airport in the header of the airspace legal description to comply with changes to FAA Order JO 7400.2N, Procedures for Handling Airspace Matters. This action is necessary due to an airspace review caused by the decommissioning of the Weatherford NDB which provided navigation information for the instrument procedures this airport.

FAA Order JO 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic

procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5-6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

Lists of Subjects in 14 CFR 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021, is amended as follows:

Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.

* * * * *

ASW OK E5 Weatherford, OK [Amended]

Thomas P. Stafford Airport, OK
(Lat. 35°32'45" N, long. 98°40'07" W)

That airspace extending upward from 700 feet above the surface within a 6.5-mile radius of Thomas P. Stafford Airport.

Issued in Fort Worth, Texas, on May 2, 2022.

Martin A. Skinner,

Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. 2022-09754 Filed 5-9-22; 8:45 am]

BILLING CODE 4910-13-P