(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 737–53A1384 RB, dated September 10, 2020, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737–53A1384 RB, dated September 10, 2020.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737–53A1384, dated September 10, 2020, which is referred to in Boeing Alert Requirements Bulletin 737–53A1384 RB, dated September 10, 2020.

(h) Exceptions to Service Information Specifications

(1) Where the Compliance Time column and the notes of the tables in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 737–53A1384 RB, dated September 10, 2020, use the phrase "the Original Issue date of Requirements Bulletin 737–53A1384 RB," this AD requires using "the effective date of this AD."

(2) Where Boeing Alert Requirements Bulletin 737–53A1384 RB, dated September 10, 2020, specifies contacting Boeing for repair instructions or for alternative inspections: This AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions, using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

For more information about this AD, contact Bill Ashforth, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3520; email: bill.ashforth@faa.gov.

(k) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.
- (i) Boeing Alert Requirements Bulletin 737–53A1384 RB, dated September 10, 2020.
- (ii) [Reserved]
- (3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet https://www.myboeingfleet.com.
- (4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.
- (5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, fr.inspection@nara.gov, or go to: https://www.archives.gov/federal-register/cfr/ibrlocations.html.

Issued on May 25, 2022.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-13750 Filed 6-28-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2021-0864; Airspace Docket No. 21-AAL-13]

RIN 2120-AA66

Establishment of United States Area Navigation (RNAV) Route T–415; Gulkana, AK

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes United States Area Navigation (RNAV) route T–415 in the vicinity of Gulkana, AK in support of a large and comprehensive Troute modernization project for the state of Alaska.

DATES: Effective date 0901 UTC, September 8, 2022. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments. ADDRESSES: FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Rules and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

FOR FURTHER INFORMATION CONTACT:

Jesse Acevedo, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I. Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it expands the availability of RNAV in Alaska and improve the efficient flow of air traffic within the National Airspace System by lessening the dependency on ground based navigation.

History

The FAA published a notice of proposed rulemaking for Docket No. FAA–2021–0864 in the **Federal Register** (86 FR 59068; October 26, 2021), establishing United States Area Navigation (RNAV) route T–415 in the vicinity of Gulkana, AK in support of a large and comprehensive T-route modernization project for the state of Alaska. Interested parties were invited to participate in this rulemaking effort by submitting comments on the proposal. There were no comments received.

United States Area Navigation Routes are published in paragraph 6011 of FAA Order JO 7400.11F dated August 10, 2021 and effective September 15, 2021, which is incorporated by reference in 14 CFR 71.1. The RNAV route listed in this document would be published subsequently in FAA Order JO 7400.11F.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021. FAA Order JO 7400.11F is publicly available as listed in the **ADDRESSES** section of this document. FAA Order JO 7400.11F lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Rule

This action amends 14 CFR part 71 by establishing RNAV route T-415 in the vicinity of Gulkana, AK in support of a large and comprehensive T-route modernization project for the state of Alaska.

The route is described below. *T–415*: This action establishes T–415 extending between the WRNGL, AK, waypoint (WP), located over the McCarthy Airport (PAMX), AK and the Gulkana, AK, (GKN) VHF Omnidirectional Range/Distance Measuring Equipment (VOR/DME) navigational aide (NAVAID).

FÃA Order JO 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

Regulatory Notices and Analyses

The FAA determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034;

WRNGL, AK GRYNE, AK DUYZI, AK Gulkana, AK (GKN) February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA determined that this airspace action of establishing RNAV route T-415 in the vicinity of Gulkana, AK qualifies for categorical exclusion under the National Environmental Policy Act (42 U.S.C. 4321 et seq.) and its implementing regulations at 40 CFR part 1500, and in accordance with FAA Order 1050.1F, Environmental Impacts: Policies and Procedures, paragraph 5-6.5a, which categorically excludes from further environmental impact review rulemaking actions that designate or modify classes of airspace areas, airways, routes, and reporting points (see 14 CFR part 71, Designation of Class A, B, C, D, and E Airspace Areas; Air Traffic Service Routes: and Reporting Points), and paragraph 5-6.5i, which categorically excludes from further environmental review the establishment of new or revised air traffic control procedures conducted at 3,000 feet or more above ground level (AGL); procedures conducted below 3,000 feet AGL that do not cause traffic to be routinely routed over noise sensitive areas; modifications to currently approved procedures conducted below 3,000 feet AGL that do not significantly increase noise over noise sensitive areas; and increases in minimum altitudes and landing minima. As such, this action is not

expected to result in any potentially significant environmental impacts. In accordance with FAA Order 1050.1F, paragraph 5–2 regarding Extraordinary Circumstances, the FAA has reviewed this action for factors and circumstances in which a normally categorically excluded action may have a significant environmental impact requiring further analysis. Accordingly, the FAA has determined that no extraordinary circumstances exist that warrant preparation of an environmental assessment or environmental impact study.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021, is amended as follows:

Paragraph 6011 United States Area Navigation Routes.

T-415 WRNGL, AK to Gulkana, AK (GKN) [New]

WP (Lat. 61°28′54.40″ N, long. 143°59′24.23″ W)
WP (Lat. 61°33′21.59″ N, long. 144°15′00.78″ W)
WP (Lat. 61°45′00.59″ N, long. 144°46′01.75″ W)
VOR/DME (Lat. 62°09′13.51″ N, long. 145°26′50.51″ W)

Issued in Washington, DC, on June 22, 2022.

Scott M. Rosenbloom,

 $\label{lem:manager} Manager, Airspace \, Rules \, and \, Regulations. \\ [FR \, Doc. \, 2022-13690 \, Filed \, 6-28-22; \, 8:45 \, am]$

BILLING CODE 4910-13-P