

# Proposed Rules

Federal Register

Vol. 88, No. 163

Thursday, August 24, 2023

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2023-1715; Project Identifier MCAI-2023-00548-T]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier, Inc., Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model CL-600-2B16 (604 Variant) airplanes. This proposed AD was prompted by a report that some airplanes were delivered without a portable protective breathing equipment (PBE) device located in the forward left side cabin area of the airplane. This proposed AD would require visually inspecting the forward left side cabin area of the airplane to determine if the portable PBE device is installed and, if not installed, would require installing the portable PBE device along with the associated placard. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by October 10, 2023.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5

p.m., Monday through Friday, except Federal holidays.

**AD Docket:** You may examine the AD docket at *regulations.gov* under Docket No. FAA-2023-1715; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

**Material Incorporated by Reference:**

- For service information identified in this NPRM, contact Bombardier Business Aircraft Customer Response Center, 400 Côte Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514 855 2999; email: *ac.yul@aero.bombardier.com*; website: *bombardier.com*.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

**FOR FURTHER INFORMATION CONTACT:**

Gabriel Kim, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email *9-avs-nyaco-cos@faa.gov*.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2023-1715; Project Identifier MCAI-2023-00548-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each

substantive verbal contact received about this NPRM.

**Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Gabriel Kim, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email *9-avs-nyaco-cos@faa.gov*. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Background**

Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF-2023-21, dated March 30, 2023 (Transport Canada AD CF-2023-21) (also referred to after this as the MCAI), to correct an unsafe condition on certain Bombardier, Inc., Model CL-600-2B16 (604 Variant) airplanes. The MCAI states that some airplanes were delivered without a portable PBE device located in the forward left side cabin area of the airplane. The portable PBE device is required to meet the certification standards of Transport Canada and the FAA<sup>1</sup> and provides protection for crew members when investigating or combatting a fire in the cabin.

The FAA is proposing this AD to address the unsafe condition on these products. You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA-2023-1715.

<sup>1</sup> 14 CFR 25.1439.

**Related Service Information Under 14 CFR Part 51**

The FAA reviewed Bombardier Service Bulletin 604–35–008, Revision 02, dated January 13, 2023. This service information specifies procedures for performing a general visual inspection of the forward left side cabin area of the airplane for a portable PBE device and, if missing, installing a portable PBE device and its associated placard. This service information is reasonably available because the interested parties have access to it through their normal

course of business or by the means identified in the ADDRESSES section.

**FAA’s Determination**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop

on other products of the same type design.

**Proposed AD Requirements in This NPRM**

This proposed AD would require accomplishing the actions specified in the service information already described.

**Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 139 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
0.5 work-hour × \$85 per hour = \$43 .....	\$0	\$43	\$5,977

The FAA estimates the following costs to do any necessary on-condition action that would be required based on the results of any required actions. The FAA has no way of determining the number of aircraft that might need this on-condition action:

**ESTIMATED COSTS OF ON-CONDITION ACTIONS**

Labor cost	Parts cost	Cost per product
2 work-hours × \$85 per hour = \$170 ....	\$2,157	\$2,327

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Bombardier, Inc.:** Docket No. FAA–2023–1715; Project Identifier MCAI–2023–00548–T.

**(a) Comments Due Date**

The FAA must receive comments on this airworthiness directive (AD) by October 10, 2023.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Bombardier, Inc., Model CL–600–2B16 (604 Variant) airplanes, certificated in any category, with serial numbers as identified in the Bombardier Service Bulletin 604–35–008, Revision 02, dated January 13, 2023.

**(d) Subject**

Air Transport Association (ATA) of America Code: 35, Oxygen.

**(e) Unsafe Condition**

This AD was prompted by a report that some airplanes were delivered without a portable protective breathing equipment (PBE) device located in the forward left side cabin area of the airplane. The FAA is issuing this AD to address a missing portable PBE device. The unsafe condition, if not addressed, could result in inadequate protection for crew members when investigating or combatting a fire in the cabin.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Visual Inspection for Portable PBE**

Within 12 months from the effective date of this AD, do a general visual inspection of the forward left side cabin area of the airplane and verify if a portable PBE device, marked with Technical Standard Order (TSO) C116 or C116a, is installed and placarded, in accordance with Section 2.B. of

the Accomplishment Instructions of Bombardier Service Bulletin 604–35–008, Revision 02, dated January 13, 2023. If the PBE device is missing, before further flight, install a portable PBE device marked with TSO C116 or TSO C116a and its associated placard, in accordance with section 2.B. of the Accomplishment Instructions of Bombardier Service Bulletin 604–35–008, Revision 02, dated January 13, 2023.

#### (h) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager, International Validation Branch, mail it to the address identified in paragraph (i)(2) of this AD or email to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov). If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada or Bombardier, Inc.'s Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

#### (i) Additional Information

(1) Refer to Transport Canada AD CF–2023–21, dated March 30, 2023, for related information. This Transport Canada AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–1715.

(2) For more information about this AD, contact Gabriel Kim, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

#### (j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 604–35–008, Revision 02, dated January 13, 2023.

(ii) [Reserved]

(3) For service information identified in this AD, contact Bombardier, Inc., Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–2999; email: [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); website: [bombardier.com](http://bombardier.com).

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th

Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: [www.archives.gov/federal-register/cfr/ibr-locations.html](http://www.archives.gov/federal-register/cfr/ibr-locations.html).

Issued on August 17, 2023.

#### Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–18169 Filed 8–23–23; 8:45 am]

BILLING CODE 4910–13–P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2023–1716; Project Identifier MCAI–2022–00168–Q]

RIN 2120–AA64

#### Airworthiness Directives; Thales AVS France SAS Flight Management Computer Navigation Modules

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Thales AVS France SAS (Thales) flight management computer navigation modules (FMC2 NAVM) installed on, but not limited to, airplanes. This AD was prompted by reports that, due to software issues, certain FMC2 NAVM navigation modules provide erroneous data to the flight management computer, compromising safe flight of the airplane. This proposed AD would require revising the existing aircraft flight manual (AFM) for your airplane and updating the navigation database. This proposed AD would also prohibit installing a database unless certain procedures were removed. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this NPRM by October 10, 2023.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.
- *Fax:* (202) 493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–

30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–1716; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

*Material Incorporated by Reference:*

• For service information identified in this NPRM, contact Thales AVS France SAS, 75–77 Avenue Marcel Dassault, 33700 Merignac, France; phone: +33 7 86 33 59 20; email: [continued.airworthiness@thalesgroup.com](mailto:continued.airworthiness@thalesgroup.com).

• You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110.

**FOR FURTHER INFORMATION CONTACT:** Nicholas Rediess, Aviation Safety Engineer, FAA, 1701 Columbia Avenue, College Park, GA 30337; phone: (781) 238–7159; email: [9-AVS-AIR-BACOCOS@faa.gov](mailto:9-AVS-AIR-BACOCOS@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2023–1716; Project Identifier MCAI–2022–00168–Q” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.